COMMERCIAL PROPERTY INSURANCE BROKER SUBMISSION

Insured:

Crestview Hospitality & Retail Properties LLC

Mixed-Occupancy Commercial Portfolio | 4 Locations Across 4 States

Submission Detail	Information
Submission Date	May 12, 2026
Requested Effective Date	July 1, 2026
Policy Period	July 1, 2026 — June 30, 2027
Total Insured Value (TIV)	$39,540,000
Number of Locations	4 (New Orleans LA | Tulsa OK | Miami FL | Seattle WA)
Expiring Annual Premium	$618,400
Target Premium Range	$620,000 – $680,000
Submitting Broker	Harrington & Associates Insurance Brokers LLC
Broker Contact	Renee M. Harrington, CIC CPCU | (504) 555-0212 | r.harrington@harribrokers.com

HARRINGTON & ASSOCIATES INSURANCE BROKERS LLC

909 Poydras St, Suite 1800 | New Orleans, LA 70112 | License No. LA-0291047

SECTION 1 — BROKER COVER LETTER

May 12, 2026

Dear Underwriter,

Harrington & Associates Insurance Brokers LLC submits this commercial property package on behalf of Crestview Hospitality & Retail Properties LLC ("Crestview" or the "Insured"), a privately-held mixed-use real estate company based in New Orleans, Louisiana. We have managed this account for six years and are seeking renewal terms for the July 1, 2026 effective date following a non-renewal from incumbent carrier AmTrust Financial Services.

Crestview owns and operates a portfolio of hospitality, retail, and restaurant properties across the Gulf South and Pacific Northwest. The portfolio is diverse in both occupancy class and construction vintage — ranging from a 1985-built boutique hotel in New Orleans to a 2015-built waterfront restaurant in Miami. We acknowledge this portfolio presents a more complex risk profile than a homogeneous industrial book and have prepared this submission to address each location's specific underwriting considerations in full.

Key submission highlights and candid risk disclosures:

- LOC-1 (New Orleans, LA — Boutique Hotel): The highest-risk location in the portfolio. Zone VE coastal flood exposure, Joisted Masonry construction (1985 vintage), partial sprinkler coverage (60%), and an aging plumbing system with confirmed galvanized sections. The insured has committed to a 180-day sprinkler extension plan and plumbing remediation program — detailed in Section 4 and Exhibit N.
- LOC-2 (Tulsa, OK — Retail Center): Modern Non-Combustible Light Steel construction (2005), but situated in the highest hail-frequency corridor in the US (Hail Score 9 — High). Roof replacement budgeted for Q3 2026. Prior attritional hail loss in 2024 ($28,000) is fully documented.
- LOC-3 (Miami, FL — Waterfront Restaurant): MNC construction (2015), HVHZ zone. High occupancy hazard class (B1: 120 pts — Restaurant/Food Service). Full sprinkler and suppression systems throughout including Ansul hood suppression. Loss-free since acquisition.
- LOC-4 (Seattle, WA — Mixed-Use Office/Retail): Modified Fire Resistive construction (1999), moderate vacancy (18%), situated in Zone AH/AO (Seattle flood fringe) with wildfire moderate exposure and EQ PML of 18% (Cascadia fault zone). ADA improvements pending — timeline enclosed.
- Prior Carrier Non-Renewal (LOC-1 and LOC-2): AmTrust issued underwriting non-renewals for LOC-1 (citing sprinkler deficiency and aging systems) and LOC-2 (citing hail frequency). LOC-3 and LOC-4 are being re-marketed simultaneously for portfolio consolidation. Full non-renewal notices and our response letters are enclosed as Exhibit F.
- Loss history: 4 losses over 5 years, total incurred $433,500. Three of four losses are at LOC-1 (water, fire suppression activation, wind). One hail loss at LOC-2. Full narratives in separate Loss Run document (Exhibit A).

We request quotations by June 5, 2026. Given the complexity of LOC-1, we welcome a pre-submission call with the underwriter and can arrange a loss control inspection at short notice.

Respectfully submitted,

Renee M. Harrington, CIC CPCU
President, Harrington & Associates Insurance Brokers LLC
Direct: (504) 555-0212 | r.harrington@harribrokers.com

SECTION 2 — INSURED ACCOUNT OVERVIEW

2.1 Named Insured & Entity Information

Field	Detail
Named Insured	Crestview Hospitality & Retail Properties LLC
Entity Type	Limited Liability Company
State of Formation	Louisiana (registered: LA, OK, FL, WA)
Federal Tax ID	On file with broker
Principal Office	400 Magazine St, Suite 300, New Orleans, LA 70130
Year Founded	2011
Ownership	Privately held — founder-operated; two principal partners
Key Executive	Thomas R. Crestview III, President & Managing Member
Years in Business	15

2.2 Business Operations

Operating Metric	Value
Annual Gross Revenues (2025)	$8,940,000 (combined hospitality, retail, F&B revenues)
Total Managed Square Footage	173,500 sq. ft. (all locations)
Number of Employees (Crestview owned/managed)	42 FTE + 85 seasonal/PT
Portfolio Occupancy	86% (LOC-4 partial vacancy — see detail)
NAICS Codes	721110 (Hotels); 722511 (Restaurants); 531120 (Lessors of Nonresidential)

SECTION 3 — SCHEDULE OF LOCATIONS / STATEMENT OF VALUES

3.1 Location Summary

Loc #	Address	City	Occupancy	Const. Class	Yr Built	Sq Ft	Bldg RCV	BPP	BI/EE	TIV
LOC-1	124 Bourbon St	New Orleans, LA 70116	Hospitality/Hotel	JM Class 2	1985	68,000	$12,400,000	$1,800,000	$3,200,000	$17,400,0
LOC-2	5501 E 41st St	Tulsa, OK 74135	Retail — General	NC Light Steel Class 3	2005	45,000	$5,200,000	$680,000	$820,000	$6,700,0
LOC-3	3800 NE 2nd Ave	Miami, FL 33137	Restaurant / Food Svc	MNC Class 4	2015	8,500	$2,100,000	$420,000	$960,000	$3,480,0
LOC-4	1420 5th Ave	Seattle, WA 98101	Mixed Use Office+Retail	MFR Class 5	1999	52,000	$9,800,000	$760,000	$1,400,000	$11,960,0
TOTAL						**173,500**	**$29,500,000**	**$3,660,000**	**$6,380,000**	**$39,540,0**

Construction Key: JM = Joisted Masonry (Class 2) | NC = Non-Combustible Light Steel (Class 3) | MNC = Masonry Non-Combustible (Class 4) | MFR = Modified Fire Resistive (Class 5)

3.2 Valuation Methodology

Parameter	Detail
Valuation Basis	Replacement Cost Value (RCV) — Agreed Value endorsement requested
Appraisal Platform	Cotality Marshall & Swift RCT Express — Per-location appraisals, March 2026
Insurance-to-Value (ITV)	100% at all locations — ITV certification enclosed (Exhibit G)
Co-Insurance	Agreed Value Endorsement requested — waiving co-insurance at all locations
Business Income Basis	Actual Loss Sustained — 18 months all locations
Inflation Guard	4% automatic annual increase requested

SECTION 4 — PROPERTY CHARACTERISTICS & RISK QUALITY

4.1 Construction & Building Age (Parameters A1, A2)

Loc	Construction Class	ISO Class	Yr Built	Age	A1 Pts	A2 Pts	UW Notes
LOC-1	Joisted Masonry	Class 2	1985	40 yrs	120	65	Masonry walls / wood floor joists; highest fire severity class — surcharge required; inspection mandatory
LOC-2	Non-Combustible Lt. Steel	Class 3	2005	20 yrs	90	15	Light steel frame; gypsum board finish; standard terms applicable
LOC-3	Masonry Non-Combustible	Class 4	2015	10 yrs	50	0	CMU walls; non-comb. steel deck; preferred construction for occupancy class
LOC-4	Modified Fire Resistive	Class 5	1999	26 yrs	35	35	Partial fire-resistive elements; 1-hr rating; renovation 2008 and 2018

4.2 Roof Details (Parameter A6)

Loc	Roof Type	Material	Installed	Age	A6 Pts	Condition / UW Action
LOC-1	Low-slope	Built-up Asphalt (BUR)	2008	17 yrs	60	Fair — exceeds 15-yr threshold; ACV basis on roof; replacement plan required — Exhibit H
LOC-2	Low-slope	TPO 45-mil	2005	20 yrs	60	Fair — 20-yr old roof; hail damage history; replacement budgeted Q3 2026 — Exhibit H
LOC-3	Low-slope	TPO 60-mil	2018	8 yrs	25	Good — Miami-Dade NOA rated; current condition report enclosed — Exhibit D
LOC-4	Low-slope	EPDM 45-mil	2010	15 yrs	25	Good — upper limit of 8-15 yr band; inspection completed Jan 2026

4.3 Building Systems (Parameters A7, A8, A9)

Loc	Electrical (A8)	Elec Age / Pts	Plumbing (A9)	Plumb Age / Pts	HVAC (A7)	HVAC Age / Pts
LOC-1	200A — updated 2001 (24 yrs)	24 yrs / 20 pts	Mixed CPVC + galvanized (40 yrs — partial)	40 yrs / 80 pts	Carrier split systems — 2010 (15 yrs)	15 yrs / 20 pts
LOC-2	400A Copper — 2005 (20 yrs)	20 yrs / 20 pts	CPVC — 2005 (20 yrs)	20 yrs / 15 pts	Rooftop RTU — 2015 (10 yrs)	10 yrs / 0 pts

Loc	Electrical (A8)	Elec Age / Pts	Plumbing (A9)	Plumb Age / Pts	HVAC (A7)	HVAC Age / Pts
LOC-3	200A Copper — 2015 (10 yrs)	10 yrs / 0 pts	CPVC — 2015 (10 yrs)	10 yrs / 0 pts	Commercial kitchen HVAC — 2015 (10 yrs)	10 yrs / 0 pts
LOC-4	600A Copper — updated 2008 (17 yrs)	17 yrs / 20 pts	CPVC — 1999 updated 2008 (17 yrs)	17 yrs / 15 pts	VRF system — 2018 (7 yrs)	7 yrs / 0 pts

LOC-1 CRITICAL NOTE: Plumbing system is original 1985 (40 years). Plumbing inspection confirmed mixed CPVC and galvanized piping in basement and lower service areas. A9 score: 80 pts. Full replacement timeline required as condition of coverage — see Exhibit N.

4.4 Fire Protection & Life Safety (Parameters E1, E3, E5, E6, E8)

Loc	Sprinkler System	E1 Pts	Fire Alarm	E3 Pts	Security	E5 Pts	Last Insp	E6 Pts	Backup Power
LOC-1	Partial — 60% coverage (guest rooms covered; basement/kitchen not sprinklered)	60	Local alarm + smoke detectors	20	Central monitored	0	20 months ago	70	UPS only (no generator)
LOC-2	NFPA 13 Wet 100%	-50	UL Central Station (ADT)	-20	Central + 8-camera video	-15	9 months ago	0	No generator
LOC-3	NFPA 13 Wet 100% + Ansul hood suppression	-50	UL Central Station	-20	Central + video + guard	-15	4 months ago	0	No generator
LOC-4	NFPA 13 Wet 100%	-50	UL Central Station	-20	Central + 12-camera video	-15	11 months ago	0	Generator single unit

LOC-1 CRITICAL — Sprinkler Deficiency: Only 60% coverage (E1: 60 pts). Engineering plan for 100% coverage extension enclosed — Exhibit N. Insured committed to completion within 180 days of binding. Coverage condition: sprinkler completion required within 180 days or mid-term exclusion applies.

LOC-1 Fire Inspection: Last inspection 20 months ago (E6: 70 pts). New inspection required within 30 days of binding as coverage condition — Exhibit I.

4.5 Geographic & CAT Hazard Profile (Parameters C2, C4, C5, C6, C7, C10)

Loc	City	FEMA Zone	C2 Pts	Wildfire	C4 Pts	Wind Zone	C5 Pts	EQ PML	C6 Pts	Hail	C7 Pts	PPC	C10 Pts
LOC-1	New Orleans, LA	Zone VE/V	150	0 — Low	0	Zone 3 Gulf	60	<5%	10	3 — Low	0	Class 5	0
LOC-2	Tulsa, OK	Zone AH/AO	40	5 — Low	0	Zone 1-2	10	<5%	10	9 — HIGH	70	Class 4	0

Loc	City	FEMA Zone	C2 Pts	Wildfire	C4 Pts	Wind Zone	C5 Pts	EQ PML	C6 Pts	Hail	C7 Pts	PPC	C10 Pts
LOC-3	Miami, FL	Zone AE	80	5 — Low	0	Zone 3 HVHZ	60	<5%	10	2 — Low	0	Class 2	-20
LOC-4	Seattle, WA	Zone AH/AO	40	30 — Mod.	35	Zone 1-2	10	18% (Cascadia)	100	1 — Low	0	Class 3	-20

LOC-1 CAT Note: Zone VE/V is the highest coastal flood designation (C2: 150 pts). This is the most significant CAT driver in the portfolio. Separate NFIP policy in force ($500,000 building). Excess flood coverage via admitted carrier required.

LOC-2 Hail Note: Tulsa, OK carries Hail Score 9 (High — C7: 70 pts). This is Tornado Alley / hail corridor. Named windstorm and hail deductible of 3% TIV minimum required. Prior hail loss 2024 ($28,000) documented.

LOC-4 EQ Note: Seattle carries EQ PML of 18% (Cascadia Subduction Zone + local faults — C6: 100 pts). Earthquake sublimit endorsement required. Separate earthquake policy recommended.

SECTION 5 — COVERAGE SPECIFICATIONS & TERMS REQUESTED

5.1 Primary Coverage Terms

Coverage Element	Requested Terms
Coverage Form	Special Form (ISO CP 10 30) — All-Risk open perils
Valuation	Replacement Cost Value — Agreed Value Endorsement (no co-insurance)
Building	$29,500,000 per SOV
Business Personal Property	$3,660,000 per SOV
Business Income & Extra Expense	$6,380,000 / Actual Loss Sustained — 18 months all locations
Ordinance or Law	25% of building value per location (code gaps 10–40 yrs — mandatory at LOC-1, LOC-4)
Equipment Breakdown	Included — $10,000 per occurrence deductible
Liquor Liability — LOC-1, LOC-3	Requested separately — not included in this property submission
Newly Acquired Property	60 days / $2,000,000 blanket
Inflation Guard	4% annual

5.2 Deductible Structure

Peril / Location	Requested Deductible	Basis
All Perils — LOC-2, LOC-3, LOC-4	$50,000 per occurrence	Per occurrence
All Perils — LOC-1 (New Orleans)	$100,000 per occurrence	Per occurrence — elevated given loss frequency
Named Windstorm / Hail — LOC-1 (Zone VE, Gulf)	5% of TIV min. $250,000	Per occurrence
Named Windstorm / Hail — LOC-2 (Tulsa — hail corridor)	3% of TIV min. $150,000	Per occurrence
Named Windstorm / Hail — LOC-3 (Miami HVHZ)	3% of TIV min. $150,000	Per occurrence
Flood — LOC-1 (Zone VE) excess over NFIP	$100,000 excess over NFIP limit	NFIP primary; excess flood admitted
Earthquake — LOC-4 (Seattle)	5% TIV min. $200,000	Per occurrence

5.3 Special Endorsements & Binding Conditions

Endorsement / Condition	Location(s)	Status / Basis
Agreed Value — waive co-insurance	All	ITV 100%; Cotality Marshall & Swift RCT Express, March 2026

Endorsement / Condition	Location(s)	Status / Basis
Ordinance & Law — A, B, C	All	Code gaps 10–40 yrs; mandatory LOC-1 (40-yr gap) and LOC-4 (26-yr gap)
NFIP + Excess Flood Policy	LOC-1	Zone VE — NFIP policy in force; excess flood required — Exhibit P
Sprinkler Extension to 100%	LOC-1	CONDITION: completion within 180 days of bind — Exhibit N
Fire Inspection Prior to Bind	LOC-1	CONDITION: inspection within 30 days of bind — Exhibit I
Plumbing Remediation Plan	LOC-1	CONDITION: galvanized replacement timeline required — Exhibit N
Hail / Wind Deductible — 3% TIV	LOC-2, LOC-3	Hail score 9 (LOC-2) and HVHZ (LOC-3) — mandatory
Roof Replacement Confirmation	LOC-2	Replacement budgeted Q3 2026; premium adjustment at completion
ADA Improvement Timeline	LOC-4	F2: pending improvements — timeline and budget enclosed — Exhibit Q
Earthquake Sublimit — $8M per occ.	LOC-4	EQ PML 18% Cascadia Zone
FBC 7th Edition Compliance	LOC-3	Miami HVHZ; 2015 construction FBC-compliant; documentation enclosed

SECTION 6 — LOSS HISTORY OVERVIEW

Full certified 5-year loss runs are in Exhibit A. Carrier: AmTrust Financial Services / AmTrust International. This portfolio has experienced four losses over the 5-year period, concentrated at LOC-1.

Metric	Value
5-Year Loss Count	4 losses
5-Year Total Incurred	$433,500
5-Year Cumulative Premiums	$2,942,000
5-Year Loss Ratio	14.7%
Loss 1 (LOC-1)	$245,000 — Water / burst pipe (January 2022); guest room damage; Closed
Loss 2 (LOC-1)	$112,000 — Fire suppression system activation, kitchen (March 2024); Closed
Loss 3 (LOC-1)	$48,500 — Wind / roof flashing damage (August 2025); Closed
Loss 4 (LOC-2)	$28,000 — Hail / roof surface damage (May 2024); Closed
Open Claims	None
Prior Carrier Departure	Non-renewal — underwriting (LOC-1 and LOC-2); D1: 50 pts per location
Years in Business	15 — D8 credit of -10 pts applied

Broker Commentary: The 14.7% loss ratio is elevated but manageable given the occupancy class (hospitality). Three of four losses are attritional maintenance-related events at LOC-1. The kitchen suppression activation (2024) triggered a comprehensive kitchen fire safety audit — documentation enclosed Exhibit R. The insured has invested $180,000 in fire safety upgrades since 2024.

SECTION 7 — REGULATORY COMPLIANCE & RISK MANAGEMENT

Parameter	Location	Condition	Action / Status
Building Code (F1)	LOC-1 — 1985 (40 yrs)	30+ yr gap (90 pts)	O&L MANDATORY; engineering assessment required — Exhibit S
Building Code (F1)	LOC-2 — 2005 (20 yrs)	16-30 yr band (50 pts)	O&L mandatory — included in coverage request
Building Code (F1)	LOC-3 — 2015 (10 yrs)	6-15 yr band (20 pts)	O&L recommended; FBC 7th Ed. compliant
Building Code (F1)	LOC-4 — 1999 (26 yrs)	16-30 yr band (50 pts)	O&L mandatory — included
ADA Compliance (F2)	LOC-1, 2, 3	Fully Compliant	No action required
ADA Compliance (F2)	LOC-4	Pending improvements — documented plan (20 pts)	Timeline and budget enclosed — Exhibit Q
Environmental (F3)	LOC-2, LOC-3	Phase I — Clean	Standard terms; pollution exclusion
Environmental (F3)	LOC-1	Phase I — Recommendations (20 pts)	Petroleum residual (prior fuel oil heating); remediation plan enclosed — Exhibit T
Environmental (F3)	LOC-4	Phase I — Recommendations (20 pts)	Prior dry-cleaning tenant; PCE testing completed; below action level — Exhibit T
ERM Program (F4)	LOC-1, 2, 3, 4	Ad hoc — verbal only (25 pts)	Loss control survey recommended — Exhibit U
Deferred Maintenance (F5)	LOC-1	Score 7 — Significant (80 pts)	Inspection + remediation plan required — Exhibit V; scheduled property exclusions may apply
Deferred Maintenance (F5)	LOC-2	Score 4 — Moderate (25 pts)	Roof replacement plan and parking lot drainage — Exhibit V
Deferred Maintenance (F5)	LOC-3, LOC-4	Score 2 — Minimal (0 pts)	No action required
Claims Litigation (F6)	All Locations	None	No action required

SECTION 8 — EXPIRING POLICY INFORMATION

Detail	Information
Expiring Carrier	AmTrust Financial Services (AmTrust International Underwriters)
Policy Number	CPP-7741-2025-CRVW
Policy Period	July 1, 2025 — June 30, 2026
Expiring Premium	$618,400 (all locations combined; taxes and fees inclusive)
Expiring TIV	$37,200,000 (pre March 2026 appraisal update)
Expiring Deductible	$50,000 all perils; 5% NW/Hail Gulf/Tornado Alley locations
Carrier Financial Rating	A- / XII (A.M. Best) — downgraded from A / XII in November 2025
Reason for Non-Renewal	LOC-1: sprinkler deficiency + aging systems; LOC-2: hail frequency — non-renewal notices enclosed Exhibit F
Mid-Term Changes	TIV update March 2026 — increase of $2,340,000 (6.3%) per Cotality Marshall & Swift RCT Express

SECTION 9 — EXHIBITS INDEX

Exhibit	Description	Status
A	Certified 5-Year Loss Run — AmTrust Financial Services (2021–2026)	Enclosed — separate document
B	Statement of Values (SOV) — Full Location Detail	Enclosed — separate document
C	Sprinkler Inspection Reports — LOC-2, LOC-3, LOC-4 (Q1 2026)	Enclosed
D	Roof Inspection Reports — All 4 Locations (Jan–Mar 2026)	Enclosed
E	Cotality Marshall & Swift RCT Express Appraisal — Portfolio (March 2026)	Available on Request
F	AmTrust Non-Renewal Notices (LOC-1 and LOC-2) + Broker Response Letters	Enclosed
G	Insurance-to-Value (ITV) Certification — All Locations	Enclosed
H	Roof Condition Reports + Replacement Plan (LOC-1 and LOC-2)	Enclosed
I	LOC-1 Fire Inspection Scheduling Confirmation — within 30 days of bind	Enclosed
J	LOC-3 FBC 7th Edition (2023) Compliance Documentation — Miami HVHZ	Enclosed
K	ACORD 140 — Commercial Property Application (signed)	Enclosed
L	ACORD 125 — Commercial Insurance Application (signed)	Enclosed
M	Current Declarations Page — AmTrust CPP-7741-2025-CRVW	Enclosed
N	LOC-1 Sprinkler Extension Plan (180-day) + Plumbing Remediation Timeline	Enclosed
O	LOC-1 NFIP Policy Summary + Excess Flood Coverage Binder	Enclosed
P	LOC-1 Flood Elevation Certificate + FEMA Zone VE Documentation	Enclosed
Q	LOC-4 ADA Improvement Plan — Timeline, Budget, Contractor Quotes	Enclosed
R	LOC-1 Kitchen Fire Safety Audit + Post-Suppression Upgrade Documentation (2024)	Enclosed
S	LOC-1 Engineering Assessment — Building Code Compliance Report	Enclosed
T	LOC-1 + LOC-4 Phase I Environmental Reports + Recommendations Resolution	Enclosed
U	Portfolio Loss Control Survey — Harrington & Associates Risk Management	Enclosed
V	Deferred Maintenance Inspection Reports + Remediation Plans (LOC-1, LOC-2)	Enclosed

— END OF SUBMISSION —

Questions: Renee M. Harrington, CIC CPCU | (504) 555-0212 | r.harrington@harribrokers.com
Harrington & Associates Insurance Brokers LLC | 909 Poydras St, Suite 1800 | New Orleans, LA 70112

This document is confidential and intended solely for the named underwriting party.