# COMMERCIAL PROPERTY INSURANCE
## BROKER SUBMISSION — CROSS-BORDER PORTFOLIO

Insured:

**Meridian Cross-Border Property Fund LP**

United States (Chicago IL, San Francisco CA) | United Kingdom (London, Edinburgh)

| Submission Detail | Information |
|---|---|
| Submission Date | August 5, 2026 |
| Requested Effective Date | October 1, 2026 |
| Policy Period | October 1, 2026 — September 30, 2027 |
| Total Insured Value (TIV) | $72,095,000 (USD equivalent — see FX note) |
| Number of Locations | 4 (2 US \| 2 UK) |
| Expiring Annual Premium | $892,000 (USD equivalent) |
| Target Premium Range | $850,000 – $950,000 |
| Submitting Broker | Thornton Global Risk Partners (US) / Thornton Brokers UK Ltd (UK) |
| Broker Contact | James F. Thornton, CPCU ARM \| (312) 555-0388 \| j.thornton@thorntonglobal.com |
| Currency Note | UK locations valued in GBP (£1 = $1.26 USD at submission date). All TIV totals expressed in USD. |

**THORNTON GLOBAL RISK PARTNERS**

111 W Monroe St, Suite 900 | Chicago, IL 60603 | US License: IL-0512388 | UK FCA Ref: 987654

# SECTION 1 — BROKER COVER LETTER

August 5, 2026

Dear Underwriter,

Thornton Global Risk Partners is pleased to present this cross-border commercial property submission on behalf of Meridian Cross-Border Property Fund LP ("Meridian" or the "Fund"), a Delaware-based private real estate fund with US and UK commercial property holdings. We have arranged the Fund's property insurance since its 2014 inception and are seeking renewal terms effective October 1, 2026 following the expiry of the current Zurich Global Corporate programme.

The Fund holds a deliberately diversified portfolio of four specialist commercial properties: a mission-critical data center in Chicago, a medical office clinic in San Francisco, a Class A office tower in Canary Wharf (London), and an educational facility in Edinburgh. Each property serves a different occupancy class and presents a distinct risk profile.

Key submission highlights:

- LOC-1 (Chicago, IL — Data Center): Fire Resistive Class 6 (2008), mission-critical occupancy with Generator N+1 redundancy, formal ISO 31000 ERM program, and an industry-leading fire protection posture. Zero losses in 5 years. Domain E credits reduce raw E score to negative — this is the lowest-risk location in the portfolio.
- LOC-2 (San Francisco, CA — Medical Office): Modified Fire Resistive Class 5 (2003). The dominant risk driver is the combined CAT load: FEMA Zone AH/AO (40 pts), Wildfire Score 55 High (80 pts), and EQ PML 25% on the Hayward/San Andreas fault system (100 pts). Phase II environmental clean (prior dry-cleaning tenant, DTSC closure received). Two losses in 5 years: one minor water event, one brief power outage.
- LOC-3 (London, UK — Class A Office): Fire Resistive (2012), Canary Wharf. Environment Agency Flood Zone 3 (High) — Thames tidal flood risk; Tideway Tunnel mitigates but does not eliminate long-term risk. Loss-free. UK Building Regulations 2010 + 2023 Fire Safety amendments fully compliant.
- LOC-4 (Edinburgh, UK — Educational Facility): Masonry Non-Combustible (Victorian stone + 2018 modern extension). Environment Agency equivalent Flood Zone 2 (Medium). Zone 3 Atlantic storm exposure. The 2018 comprehensive renovation brings the effective building age to 7 years for systems scoring purposes. All Scottish Building Standards fully compliant.
- UK Framework Note: For LOC-3 and LOC-4, this submission applies adapted UK regulatory equivalents to each risk scoring parameter: Environment Agency flood zones (Zones 1–3) are mapped to FEMA-equivalent point values; UK Fire Safety Order 2005 and BS EN 12845 sprinkler standards are applied in lieu of NFPA; UK Building Regulations 2010 and 2023 amendments replace IBC for code compliance scoring; and UK Fire and Rescue Service response times are used for PPC-equivalent scoring.
- The portfolio composite score is approximately 380 (Band 3 — STANDARD), driven primarily by LOC-2's elevated CAT profile. LOC-1 (data center) and LOC-3 (London office) are the strongest performers, both in Band 2 territory individually.

We request quotations by September 5, 2026. We are open to ground-up or excess placement structures for this account. London slip market capacity for Canary Wharf is also available if preferred for LOC-3.

Respectfully submitted,

**James F. Thornton, CPCU ARM**

Managing Partner, Thornton Global Risk Partners
Direct: (312) 555-0388 | j.thornton@thorntonglobal.com

# SECTION 2 — INSURED ACCOUNT OVERVIEW

## 2.1 Named Insured & Entity Information

| Field | Detail |
|---|---|
| Named Insured | Meridian Cross-Border Property Fund LP |
| Entity Type | Limited Partnership |
| State of Formation | Delaware USA (UK registered as overseas entity — Companies House No. FC041872) |
| Registered Office (US) | 350 N Orleans St, Suite 9000N, Chicago, IL 60654 |
| Registered Office (UK) | 1 Canada Square, Canary Wharf, London E14 5AB |
| Year Established | 2014 |
| Fund Size (AUM) | Approx. $1.2 billion (USD equivalent) |
| Key Executive | Dr. Priya Mehta, Managing Partner & Fund Manager |
| Fund Administrator | State Street Bank & Trust (US); Aztec Group (UK) |
| Years in Business | 12 — D8 credit applied |

## 2.2 Business Operations

| Operating Metric | Value |
|---|---|
| Annual Gross Revenues — US (2025) | $18,400,000 USD (data center + medical office rental income) |
| Annual Gross Revenues — UK (2025) | £8,200,000 GBP (~$10,330,000 USD) (office + educational facility) |
| Total Managed Square Footage | 139,000 sq. ft. (all locations; mixed US/UK measure) |
| Portfolio Occupancy | 89% (LOC-3 London partial vacancy) |
| Currency Hedging | USD/GBP FX risk hedged quarterly via JPMorgan FX Forward programme |
| Regulatory Jurisdictions | US: IL, CA; UK: England (FCA/PRA); Scotland (Scottish Financial Conduct) |

# SECTION 3 — SCHEDULE OF LOCATIONS / STATEMENT OF VALUES

## 3.1 Location Summary

| Loc # | Address | Country | Occupancy | Construction | Yr Built | Sq Ft | Bldg RCV (USD) | BPP (USD) | BI/EE (USD) |
|---|---|---|---|---|---|---|---|---|---|
| LOC-1 | 420 N Wabash Ave, Chicago, IL 60611 | USA | Data Center / Co-Location | FR Class 6 | 2008 | 28,000 | $18,500,000 | $4,200,000 | $5,800,000 |
| LOC-2 | 580 California St, San Francisco, CA 94104 | USA | Medical Office / Clinic | MFR Class 5 | 2003 | 24,000 | $8,200,000 | $1,400,000 | $2,100,000 |
| LOC-3 | 25 Canada Square, London E14 5LB | UK | Class A Office | FR Class 6 | 2012 | 35,000 | $17,900,000 | $1,010,000 | $2,650,000 |
| LOC-4 | 14 George Square, Edinburgh EH8 9LD | UK | Educational Facility | MNC Class 4 | 1965/2018 | 42,000 | $8,570,000 | $605,000 | $1,160,000 |
| **TOTAL** | | | | | | **129,000** | **$53,170,000** | **$7,215,000** | **$11,710,000** |

*UK TIV in USD equivalent at $1.26/GBP (August 5, 2026). LOC-3: £17,222,222 GBP; LOC-4: £8,202,381 GBP. UK values will be re-rated at binding using prevailing spot rate. Agreed Value endorsement requested for all locations.*

## 3.2 Valuation Methodology

| Parameter | Detail |
|---|---|
| US Locations (LOC-1, LOC-2) | Cotality Marshall & Swift RCT Express — per-location appraisals, June 2026 |
| UK Locations (LOC-3, LOC-4) | BCIS (Building Cost Information Service) — Royal Institution of Chartered Surveyors (RICS) rebuild cost assessment, June 2026. BCIS is the UK equivalent standard for insurance reinstatement valuations. |
| Valuation Basis | Replacement Cost Value (RCV) — full reinstatement basis (US and UK) |
| ITV | 100% at all locations — certification enclosed (Exhibit G) |
| Co-Insurance / Average Clause | Agreed Value (US) / Basis of Settlement — full reinstatement without average (UK) — waiving average clause at all locations |
| Currency Risk | UK values fixed in GBP at binding; USD equivalent shown for portfolio purposes only |

| Parameter | Detail |
|---|---|
| Business Income Basis | US: Actual Loss Sustained (ALS); UK: Gross Profit basis per UK market convention — 24 months all locations |

# SECTION 4 — PROPERTY CHARACTERISTICS & RISK QUALITY

## 4.1 Construction & Building Age (Parameters A1, A2)

| Loc | Construction Class | ISO Class | Yr Built | Eff. Age | A1 Pts | A2 Pts | Notes |
|---|---|---|---|---|---|---|---|
| LOC-1 | Fire Resistive | Class 6 | 2008 | 17 yrs | 10 | 15 | Tilt-up concrete + raised floor data hall; purpose-built data center; full 2-hr fire rating |
| LOC-2 | Modified Fire Resistive | Class 5 | 2003 | 22 yrs | 35 | 15 | Partial 1-hr fire rating; reinforced concrete frame; medical-grade HVAC and electrical |
| LOC-3 | Fire Resistive | Class 6 | 2012 | 13 yrs | 10 | 15 | Canary Wharf Grade A; steel+concrete composite; BS 9999 fire safety compliant — UK adapted |
| LOC-4 | Masonry Non-Combustible | Class 4 | 1965 / 2018 | 7 yrs (post-reno) | 50 | 0 | Victorian stone facade + full 2018 modern extension; A2 uses 2018 renovation as effective build date |

## 4.2 Roof Details (Parameter A6)

| Loc | Material | Installed | Age | A6 Pts | Condition |
|---|---|---|---|---|---|
| LOC-1 | TPO 60-mil (data hall); EPDM (office wing) | 2018 | 7 yrs | 0 | Excellent — current warranty; annual inspection program |
| LOC-2 | TPO 60-mil | 2015 | 11 yrs | 25 | Good — within 8-15 yr inspection band; last inspected January 2026 |
| LOC-3 | EPDM 45-mil; green sedum roof terrace (partial) | 2020 | 6 yrs | 0 | Excellent — EPC A-rated building; BREEAM Excellent certification |
| LOC-4 | Scottish blue slate (original, repointed 2018) + EPDM flat extension | 2018 | 7 yrs | 0 | Excellent — 2018 renovation; heritage-compliant slate restoration; Listed Building consent obtained |

## 4.3 Building Systems (Parameters A7, A8, A9)

| Loc | Electrical | Elec Age/Pts | Plumbing | Plumb Age/Pts | HVAC | HVAC Age/Pts |
|---|---|---|---|---|---|---|
| LOC-1 | 2,000A + dedicated UPS infrastructure; | 7 yrs / 0 | CPVC; 2018 | 7 yrs / 0 | Precision cooling CRAC units; N+1 redundancy; 2018 | 7 yrs / 0 |

| Loc | Electrical | Elec Age/Pts | Plumbing | Plumb Age/Pts | HVAC | HVAC Age/Pts |
|---|---|---|---|---|---|---|
| | 2018 upgrade; copper | | | | | |
| LOC-2 | 400A medical-grade; 2003 (22 yrs); copper | 22 yrs / 20 | CPVC; 2003 (22 yrs) | 22 yrs / 15 | Medical-grade HVAC (HEPA filtration); replaced 2019 (7 yrs) | 7 yrs / 0 |
| LOC-3 (UK) | HV/LV switchgear; 2012 (13 yrs); copper per BS 7671 | 13 yrs / 0 | MDPE/copper per BS EN 806; 2012 | 13 yrs / 0 | Adiabatic cooling + VRF; 2020 (6 yrs); EPC A | 6 yrs / 0 |
| LOC-4 (UK) | 3-phase copper; full 2018 replacement | 7 yrs / 0 | Copper/CPVC; full 2018 replacement | 7 yrs / 0 | Heat pump + mechanical ventilation; 2018 (7 yrs) | 7 yrs / 0 |

## 4.4 Fire Protection & Life Safety (Parameters E1, E3, E5, E6, E8)

| Loc | Sprinkler System | E1 Pts | Fire Alarm | E3 Pts | Security | E5 Pts | Last Insp | E6 Pts | Backup Power |
|---|---|---|---|---|---|---|---|---|---|
| LOC-1 | NFPA 13 Wet 100% + Inergen gas suppression (server halls) | -50 | UL Central (24/7 NOC monitoring) | -20 | Biometric + CCTV + 24/7 guard + man-trap | -15 | 3 months | 0 | Generator N+1 redundancy + UPS (Tier III) |
| LOC-2 | NFPA 13 Wet 100% | -50 | UL Central Station (ADT) | -20 | Central + 16-camera video + guard | -15 | 8 months | 0 | Generator — single unit |
| LOC-3 (UK) | BS EN 12845 wet sprinkler 100% (equiv. NFPA 13) | -50 | NSI Gold central station (UK equiv. UL Central) | -20 | Central + 24-camera + 24/7 guard | -15 | 5 months | 0 | Generator — single unit |
| LOC-4 (UK) | BS EN 12845 wet sprinkler 100% | -50 | NSI Gold central station | -20 | Central + 10-camera + access control | -15 | 4 months | 0 | Generator — single unit |

## 4.5 CAT Hazard Profile — US Locations (Parameters C2–C10)

| Loc | FEMA Zone | C2 Pts | Wildfire | C4 Pts | Wind Zone | C5 Pts | EQ PML | C6 Pts | Hail | C7 Pts | PPC | C10 Pts | Domai C |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOC-1 Chicago | Zone X | 0 | 0 — Low | 0 | Zone 1-2 | 10 | <5% | 10 | 5 — Mod. | 30 | Class 3 | -20 | 30 |
| LOC-2 San Francisco | Zone AH/AO | 40 | 55 — High | 80 | Zone 1-2 | 10 | 25% (Hayward/SF) | 100 | 0 — Low | 0 | Class 3 | -20 | 210 |

*LOC-2 CAT Note: San Francisco carries a combined CAT score of 210 (capped at 200). Wildfire Score 55 (CAL FIRE High FHSZ) and EQ PML 25% (USGS Hayward/San Andreas) are the primary drivers. FR Class 5 construction and Phase II clean environmental status are material mitigants.*

## 4.6 CAT Hazard Profile — UK Locations (Adapted UK Framework)

*UK CAT parameters are assessed using adapted equivalents to the US framework, applied consistently with the carrier scoring methodology. Environment Agency Flood Zone 3 (High) is treated as equivalent to FEMA Zone AE for C2 scoring. UK Fire and Rescue Service response data is used in lieu of ISO PPC. Atlantic storm exposure is mapped to Wind Zone 3 for Edinburgh.*

| Loc | EA Flood Zone | C2 Pts (adapted) | Wildfire | C4 Pts | Wind Zone | C5 Pts | EQ PML | C6 Pts | Hail | C7 Pts | UK FRS Response | C P |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LOC-3 London | EA Zone 3 (High) — Thames | 80 (equiv. AE) | 0 — Low | 0 | Zone 1-2 | 10 | <5% | 10 | 2 — Low | 0 | Equiv. Class 3 | -2 |
| LOC-4 Edinburgh | EA Zone 2 (Medium) — Water of Leith | 40 (equiv. AH/AO) | 0 — Low | 0 | Zone 3 (Atlantic) | 60 | <5% | 10 | 1 — Low | 0 | Equiv. Class 4 | 0 |

*LOC-3 Flood Note: Canary Wharf sits within Environment Agency Flood Zone 3 (High) — Thames tidal flood risk. The Thames Barrier and Tideway Tunnel (completed 2025) provide primary protection; however, the EA zone designation is maintained pending long-term climate modelling. Separate flood coverage via UK admitted insurer is in force.*

## 4.7 UK Regulatory Framework — Building Regulations & Fire Safety Compliance

UK locations are assessed under adapted equivalents to the US F-parameter compliance framework. The following table maps UK regulatory requirements to the scoring parameters for LOC-3 (London) and LOC-4 (Edinburgh).

| US Parameter | UK Equivalent Applied | LOC-3 London Status | LOC-4 Edinburgh Status |
|---|---|---|---|
| F1 — Building Code Compliance | UK Building Regulations 2010 + 2023 Fire Safety (Regulatory Reform) Act amendments | Compliant — 2012 construction; post-2010 Regulations; EPC A; BREEAM Excellent — code gap 13 yrs: 20 pts | Compliant — 2018 renovation to current Scottish Building Standards; code gap 7 yrs (effective): 20 pts |
| F2 — ADA Compliance | Equality Act 2010 (Disability Discrimination provisions) + Building Regulations Part M | Fully compliant — Part M audit 2024, no deficiencies | Fully compliant — 2018 renovation included full Part M accessibility compliance |
| F3 — Environmental | UK Environment Act 2021; Phase I equivalent = Environmental Desk Study (EDS) | EDS clean — no contamination history; Canary Wharf brownfield remediation (pre-2000) complete | EDS clean — George Square academic use throughout; no contamination history |
| F4 — ERM Program | ISO 31000 / UK COSO equivalent | Informal (written policies) — fund-level ERM in place but not location-specific | Informal — university operator ERM; not location-specific |
| F5 — Deferred Maintenance | RICS Condition Survey Score | Score 1 (Minimal) — Grade A building; active maintenance programme | Score 1 (Minimal) — 2018 renovation; all systems new or recently replaced |
| F6 — Claims Litigation | UK Courts Act / insurance dispute resolution | None | None |
| E1 — Sprinkler | BS EN 12845 wet sprinkler system | 100% coverage — BS EN 12845 certified; annual inspection | 100% coverage — BS EN 12845; biannual inspection |
| E3 — Fire Alarm | BS 5839 / NSI Gold central station monitoring | NSI Gold (equivalent to UL Central Station) | NSI Gold certified |
| Fire Safety Act | Fire Safety (Regulatory Reform) Order 2005 + Fire Safety Act 2021 | Compliant — Fire Risk Assessment current (2025); Responsible Person designated | Compliant — Fire Risk Assessment current (2026); Scottish Fire Safety legislation |

# SECTION 5 — COVERAGE SPECIFICATIONS & TERMS REQUESTED

## 5.1 Primary Coverage Terms

| Coverage Element | US Locations (LOC-1, LOC-2) | UK Locations (LOC-3, LOC-4) |
|---|---|---|
| Coverage Form | Special Form (ISO CP 10 30) — All-Risk | All Risks Material Damage (UK commercial wording — Lloyds MAR form or equivalent) |
| Valuation | Replacement Cost Value — Agreed Value | Full Reinstatement Value — without average clause |
| Business Income | Actual Loss Sustained — 24 months | Gross Profit basis — 24 months indemnity period |
| Ordinance & Law | 25% of building value — mandatory (code gaps 13–22 yrs) | Not applicable (UK reinstatement basis covers regulatory compliance costs) |
| Equipment Breakdown | Included — $10,000 per occ. | Included — £8,000 per occurrence |
| Inflation Guard | 4% annual — all US locations | Index-linking to BCIS Tender Price Index — UK locations |

## 5.2 Deductible Structure

| Peril / Location | Deductible | Currency |
|---|---|---|
| All Perils — LOC-1 (Data Center) | $100,000 per occurrence | USD |
| All Perils — LOC-2 (San Francisco) | $100,000 per occurrence | USD |
| Earthquake — LOC-2 (CA — 25% PML) | 5% of TIV per occurrence, min. $250,000 | USD |
| Wildfire — LOC-2 (CA — High FHSZ) | $250,000 per occurrence | USD |
| Flood excess over NFIP — LOC-2 (Zone AH/AO) | $50,000 per occurrence | USD |
| All Perils — LOC-3 (London) | £75,000 per occurrence | GBP |
| Flood excess over NFIP equiv. — LOC-3 (Thames) | £100,000 per occurrence | GBP |
| All Perils — LOC-4 (Edinburgh) | £50,000 per occurrence | GBP |
| Storm / Wind — LOC-4 (Atlantic Zone 3) | £75,000 per occurrence | GBP |

## 5.3 Special Endorsements & Conditions

| Endorsement / Condition | Location(s) | Basis |
|---|---|---|
| Agreed Value / No Average Clause | All | ITV 100%; Cotality RCT (US) + BCIS RICS (UK) appraisals June 2026 |

| Endorsement / Condition | Location(s) | Basis |
|---|---|---|
| Ordinance & Law — A, B, C (US) | LOC-1, LOC-2 | Code gaps 13-22 yrs; included in coverage request |
| Earthquake Sublimit — $12M per occ. | LOC-2 (SF) | EQ PML 25%; Hayward/San Andreas system |
| Wildfire Endorsement | LOC-2 (SF) | CAL FIRE High FHSZ score 55; FR Class 5 construction credited |
| Thames Flood Excess Policy | LOC-3 (London) | EA Zone 3 (High); UK admitted insurer supplement in force |
| BI Generator N+1 Credit | LOC-1 (Chicago) | E8: -10 pts; data center mission-critical — BI credit applied |
| ERM Premium Credit (ISO 31000) | LOC-1 (Chicago) | F4: Formal ISO 31000 — -15 pts; documentation Exhibit L |
| Phase II Environmental — Clean | LOC-2 (SF) | F3: Phase II clean; prior dry-cleaning tenant; DTSC closure — Exhibit K |
| UK Fire Safety Act Compliance | LOC-3, LOC-4 | Fire Safety Act 2021 + Regulatory Reform Order 2005 compliance confirmed |
| Scottish Building Standards | LOC-4 (Edinburgh) | 2018 renovation to current SBS; Listed Building consent — Exhibit Q |
| BREEAM Excellent Endorsement | LOC-3 (London) | EPC A; green building credit applied per carrier sustainability programme |

# SECTION 6 — LOSS HISTORY OVERVIEW

Full certified 5-year loss runs are provided as a separate document (Exhibit A). Carrier: Zurich Global Corporate. US and UK loss histories are presented separately below.

## 6.1 US Locations (LOC-1 Chicago, LOC-2 San Francisco)

| Metric | Value |
|---|---|
| 5-Year Loss Count (US) | 2 losses — both at LOC-2 |
| US 5-Year Total Incurred | $80,200 |
| Loss 1 (LOC-2) | $55,000 — Water / domestic pipe joint failure (August 2023) — Closed |
| Loss 2 (LOC-2) | $25,200 — Power outage / UPS failure (November 2024) — Closed; no BI invoked |
| LOC-1 (Chicago Data Center) | Loss-free 5 years — signed loss-free affidavit provided |
| US Prior Carrier Departure | Voluntary — Zurich non-renewal driven by global portfolio restructuring (not account-specific) |

## 6.2 UK Locations (LOC-3 London, LOC-4 Edinburgh)

| Metric | Value |
|---|---|
| 5-Year Loss Count (UK) | 2 losses — one each location |
| UK 5-Year Total Incurred | £52,400 GBP (~$66,000 USD) |
| Loss 1 (LOC-3 London) | £34,000 — Water / cooling system leak (March 2024) — Closed |
| Loss 2 (LOC-4 Edinburgh) | £18,400 — Storm / slating damage (January 2025) — Closed; slate tiles displaced by North Atlantic storm system |
| UK Prior Carrier Departure | Voluntary — Zurich global restructuring; London market alternative sought |

*Portfolio 5-year combined loss ratio: approximately 8.2% — well within acceptable parameters for this occupancy mix. Zero large losses, zero CAT losses, zero fire losses in 5-year period.*

# SECTION 7 — REGULATORY COMPLIANCE & RISK MANAGEMENT

| Parameter | Location | Condition | Action / Status |
|---|---|---|---|
| Building Code / Regs (F1) | LOC-1 — 2008 (17 yrs) | IBC 2006 / IL — 16-30 yr band (50 pts) | O&L endorsement mandatory — included |
| Building Code / Regs (F1) | LOC-2 — 2003 (22 yrs) | IBC 2000 / CA CBC — 16-30 yr band (50 pts) | O&L mandatory — included |
| Building Code / Regs (F1) | LOC-3 — 2012 (13 yrs) | UK Building Regs 2010 — 6-15 yr band (20 pts) | Compliant; BREEAM Excellent documentation — Exhibit P |
| Building Code / Regs (F1) | LOC-4 — 2018 reno (7 yrs) | Scottish Building Standards 2017 — 0-10 yr band (0 pts) | Compliant; Listed Building consent — Exhibit Q |
| ADA / Equality Act (F2) | All Locations | Fully Compliant | No action required |
| Environmental (F3) | LOC-1 | Phase I — Clean | Standard terms; pollution exclusion applies |
| Environmental (F3) | LOC-2 | Phase II — Clean (DTSC closure) | Prior dry-cleaning tenant; closure letter — Exhibit K |
| Environmental (F3) | LOC-3, LOC-4 | UK EDS — Clean | Standard UK terms |
| ERM Program (F4) | LOC-1 | Formal ISO 31000 (-15 pts) | Premium credit applied; ERM documentation — Exhibit L |
| ERM Program (F4) | LOC-2, LOC-3, LOC-4 | Informal (written policies) | Standard terms |
| Deferred Maintenance (F5) | All Locations | Score 1-2 (Minimal) | No action required — all locations well-maintained |
| Claims Litigation (F6) | All Locations | None | No action required |
| UK Fire Safety Act 2021 | LOC-3, LOC-4 | Fully Compliant | Fire Risk Assessments current — Exhibit R |
| BREEAM / EPC | LOC-3 | BREEAM Excellent; EPC A | Green building credit applied — Exhibit P |

# SECTION 8 — EXPIRING POLICY INFORMATION

| Detail | Information |
|---|---|
| Expiring Carrier | Zurich Global Corporate (US: Zurich American Insurance; UK: Zurich Insurance plc) |
| Policy Structure | Combined US/UK global programme — master policy (US) + local admitted policies (UK) |
| Policy Number | ZGC-MCBPF-2025-0001 |
| Policy Period | October 1, 2025 — September 30, 2026 |
| Expiring Premium (Combined) | $892,000 USD equivalent (US portion $540,000; UK portion £280,000 GBP) |
| Expiring TIV | $69,400,000 USD equivalent (pre June 2026 BCIS/RCT appraisal update) |
| Carrier Financial Rating | AA- (S&P) / Aa3 (Moody's) |
| Non-Renewal Reason | Zurich Global Corporate portfolio restructuring — exit from sub-$100M US/UK cross-border fund programme segment |
| Mid-Term Changes | SOV update June 2026 — TIV increased $2,695,000 (3.9%) per Cotality RCT Express (US) and BCIS (UK) |

# SECTION 9 — EXHIBITS INDEX

| Exhibit | Description | Status |
|---|---|---|
| A | Certified 5-Year Loss Run — Zurich Global Corporate (2021–2026) — US and UK separate | Enclosed — separate document |
| B | Statement of Values (SOV) — Full Location Detail — US and UK | Enclosed — separate document |
| C | Sprinkler/Fire System Inspection Reports — All 4 Locations (2026) | Enclosed |
| D | Roof Inspection Reports — LOC-2 (2026); LOC-3, LOC-4 condition reports | Enclosed |
| E | Cotality Marshall & Swift RCT Express — LOC-1, LOC-2 Appraisals (June 2026) | Available on Request |
| F | BCIS RICS Reinstatement Cost Assessments — LOC-3, LOC-4 (June 2026) | Available on Request |
| G | Insurance-to-Value Certification — All Locations (US RCV + UK Reinstatement) | Enclosed |
| H | Current Declarations Page — Zurich Global Corporate ZGC-MCBPF-2025-0001 | Enclosed |
| I | Zurich Non-Renewal Notice + Thornton Response Letter | Enclosed |
| J | LOC-1 ISO 31000 ERM Programme Summary (Meridian Fund ERM Manual) | Enclosed |
| K | LOC-2 Phase II Environmental Assessment — DTSC Closure Letter (2022) | Enclosed |
| L | LOC-1 Data Center Tier III Certification + Generator N+1 Commissioning Report | Enclosed |
| M | LOC-2 Medical Office HEPA/HVAC Certification + Infection Control Documentation | Enclosed |
| N | ACORD 140 + ACORD 125 — Commercial Applications (signed) | Enclosed |
| O | UK Property Information Questionnaire (PIQ) — LOC-3 and LOC-4 | Enclosed |
| P | LOC-3 BREEAM Excellent Certificate + EPC A Rating + Building Regs Compliance | Enclosed |
| Q | LOC-4 Scottish Building Standards Completion Certificate + Listed Building Consent | Enclosed |
| R | LOC-3 + LOC-4 Fire Risk Assessments (UK Fire Safety Act 2021 compliant) | Enclosed |
| S | FX Hedging Summary — USD/GBP Forward Programme (JPMorgan) | Enclosed |

## — END OF SUBMISSION —

*Questions: James F. Thornton, CPCU ARM | (312) 555-0388 | j.thornton@thorntonglobal.com*

Thornton Global Risk Partners | 111 W Monroe St, Suite 900 | Chicago, IL 60603 | UK: 20 Fenchurch St, London EC3M 3AZ

*Confidential — for named underwriting party only. UK locations placed under FCA-regulated broker authorisation.*