<u>Dashboard</u> / <u>Courses</u> / <u>Embedded Systems Workshop</u> / Quiz / <u>Quiz-1</u>

Started on	Monday, 6 September 2021, 5:04 PM
State	Finished
Completed on	Monday, 6 September 2021, 5:17 PM
Time taken	13 mins 44 secs
Grade	8.75 out of 10.00 (88 %)

Question **1**

Correct

Mark 1.00 out of 1.00

What is the key disadvantage of using analog signals for communicating sensor information?

- o a. All of the given options
- b. Susceptibility to Noise
- o c. Transmission Delay
- Od. High power consumption

Your answer is correct.

The correct answer is:

Susceptibility to Noise

Question 2	
Correct	
Mark 1.00 out of 1.00	

What is the advantage of serial digital communication over parallel?

- a. Use of less pins
- b. Fast Transmission
- oc. Ease of Implementation
- Od. Low Power

Your answer is correct.

The correct answer is:

Use of less pins

2 of 9

Question 3	
Incorrect Mark -0.25 out of 1.00	
Zero offset in a sensor is	
a. The smallest output change when input is zero	×
O b. The value of the output when the input is zero	
o c. How often the readings are repeatable	
Od. The difference in min and max values that can be measured	
Your answer is incorrect.	
The correct answer is: The value of the output when the input is zero	
Question 4	
Correct	
Mark 1.00 out of 1.00	
What processing is beneficial before obtaining a output reading	
a. Amplification	
O b. None	
c. Digitization	~
O d. Filtering out noise	
o e. Inversion	
Your answer is correct.	
The correct answer is: Digitization	

Question 5
Correct
Mark 1.00 out of 1.00

The pull-up resistors perform which of these functions in I2C communication?

- a. Reduce power consumption
- O b. Increase the speed of communication
- o c. Drive the pin to logic High
- O d. Perform voltage level conversion

Your answer is correct.

The correct answer is:

Drive the pin to logic High

Question 6
Correct
Mark 1.00 out of 1.00

In SPI communication, the slave device is selected by the master using

- o a. MISO Line
- O b. Slave Address
- o c. Slave select line
- Od. MOSI Line

Your answer is correct.

The correct answer is:

Slave select line

Question 7
Complete
Mark 1.00 out of 1.00

List five main sensors in the human body

- 1.Eyes
- 2. Ears
- 3 Nose
- 4 Skin
- 5 Tounge

Comment:

Question 8	
Correct	
Mark 1.00 out of 1.00	

Precision of a sensor is

- \circ a. The smallest quantity that can be measured
- O b. The difference in min and max values that can be measured
- o c. How often the readings are repeatable
- O d. The smallest change that can be measured

Your answer is correct.

The correct answer is: How often the readings are repeatable

Question 9	
Correct	
Mark 1.00 out of 1.00	

If we need to read temperature with a resolution of 0.01 C, using a 10-bit, 5V ADC, which of these sensitivities can be used?

- a. 0.488 V/C
- O b. 10 mV/C
- o c. 5 mV/C
- O d. 5 V/C

Your answer is correct.

The correct answer is:

0.488 V/C

8 of 9

empt review	https://courses.iiit.ac.in/mod/quiz/review.php?attempt=282658
Question 10	
Correct	
Mark 1.00 out of 1.00	
It is important to specify the baud ra	ate in UART communication to:
a. Synchronize communication	✓
o b. Save time	
o c. Indicate Rx/Tx pins	
Od. Indicate start/stop of commu	nication
Your answer is correct.	
The correct answer is:	
Synchronize communication	
)21
Jump to	
	Lab-3 Submission ▶