## Arduino Code (prepaid\_meter.ino).

```
Program:
#include <LiquidCrystal.h>
LiquidCrystal lcd(12, 11, 5, 4, 3, 2);
void setup() {
  lcd.begin(16, 2);
  lcd.print("Prepaid Meter");
}

void loop() {
  lcd.setCursor(0, 1);
  lcd.print("Balance: 100Rs");
  delay(2000);
}
```