VESSEL CORROSION INSPECTION REPORT

Vessel: **Sumatera Express**
Area: **CARGO_HOLD**
Inspection Photos: **20**

Metric	Value
Inspection Photos	20
Average Rust %	9.74
Maximum Rust %	45.47

Inspection Photo 1

Location	Hold No. 1_0.jpg
Rust %	13.25
Severity	HIGH



Inspection Photo 2

Location	Hold No. 1_1.jpg
Rust %	14.71
Severity	HIGH

Inspection Photo 3

Location	Hold No. 1_10.jpg
Rust %	5.86
Severity	MODERATE

Inspection Photo 4

Location	Hold No. 1_2.jpg
Rust %	8.69
Severity	MODERATE

Inspection Photo 5

Location	Hold No. 1_3.jpg
Rust %	8.59
Severity	MODERATE

Inspection Photo 6

Location	Hold No. 1_4.jpg
Rust %	5.57
Severity	MODERATE



Inspection Photo 7

Location	Hold No. 1_5.jpg
Rust %	12.20
Severity	HIGH



Inspection Photo 8

Location	Hold No. 1_7.jpg
Rust %	6.25
Severity	MODERATE

Inspection Photo 9

Location	Hold No. 1_8.jpg
Rust %	0.70
Severity	LOW

Inspection Photo 10

Location	Hold No. 1_9.jpg
Rust %	7.69
Severity	MODERATE

Inspection Photo 11

Location	Hold No. 2_0.jpg
Rust %	6.51
Severity	MODERATE



Inspection Photo 12

Location	Hold No. 2_1.jpg
Rust %	10.88
Severity	HIGH



Inspection Photo 13

Location	Hold No. 2_10.jpg
Rust %	4.43
Severity	MODERATE

Inspection Photo 14

Location	Hold No. 2_2.jpg
Rust %	7.40
Severity	MODERATE

Inspection Photo 15

Location	Hold No. 2_3.jpg
Rust %	20.34
Severity	SEVERE



Inspection Photo 16

Location	Hold No. 2_4.jpg
Rust %	45.47
Severity	SEVERE



Inspection Photo 17

Location	Hold No. 2_5.jpg
Rust %	5.88
Severity	MODERATE

Inspection Photo 18

Location	Hold No. 2_7.jpg
Rust %	3.39
Severity	LOW

Inspection Photo 19

Location	Hold No. 2_8.jpg
Rust %	3.81
Severity	LOW

Inspection Photo 20

Location	Hold No. 2_9.jpg
Rust %	3.24
Severity	LOW