

1

PREVENTIVE MAINTENANCE LOG

2

ABC Manufacturing Pvt. Ltd.

3

=====

4

Equipment : Hydraulic Press HP-05

5

Equipment ID : EQ-HPR-005

6

Location : Shop Floor B, Bay 3

7

PM Schedule : Monthly (every 30 days)

8

Log Period : October 2024

9

Technician : Rajesh Sharma (Maintenance Engineer)

10

Reviewed By : K. Narayanan (Maintenance Manager)

11

=====

12

13

PM DATE : 07-Oct-2024

14

Previous PM : 06-Sep-2024

15

Next PM Due : 07-Nov-2024

16

17

18

CHECKLIST:

19

20

S.No | Task | Status | Remarks

21

-----|-----|-----|-----

22

1 | Check hydraulic fluid level | Done | Level OK – topped up 4 Ltrs (LUB-HYD-46)

23

2 | Check hydraulic fluid condition/colour | Done | Slight darkening noted. Acceptable for now. To monitor.

24

3 | Inspect all hoses and fittings for leaks | Done | No leaks found

25

4 | Check pressure relief valve setting | Done | Set at 220 bar – OK

26

5 | Lubricate guide columns | Done | Grease applied (GREAS-LIT-00)

27

6 | Check and tighten electrical connections | Done | Terminal block tightened at control panel

28

7 | Test emergency stop function | Done | Functional

29

8 | Inspect ram seal condition | Done | Minor wear on lower ram seal. Flagged for next PM.

30

9 | Check pump motor temperature (running) | Done | 68°C – within normal range (<75°C)

31

10 | Clean strainer/filter element | Done | Strainer cleaned. Filter element not replaced (due at 6-month interval, Feb 2025)

32

11 | Verify pressure gauge calibration | Done | Gauge reads 220 bar steady under test load – OK

33

12 | Record hydraulic fluid consumption since last PM | Done | 4 Ltrs topped up this PM (consumption slightly above average of 2–3 Ltrs/month)

34

35

36

OBSERVATIONS:

37

– Hydraulic fluid showing early signs of degradation (darkening). Recommend full fluid change at next PM (Nov 2024) if condition worsens.

38

39 - Lower ram seal showing minor wear - part to be kept ready (Part No. SEAL-RAM-HP5-L).
40 - Fluid consumption (4 Ltrs this cycle) is higher than typical. To investigate
41 if trend continues.
42

43 -----

44 PARTS CONSUMED THIS PM:

45 LUB-HYD-46 Hydraulic Fluid : 4 Ltrs (Issue Slip IS-2024-1089)

46 GREAS-LIT-00 Lithium Grease : 0.2 Kg

47

48 PARTS ORDERED FOR NEXT PM:

49 SEAL-RAM-HP5-L (Lower Ram Seal) - to be kept in stock

50

51 -----

52 Technician Sign : Rajesh Sharma

53 Date : 07-Oct-2024

54 Manager Sign : K. Narayanan

55 Date : 08-Oct-2024

56 =====

57