

1	PRODUCTION SHIFT LOG – EVENING SHIFT
2	ABC Manufacturing Pvt. Ltd.
3	=====
4	Date : 04-Nov-2024
5	Shift : Evening (14:00 – 22:00)
6	Supervisor : Anita Verma
7	Operators : Suresh Kumar, Deepak Yadav, Ramesh Pillai
8	Lines : Pump Line 2 Shop Floor B
9	=====
10	
11	PRODUCTION SUMMARY:
12	Planned Output (Pump Line 2) : 120 units
13	Actual Output (Pump Line 2) : 107 units
14	Variance : -13 units
15	
16	-----
17	SHIFT NOTES:
18	14:00 – Shift started normally. Line 2 carrying WIP batch PL2-NOV-041 from
19	morning shift.
20	15:20 – HP-05 pressure fluctuation noted again (carry-over from morning shift).
21	MWO-2024-0843 already raised. Maintenance informed. Deepak Yadav
22	instructed to monitor press and reduce cycle load.
23	16:45 – Output pace reduced on HP-05 as precaution. No breakdown. Machine
24	operational.
25	18:00 – Routine break. Conveyor C-04 belt alignment checked visually – OK.
26	19:30 – Batch PL2-NOV-041 completed. 107 units produced. 13 units deferred to
27	next shift due to HP-05 slowdown.
28	20:00 – Setup started for batch PL2-NOV-042. Raw material issued from stores
29	(Issue Slip IS-2024-1147).
30	21:45 – End-of-shift machine status check done. HP-05 still showing occasional
31	fluctuation. Maintenance scheduled for 05-Nov morning before shift.
32	22:00 – Shift handed over to night shift. Handover note given to Suresh Mehta.
33	
34	-----
35	DOWNTIME RECORD:
36	Machine : HP-05
37	Reason : Precautionary speed reduction (pressure fluctuation)
38	Duration : Not classified as breakdown
39	Output Impact (est.) : 13 units
40	
41	-----
42	MATERIAL CONSUMED:
43	Batch PL2-NOV-041 – casting blanks (250 units), ref: IS-2024-1143
44	Batch PL2-NOV-042 setup – casting blanks (50 units drawn), ref: IS-2024-1147
45	
46	-----
47	QUALITY NOTES:

48 2 units from PL2-NOV-041 sent to QA for dimensional check (routine sampling).
49 No rejections reported this shift.
50
51 -----
52 Supervisor Signature : Anita Verma
53 Date : 04-Nov-2024
54 =====
55