

RT58x SDK Release Notes



Contents

| RT: | 58x SDK Release Notes | 1 |
|-----|---------------------------|----|
| Cor | ntents | 2 |
| 1 | Revision History | 3 |
| 2 | RT58x_SDK_v1.9.0 | 8 |
| 3 | RT58x_SDK_v1.8.0 | 9 |
| 4 | RT58x_SDK_v1.8.0 | 10 |
| 5 | RT58x_SDK_v1.7.0 | 11 |
| 6 | RT58x_SDK_v1.6.0 | 12 |
| 7 | RT58x_SDK_v1.5.0 | 13 |
| 8 | RT58x_SDK_v1.4.0 | 14 |
| 9 | RT58x_SDK_v1.3.0 | 15 |
| 10 | RT58x_SDK_v1.2.3_BLE_Mesh | 17 |
| 11 | RT58x_SDK_v1.2.2_Zigbee | 18 |
| 12 | RT58x_SDK_v1.2.1 | 19 |
| 13 | RT58x_SDK_v1.2.0 | 20 |
| 14 | RT58x_SDK_v1.1.1 | 22 |
| 15 | RT58x_SDK_v1.1.0 | 23 |
| 16 | RT58x_SDK_v1.0.1 | 25 |
| 17 | RT58x_SDK_v1.0.0_Mesh | 26 |
| 18 | RT58x_SDK_v1.0.0 | 27 |
| 19 | RT58x_SDK_v0.3.1 | 30 |
| 20 | RT58x_SDK_v0.2.0 | 32 |
| 21 | RT58x SDK v0.1.0 | 33 |



1 Revision History

| Date | Version | Description |
|------------|---------------|---|
| 2021/11/05 | 0.1.0 (alpha) | - Initial version |
| 2022/01/11 | 0.2.0 (alpha) | - For SubG only |
| 2022/02/16 | 0.3.1 (alpha) | - Added GCC project for all examples |
| | | - Added Zigbee/BLE multi-protocol demo |
| | | - Added more Zigbee examples |
| | | - Added more tools and related documents |
| | | - Unified application architecture of different protocols |
| | | - Modified power saving example |
| 2022/03/31 | 1.0.0 | - Added more peripheral drivers and examples |
| | | - Added BLE demos with low power mode mechanism |
| | | - Added more tools and related documents |
| | | - Integrated DTM function |
| | | - Fixed bug in BLE multi-link demo |
| 2022/04/08 | 1.0.0 (Mesh) | - Added BLE Mesh demo example |
| | | - Added BLE Mesh App |
| | | - Added BLE Mesh documents |
| 2022/05/18 | 1.0.1 | - Added software PMU calibration |
| | | - Extend Zigbee maximum network nodes |
| | | - Fixed low speed timer reload issue |
| 2022/06/10 | 1.1.0 | -Added examples: I2S digital microphone |
| | | -Added Address protect in flash driver. |
| | | -Modify PWM example |
| | | -Added BLE UART_cmd demo |
| | | -Added BLE Beacon demo |
| | | -Added Zigbee Gateway command example |
| | | -Added Zigbee User_specific cluster |
| | | -Added Thermostat cluster |
| | | -Fixed Zigbee two end-point bug |
| | | -Fixed Zigbee OTA buffer issue |
| | 1.1.1 | -RF_Lab_Test_Tool support SubG RF test |
| 2022/07/08 | 1.1.1 | - Modify PMU DCDC initial setting to enhance the |
| | | stability under stress environment |
| 2022/07/19 | 1.2.0 | -BLE: add Privacy and connect CTE API |
| | | -Zigbee: now can pre-configure network parameter. |



| | | 7' 1 11 OTH C |
|------------|-------|--|
| | | -Zigbee: add OTA function in new gateway demo |
| | | -Zigbee: AES by HW accelerator. |
| | | -Add multi-protocol demo: Zigbee Easy Gateway |
| | | -Add multi-protocol demo: utilize BLE to reset Zigbee device |
| | | |
| 2022/00/07 | 1.2.1 | -Add Android app for multi-protocol demos. |
| 2022/09/05 | 1.2.1 | -Tools: MP_Tool add Tx power 0/4 dBm target |
| | | -Zigbee: optimize RX current consumption |
| | | -Zigbee: device send leave command to gateway after |
| | | factory reset |
| 2022/09/30 | 1.2.2 | Zigbee Gateway module: |
| | | - Revise binding command |
| | | - Add read attribute, write attribute, configure report |
| | | command |
| | | Zigbee Light: |
| | | - Add OTA client cluster |
| | | - Add finding & binding process |
| | | Zigbee Switch: |
| | | - Remove endpoint 1&3 |
| | | - Add OTA client cluster |
| | | - Add finding & binding process |
| | | Zigbee OTA Server: |
| | | - Removed (gateway module replace) |
| | | Zigbee OTA Client: |
| | | - Removed (light/switch replace) |
| 2022/10/13 | 1.2.3 | BLE Mesh: |
| | | -Implement Model and Lighting Demo. |
| | | -BLE Mesh Performance Tuning |
| | | -BLE Mesh Document |
| 2023/01/17 | 1.3.0 | Platform & Peripheral: |
| | | - Update ADC setting to improve accuracy of chip |
| | | variation |
| | | - Bootloader support FOTA image decompression. |
| | | Zigbee: |
| | | - Power on/off 5 times to reset light device |
| | | - Add sensor related clusters |
| | | - New flash update algorithm |
| | | - Add library version |
| | | |



| | | - Modify private cluster ID |
|------------|-------|---|
| | | |
| | | - Improve interoperability with other Zigbee device |
| | | - Fix under multi-PAN environment, device may accept |
| | | packet from different PAN_ID. |
| | | BLE: |
| | | - Use 2 bytes to indicate LL TX data sequence |
| | | - FOTA flow update. Support image compression |
| | | BLE Mesh: |
| | | - Fixed transparent transmission bug: now different packet |
| | | size are all right |
| | | Sub-G: |
| | | - Add OQPSK 6.25k data rate |
| | | - Add field test demo code |
| | | Tool: |
| | | - Android app: support BLE Mesh demo |
| | | - Android app: support Zigbee smart home |
| | | - MP_tool: separate BLE/Zigbee Tx power target |
| | | - FOTA tool: support OTA image compression |
| | | - RF_lab_test_tool: modify SubG test option |
| 2023/03/07 | 1.4.0 | Platform: |
| 2025/05/07 | 1.4.0 | i iddoiiii. |
| 2023/03/07 | 1.7.0 | - Add 2MB Flash FLM |
| 2023/03/07 | 1.4.0 | |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM- Update flash driving setting to improve RX sensitivity- Fix Deep Sleep issue |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: |
| 2023/03/07 | 1.1.0 | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document |
| 2023/03/01 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: |
| 2023/03/07 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: - 2MB flash OTA add secure upgrade |
| 2023/03/01 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: - 2MB flash OTA add secure upgrade FW: |
| 2023/03/01 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: - 2MB flash OTA add secure upgrade FW: - Fixed getting wrong RSSI value when TX power is very |
| 2023/03/07 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: - 2MB flash OTA add secure upgrade FW: - Fixed getting wrong RSSI value when TX power is very low on Sub-G |
| 2023/03/01 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: - 2MB flash OTA add secure upgrade FW: - Fixed getting wrong RSSI value when TX power is very low on Sub-G - Enable MAC features for multi-protocol |
| 2023/03/07 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: - 2MB flash OTA add secure upgrade FW: - Fixed getting wrong RSSI value when TX power is very low on Sub-G - Enable MAC features for multi-protocol - Support up to 32 sets of source match address - Security key setup failed when BLE is enabled on |
| 2023/03/01 | | - Add 2MB Flash FLM - Update flash driving setting to improve RX sensitivity - Fix Deep Sleep issue - Turn off LDO Enable when not loading 80251 FW. Tool: - MP_tool support 2MB flash Multi-Protocol: - Modify Zigbee/BLE application document Other: - 2MB flash OTA add secure upgrade FW: - Fixed getting wrong RSSI value when TX power is very low on Sub-G - Enable MAC features for multi-protocol - Support up to 32 sets of source match address |



| 2023/06/29 | 1.5.0 | [Platform]: - Modify VS Code and SDK Getting Start document Add SDK Quick Start document [Tool]: - MP Tool v1.4.0 support Sub-G power trim, matter production with certificates, and 1 to 16 parallel test - BLE Mesh Android app support Scenes, Rafael TRSP Server, and Rafael TRSP Client modes [BLE Mesh]: - Add gateway project and document - Restructure the file and folder for client model - Fixed provisioning fail issue |
|------------|-------|--|
| 2023/08/23 | 1.6.0 | [Platform]: - Add SRAM power enable at initial function Modify WDT setting to let WDT can reset all blocks - Modify WDT example - Fix Bootloader OTA decoder error at some image length [SubG]: - Support 433MHz [BLE]: - Add Privacy for Direct ADV, Scan [BLE Mesh]: - Gateway support BLE Transparent Transmission [Tool]: - MP Tool apply RF Trim calibration value - RF Lab Test Tool add SubG Tx power selection for band0 915Mhz to band2 433Mhz. |
| 2024/01/08 | 1.7.0 | [BLE]: - Add privacy demo example - Support LE Secure Connection [BLE Mesh]: - Server library support BLE TRSP service [Thread]: - Add Thread example and document [Zigbee]: - Modify gateway command document [Tool]: |



| | | - Mobile App add LE commission for SubG device to |
|------------|-------|--|
| | | join SubG network |
| 2024/03/21 | 1.8.0 | [Platform]: |
| | | - Add examples projects: Flash_RW, GPIO_Interrupt, |
| | | Gpio_Input, GPIO_Output, SADC_Polling, |
| | | Timer_Periodic, Timer_Freerun, WDT_Interrupt |
| | | [SubG]: |
| | | - Support 470~510MHz |
| | | - Keep Tx constant power (15dBm) regardless Vbat |
| | | voltage |
| | | [Thread]: |
| | | -Add SubG frequency band setting (915M, 868M, 433M) |
| | | [Tool]: |
| | | -RF lab test tool: add SubG 470~510MHz |
| 2024/05/06 | 1.9.0 | [Platform]: |
| | | - Update flash DS (Data Set) examples |
| | | - Fix flash DS API read fail issue. |
| | | [Thread]: |
| | | -Add 2.4G MTD Project |
| | | -Fix MTD task idle can't enter sleep issue. |
| | | [SubG]: |
| | | -Add support tx_continuous_wave_set API. |
| | | [Tool]: |
| | | -ISP tool: Auto reset and write/clear signature public key |
| | | -FOTA tool: Output signature bin option for ISP tool. |
| | | |
| | | |



2 RT58x_SDK_v1.9.0

New Features

- -Thread
 - ➤ Add 2.4G MTD Project
- SubG
 - ➤ Add support tx_continuous_wave_set API.

• Feature Changes

- -Platform
 - ➤ Update flash DS (Data Set) examples
- -Tool
 - ➤ ISP tool: Auto reset and write/clear signature public key
 - > FOTA tool: Output signature bin option for ISP tool.

Bug Fixes

- Thread
 - Fix MTD task idle can't enter sleep issue.
- Platform
 - Fix flash DS API read fail issue.



3 RT58x_SDK_v1.8.0

New Features

- -Platform
 - ➤ Add examples project:
 Flash_RW/GPIO_Interrupt/GPIO_Input/GPIO_Output
 SADC Polling/Timer Periodic/Timer Freerun/WDT Interrupt
- -SubG
 - > Add 470~510MHz band
 - ➤ Keep Tx constant power (15dBm) regardless Vbat voltage (Frequency: 433~510MHz)
- -Thread
 - ➤ Add SubG frequency band setting (915M, 868M, 433M)

• Feature Changes

- -Tool
 - > RF lab test tool: add SubG 470~510MHz

Bug Fixes



4 RT58x_SDK_v1.8.0

New Features

- -Platform
 - ➤ Add examples project:
 Flash_RW/GPIO_Interrupt/GPIO_Input/GPIO_Output
 SADC_Polling/Timer_Periodic/Timer_Freerun/WDT_Interrupt
- -SubG
 - > Add 470~510MHz band
 - ➤ Keep Tx constant power (15dBm) regardless Vbat voltage (Frequency: 433~510MHz)
- -Thread
 - ➤ Add SubG frequency band setting (915M, 868M, 433M)

• Feature Changes

- -Tool
 - > RF lab test tool: add SubG 470~510MHz

Bug Fixes



5 RT58x_SDK_v1.7.0

New Features

- -BLE
 - ➤ Add privacy demo example
 - > Support LE secure connection
- -BLE Mesh
 - ➤ Server library support BLE TRSP service
- -Thread
 - ➤ Add Thread example and document

• Feature Changes

- -Zigbee
 - ➤ Modify gateway command document
- -Tool
 - ➤ Mobile App add BLE commission for Sub_G device to join Sub_G network

Bug Fixes



6 RT58x_SDK_v1.6.0

New Features

- -SubG
 - ➤ Support 433MHz
- -BLE
 - > Add Privacy for Direct ADV, Scan
- -BLE Mesh
 - ➤ Gateway supports BLE Transparent Transmission

Feature Changes

- -Platform
 - > SRAM power enable at the start of system initial function. To avoid operation abnormal after wakeup from Deep Sleep
- -Tool
 - ➤ ISP tool add SubG Tx power selection band0 [915Mhz] and band2 [433Mhz].
 - ➤ RF Lab Test Tool add SubG Tx power selection band0[915Mhz] to band2 [433Mhz].

Bug Fixes

- -Tool
 - > MP Tool apply RF Trim calibration value to solve random RX fail issue
- Platform
 - ➤ Modify WDT setting to let WDT can reset all blocks
 - > Fix Bootloader OTA decoder error at some image length



7 RT58x_SDK_v1.5.0

New Features

• Feature Changes

-Platform

- ➤ Modify VS Code and SDK Getting Start document.
- > Add SDK Quick Start document

-Tool

- ➤ BLE Mesh app: Android app support Scenes, Rafael TRSP Server, and Rafael TRSP Client modes
- ➤ MP Tool v1.4.0: support Sub-G power trim, matter production with certificates, and 1 to 16 parallel test

-BLE Mesh

- > Implement gateway project and document
- Restructure the file and folder for client model

Bug Fixes

- -BLE Mesh
 - > Fixed provisioning fail issue

Known Issues

-None



8 RT58x_SDK_v1.4.0

New Features

- -Platform
 - ➤ Add 2MB Flash FLM
 - > Update flash driving setting to improve RX sensitivity

Feature Changes

- -Tool
 - ➤ MP tool support 2MB flash
- -Multi Protocol
 - ➤ Modify Zigbee/BLE application document for first time join Zigbee network
- -Other
 - ➤ 2MB flash OTA support secure upgrade
- -FW
 - ➤ Enable MAC features for multi-mode
 - ➤ Support Up to 32 Sets of Source Match Address
 - > Security key setup failed when BLE is enabled on multi-mode FW

Bug Fixes

- -Platform
 - Fix Deep Sleep issue
 - > Turn off LDO Enable when not loading 80251 FW.

Known Issues

-None



9 RT58x_SDK_v1.3.0

New Features

-Zigbee:

- ➤ New flash update algorithm
- > Add library version

-Tool:

➤ Android app: add Zigbee smart home

Feature Changes

-Zigbee:

- ➤ Power on/off 5 times to reset light device
- Gateway for Home Automation
 - Add sensor related clusters
- ➤ Modify private cluster ID

-BLE:

- ➤ Use 2 bytes to indicate LL TX data sequence
- > FOTA flow update to support image compression

-BLE Mesh:

➤ Change ADV_enable complete event response timing from "TX complete" to "constant delay"

-SubG:

➤ Add SubG_Field_Test demo



-Platform:

- ➤ Bootloader Support LZMA decompression for FOTA
- ➤ Add "volatile" to avoid optimization in Sleep mode

-Tool:

- ➤ Android app: modify BLE Mesh demo
- ➤ MP tool
 - Separate BLE/Zigbee Tx power target
 - Manual set X'tal cap
- > ISP tool
 - Support SubG
 - FOTA with image compression

Bug Fixes

-Peripheral:

➤ Update ADC setting to overcome chip variation issue.

-Zigbee:

- ➤ Solve one interoperability issue with Legacy Zigbee gateway
- Fix under multi-PAN environment, device may accept packet from different PAN_ID.

-BLE Mesh:

- ➤ Fixed bug: in transparent transmission, different packet size stress test assert
- Fixed bug: sometimes Provision fail

-Sub G:

- ➤ Fixed GCC project
- > Fixed received data sequence in SubG TRX demo example

Known Issues

-Platform:

➤ Cortex M3 can't enter deep sleep mode if communication subsystem still working. Will fix it in SDK v1.3.1



10 RT58x_SDK_v1.2.3_BLE_Mesh

- New Features
- None.

• Feature Changes

- -BLE Mesh:
 - ➤ Implement Model and Lighting Demo.
 - > BLE Mesh Performance Tuning.
 - > BLE Mesh Document.
- Bug Fixes
- None.
- Known Issues
- None.



11 RT58x_SDK_v1.2.2_Zigbee

New Features

- None.

• Feature Changes

-Zigbee:

- > Gateway module:
- Revise binding command
- Add read attribute, write attribute, configure report command
- Light:
- Add OTA client cluster
- Add finding & binding process
- > Switch:
- Remove endpoint 1&3
- Add OTA client cluster
- Add finding & binding process
- > OTA Server:
- Removed (gateway module replace)
- > OTA Client:
- Removed (light/switch replace)

Bug Fixes

- None.

Known Issues



12 RT58x_SDK_v1.2.1

New Features

- Tools:
 - ➤ MP_Tool add Tx power 0/4 dBm target

• Feature Changes

- -Zigbee:
 - ➤ Optimize RX current consumption
 - ➤ Device send leave command to gateway after factory reset
- Bug Fixes
- None.
- Known Issues
 - None.



13 RT58x_SDK_v1.2.0

New Features

-BLE:

➤ Add Privacy and connect CTE API.

-Zigbee:

- ➤ Now can pre-configure the network parameters.
- ➤ Add OTA function in new gateway demo.

-Multi-protocol:

- ➤ Zigbee Easy Gateway: implement Zigbee gateway by one RT582 chip. Running BLE/Zigbee multi-protocol on RT582 to replace traditional Zigbee gateway.
- ➤ Utilize BLE to reset Zigbee Device when Gateway is broken or offline.

-Tools:

- ➤ Android app: Easy Gateway app
- > Android app: utilize BLE to reset Zigbee Device

Feature Changes

- Zigbee AES by HW accelerator.



Bug Fixes

- Zigbee address generation form MAC address in flash OTP

Known Issues



14 RT58x_SDK_v1.1.1

New Features

- None.

Feature Changes

- Modify PMU DCDC initial setting to enhance the stability under stress environment.

Bug Fixes

- None.

Known Issues



15 RT58x_SDK_v1.1.0

New Features

- -Added examples: I2S digital microphone
- -Modify PWM example
- -BLE:
 - ➤ Added UART cmd demo
 - ➤ Added Beacon demo

-Zigbee:

- ➤ Gateway example support more commands
- ➤ Added User_specific_cluster
- ➤ Added Scene in light demo
- ➤ Added Thermostat cluster

-Multi-protocol:

➤ Added Zigbee ZED with BLE OTA demo

-Tools:

- > RF_Lab_Test_Tool: supports SubG RF test. On the GUI, remove WiSun mode and change to SubG mode
- ➤ ISP Tool: (1) remove MP sector Download and Erase button



- (2) Judge If IC had been MP_calibrated or not? If not, UI show warning message.
- Android App: add BLE Mesh On/Off demo

Feature Changes

- Projects include TX_power compensation. Default is disable

Bug Fixes

- Fixed Zigbee two end-point bug.
- Fixed Zigbee OTA buffer issue.

Known Issues



16 RT58x_SDK_v1.0.1

New Features

- Added software PMU calibration.

Feature Changes

- Extend Zigbee maximum network nodes to 200.

Bug Fixes

- Fixed low speed timer reload abnormal issue under low temperature.

Known Issues



17 RT58x_SDK_v1.0.0_Mesh

New Features

- Added BLE Mesh demo example.
 - ➤ \Project\Application\BLE Mesh\GenericOnOff\.
- Added BLE Mesh App.
 - ➤ \Tools\Android App\.
- Added BLE Mesh documents.
 - ➤ \Tools\Android App\User guide\

Android APP BLE Mesh user guide V1.2.pdf.

- ➤ \Docs\RT58x_BLE_Mesh_User_Guide_V1.0.pdf.
- ➤ \Docs\RT58x_SDK_for_BLE_Mesh_Demo_Guide_V1.0.pdf.

Feature Changes

- None.

Bug Fixes

- None.

Known Issues



18 RT58x_SDK_v1.0.0

New Features

- Added peripheral drivers and examples for I2S, Timer, Watchdog, and SADC.
- Added BLE demo example with low power mode mechanism.
- Added BLE UART_TRSP demo with low power mode mechanism and wakeup by URAT break in "Rafael UART Break tool".
- Added more tools.
 - ➤ Upgraded xcode from v5.5 to v5.6 in iOS App.
 - ➤ Added Zigbee/BLE multi-standard demo in iOS App.
 - ➤ Added UART_Break_Tool to send break signal to wakeup BLE before sending characters for BLE UART TRSP demo.
 - ➤ Added Tx Power trim, ADC trim, and Comparator trim to MP Tool.
- Added related documents.
 - ➤ [SW_15]RT58x_Zigbee_Gateway_Light_Switch_Operation_Guide_V1.0.
 - > RT58x SDK Reference Guide in Doxygen format.



Feature Changes

- Removed Direct_Test_Mode demo and integrated DTM function into "RF Lab Test Tool FW".

Bug Fixes

- Fixed bug in BLE multi-link demo.

Known Issues

- None.

Notes

- SDK includes MCU peripheral examples, BLE examples, and Zigbee examples. All examples support Keil and GCC projects.
 - ➤ Peripheral: \Project\Examples\.
 - ➤ BLE: \Project\Application\BLE Demo\.
 - ➤ Zigbee: \Project\Application\Zigbee Demo\.
 - ➤ Zigbee & BLE: \Project\Application\Multi_Protocol_Demo\.
- For all examples to work properly, the bootloader needs to be downloaded first. Please refer to the documentation for details.
 - ➤ \Docs\[SW_02]RT58x_SDK_IOT_Application_Overview_V1
 .0.
- Measure sleep power consumption project.



- ➤ \Project\Examples\Sleep.
- Tool and test image to measure RF performance.
 - ➤ \Tools\IOT_Evaluation_Tool.
 - ➤ \Tools\IOT_Evaluation_Tool\RF_Lab_Test_Tool_FW.



19 RT58x_SDK_v0.3.1

New Features

- Added GCC project for all examples.
- Added Zigbee/BLE multi-protocol demo.
- Added more Zigbee examples, eg: Gateway, OTA, etc.
- Added more tools.
 - ➤ ISP Tool
 - > RF_Lab_Test_Tool
 - Security_Boot_Tool
 - ➤ Mass_Production_Tool
 - ➤ Android_App
 - ➤ iOS_App
- Added related documents.
 - ➤ [SW_01]RT58x_SOC_Platform_Getting_Started_V1.1
 - ➤ [SW_02]RT58x_SDK_IOT_Application_Overview_V1.0
 - > [SW 03]RT58x Zigbee SDK User Guide V1.0
 - ➤ [SW_04]RT58x_Zigbee_Application_Guide_V1.0
 - > [SW 06]RT58x BLE SDK User Guide V1.0
 - ➤ [SW 07]RT58x BLE SDK Application Guide v1.0



- > [SW_08]RT58x_BLE_SDK_OTA_Guide_V1.0
- > [SW_09]RT58x_BLE_SDK_Service_Profile_Guide_V1.0
- > [SW_13]RT58x_Multi_Protocol_Application_Guide_V1.0

Feature Changes

- Unified application architecture of different protocols.
- Modified power saving example.

Bug Fixes

- None.

Known Issues



20 RT58x_SDK_v0.2.0

New Features

- For SubG only.

Feature Changes

- None.

Bug Fixes

- None.

Known Issues



21 RT58x_SDK_v0.1.0

New Features

- Initial version.
- Added peripheral drivers and examples.
- Added BLE stack and BLE applications.

Feature Changes

- None.

Bug Fixes

- None.

Known Issues