BeSafe SGFL Injuries

Generated on: 2023-10-23

S.NO	1	ID	10	Reference	809			Time	06:59:00		Date 2	11-07- 2023	Initiated By	admir
Unit	Unit 1	Department	Production	Location	location 1			Other Location	Hall -2 Firs	st Floor				
Line	116	Meta Injury Category	First Aid Case	Meta Incident Category	Stitching									
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Ali Shan									
Witness Name			During stitching the shoes Upper on stitching machine suddenly paddle was pressed by foot and finger caught in between the needle.	Immediate Action	First aidAw start of s	areness Session	should be conducted by foreman before							
Key Finding		Created At	04-08-2023	Immediate Causes		ure to Identify Haz nent/machinery/de	ard, SA7- Improper operation of vice							
Root Cause		Contact Types		Updated At	15-08-2023	3								
Actions	Description	n	Responsibility			Т	imeline		Statu	ıs				
S.NO	2	ID	11			Reference	810		Time	13:30:00	Date		Initiated	admi
Jnit	Unit 2	Department	Production			Location	Production Hall - Female		Other			2023	Ву	
Offic	Offit 2	·	Floudcion				Froduction Hair - Female		Location					
Line	SL-14	Meta Injury Category	First Aid Case			Meta Incident Category	Press Machine							
Meta Incident Status	Completed	Employee Involved	yes			Injured Person	Esha Ijaz							
Witness Name			During working on press machine, the leather upper was stick to the machine while removing uppr fingers pressed by the heat pressing machine and burned.	er directly from mad	hine his	Immediate Action	First aid was provided inhouse dispe investigation started	nsary and						
Key Finding		Created At	04-08-2023			Immediate Causes	SA17- Failure to Follow Procedure/Ir	nstruction						
Root Cause		Contact Types				Updated At	15-08-2023							
	Descriptio	n					Responsibility		Timeline			Stat	us	
Actions	Tool Shoul	d be used in case	of removing upper directly from the machine.				Production		17-07-2023	3		close	∌d	
S.NO	3	ID	12		Refe	erence 8	11	Т	ime	11:25:00	Date	19-07- 2023	Initiated By	admi
Unit	Unit 1	Department	Production		Loc	ation lo	ocation 1		ocation					
Line	I-127	Meta Injury Category	First Aid Case			a Incident egory	yelet Machine							
Meta Incident Status	Completed	Employee Involved	yes		Inju	red Person	hahid Bau							

Witness Name		Details	He was working on eyelet machine, during placing washer on upper, suddenly his foot pressed on pedal and his right- hand thumb caught in between the machine.	Immediate Action	First aid was provided inhouse dispensary and investigation started		
Key Finding		Created At	04-08-2023	Immediate Causes	SA15- Improper/inapproriate behaviour		
Root Cause		Contact Types		Updated At	15-08-2023		
	Descripti	on			Responsibility	Timeline	Status
Actions	Installation	n of infrared senso	r is required to avoid eyelet injuries		Engineering	20-09-2023	pending

S.NO	4	ID	13	Reference	812		Time	11:59:00		07-07- 2023	Initiated By	admin
Unit	Unit 1	Department	Production	Location	location 1		Other Location					
Line	L-125	Meta Injury Category	First Aid Case	Meta Incident Category	Eyelet Machine							
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	M.Waqas							
Witness Name		Details	While standing up from his seat, his Right Hand index finger caught in eyelet machine and unintentionally paddle pressed by foot.	Immediate Action	First aid was provided inhouse dispensar investigation started	y and						
Key Finding		Created At	04-08-2023	Immediate Causes	SA14- Improper Position for Task							
Root Cause		Contact Types		Updated At	15-08-2023							
	Descriptio	n				Responsibilit	у	Timelin	ne		Status	

Actions

Meta Incident

Status

Completed Employee Involved

yes

Awareness Session should be conducted by foreman before start of shift to avoid eyelet machine injuries

S.NO	5	ID	14	Reference	813	Time	11:30:00	Date	23-07-2023	Initiated By	admin
Unit	Unit 1	Department	Production	Location	location 1	Other Location					
Line	L-118	Meta Injury Category	First Aid Case	Meta Incident Category	Eyelet Machine						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Babar Ali						
Witness Name		Details	Right hand Index Finger Eyelet Machine injury	Immediate Action	First aid was provided inhouse dispensary and investigation started						
Key Finding		Created At	04-08-2023	Immediate Causes	SA14- Improper Position for Task						
Root Cause		Contact Types	Caught In	Updated At	15-08-2023						
	Description	Description				Responsibility	٦	Γimelin	е	Status	
Actions	Automatic (tomatic Conveyor should be installed for washer to avoid manual working on eyelet machine					2	20-09-20	023	pending	

Production

15-07-2023

closed

S.NO	6	ID	15	Reference	814	Time	14:03:00	Date 20- 07- 2023	Initiated By	admin
Unit	Unit 1	Department	Production	Location	Hall-1 Production	Other Location				
Line	L-125	Meta Injury Category	First Aid Case	Meta Incident Category	Eyelet Machine					

Injured Person

Ahmad Raza

Witness Name	Deta		Left hand Index Finger Eyelet Machine injury. He was standing back side of the machine in inappropriate manner by placing his left hand index finger in between the machine bolt and pump.	Immediate Action	First aid was provided inhouse dispensary and in	vestigation started		
Key Finding	Cre	eated At	04-08-2023	Immediate Causes	SA15- Improper/inapproriate behaviour, SA17- Fa Procedure/Instruction, SA18- Failure to Identify H			
Root Cause	Con Typ	ntact pes	Caught In	Updated At	15-08-2023			
	Description					Responsibility	Timeline	Status
Actions	Awareness Session should be conducted by foreman before start of shift to avoid eyelet machine injuries					Production	24-07-2023	closed

S.NO	7	ID	16	Reference	815	Time	15:25:00	Date	02-08-2023	Initiated By	admir
Unit	Unit 1	Department	Production	Location	location 1	Other Location					
Line	L-123	Meta Injury Category	Medical Treatment Case	Meta Incident Category	Eyelet Machine						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Mansoor						
Witness Name		Details	Left Hand index Finger eyelet machine injury	Immediate Action	First aid was provided inhouse dispensary and investigation started						
Key Finding		Created At	05-08-2023	Immediate Causes	Others, SA14- Improper Position for Task						
Root Cause		Contact Types	Caught In	Updated At	15-08-2023						
	Description	1				Responsibility		Timel	ine	Status	
Actions	Automatic (Conveyor should be installe	d for washer to avoid manual working on eyelet mac	chine		Engineering		20-9-2	2023	pending	

S.NO	8	ID	17	Reference	809		Time	17:20:00	02-08- 2023	Initiated By	admir
Unit	Unit 2	Department	Production	Location	Production Hall - Lasting		Other Location				
Line		Meta Injury Category	First Aid Case	Meta Incident Category	Elfy						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	M.Ahmed						
Witness Name		Details	He opened bottle of Elfy for working on shoes, suddenly Elfy gets is his eye during opening of cover.	Immediate Action	First aid was provided inhouse dispensary and investigate refer to THQ Muridke.	ation started and Patient					
Key Finding		Created At	15-08-2023	Immediate Causes	SA10- Failure to use PPE properly, Others:_						
Root Cause		Contact Types		Updated At	15-08-2023						
	Description	n				Responsibility	Tir	neline	s	tatus	
Actions	Safety Gog	ggles should be prov	vided to workers for working with Elfy for Shoe Finishing			Production	10-	-08-2023	cl	losed	

S.NO	9	ID	18	Reference	810	Time	11:59:00	Date	04- 08- 2023	Initiated By	admin
Unit	Unit 1	Department	Production	Location	Hall-1 Production	Other Location					
Line	L-130	Meta Injury Category	Medical Treatment Case	Meta Incident Category	Sharp Tool						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Qamar Abbass						

Witness Name		Details	There should be proper location and identification for usage of sharp blade in shoe processing	Immediate Action	First aid was provided inhouse dispensary	and investigation	started and Patient re	efer to THQ Muridke.						
Key Finding		Created At	15-08-2023	Immediate Causes	SA3- Failure to secure, SA12- Improper Pl operation of tool/equipment/machinery/dev		Failure to Identify Haz	ard, SA7- Improper						
Root Cause		Contact Types	Slip	Updated At	15-08-2023									
	Descripti	on						Responsibility	Tir	meline		Sta	atus	
Actions	There sho	ould be proper loca	tion and identification for usage of sharp blade in shoe processing.					Production	10	-08-2023		clos	sed	
SNO	10	ID.	21			Reference	813		Time	11:01:00	Data	11- 04 In	nitiated	admir

S.NO	10	ID	21	Reference	813		Time	11:01:00	Date 04- 2023		admin
Unit	Unit 3	Department	Engineering	Location	Workshop Area		Other Location				
Line		Meta Injury Category	First Aid Case	Meta Incident Category	Mould						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Ehsanullah						
Witness Name		Details	To pick stamp for mould, he went to production site, Already 3 of the moulds were placed, 2nd person came and place 4th mould on above the 3 moulds. Due to unbalanace mould hit on his foot	Immediate Action	First aid was provide and investigation sta	ed inhouse dispensary arted					
Key Finding		Created At	15-08-2023	Immediate Causes	SA10- Failure to use	PPE properly					
Root Cause		Contact Types	Fall to Below	Updated At	15-08-2023						
	Description	on				Responsibility	Т	imeline		Status	
Actions	Provide Sa	afety Shoes to We	orkers during working on Moulding machine/Engineering Workshop			Engineering	2	0-4-2023		closed	
	Proper Ra	cks for the storag	e of Mould in Engginering Workshop/Production			Engineering	2	0-4-2023		closed	

S.NO	11	ID	22	Reference	814	Time	11:09:00	14-04- 2023	Initiated By	admin
Unit	Unit 2	Department	Production	Location	Production Hall - Lasting	Other Location				
Line	L-236	Meta Injury Category	First Aid Case	Meta Incident Category	Chemical					
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Khadim Hussain					
Witness Name		Details	Sole Cleaning Chemical Drop in both Eyes. He was sitting on the floor & eating. Suddenly, he stand up and the edge of table hit on his head.	Immediate Action	First aid was provided inhouse dispensary and investigation started					
Key Finding		Created At	15-08-2023	Immediate Causes	Others:_					
Root Cause		Contact Types	Caustic / Acid	Updated At	16-08-2023					
	Descriptio	n			Responsibility	imeline		Status		
Actions	Chemical s	should be covered of	uring handling & Storage,		Production 1	5-04-2023		closed		
Actions	All chemica	als should be palce	in secondary Containment.		Production 1	5-04-2023		closed		

S.NO	12	ID	26	Reference		Γime	05:23:00 Date	19- 04- 2023	nitiated By	admin	
------	----	----	----	-----------	--	------	----------------------	--------------------	----------------	-------	--

Unit	Unit 2	Department	Production	Location	Production Hall - Closing Male	Other Location
Line	SL-15	Meta Injury Category	Medical Treatment Case	Meta Incident Category	Press Machine	
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Murtaza	
Witness Name		Details	Right hand middle and ring finger got injured during working on press machine. During working on press machine, the leather upper was stick to the machine while removing upper directly from machine his fingers pressed by the heat pressing machine and burned.	Immediate Action	First aid was provided inhouse dispensary and investigation started and Patient refer to THQ Muridke.	
Key Finding		Created At	22-08-2023	Immediate Causes	SA15- Improper/inapproriate behaviour, SA7- Improper operation of tool/equipment/machinery/device	
Root Cause	Machine power turned on while removing upper directly from hand. Effective tool was not used to remove upper from machine	Contact Types	Struck-By	Updated At	22-08-2023	
	Description				Responsibility	Timeline

Actions Tool should be used in case of removing upper directly from the machine

S.NO	13	ID	27	Reference	816	Time	05:35:00	Date	Initiated By	admin
Unit	Unit 3	Department	Engineering	Location	Workshop Area	Other Location				
Line		Meta Injury Category	First Aid Case	Meta Incident Category	Mould					
Meta Incident Status	Completed	Employee Involved	no	Injured Person						
Witness Name		Details	Having mould in his hand, He went to engineering workshop with one of his friend, suddenly mould slip from his friend hand and hit on his left foot and got injured.	Immediate Action	First aid was provided inhouse dispensary and investigation started					
Key Finding		Created At	22-08-2023	Immediate Causes	SC33- Inadequate/Improper Personal Protective Equipment					

Status

closed

21-04-23

Production

	Safety Shoes was not wear during working.	Contact Types	Slip	Updated At	22-08-2023			
	Description					Responsibility	Timeline	Status
Actions	Safety Shoes must be provide	ed to workers for v	working in workshop , production moulding area			Engineering	08-05-23	pending

S.NO	14	ID	33	Reference	915	Time	03:27:00	Date	11- 09- 2023	Initiated By	ac
Unit	Unit 1	Department	Production	Location	Hall-3 First Floor	Other Location					
Line	L-322	Meta Injury Category	First Aid Case	Meta Incident Category	Stitching						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Shahid Ali						
Witness Name		Details	Right Hand Thumb, Needle Injury. He was working on stitching machine, during stitching of shoe upper suddenly, paddle was press by his foot and his right hand thumb caught in between the machine.	Immediate Action	First aid was provided inhouse dispensary and investigation started						
Key Finding		Created At	16-09-2023	Immediate Causes	SA17- Failure to Follow Procedure/Instruction, SA15- Improper/inapproriate behaviour						

		Contact Types	Caught In				Updated A	At 09-10-202	23							
	Description										Respo	nsibility	Time	eline	Statu	s
Actions	Awareness Se	ssion should	pe conducted before	e the start of the s	shift by foreman on machine safety and awareness on use of needle gu	ard, eye guard, to a	void stitching ma	achine injuries.			Produ	ction/HSE	19-09	9-2023	closed	Ł
S.NO	15			ID	34		F	Reference	916		Time	03:53:00			iated a	dmin
Unit	Unit 1			Department	Production		L	_ocation	Hall-2 Stitching Ground Floor		Other Location					
Line	L-101			Meta Injury Category	First Aid Case			Meta Incident Category	Press Machine							
Meta Incident Status	Completed			Employee Involved	yes		li	njured Person	Abdul Sattar							
Witness Name					He was working on heavy press machine, during setting of synthetic signessed by his left finger and his right hand wrist got injured.	heets suddenly butto		mmediate Action	First aid was provided inhouse of and investigation started	dispensary						
Key Finding				Created At	16-09-2023			mmediate Causes	SA8- Inadequate servicing of equipment/machinery in operation	on						
Root Cause	Machine press of focus on wor		ghtly loose. lack	Contact Types	Struck-By		U	Jpdated At	08-10-2023							
	Description								Responsi	ibility	-	Γimeline		Statu	ıs	
Actions	By the suppor	t of engineering	ng team, it was disc	ussed to change	the machine press button to reduce injury.				Engineeri	ng		19-09-2023		pendi	ing	
S.NO	16			ID	35	Reference	1017			т	ime	17:10:00			i ated a	dmin
Unit	Unit 1			Department	Production	Location	Hall-3 First Fl	loor			ther ocation					
Line	L-315			Meta Injury Category	First Aid Case	Meta Incident Category	Stitching									
Meta Incident Status	Completed			Employee Involved	yes	Injured Person	Nasir Javed									
Witness Name				Details	During working on stitching machine needle prick on his right hand index finger and he got injured.	Immediate Action		provided inhouse to THQ Muridke.	e dispensary and investigation sta	arted and						
Key Finding				Created At	09-10-2023	Immediate Causes	SA18- Failure	e to Identify Haza	ard, SC32- Inadequate Guard/Bar	rrier						
Root Cause	Usage of need Lack of focus		not effective.	Contact Types	Caught In	Updated At	17-10-2023									
	Description								Responsibil	ity	Т	imeline		Status	s	
Actions	Awareness S	Session shoul	d be conducted on	general safety ind	uction to identify the machine hazards.				Production/H	SE	2	5-09-2023		pendir	ng	
S.NO	17			ID	77			Reference	1058		Tim		Date 20:	-06- Initi 23 By	a	dmin

Line	L-311	Meta Injury Category	First Aid Case	Meta Incident Category	Sharp Tool			
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	M.Kashif			
Witness Name		Details	While trimming excess thread from the upper, the sharp edge of the clipper accidentally struck the worker's left-hand middle finger, causing an injury.	Immediate Action	First aid was provided inhouse dispensary and investigation started			
Key Finding		Created At	17-10-2023	Immediate Causes	SA18- Failure to Identify Hazard			
Root Cause	Lack of awareness of potential hazards associated with the sharp tool.	Contact Types	Struck-By	Updated At	20-10-2023			
	Description					Responsibility	Timeline	Status
Actions	Implement a training and awareness program of	n sharp tool mana	agement This program should cover safe operation, potential hazards, and proper hand placement during	ng the trimming pro	cess.	Production/HSE	19-06-2023	closed

S.NO	18	ID	79	Reference	1060		Time	Date	nitiated By	admi
Unit	Unit 1	Department	Production	Location	Hall 02 First Floor		Other Location			
Line	L-101	Meta Injury Category	First Aid Case	Meta Incident Category	Skiving Machine					
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Khuram Shazad					
Witness Name		Details	While operating the skiving machine, the worker's momentary distraction led to an unfortunate incident where his right-hand middle finger came into contact with the skiving machine blade, resulting in an injury	Immediate Action	First aid was provided in and investigation started					
Key Finding		Created At	17-10-2023	Immediate Causes	SA15- Improper/inappro	riate behaviour				
Root Cause	Skiving machine guard was not installed.	Contact Types	Struck-By	Updated At	20-10-2023					
	Description					Responsibility	Tim	eline	Status	
Actions	Implementing a skiving n	nachine guard ins	stallation as a corrective measure to prevent incidents related to contact with the sharp blade.			Engineering	30-0	06-2023	pending	

S.NO	19	ID	81	Reference	1062	Time	13:37:00	Date	10- 06- 2023	Initiated By	admin
Unit	Unit 2	Department	Production	Location	Production Hall - Female	Other Location					
Line	SL-11	Meta Injury Category	First Aid Case	Meta Incident Category	Eyelet Machine						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Nazia Amanat						
Witness Name		Details	While operating the Eyelet machine between approximately 12:36 pm and 1:36 pm, at around 1:37 pm, a colleague called out to her from behind, and she felt that her chair had shifted slightly. This distraction caused her to lose focus on her work, leading to the accidental pressing of the machine's pedal and subsequent contact of her right-hand index finger with the Eyelet machine.	Immediate Action	First aid was provided inhouse dispensary and investigation started and Patient refer to THQ Muridke.						

Key Finding		Created At	17-10-2023	Immediate Causes	SA18- Failure to Identify Hazard, SA15- Improper/inapproriate behaviour, SA3- Failure to secure			
Root Cause	lack of sufficient training or awareness regarding safe machine operation and the importance of maintaining focus during work. Workplace Distraction. Automatic conveyor was not installed specifically for washer.	Contact Types	Caught In	Updated At	20-10-2023			
	Description					Responsibility	Timeline	Status
Actions	Provide refresher safety training for all workers operating the E	yelet machine.	This training should include awareness of potential distractions and the significance of adhering to safety procedu	es.		HSE	19-06-2023	closed
Addidio	Installation of double stock mechanism to avoid eyelet machine	e injuries by sir	igle press.			Engineering 15-07-2023		pending

									00		
S.NO	20	ID	82	Reference	1063	Time	•			nitiated By	ıdmi
Unit	Unit 1	Department	Production	Location	Hall-1 Production	Othe Loca					
Line	L-137	Meta Injury Category	First Aid Case	Meta Incident Category	Shoe Polishing Machine						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Illyas						
Witness Name		Details	While finishing the shoes on the automatic shoe polishing machine, the shoe lace caught in between the machine and shoe last hit on his right-hand wrist.	Immediate Action	First aid was provided inhouse dispensary and investanted and Patient refer to THQ Muridke.	stigation					
Key Finding		Created At	17-10-2023	Immediate Causes	SA17- Failure to Follow Procedure/Instruction, SA12 Improper Placement	2-					
Root Cause	Lack of adequate safety measures or safeguards in place to prevent such entanglements.	Contact Types	Caught In	Updated At	20-10-2023						
	Description					Responsibility		Timeli	ne	Statu	
Actions	Awareness session should be conducted to educate	workers about i	machine hazards and proper shoe lace binding procedures before using the polishing machine			Production/HSE		19-06-	2023	closed	

11:01:00 **Date** 12-06-2023 **Initiated** admin

S.NO	21	ID	84	Reference	1065	Time	
Unit	Unit 1	Department	Production	Location	Hall-3 First Floor	Other Location	
Line	L-313	Meta Injury Category	First Aid Case	Meta Incident Category	Stitching		
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	M. Waqar		
Witness Name		Details	During sitting on stitching machine, suddenly paddle was pressed by foot and thumb caught in between the needle and he got right hand thumb needle injury.	Immediate Action	First aid was provided inhouse dispensary and investigation started		
Key Finding		Created At	17-10-2023	Immediate Causes	SA15- Improper/inapproriate behaviour		
Root Cause	Inadequate training and awareness about the risks associated with machine operation.	Contact Types	Caught In	Updated At	20-10-2023		

	Description							nesponsibility	111	nemie	Status
Actions	Awareness session should be conducted before s	start of shift by	the line incharge	to identify machine hazards and safety.				Production	14	-06-2023	closed
S.NO	22		ID	86	Reference	1067			Time	Date 12- 06- 2023	Initiated adr
Unit	Unit 1	Depa		t Production Location		Hall-3 Fir	Hall-3 First Floor		Other Location		
Line	L-326			Meta Incider Category	nt Stitching						
Meta ncident Status	Completed		Employee Involved	yes	Injured Person	M.Afzal					
Witness Name			Details	He was working on stitching machine, during stitching of shoe upper his right hand index finger got injured.	Immediate Action	First aid was provided inhouse dispensary and investigation started					
Key Finding			Created At	17-10-2023	Immediate Causes		adequate Guard/Ba proper/inapproriate	rrier, SA18- Failure to Identify Hazard, behaviour			
Root Cause	Needle Guard & Eye Guard was not installed on n worker Inability to concentrate on his task.	nachine.	Contact Types	Caught In	Updated At	20-10-20	23				
	Description							Responsibility		Timeline	Status
Actions	Requested to engineering team to install needle	and eye guard	on machine and a	awareness session should be conducted by lineincahrge to identify the	hazards.			Production/Engin	eering	19-06-2023	B pending
	23	ID	87				068		Time	Date 06- 202	Initiated By
Jnit	Unit 1	Department	Production		Lo	ocation H	Hall- 3 Ground floor		Other Location	,	
_ine	L-334	Meta Injury Category	Medical Treatm	ent Case	In	leta ncident S ategory	Sharp Tool				
Meta Incident Status	Completed	Employee Involved	yes			njured Person	Aamir Ali				
Witness Name		Details		in Hall 03 Line 334 (Lasting Department), During cutting of paper for p sharp edge of the blade cut his left-hand index finger and he got major				d inhouse dispensary and investigation efer to THQ Muridke.			
Key Finding		Created At	17-10-2023					equate Tool/Equipment, SA18- Failure 65- Improper/inapproriate behaviour	to		
	Anti-cut gloves were not used for cutting tasks, and a suitable tool for paper cutting was not utilized.	Contact Types			U	pdated At 2	0-10-2023				
	Description							Responsibility	Timeline	;	Status
Actions	Mesh gloves/Anti cut gloves should be provided for	cutting purpose	Э					Production	10-08-2023	1	pending
	Paper cutter tool and cutting machine should be use	ed for cutting in	stead of using sh	arp blade.				Production	10-08-2023	1	pending
S.NO	24	ID	89			Reference	1070		Time	Date 06- 202	Initiated By adr
Jnit	Unit 1	Department	Production			Location	Hall- 3 Ground fl	oor	Other Location	1	

Responsibility

Timeline

Status

Description

Line	L-334	Meta Injury Category	Medical Treatment Case	Meta Incident Category	Sharp Tool			
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Jahanzeb			
Witness Name		Details	He was working in Hall 03 Line 334 (Lasting Department), During cutting of paper for packing box with blade, sharp edge of the blade cut his right hand inner side got major injury.	Immediate Action	First aid was provided inhouse dispensar investigation started and Patient refer to			
Key Finding		Created At	17-10-2023	Immediate Causes	SC25- Defective Tool/Equipment, SA18- Identify Hazard	Failure to		
Root Cause	Anti Cut gloves not used for cutting tasks. Effective tool was not utilized for paper cutting.	Contact Types		Updated At	20-10-2023			
	Description			ı	Responsibility	Timeline	Status	
Actions	Mesh gloves/Anti cut gloves should be provided to	or cutting purpo	ose	F	Production	10-08-2023	g pending	

S.NO	25	ID	91	Reference	1072	Time	04:54:00	Date 06 20	Initiated	admi
Unit	Unit 1	Department	Production	Location	Hall 02 First Floor	Other Location				
Line	L-126	Meta Injury Category	First Aid Case	Meta Incident Category	Stitching					
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Sahil Masih					
Witness Name		Details	Worker was working in Hall 01 at line no. 126, during stitching of shoe upper, he moved the side of upper for stitching, suddenly his right-hand index finger hit with needle got injured	Immediate Action	First aid was provided inhouse dispensary and investigation started					
Key Finding		Created At	17-10-2023	Immediate Causes	SA14- Improper Position for Task, SC32-Inadequate Guard/Barrier					
	The worker's utilization of the needle guard was ineffective.	Contact Types		Updated At	20-10-2023					
	Description				Responsibility		Timelin	ie	Status	
Actions	Awareness session should be conducted	cted by production	on in charge for effective usage of needle guard during stitching		Production		21-06-2	023	closed	

Date 19-06-2023 Initiated By admin

S.NO	26	ID	92	Reference	1073	Time
Unit	Unit 1	Department	Production	Location	Hall-3 First Floor	Other Location
Line	L-126	Meta Injury Category	First Aid Case	Meta Incident Category	Stitching	
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Azam Ali	
Witness Name		Details	Worker was working on stitching machine in hall#3 at line#312, during picking of thread from needle his foot was pressed on paddle and his right-hand index finger got injured.	Immediate Action	First aid was provided inhouse dispensary and investigation started	
Key Finding		Created At	17-10-2023	Immediate Causes	SA15- Improper/inapproriate behaviour, SA17- Failure to Follow Procedure/Instruction, SC32- Inadequate Guard/Barrier	
Root Cause	The worker's utilization of the needle guard was ineffective.	Contact Types	Caught In	Updated At	20-10-2023	

	Description								Responsibi	ility		Timeli	ne		Status	
Actions	Awareness session should be co	nducted on stitc	hing machi	nine hazards and opera	ations				Production/h	HSE		28-06-	2023		closed	
S.NO	27	ID	94				R	eference	1075			Time	04:43:00	Date 0	5- 6- 023 Initiated By	admin
Unit	Unit 1	Department	Production	ion			L	ocation	Hall-1 Production			Other Location				
Line	L-136	Meta Injury Category	First Aid	l Case				leta Incident ategory	Toe Lasting							
Meta Incident Status	Completed	Employee Involved	yes					njured erson	Shabbir							
Witness Name		Details	While Sh came into	habir was moving throut to contact with the sha	ugh the toe-shaping machine on Line No. 1 rp edge of a paddle, resulting in an injury.	36, his right foot accident		nmediate ction	First aid was provided inhouse dis investigation started	spensary and	d					
Key Finding		Created At	17-10-20	023				nmediate auses	SA3- Failure to secure, SA18- Failure to secure, SA18- Failured, SC32- Inadequate Guard		ify					
Root Cause	Sharp edge of the machine was not covered properly.	Contact Types	Caught C	On			U	pdated At	20-10-2023							
	Description									Responsi	bility		Timeline		Status	
Actions	Requested to engineering team	for installation o	f metal sha	ape edge protector to c	cover sharp edge of paddle.					Engineerin	ng		30-6-2023		pending	
S.NO	28			ID	95	Reference	1076				Time	04:3	:00 Date	27-06- 2023	Initiated By	admin

			Reference	1076	Time	04:31:00	Date	2023	Ву	admi	
it 1	Department	Production	Location	Hall 02 First Floor		Other Location					
22	Meta Injury Category	First Aid Case	Meta Incident Category	Eyelet Machine							
mpleted	Employee Involved	yes	Injured Person	M. Shafiq							
	Details	Right hand index finger Eyelet Machine injury.	Immediate Action	First aid was provided inhouse dispensary and investig	gation started						
	Created At	17-10-2023	Immediate Causes	SA14- Improper Position for Task, SA17- Failure to Fo Procedure/Instruction							
Carelessness. Double stock mechanism was not installed. Contact Types Caught In Updated At 20-10-2023											
Description							Timeline		5	Status	
utomatic Conveyor should be installed for washer to	o avoid manual worki	ng on eyelet machine			Engineering		31-07-202	3	t	pending	
mp relitali	pleted lessness. Double stock mechanism was not led.	Meta Injury Category Employee Involved Details Created At Lessness. Double stock mechanism was not led. Contact Types	Meta Injury Category First Aid Case Employee Involved Details Right hand index finger Eyelet Machine injury. Created At 17-10-2023 Lessness. Double stock mechanism was not led. Contact Types Caught In	Meta Injury Category First Aid Case Meta Incident Category poleted Employee Involved Details Right hand index finger Eyelet Machine injury. Created At 17-10-2023 Immediate Causes Jessness. Double stock mechanism was not led. Contact Types Caught In Updated At	Meta Injury Category First Aid Case Meta Incident Category Explored Details First Aid Case First Aid Case Injured Person M. Shafiq M. Shafiq Meta Incident Category M. Shafiq Meta Incident Category M. Shafiq M. Shafiq Meta Incident Category Meta Incident C	Meta Injury Category First Aid Case Meta Incident Category Procedure/Instruction Employee Involved Details Right hand index finger Eyelet Machine Immediate Action Immediate Causes SA14- Improper Position for Task, SA17- Failure to Follow Procedure/Instruction Created At 17-10-2023 Immediate Causes SA14- Improper Position for Task, SA17- Failure to Follow Procedure/Instruction Contact Types Caught In Updated At 20-10-2023 Responsibility	Meta Injury Category First Aid Case Meta Incident Category Eyelet Machine Employee Involved Person M. Shafiq Details Right hand index finger Eyelet Machine Injury. Created At 17-10-2023 Immediate Causes Procedure/Instruction Contact Types Caught In Updated At 20-10-2023 Responsibility	Meta Injury Category First Aid Case Meta Injury Category First Aid Case Meta Incident Category Eyelet Machine Procedure/Instruction Procedure/Ins	Meta Injury Category First Aid Case Meta Incident Category Eyelet Machine Injured Person M. Shafiq Details Right hand index finger Eyelet Machine Immediate Action injury. Inmediate Causes SA14- Improper Position for Task, SA17- Failure to Follow Procedure/Instruction Created At 17-10-2023 Immediate Causes SA14- Improper Position for Task, SA17- Failure to Follow Procedure/Instruction Contact Types Caught In Updated At 20-10-2023 Responsibility Timeline	Meta Injury Category First Aid Case Meta Injury Category First Aid Case Meta Injured Person M. Shafiq Details Right hand index finger Eyelet Machine Injury. Immediate Action First aid was provided inhouse dispensary and investigation started Created At 17-10-2023 Immediate Causes SA14- Improper Position for Task, SA17- Failure to Follow Procedure/Instruction Contact Types Caught In Updated At 20-10-2023 Responsibility Timeline Sandard Septimber Sep	Meta Injury Category First Aid Case Meta Incident Category Eyelet Machine Meta Injury Category First Aid Case Meta Incident Category Eyelet Machine Meta Injury Category Eyelet Machine Meta Incident Category Eyelet Machine Might hand index finger Eyelet Machine Injury. Immediate Action First aid was provided inhouse dispensary and investigation started Created At 17-10-2023 Immediate Causes Procedure/Instruction Contact Types Caught In Updated At 20-10-2023 Meta Injury Category Eyelet Machine Injury Procedure/Instruction Procedure/Instruction Responsibility Timeline Status

S.NO	29	ID	97	Reference	1078	Time	10:40:00	Date	13- 10- 2023	Initiated By	min
Unit	Unit 1	Department	Production	Location	Hall-1 Production	Other Location	Laser Punching				
Line		Meta Injury Category	First Aid Case	Meta Incident Category	Sharp Tool						

Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Muzammal			
Witness Name		Details	The incident took place while he was operating in the laser punching area, attempting to remove tape from his left hand using a blade. During this process, the blade unexpectedly struck the inner corner of his right hand.	Immediate Action		s provided inhouse and investigation started		
Key Finding		Created At	17-10-2023	Immediate Causes		re to Identify Hazard, SC25- pol/Equipment		
Root Cause	lack of appropriate tools or equipment for the task	Contact Types	Struck-By	Updated At	20-10-2023			
	Description					Responsibility	Timeline	Status
Actions	Appropriate and safe tool sh	ould be provide	ed for cutting and tape removing in laser punching area.			Production	31-10-2023	pending

S.NO	30	ID	100	Reference	1081	Time	10:24:00	Date		nitiated By	admin
Unit	Unit 1	Department	Production	Location	Hall-3 First Floor	Other Location					
Line	L-334	Meta Injury Category	First Aid Case	Meta Incident Category	Chemical						
Meta Incident Status	Completed	Employee Involved	yes	Injured Person	Rizwan Ali						
Witness Name		Details	An injury to the right eye occurred while attempting to open an Elfy bottle for shoe sole fixing	Immediate Action	First aid was provided inhouse dispensary and investigation started						
Key Finding		Created At	17-10-2023	Immediate Causes	SA3- Failure to secure, SC33- Inadequate/Improper Personal Protective Equipment						
Root Cause	Lack of awareness about potential hazards while opening the bottle. Lack of usage of safety googles.	Contact Types		Updated At	20-10-2023						
	Description					Respon	sibility	Time	eline	Statu	ıs
Actions	Provide workers with appropriate safety equipment, such as eye prot	ection, to prevent	t future eye injuries while handling Elfy bottles.			Producti	on/HSE	30-1	0-2023	pendi	ing
Actions	Conduct comprehensive training sessions for all personnel involved in	Producti	on/HSE	30-1	0-2023	pendi	ing				