## BeSafe SGFL Hazards

Generated on: 2023-09-26

ID	Unit	Initiated By	Department	Line	Risk Level	Department Tag	Incident Status	Location	Description	Date	Created At
29	Unit 1	admin	Production		В	Engineering	Completed		Plugs lying on the floor and cables with damaged insulation which may cause short circuit or electric shock,	2023- 06-13	08-29- 2023
30	Unit 1	admin	Production		С	Engineering	Completed		The power supply panel of the folding machine was open in the socks working area Hall #1	2023- 06-13	08-29- 2023
31	Unit 1	admin	Admin		В	Engineering	Completed		kindly remove this outer door Ac stand, in morning this stand hit on worker head and he got serious head injury.	2023- 06-15	08-29- 2023