BeSafe SGFL Hazards

Generated on: 2023-10-16

ID U		Initiated By	Department	Line	Risk Level	Department Tag	Incident Status	Location	Description	Action	Date	Created At
29 L	Jnit	admin	Production		В	Engineering	Completed	Hall-1 Production	Plugs lying on the floor and cables with damaged insulation which may cause short circuit or electric shock,	Cables and plugs dressed on suitable place.	13-06- 2023	29-08- 2023
30 L	Jnit	admin	Production		С	Engineering	Completed	Hall-1 Production	The power supply panel of the folding machine was open in the socks working area Hall #1	Panel has been closed	13-06- 2023	29-08- 2023
31 L	Jnit	admin	Admin		В	Engineering	Completed	Time Office	kindly remove this outer door Ac stand, in morning this stand hit on worker head and he got serious head injury.	Frame was Removed	15-06- 2023	29-08- 2023
33 L	Jnit	Rashid	Production	L- 301	В	Engineering	Completed	Hall- 3 Ground floor	Some skiving machines guards are missing in hall #3, which may present a risk of hand injury to the machine. You are requested to install guards.	The guards have been installed on all skiving machines.	05-09- 2023	10-10- 2023
34 L	Jnit	Rashid	Production	L- 301	В	Engineering	In Progress	Hall- 3 Ground floor	Some skiving machines guards are missing in hall #3, which may present a risk of hand injury to the machine. You are requested to install guards.	Reported to concerned department	09-05- 0023	13-10- 2023