

Gaming PC Diagnostic PBQ – Answer Key

Correct Cause:

Overclocking

The CPU specification lists a base clock of 3.2GHz, but the BIOS shows it running at 4.5GHz. This indicates the processor has been overclocked beyond its rated speed, leading to instability and system freezing.

Correct Resolution:

Lower CPU clock speed

Reducing the CPU clock speed back to its rated base frequency restores stability and prevents overheating and voltage strain caused by overclocking.

Total Score: 2 / 2