# **IDENTIFICATION**

Product Code:

MAINDEC-8/I-DO1C-D

Product Name:

 ${\bf Instruction\ Test\ 1}$ 

Date Created:

December 10, 1969

Maintainer:

Diagnostic Group

#### MAINDEC-8/I-DO1C-D

### 1. ABSTRACT

This is a diagnostic program for testing the AND, TAD, and OPERATE instructions of the PDP-81  $\underline{\text{ONLY}}$ .

#### 2. REQUIREMENTS

### 2.1 Equipment

A PDP-8I equipped with Teletype.

## 2.2 Storage

This program uses locations 0000-4421. The Binary Loader must be stored in the last memory page.

#### 2.3 Preliminary Programs

### 3. LOADING PROCEDURE

### 3.1 Method

The standard Binary Loader is used.

### 4. STARTING PROCEDURE

### 4.1 Control Switch Settings

SR = 7777

## 4.2 Starting Address

0144

#### 4.3 Operator Action

- 1. Set SR to 144 and press LOAD ADDRESS.
- 2. Set SR to 7777 and push START.
- 3. Program will halt. MA=146
- 4. If AC = 0000 an error has occurred.
- 5. Push CONTINUE. Program will run until stopped or until an error is encountered.

#### OPERATING PROCEDURE

Same as section 4.

- 6. ERRORS
- 6.1 Error Halts and Description

See listing.

#### 6.2 Error Recovery

If it is desired to loop on the test causing the error, replace the operate instruction preceding the HLT with a JMP to the beginning of the test.

- 7. RESTRICTIONS
- 7.1 Starting Restrictions: None
- 7.2 Operating Restrictions: None
- 8. MISCELLANEOUS
- 8.1 <u>Execution Time</u>

256 program loops per second.

### 9. PROGRAM DESCRIPTION

The program consists of many individual tests. In most cases each test checks only one function and uses previously tested functions as a basis for the test. The program counter action is strictly sequential except for SKIPS. The only JMP instructions used are at the end of the program.

The sequence of testing is as follows:

- 1. Test all operate functions individually except for rotates.
- 2. Test TAD instruction.
- Test ROTATE functions.
- 4. Group 1 operate instruction test. All possible combinations.

## MAINDEC-8/I-DO1C-D

- 5. Group 2 operate instruction test. All possible combinations.
- Test AND instruction.

The Teletype bell rings after each 128 program loops.

10. LISTING

#### /INSTRUCTION TEST = 1 /TAPE 1

```
8688
               #0
      0000
0000
0021
      5001
                        JMP 1
0002
      0002
                        0002
                        0003
0003
      0003
                        Ø
0004
      0000
                        0000
0005
      0000
0006
      7402
               HALTA
                        HLT
      7000
0007
               NOOP,
                        NOP
0010
      0000
                        0
                        /CONSTANTS AND VARIABLES
               420
      0020
      0000
               K0000,
                        0000
0020
                        0001
0021
      0001
               K0001.
      0002
               KØØØ2,
                        0002
0022
               K0004.
                        0004
0023
      0004
0024
      0010
               K0010,
                        0010
                        0020
0025
      0020
               K0020.
      0040
               KØØ42.
                        0040
0026
0027
                        0100
      0100
               K0100.
               KØ2ØØ.
                        0200
0030
      6566
0031
      0400
               KØ4ØØ.
                        2400
                        1000
0032
      1000
               K1000.
                        2000
0033
      2000
               K2000,
                        4000
      4000
               K4000.
0034
0035
      7776
               K7776:
                        7776
      7775
                        7775
0036
               K7775,
0037
      7773
               K7773,
                        7773
      7767
               K7767.
                        7767
0040
                        7757
      7757
               K7757.
0041
0042
      7737
               K7737;
                        7737
      7677
               K7677,
                        7677
0043
      7577
               K7577.
                        7577
0044
0045
      7577
               K7377.
                        7377
0046
      6777
               K6777.
                        6777
      5777
               K5777,
                        5777
0047
                        3777
0050
      3777
               K3777:
                        7777
0051
      7777
               K77771
0052
      5252
               K5252.
                        5252
0053
      2525
               K2525,
                        2525
0054
      6000
               K6000,
                        6000
                        7000
0055
      7000
               K7000.
      7400
                K7402.
                        7400
0056
0057
      7600
                K7600.
                        7600
                        7740
0060
      7740
               K7740,
                        776Ø
0061
      7760
               K7760.
                        7770
      7770
                K7770.
0062
```

K7774.

K0003.

VINSTRUCTION TE	S.T - 1	PAL10	V141	3-DEC-69	9187	PAGE 2
/\$ \tau \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	2747	20007	4007			
Ø Ø 6 5	3927	K0007;	0007			
0066	2267	K0067.	0067			
8867	2017	K0017,	0017			
0070	₹037	K0037,	3037			
0071	ØØ77	K0077,	0077			
0072	2177	KØ177:	0177			
0073	0377	KØ377.	0377			
0274	¥777	KØ777.	0777			
0075	1,777	K1777.	1777			
0076	7/00	K7700,	7700			

/INSTRUCTION TEST - 1	PAL1# V141	3-DEC-69	9107 PAGE 3
Ø144	<b>*1</b> 44		
₹ ♣ ↑ ↑	/TAD, CLA, HLT, TE	S T	
0144 1051	START: TAD K77		
	CLA	•	
	HLT	/AC SHO	เม กิ≖0
0146 7402	m Li		TO 7777, CONTINUE
	SKIP TEST	, 52 f 5 h	
Ø147 7 <b>41</b> Ø	SKP		
	HLT	/SKP FA	II FO
0150 7402	/SZA TEST 1	, 5Kt	1 7 6 0
0151 7200	CLA		and the
	SŽĀ		
# * * * * <b>#</b> * * * * <b>#</b> * * * * * <b>#</b> * * * * * * * * * * * * * * * * * * *	H <b>L</b> 1	/934 SH	OULD HAVE SKIPPED
0153 7402	7 to 1		ULD EQUAL ZERO
0154 7450	SNA	7,40 0,10	OFD FRANK SELVA
Ø155 7410	SKP		
Ø156 74Ø2	HLT	ZSNA SH	OULD NOT HAVE SKIPPED
2077 0010	□ <b>□</b>		ULD EQUAL ZERO
	/SZA TEST 2	, 40 5110	
Ø157 72ØØ	CLA		
Ø157 7200 Ø160 1034	TÃO KAK	000	
0161 7440	SZA	* *	
0162 7410	SKP		
0163 7402	HLT	/S¥A SH	OULD NOT HAVE SKIPPED
DI00 1755			ULD EQUAL 4888
0164 7450	SNA	,	
0165 7402	нцт	/SNA SH	OULD HAVE SKIPPED
2102 1795	, , , , , , , , , , , , , , , , , , ,	/AC SHO	ULD EQUAL 4000
	•		
	/SEA TEST 3		
0166 7200	CLA		•
0167 1033	TÃD KZE	900	
0170 7440	SZA		
0171 7410	SKP		
0172 7402	HLT	/SZA SH	HOULD NOT HAVE SKIPPED
##### * ## * ## * ## * ## * ## * ## *	_	/AC SHO	ULD EQUAL 2000
0173 7450	SNA		•
0174 7402	HLT	/SNA SH	OULD HAVE SKIPPED
0175 7000	NOP	/AC SHO	ULD EQUAL 2000
0176 7000	NOP		
0177 7000	NOP		

	3200	*200	
		/SEA TEST 4	
0200	7200	CLA	
0201	1032		1000
0232	7442	SZA	
0223	7412	SKP	
0204	7422	HLT	/SZA SHOULD NOT HAVE SKIPPED
			/AC SHOULD EQUAL 1000
0225	7 2	SNA	FACE BUILDING WARE
0236	7432	HLT	/SNA SHOULD HAVE SKIPPED
* 204	,	· ( Inc. )	/AC SHOULD EQUAL 10000
		ISEA TEST 5	Aug ou dolla marie anna
0237	7200	CLA	
0210	1231		0400
	7440	SZA	
0212	7410	SKP	9
Ø213	7402	HLT	/SZA SHOULD NOT HAVE SKIPPED
~~.	•		/AC SHOULD EQUAL 8428
0214	7450	SNA	AND CHOOSE EMANE A 199
0215	7402	HLT	/SNA SHOULD HAVE SKIPPED
	-		/AC SHOULD EQUAL 0400
		/SZA TEST 6	the substant market with
0216	7200	CLA	
0217	1032		0200
0220	7448	SZA	*
0221	7410	SKP	
0222	7402	HLT	/SZA SHOULD NOT HAVE SKIPPED
		•	/AC SHOULD EQUAL 0200
0223	7450	SNA	And minaths manife aware.
0224	7402	HLT	/SNA SHOULD HAVE SKIPPED
		· •	/AC SHOULD EQUAL 0200
		/SZA TEST 7	
0225	7200	CLA	
	1027		0100
0227	7440	SZA	
0230	7410	SKP	
0231	7482	HLT	/SZA SHOULD NOT HAVE SKIPPED
	· <del>-</del>	<b>-</b> '	/AC SHOULD EQUAL 0100
0232	7450	SNA	The state of the s
0233	7482	HLT	/SNA SHOULD HAVE SKIPPED
-			/AC SHOULD EQUAL 0100

9107

PAGE 4

/INSTRUCTION TEST - 1 PALIS V141

INSTRUCTION TES	ST - 1	PAL10	V141	3-DEC-69	9107 PAGE 5	
		/SZA TE	EST 8			
0234	7200		CLA			
0235	1026		TAD KEE	940	•	
0236	7440		SZA			
0237	7410		SKP			
0240	7402		HLT		SZA SHOULD NOT HAVE SKIPPE	D
	•			/	AC SHOULD EQUAL 0040	
0241	7450		SNA			
0242	7402		HLT	/	SNA SHOULD HAVE SKIPPED	
	_			/	AC SHOULD EQUAL 0040	
		/SZA T	EST 9			
0243	7200	-	CLA			
0244	1025		TAD KO	020		
0245	7440		SZA			
0246	7410		SKP		and the same of th	13
Ø247	7402		HLT	/	SZA SHOULD NOT HAVE SKIPPE	U
					AC SHOULD EQUAL 8020	
0250	7450		SNA		THE RESERVE THE PROPERTY OF TH	
0251	7402		HL T	,	SNA SHOULD HAVE SKIPPED	
					AC SHOULD EQUAL 0020	
		/SZA T				
0252	7200		CLA			
0253	1024		TAD KØ	010		
0254	7440		SZA			
0255	7410		SKP		THE STATE OF LAND OF STATE	
0256	7402		HLT		SZA SHOULD NOT HAVE SKIPPE	U
				•	/AC SHOULD EQUAL 0010	
	- 455		0114			
0257	7450		SNA		SNA SHOULD HAVE SKIPPED	
0260	7402		HĻT	1	AC SHOULD EQUAL 0010	
		4031 7			AND DUOOFS ERENE ANSE	
		/52A	EST 11			
0261	7200		CLA	10.00		
0262	1023		TÃD KU	אַשעיי		
0263	7440		SZA			
0264	7410		SKP		SEA SHOULD NOT HAVE SKIPPE	0.3
0265	7402		HLT		VAC SHOULD EQUAL 0004	
Ø266	7450		SNA			
0267	7402		HLT		ISNA SHOULD HAVE SKIPPED	
2207	7 2 7 8		· · · · ·		/AC SHOULD EQUAL 0004	

		/SZA TEST 12	
0270	7200	CLA	
0271	1022	TAD KUUBZ	
0272	7440	SZA	
0275	7410	SKP	
0274	7402	HLT	/SZA SHOULD NOT HAVE SKIPPED
			/AC SHOULD EQUAL 0002
0275	7450	SNA	
0276	7402	HLT	SNA SHOULD HAVE SKIPPED
			/AC SHOULD EQUAL 0002
		/SZA TEST 13	
0277	7200	CLA	
0330	1021	TAD KOUEL	
0391	7440	SZA	
0302	7410	SKP	
0303	7402	HLT	ASEA SHOULD NOT HAVE SKIPPED
			/AC SHOULD EQUAL 0001
0304	7450	SNA	
0305	7402	HLT	/SNA SHOULD HAVE SKIPPED
		•	/AC SHOULD EQUAL 0001
		/SPA TEST 1	
0306	7200	CLA	
0307	1850	TAD K3777	1
0310	7510	SPA	
0311	7402	HLT	/SPA SHOULD HAVE SKIPPED
			/AC SHOULD EQUAL 3777
		/SPA TEST 2	
0312	7200	CLA	
	1034	TAD K4000	
	7510	SPA	
0315	7410	SKP	
0316	7402	HLT	/SPA SHOULD NOT HAVE SKIPPED
			/AC SHOULD EQUAL 4000
		/SMA TEST 1	
0317	7200	CLA	
0320	1050	TAD K3777	
0321	7500	SMA	
0322	7410	SKP	
0323	7402	HLT	/SMA SHOULD NOT HAVE SKIPPED
	•	· <del>w</del>	/AC SHOULD EQUAL 3777
			to a september of the second

				, , ,	•		. ,	
			/SMA	TEST 2				
32	4	7288		CLA				
					K4000			
-								
				-		/5	MA SHOULD HAVE	SKIPPED
0 2	- '	,		(Figure 1				
			ZCMA	TEST 1		, ,	a awaata taaba	, 4000
77	t (A	7290	, 4.14					
					K7777			
					******			
-								
						70	אא מות אמד ממא	DIEMENT AC
35	7	/ 256:		£1 <b>( ( ( ( ( ( ( ( ( (</b>				
			/ CM A	- 740	755+ 1		a sucoffa resixe	
77		7202	7 C 11 A		100, 1	•		
					V2525			
		-			VE 563			
_							AD DO CHA ERDO	\ C
34	1	1205		M L. I				
-	. 7	4.057		7.10	V2825	/ A	C SHOOLD ECONT	, 2222
					VESSO			
						. ==	16 60 6UL FDDA	
34	2	7402		HĻT				
							C SHOOLD EGNAL	. מטטט
			ZCMA		TEST 2	}		
					K2525			
								_
35	2	7402		HLT				
						/A	C SHOULD EQUAL	2525
					K5252			
35	5							
35	6	7402		HLT				
						/A	C SHOULD EQUAL	. 0000
	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	3334 3334 3337 3341 3344 3445 3445 345 355 355 355 355 355	1325 1254 7500 7402 1327 7402 1330 7402 1331 1051 7040 7331 7040 7402 1333 7402 1334 7402 1334 7402 1344 7402 1345 7402 1347 7402 1347 7402 1348 7402 1359 7402 1359 7402 1359 7402 1359 7402 1355 7402 1355 7404 1355 7404 1355 7404 1355 7404 1355 7404 1355 7404 1355 7404 1355 7404	7200 324 7200 325 1034 7500 327 7402 /CMA 330 7200 331 1051 332 7040 333 7402 /CMA 334 7402 /CMA 335 7040 336 1053 7450 341 7450 342 7450 344 7440 345 7402 /CMA 347 7450 348 7402 /CMA 357 7450 357 7450	1325 1234 TAD 326 7500 SMA HLT  /CMA TEST 1 330 7200 CMA 331 1051 TAD 332 7640 CMA 333 7440 SZA 1334 7402 HLT  /CMA T TAD CLA TAD CMA SZA HLT  /CMA T TAD CMA SZA HLT  /CMA T TAD CLA TAD CMA SZA HLT  /CMA T TAD CMA SZA /CMA SZA	1324   7238   CLA   TAD   K4000   SMA   HLT     1327   7402   CLA   TAD   K7777     1330   7200   CLA   TAD   K7777     1331   1051   TAD   K7777     1333   7440   SZA   HLT     1334   7492   CMA   TAD   TEST     1335   7040   SNA   HLT     1342   1053   TAD   K2525     1343   7492   CMA   SZA     1344   7492   CMA   SZA     1345   7402   CMA   SZA     1347   1052   TAD   K5252     1351   7450   SNA   HLT     1352   7402   CMA   SZA     1353   7402   CMA   SZA     1353   7402   CMA   SZA     1355   74040   SZA   SZA     1355   74040   SZA   SZA	324   7238   CLA   TAD   K4080   SMA   S	

/INSTRUCTION TEST - 1 PAL12 V141 3-DEC-69

PAGE 7

		70H - 10 TURT 7	
		/CMA - TAU TEST 3	
3357	7200	CLA	
0360	1/51	TAD K7/77	
2361	7240	CMA	
0362	7440	S₹A	
2365	7402	HLT	/TAD OR CMA EMROR
			/AC SHOULD EQUAL 0000
		/IAC TEST 1	
2364	7200	CLA	
0355	7001	IAC	au
0366	7440	SZA	
0367	7410	SKP	
0370	7402	HLT	/IAC DID NOT INCREMENT
20,2		· · • ·	/AC SHOULD EQUL 0001
		/IAC TEST 2	THE BUILDING WOLF COLUMN
0371	7200	CLA	
0372	1051	TAD K7777	
0373	7001	IAC	
0374	7440	SZA	
	-	- · · · · · · · · · · · · · · · · · · ·	/IAC DID NOT INCREMENT
0375	7402	HLT	/AC SHOULD EQUAL DOOD
	- 44.44	. 25	AND SHOOFD EGOVE DADA
0376	7000	NOP	
0377	7000	NOP	
	2400	*400	
		/IAC TEST 3	
0430	7200	CLA	
0421	1063	TAD K7774	
0422	7001	IAC	
0433	7901	IAC	
8434	7001	IAC	
0425	7001	IAC	
3426	7440	SZA	
0407	7402	HLT	/IAC NOT INCREMENTING
	-		/AC SHOULD EQUAL 0000
		/SZL TEST 1	
8418	7200	CLA	
8411	7100	CLL	/CLEAR LINK
0412	7004	RAL	/CLEAR LINK SAFETY
0413	7430	SZL	-
0414	7402	HLT	/SZL SHOULD HAVE SKIPPED
: 🕶 🚅		- <del></del>	/LINK SHOULD EQUAL ZERO
			· were consistent and a second consistency of the constant of

/INSTRUCTION TEST - :	. PAL10 V141	3-UEC-69 9107 PAGE 9
	/SEL TEST 2	
8415 7288	CLA	
Ø416 710Ø	CĻL	/CLEAR LINK
2417 7020	CML	/COMPLEMENT LINK
0420 1034	TAD K40	
0421 7004	RAL	/SET LINK SAFETY
0422 7430	SZL	
0423 7410	SKP	
0424 7402	HLT	/SEL SHOULD NOT HAVE SKIPPED
		/LINK SHOULD EQUAL ONE
	/SNL TEST 1	
0425 7200	CLA	
0426 7100	CLL	/CLEAR LINK
0427 7004	RAL	/CLEAR LINK SAFETY
0430 7420	SNL.	
0431 7410	SKP	
0432 7402	нĻТ	/SNL SHOULD NOT HAVE SKIPPED
		/LINK SHOULD EQUAL ZERO
	SNL TEST 2	
0433 7200	CLA	
0434 7100	CLL	/CLEAR LINK
0435 7020	CML	/COMPLEMENT LINK
0435 7020	TAD KAM	
0437 7004	RAL	SET LINK SAFETY
0440 7420	SNL	PURE \$170 UNITED I
0441 7402	HLT	/SNL SHOULD HAVE SKIPPED
DATE LINE	5 3 Mag. 1	ILINK SHOULD EQUAL ONE
		C 所 \$ 12.7 《 11.7 及 20.1 《 12.2 》 《 12.2 》

		/CLL TEST 1	
0442	7200	CLA	
2445	1034	TAD K4000	
2444	7004	RAL	/SET LINK
0445	7420	SNL	Age ( Play
0445	5253	JMP CLL11	/CANNOT SET LINK WITH RAL
N 4 4 0	9293	AWL CERTI	/TRY A CML
2447	71.00	C1 1 1 C1 1	YINT K UME
0447 0450	7100 7430	CLL1, CLL	
	7402	S₹L HLŤ	/CLL DIO NOT CLEAR LINK
2451	1402	HLI	
2	COC7	Mm AE	/LINK SHOULD EQUAL ONE
0452	5257	JMP .+5	ACC TO A TABLE
0453	7020	CLL11, CML	/SET LINK
0454	7420	SNL	- MANAGE MARKET - TALLE 11 M 12 1
0455	7402	HLT	CANNOT SET LINK WITH
			/RAL OR CML. CANNOT
			/PERFORM CLL TEST 1
0456	5247	JMP CLL1	
		/CML TEST 1	
0457	7100	CMLT1: CLL	
8468	7450	SŽL	
0461	7402	<del>ዘ</del> ዜኘ	ACTE DID NOT CLEAR FINK
0462	7020	CML	
2463	7420	SNL	
0464	7402	HLT	/CML DID NOT SET LINK
0465	7626	CML.	
0466	7430	S₹Ļ	
0467	7402	₩ <b>∟</b> Ť	/CML DID NOT RESET LINK
		/CLA TEST 1 (OPERATE	GROUP 2)
0470	7200	CLA	
0471	1951	TAD K7777	
0472	7600	7600	
0473	7440	SZA	
0474	7402	HLT	/CLA (7600) DID NOT CLEAR AC
			/AC SHOULD EQUAL 0000
		/OSR TEST 1	
0475	7200	CLA	
0476	7404	OSR	
0477	7848	CMA	
2500	7440	SŽA	
0501	7402	HLT	JOSR DID NOT SET AC TO 7777
		7 t 🖷 1	/AC SHOULD=Ø
			ਸ਼ਰਤ ਤਾਂ 'ਚਾਵਿੰਦੂ ਆ ਹਨ। ਹ

```
/INSTRUCTION TEST - 1
                        PAL10
                                         3-DEC-69
                                V141
                                                         9107
                                                                 PAGE 11
                        /NOP TEST 1 (OPERATE GROUP 1)
          0532 7200
                                CLA
          0505 7100
                                CLL
                                                 VAC AND LINK EQUAL ZERO
          0504 7000
                                7000
                                                 /TEST INSTRUCTION
          Ø535 745Ø
                                SNA
          0506 7430
                                SZL
          0507 7402
                                HLT
                                                 /NOP FAILURE
                                                 /AC AND LINK SHOULD BE ZERO
                        /NOP TEST 2 (OPERATE GROUP 2)
          0510 7200
                                CLA
          0511 7100
                                CLL
                                                 /AC AND LINK EQUAL ZERO
               7400
          0512
                                7400
                                                 /TEST INSTRUCTION
               7450
          0513
                                SNA
          0514 7430
                                SZL
          0515 7402
                                HLT
                                                INOP FAILURE
                                                /AC AND LINK SHOULD BE ZERO
                        /TAD TEST 1
         Ø516
               7200
                                CLA
         9517
               1050
                                TAD K3777
                                                         JOPERAND 1
         0520 1034
                                TAD K4000
                                                         /OPERAND 2
         0521 7040
                                CMA
         0522 7440
                                SZA
         0523 7402
                                HLT
                                                /TAD ERROR
                                                /AC SHOULD EQUAL ØNDO
                        /TAD TEST 2
         0524
               7200
                                CLA
         2525 1047
                                TAD K5777
                                                         /OPERAND 1
         0526
               1933
                                TAD K2000
                                                         JOPERAND 2
         0527
               7040
                                CMA
         0530 7440
                                SZA
         0531 7402
                                HLT
                                                /TAD ERROR
                                                /AC SHOULD EQUAL 0000
                        /TAD TEST 3
         0532
               7200
                                CLA
         0533 1046
                                TAD K6777
                                                        /OPERAND 1
         0534 1032
                                TAD KINGO
                                                         /OPERAND 2
         Ø535
               7040
                                CMA
         Ø536
              7440
                                SZA
         0537 7402
                                HLT
                                                /TAD ERROR
                                                /AC SHOULD EQUAL 0000
                        /TAD TEST 4
         2542
               7200
                                CLA
         0541 1045
                                TAD K7377
                                                        /OPERAND 1
         Ø542
              1031
                                TAD KU400
                                                        JOPERAND 2
         0543
              7040
                                CMA
         0544 7440
                                SZA
         0545 7402
                                HLT
                                                /TAD ERROR
                                                /AC SHOULD EQUAL ØØØØ
                       /TAD TEST 5
```

CLA

TAD K7277

/OPERAND 1

0546 7200

/INSTRUCTION TEST - 1	PAL10	V141	3-DEC-09	9107	PAGE 11-1
Ø55Ø 1 <b>Ø</b> 3Ø		TAD KØ	200	/OPERAND	2
Ø551 7040		CMA			
Ø552 7440 Ø553 7402		SZA HLT	/T.A.D	ERROR	
5550 7402		The Target		SHOULD EQUAL	0000

Ø <b>5</b> 54	7200	/TAD TEST 6			
0555	1043		K7677	/OPERAND	4
0556	1027	TAD		/OPERAND	
	7040	CMA		) OF EVAIL	<b>~</b>
0560	7440	SZA			
0561	7402	HLT		/TAD ERROR	
	-			/AC SHOULD EQUAL	2000
		/TAD TEST 7	,		
Ø562	7200	CLA	1		
0563	1042		K7737	/OPERAND	1
0564	1026	TAD		/OPERAND	2
0565	7040	CMA			
Ø566	7440	SZA			
0567	7402	HLT		/TAD ERROR	
		4514 550		/AC SHOULD EQUAL	0000
aesa	7700	/TAD TEST 8			
0570	7200	CLA			
Ø571 Ø572	1041 1025		K7757	/OPERAND	1
	7040	CMA	K0020	/OPERAND	2
0574	7440	SZA			
22/4	عدت.	SEA			
0575	7402	HLT		/TAD ERROR	
,-	. 47	, 1 mage 1		AC SHOULD EQUAL	OF OF IN IN
Ø576	7000	NOP		NO SHOOTO EMONE	0000
0577	7000	NOP			
	0600	*600			
		/TAD TEST 9			
0600	7200	CLA			
0601	1040		K7767	/OPERAND	1
0602	1824		K0010	/OPERAND	
0693	7040	CMA		, o, enano	_
0604	7440	SZA			
0605	7402	HLT		/TAD ERROR	
				/AC SHOULD EQUAL	0000

9107

PAGE 12

/INSTRUCTION TEST - 1 PAL10 V141

3=DEC=69

9107

/INSTRUCTION TE	SŤ = 1	PAL10 V1	41 3=DEC=69	9107	PAGE 14	
		/TAD TEST 1	L 4			
2637	7200	CLA				
0640	7100	CLI	•			
2641	1054	TAD	) KONNN	/OPERA	ND 1	
0642	1033	TAC	) K2000	/OPERAL	ND 2	
0643	7430	S₹l	•			
9644	7440	\$ <del>Z</del> /				
9645	7402	нլ, 1	ľ,	TAD ERROR, AC	SHOULD EQUAL	0 <b>000</b>
·	<del>-</del> ·			LINK SHOULD E		* *
		/TAD TEST 1				
0646	7200	CLA				
0647	7100	CLI				
Ø65Ø	1055		) K7000	/QPERAI	ND 1	
0651	1032	TAC	) K1000	/OPERA	ND 2	
0652	7430	SZL	•			•
0653	7440	S Z /				
Ø65 <u>4</u>	7402	H <b>L</b> ,1		/TAD ERROR. AC /Link should e		ก็ดีกิด
		/TAD TEST 1		Files augorn Fr	SOME OUE	
Ø655	7200	CLA				
Ø656	7100	CLI				
Ø657	1056		K74ØØ	/OPERA	NO 1	
0660	1031	TAT	K0400	/OPERAL		
9661	7430	ŚŻĹ		) Q: =:(···		
Ø662	7440	S Z A				
0663	7402	HĘ1	r ,	TAD ERROR, AC		กดักด
		/TAD TEST 1		LINK SHOULD E	DOAL ONE	
8664	7200	CLA				
Ø665	7100	CLI				
8666	1057		K7600	/OPERAL	ND 1	
Ø667	1030		KUŽBU	/OPERAI		
Ø67Ø	7430	ŚŻL	•	) W. W. (1977)		
9671	7440	SE				
9672	7402	HLI		TAD ERROR. AC	SHOULD FOUAL	0000
00/2	1205	11100		LINK SHOULD E		
		/TAD TEST 1		marini minaman ma	www.mar.wica	
9673	7200	CLA				
2674	7100	čĹĺ				
· Ø675	1976		K7700	/OPERAN	ND 1	
Ø676	1027		K0100	/OPERAL		
8677	7430	SZL		•	· •	
0700	7440	SZA				
0701	7402	HLI		TAD ERROR, AC	SHOULD EQUAL	0000
., .	· ,. <del>-</del>			LINK SHOULD E		
		/TAD TEST 1		- <del>-</del>		
9792	7200	CLA	1			
0733	7100	CLL	•			

VINSTRUCTION TEST	- 1. PAL10	V1.41	3-DEC-69	9107	PAGE 15	
Ø704 100	£ 7A	TAD K774	±2 <b>1</b>	/OPERAN	vD 1	
		TAD KØØ4	i Ø	/QPERAN		
Ø7Ø5 1Ø3 Ø7Ø6 743		SZL		V Q C C II A I	10 2	
		SZA				
				TAD ERROR. AC	SHOULD FOLIAL	ABBB
0710 74	u 2	HLT		LINK SHOULD EG	SUAL ONE	
	/TAD TE	ST 20	·			
0711 72	00	CLA				
0712 71	00	CLL				
0713 10		TAD K776	8	/OPERAN		
0714 10		TAD KOD2	Ø	/OPERAN	ND 2	
0715 74	30	SZL				
0716 74	40	SZA				
0717 74		HLT		YTAD ERROR, AC	SHOULD EQUAL	0000
	_			/LINK SHOULD EC		
	/TAD TE	ST 21				
Ø72Ø 72		CLA				
0721 71		CLL				
0722 10		TAD K777	0	/OPERAN	ND 1	
0723 10		TAD KOUS	Ø	/OPERAN	VD 2	
0724 74		SZL				
0725 74	40	SZÄ		/TAD ERROR AC S	SHOULD EQUAL	0000
0726 74		HLT	,	VLINK SHOULD E	DUAL ONE	
•	/TAD TE	CT 22				
0727 72		CLA				
0727 72 0730 71		CLL				
0731 10		TAD K777	14	/OPERAN	vn 1	
0732 10		TAD KODE	14	/OPERAN		
0733 74		SZL	, ,	/ Ur Shri	10 2	
2734 74		SZA				
0735 74		HLT		/TAD ERROR. AC	SHOULD FOLAL	agaa
E/32 /4	n C	m C I	•	LINK SHOULD E	SUAL ONE	
	/TAD TE	ST 23	·			
0736 72	00	CLA				
0737 71		CLL				
2740 10		TÃD K777	6	/OPERA	ND 1	
0741 10		TAD KØØR		/OPERAN		
0742 74	30	SZL		,		
0743 74	40	SZA				
0744 74		HLT		/TAD ERROR, AC	SHOULD EQUAL	0000
				/LINK SHOULD E	QUAL ONE	

```
/INSTRUCTION TEST - 1
                        PAL10
                                V141
                                        3-DEC-69
                                                         9107
                                                                 PAGE 16
                        /TAD TEST 24
          0745 7200
                                CLA
          0746 7100
                                CLL
          0747 1051
                                TÃĎ K7777
                                                         /OPERAND 1
          0750 1021
                                TAD KÚÚÚ1
                                                         /OPERAND 2
          0751 7430
                                SZL
          0752 7440
                                SZA
          0753 7402
                                HLT
                                                /TAD ERROR, AC SHOULD EQUAL 0000
                                                 /LINK SHOULD EQUAL ONE
                        /TAD TEST 25
          0754
               7200
                                CLA
          0755 7100
                                CLL
          0756 7020
                                CML
                                TAD K4000
          0757 1034
                                                        /OPERAND 1
          0760 1034
                                TAD K4000
                                                         /OPERAND 2
          0761
               7420
                                SNL
          0762 7440
                                SZA
          0763 7402
                                HLT
                                                 /TAD ERROR. AC SHOULD EQUAL 0000
                                                /LINK SHOULD EQUAL ZERO
                        /TAD TEST 26
                                CLA
          Ø764
               7200
          0765 7100
                                CLL
          0766 1050
                                TAD K3777
                                                         /OPERAND 1
                                TAD K2000
                                                         /OPERAND 2
          0767 1033
                                                         /OPERAND 3
                                TAD K2000
          0770 1033
                                CMA
          0771 7040
          0772 7420
                                SNL
          0773 7440
                                SZĀ
                                                /TAD ERROR, AC SHOULD EQUAL 0000
               7402
          0774
                                HLT
                                                /LINK SHOULD EQUAL ZERO
         Ø775
               7000
                                NOP
          0776
               7000
                                NOP
         0777 7000
                                NOP
                        *1000
                1000
                        /TAD TEST 27
                                CLA
               7200
         1000
               7100
          1001
                                CLL
                                TÃD K$777
                                                /OPERAND 1
         1002 1047
         1003 1032
                                TAD K1000
                                                /OPERAND 2
                                TAD K1000
                                                /OPERAND 3
         1004
               1032
         1005 7040
                                CMA
         1006 7420
                                SNL
         1007 7440
                                SZA
                                        /TAD ERROR AC SHOULD EQUAL 0000
         1010 7402
                                HLT
                                        /LINK SHOULD EQUAL ZERO
```

V141

/INSTRUCTION TEST - 1 PAL12

PAGE 17

```
3=DEC=69
/INSTRUCTION TEST = 1
                       PAL10
                             V141
                                                       9127
                                                               PAGE 18
                        /TAD TEST 32
         1055 7200
                                CLA
         1056 7100
                                CLL
         1057 1042
                                TAD K7737
                                                        /OPERAND 1
         1060 1025
                                TAD KUUZU
                                                        /OPERAND 2
                                TAD KUUZU
         1061 1025
                                                       JOPERAND 3
         1062
               7040
                                CMA
         1063
               7420
                                SNL
         1064 7440
                                SZA
         1065 7402
                                HLT
                                               /TAD ERROR, AC SHOULD EQUAL 0000
                                                /LINK SHOULD EQUAL ZERO
                        /TAD TEST 33
         1066
               7200
                               CLA
         1067 7100
                                CLL
                                TAD K7757
                                                       /OPERAND 1
         1070 1041
                                TAD KOO10
                                                        /OPERAND 2
         1071 1024
                                TAD KODIO
                                                        JOPERAND 3
         1072 1024
                                CMA
         1073 7040
         1074
               7420
                                SNL
         1075 7442
                                SZA
         1076 7402
                                HLT
                                               /TAD ERROR, AC SHOULD EQUAL 0000
                                               /LINK SHOULD EQUAL ZERO
                        /TAD TEST 34
         1077 7200
                               CLA
         1100 7100
                               TÃD K7767
         1101 1040
                                                        /OPERAND 1
                               TAD KØØØ4
                                                        /OPERAND 2
         1102 1023
                               TAD KÖÜÖ4
                                                        /OPERAND 3
         1103 1023
         1104
               7040
                                CMA
         1105 7420
                                SNL
         1106 7440
                                SZA
                                               /TAD ERROR, AC SHOULD EQUAL 0000
         1107 7402
                                               /LINK SHOULD EQUAL ZERO
                       /TAD TEST 35
         1110 7200
                               CLA
         1111 7100
                               CLL
                               TAD K7773
         1112 1037
                                                       /OPERAND 1
                                                       /OPERAND 2
                               TAD KOUDZ
         1113 1022
         1114 1022
                               TAD KOOO2
                                                       /OPERAND 3
         1115 7040
                               CMA
         1116 7420
                               SNL
         1117 7440
                               SZA
                                               /TAD ERROR, AC SHOULD EQUAL 8000
         1120 7402
                               HLT
                                               /LINK SHOULD EQUAL ZERO
```

9127

PAGE 19

/INSTRUCTION TEST - 1 PAL10 V141

VINSTRUCTION TE	(ST - 1	PAL10	V141	3=DEC=59	9107	PAGE 20
		/RAR TE	ST 4			
1154	7200		CLA			
1155	7122		CLL			
1156	7020		CML			
1157	1020		TAD KUK	999	/ROTATE	PATTERN
1160	7010		RAR		•	
1161	7430		SZL			
1162	7402		HLT		/RAR LINK PICKE	D UP A BIT
					/LINK SHOULD EQ	
		/RAR TE	ST 5			-
1155	7200		CLA			
1154	7100		CLL			
1165	7020		CML			
1165	1951		TAD K77	777	JROTATE.	PATTERN
3.157	7010		RAR		~	
1170	7040		CMA			
1171	7448		SZA			
1172	7982		HLT		/RAR FAILED AC	DROPPED A BIT UALS THE DROPPED BIT
1173	7002		NOP		,	ones the ottornam of
1174	7223		NOP			
1175	7000		NOP			
1175	7000		NOP			
117/	458		NOP			
*** ***	1292	<b>●12</b> 88	.,			
		JRAR TE	ST 6			
1200	7200		CLA			•
1201	7198		CLL			
1282	7828		CML			
1203	1020		TAD KOR	00	/ROTATE	PATTERN
1204	7010		RAR		• = =	
1205	1050		TAD K37	' <b>7</b> 7		
1226	7040		CMA			ч.
1227	7450		SNA			
1210	7430		SZL			
1211	7402		HLT		/RAR FAILED AC .	AND LINK
	*-				/SHOULD EQUAL D	900
		/RAR TE				
1212	7200		CLA			
1213	7100		CLL			
1214	1034		TAD K40	99	/ROTATE	PATTERN
1215	7918		RAR			·
1216	1047		TAD KO?	77		
1217	7040		CMA			
1220	7450		SNA			
1221	7430		SZĻ			
1222	7402		HL T		/RAR FAILED AC	AND LINK SHOULD
					/EQUAL 0000	

PAL10

VINSTRUCTION TEST - 1

V141

9107

		/RAR TEST 11	
1256	7200	CLA	
1257	7100	CLL	
1260	1030	TÃO KÝZĐØ	/ROTATE PATTERN
1261	7010	RAR	Free Contraction
1262	1043	TAD K7677	
1263	7949	CMA	
1264	7450	SNA	
1265	7430	SZĻ	
1266	7402	HLT	JOAD SATIST AT AND LINE
1200	7406	n <b>.</b>	/RAR FAILED AC AND LINK /EQUAL 0000
			LEACHE DADA
	1. J	/RAR TEST 12	
1267	7200	CLA	
1270	7100	čĽĈ	
1271	1027	TAD KØ1ØØ	/ROTATE PATTERN
1272	7910	RAR	AUGINIE ENITEUM
1273	1042	TAD K7737	
	7040	CMA	
1274			
1275	7450 7430	SNA	
1276		SZL	4 M A M M A 4 1 M M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A 4 1 M A
1277	7402	HLT	PRAR FAILED AC AND LINK
		(010 7507 47	/SHOULD EQUAL ØØØØ
		/RAR TEST 13	
1300	7200	CLA	
1301	7100	CLL TAD KUMAM	
1302	1026	TAD KUM40	/ROTATE PATTERN
1303	7010	RAR	
1304	1041	TAD K7757	
1305	7040	CMA	
1306	7450	SNA = .	
1307	7430	SZL	
1310	7402	H <b>⊾</b> Ť	∕RAR FAILED AC AND LINK
			/SHOULD EQUAL 0000

9137 PAGE 23 /INSTRUCTION TEST = 1

PAUSE

TION TE	ST + 1	PAL10	V141	3mDEC=69	9107	PAGE 24
			CTION T	ST 1		
		TAPE 2				
		/RAR TE				
1311 1312	7200 7100		CLA			
1313	1025		CLL TAD KØI	n a a	400m. T	F
1314	7010		RAR	.20	ZHUIAI	E PATTERN
1315	1040		TAD K7	67		
1316	7040		CMA	•		
1317	7450		SNA			
1320 1321	7430 7402	1	S₹Ļ			1
1051	7702		HLT		FAILED AC	
		/RAR TE	ST 15	/ <b>3</b> ml	DULD EQUAL	6666
1322	7200		CLA		•	
1323	7100		CLL			
1324	1024		TAD KEE	10	/ROTA <u>T</u>	E PATTERN
1325 1326	7010 1037		RAR			
1327	7040		TAD K77	73		
1330	7450		SNA			•
1331	7430		SZL			
1332	7402		HĻŤ	/RAR	FAILED AC	AND LINK
		40.40 Es		/\$H0	ULD EQUAL	0000
1333	7200	/RAR TE				
1334	7100		CLA			
1335	1023		TAD KOD	24	ZR∩TATI	E PATTERN
1336	7010		RAR		,	m / m ( 1 5m / 1 14
1337	1936		TAD K77	75		- 2
1348	7849		CMA			
1341 1342	745Ø 7430		SNA SZL	*		
1343	7402		HLT	/RAR	FAILED AC	AND LYNE
44.5		•	. ( )		ULD EQUAL F	
		IRAR TE		· #1.6	*** **********************************	
1344	7200		CLA			
1345	7100		CLL KAN	<b>A</b> D		
1346 1347	1022 7010		TAD KUU RAR	06		PATTERN
1350	1935		TAD K77	76		
1351	7040		CMA	र मर्	•	
1352	7450		SNA			
1353	7430		SZL			
1354	7402		HLT		FAILED AC	
				/SHO!	JLD EQUAL 0	000

/INSTRUCTION TEST + 1 PAL10

/RAR TEST 18  1355 7200	
1355 7200 CLA 1356 7100 CLL 1357 1021 TAD K0001 /ROTATE PATTERN 1360 7010 RAR 1361 1051 TAD K7777 1362 7040 CMA 1363 7450 SNA 1364 7420 SNL 1365 7402 HLT /RAR FAILED AC AND LINK 1365 7402 HLT /SHOULD EQUAL 0000	
1356 7100 CLL	
1357 1021 TAD K0001 /ROTATE PATTERN 1360 7010 RAR 1361 1051 TAD K7777 1362 7040 CMA 1363 7450 SNA 1364 7420 SNL 1365 7402 HLT /RAR FAILED AC AND LINK 1365 7402 HLT /SHOULD EQUAL 0000	
1362 7010 RAR 1361 1051 TAD K7777 1362 7040 CMA 1363 7450 SNA 1364 7420 SNL 1365 7402 HLT /RAR FAILED AC AND LINK 1365 7402 HLT /SHOULD EQUAL 0000	
1361 1051 TAD K7777 1362 7040 CMA 1363 7450 SNA 1364 7420 SNL 1365 7402 HLT /RAR FAILED AC AND LINK 1365 7402 HLT /SHOULD EQUAL 0000	
1362 7040 CMA 1363 7450 SNA 1364 7420 SNL 1365 7402 HLT /RAR FAILED AC AND LINK 1365 7402 HLT /SHOULD EQUAL 0000	
1363 7450 SNA 1364 7420 SNL 1365 7402 HLT /RAR FAILED AC AND LINK 1365 7402 HLT /SHOULD EQUAL 0000	
1364 7420 SNL PRAR FAILED AC AND LINK 1365 7402 HLT PSHOULD EQUAL 0000	
1365 7402 HLT /RAR FAILED AU AND LINK /SHOULD EQUAL 0000	
SHOULD EQUAL DOOR	
/DID TEST 1	
ANIN IEWI A	
1366 7200 CLA	
4747 7100 CII	
1370 1022 TAD KODO2 /ROTATE PATTERN	
1371 7012 RTR	
4772 7420 SNI	
1373 7402 HLT ARTH FAILED LINK DROPPED A BIT LINK SHOULD EQUAL A ONE	`
1374 7000 NOP	
1375 7000 NOP	
1376 7000 NOP	
1377 7000 NOP	
1400 +1400	
/RTR TEST 2	
1400 7200 CLA	
1421 7100 CLL	
1402 1020 TAD KOUDE /ROTATE PATTERN	
1403 7012 RTR	
AACIA PÄACK CZA	
1405 7402 HLT /RTR FAILED AC PICKED UP A BIT	1 7
74 ONE IN AC EQUALS THE PICKED UP B	• •
/RTR TEST 3	
1406 7200 CLA	
1407 7100 CLL	
1410 1020 TAD KODOO /ROTATE PATTERN	
1411 7012 RTR	
1412 7430 SZL	
1413 7402 HLT /RTR LINK PICKED UP A BIT /LINK SHOULD EQUAL ZERO	
/RTR TEST 4	
1414 7200 CLA	
1415 7100 CLL	
1416 7820 CML	
1417 1020 TAD KUUDU /ROTATE PATTERN	
1420 7012 RTR	
1421 7430 521	
1422 7402 HLT /RTR LINK PICKED UP A BIT /LINK SHOULD EQUAL ZERO	

/INSTRUCTION TE	ST = 1	PAL10	V141	3=DEC+69		9107	PAGE 26	
		/RTR TE	ST 5					
5423	7200		CLA					
1424	7100		CLL					
1425	7020		CML					
1426	1051		TAD K77	77		/ROTATE	PATTERN	
1427	7012		RTR					
1430	7040		CMA					
1431	7448		SZA					
1432	7402		HLT		ATTR AC	DROPPED	A BIT A ON	E IN
1405	7 2 7 2						DROPPED BIT	•
		ARTE TE	ST 6					
1433	7200		CLA		٠.			
1434	7100		CLL					
1435	7020		CML					
1436	1020		TAD KOK	100		/ROTATE	PATTERN	
1437	7212		RTR	-				
1440	1947		TAD K57	777				
1441	7040		CMA	. * *				
1442	7450		SNA					
1443	7430		SZL					
	7402		HLT		ARTH FA	TIED AC	AND LINK	
1444	/702		пь і			EQUAL		
		/RTR TE	ST 7		, 00040	Manual A		
4 4 4 5	7200	ZAIR IS	CLA					
1445	7100		CLL					
1446	1034		TAD KAR	n ca ca		/POTATE	PATTERN	
1447			RTR			/ NOINTE	1011000	
1450	7212 1246		TAD K67	177				
1451	7040		CMA	. * *				
1452	7450		SNA					
1453								
1454	7430		SŽĻ,		JOTO EA	TIED AC	AND LINK	
1455	7402		HLT			EQUAL		
		/070 T	*C* 6		/350060	EANAL E		
	<b>9</b> 3 4 3	/RTR TE						
1456	7200		CLA					
1457	7100		CLL TAD K28	A OLO		/POTATE	PATTERN	
1462	1033			200		AUTW T	. Ludit Politic	
1461	7012		RTR	( <del>7</del> 7				
1462	1045		TAD K7	211				
1463	7848		CMA					
1464	7450		SNA	1				
1465	7430		SZL		45.55 S.		ALIO L TAIM	
1466	7402		HLT		THIR FA	ILEO AC	AND LINK	
					/SHOULD	EQUAL P	שששי	

		/RTR TEST 9	
1467	7200	CLA	
1472	7120	CLL	
1471	1032	TAO K1000	/ROTATE PATTERN
1472	7012	RTR	-
1473	1044	TAD K7577	
1474	7240	CMA	
1475	7450	SNA	
1476	7430	SZL	
1477	7402	HLT	ARTR FAILED AC AND LINK
			SHOULD EQUAL DOOD
		/RTR TEST 10	
1500	7200	CLA	
1521	7100	CLL	
1502	1031	TAD KØ4ØØ	/ROTAATE PATTERN
1503	7012	RTR	
1504	1043	TAD K7077	
	7040	CMA	
1506	7450	SNA	
	7436	SZL	AMEN STATE OF AND A STATE
1510	7402	HLT	ARTH FAILED AC AND LINK
		ZRTR TEST 11	/SHOULD EQUAL 0000
1511	7200	CLA	
1512	7100	CLL	
1515	1630	TAD K0200	/ROTATE PATTERN
1514	7012	RTR	SUCTATE PATTENA
	1042	TAD K7737	
	7040	CMA	
1517	7458	SNA	
1520	7438	SZL	
1521	7402	HLT	ARTE FAILED AC AND LINK
47.4			/SHOULD EQUAL 0000
		/RTR TEST 12	
1522	7200	CLA	
1523	7100	CLL	
1524	1027	TAD KØ100	/ROTATE PATTERN
1525	7012	RTR	, , , , , , , , , , , , , , , , , , , ,
1526	1041	TAD K7757	
1527	7040	CMA	
1530	7458	SNA	
1531	7430	SŽĻ	
1532	7402	HLT	/RTR FAILED AC AND LINK
			/SHOULD EQUAL 0000

/INSTRUCTION TEST + 1 PAL10 V141

9127

/INSTRUCTION	TEST - 1	PAL18	V141	3-DEC-69	9107 PAGE 28
		/RTR TE	ST 13		
153	3 7200		CLA		
153			CLL		
153			TAD KU	040	/ROTATE PATTERN
153			RTR		
153	7 1040		TAD K7	767	
154			CMA		
154			SNA		
154	*** · · ·		SZL		
			HLT		ARTE FAILED AC AND LINK
154	ט /קשב		rate (		/SHOULD EQUAL 0000
		/9T0 T1	EST 14		
454	4 7200	FNIN II	CLA		
154			CLL		
154			TAD KØ	M D M	/ROTATE PATTERN
154				550	PROTATE PATIENT
154			RTR	772	
<b>15</b> 5			TAD KT	//3	
<b>15</b> 5			CMA		
155			SNA	1	
155	3 7430		SZL		ADMIN MATI PRI ACC AND 1 TRIM
<b>15</b> 5	4 7402		HLT		ALLED AL AND LINK
					/SHOULD EQUAL 0000
		/RTR T			
155			CLA		
<b>15</b> 5	6 7100		CLL		
155	7 1024		TAD KØ	010	/ROTATE PATTERN
156	0 7012		RTR		
156	1 1036		TAD K7	775	
156	2 7040		CMA		
156			SNA		
156			SZL		
156			HLT		ARTE FAILED AC AND LINK
					/SHOULD EQUAL 0000
		/RTR T	EST 16		
156	6 7300		CLA CL	L	
156			TAD KE		/ROTATE PATTERN
157			RTR	•	•
157			TAD K7	776	
157			CMA	•	
157 157			SNA		
			SZL		
157					ATTR FAILED AC AND LINK
157	5 7402		HLT		/SHOULD EQUAL 8000
					LANIGORN BACKET KNOW

. •			
1576	7202	NOP	
1577	7302	NOP	
	1600	<b>#16</b> ∅3	
	-	ARTE TEST 17	
1633	7200	CLA	
16/1	7100	CLL	
1602	1022	TAD KUUBZ	/ROTATE PATTERN
1693	7012	RTR	
1624	7450	SNA	
1625	7420	SNL	
1626	7402	HLT	ARTE FAILED. AC SHOULD EQUAL
	-		/0000, LINK SHOULD EQUAL ONE
		/RTR TEST 18	
1607	7200	CLA	
1610	7100	CLL	
1611	1421	TAD KUMBI	/ROTATE PATTERN
1612	7012	RTR	
1613	1050	TAD K3777	
1614	7040	CMA	
1615	7450	SNA	
1616	7430	SŽL	40 TO FILL FO. AG 410 ( 1314
1617	7402	HLT	ARTH FAILED, AC AND LINK
		404. Fen# 4	/SHOULD BE ZERO
4.04	9000	/RAL TEST 1	
1620	7200	CLA	
1621	7100	CLL	/ROTATE PATTERN
1622	1034 7004	TAD K4000	PRUTATE PATTERN
1623	7439	RAĻ SŽL	
1624	7440	SZA	
1625	7402	SEA HLT	/RAL FAILED. AC SHOULD EQUAL 0000
1626	1702	71 <b>6</b> 1	/LINK SHOULD EQUAL ONE.
		/RAL TEST 2	APTHA BURGED EMONE OUR!
1627	7200	CLA	
1630	7100	čĽĹ	
1631	1020	TAD KØØØØ	/ROTATE PATTERN
1632	7004	RAL	ENGINE ENERMON :
1633	7420	SNL	
1634	7442	SZA	
1635	7402	HLT	/RAL FAILED, AC SHOULD EQUAL 0000
# Q O >	,	City 1	/LINK SHOULD EQUAL ZERO
			र सहापार करास्यक्षण गुरूवणक जाकराच

/INSTRUCTION TEST - 1 PALLS V141

9137

		/RAL TEST 3	
1636	7200	CLA	
1637	7100	čĹĹ	
1640	7820	CML	
1641	1020	TAD KOR	000 /ROTATE PATTERN. LINK=1
1642	7884	RAL	ANDIALE PARIETY, LINKSI
1643	7430	SZĹ	
1644	7402	H <b>L</b> T	ARAL FATURE AS SHOWN B FOUND GOOD
1044	, 102		/RAL FAILURE. AC SHOULD EQUAL 0001 /Link should equal zero
		/RAL TEST 4	
1645	7200	CLA	
1646	7100	CLL	
1647		CML	
1652	1051	TAD K77	777 /ROTATE PATTERN. LINK=1
1651	7204	RAL	
1652	7040	CMA	
1653	7448	SZA	
1654	7402	HĻT	/RAL FAILURE. LINK SHOULD EQUAL ONE /AC SHOULD EQUAL 0000
		/RAL TEST 5	
1655	7200	CLA	
1656	7100	CLL	
1657	1333	TAD K2K	000 /ROTATE PATTERN
1662	7004	RAL	
1661	1250	TAD KS	5777
1662	7040	CMA	
1663	7450	SNA	
1664	7430	SZL	
1665	7402	<b>н<u>г</u>т</b>	/RAL FAILURE, AC SHOULD EQUAL 0000
			/LINK SHOULD EQUAL ONE
		/RAL TEST 6	
1665	7200	CLA	
1667	7100	CLL	
1678	1032	TAD K10	PROTATE PATTERN
1671	7004	RAL	· • • • • • • • • • • • • • • • • • • •
1672	1847	TAD K57	<b>'7</b> 7
1673	7040	CMA	
1674	7440	SZA	
1675	7402	HLT	/RAL FAILURE, AC SHOULD EQUAL 0000
	- : -	· · · · · ·	/LINK SHOULD EQUAL ZERO

9127

PAGE 30

/INSTRUCTION TEST = 1 PAL10 V141 3-DEC=69

V141

VINSTRUCTION TEST - 1 PAL12

PAGE 31

/LINK SHOULD EQUAL A ZERO

VINSTRUCTION TEST - 1 PALIM V141 3-DEC-69 - 9107 PAGE 32

HLT

1763 7402

		/RAL TEST 13		
1764	7200	CLA		
1760	7100	CLL		
1766	1223	TAD KEDE4	/ROTATE PATTERN	
1767	7884	RAL		
1773	1042	TAD K7767		
1771	7042	CMA		
1772	7450	SNA		
1773	7433	SZL	TRAL FAILED AC SHOULD EQUAL O	000
1774	7462	HLT	/LINK SHOULD EQUAL A ZERO	
1775	7300	NOP		
1775	7000	NOP		
1777	7000	NOP		
	2002	◆2₫₫₫		
		/RAL TEST 14		
2330	7200	CLA		
2331	7100	CLL		
22.2	1222	TAD KUU02	/ROTATE PATTERN	
2203	7004	RAL		
2€04	1037	TAD K7773		
2005	7042	CMA		
2236	7450	SNA	in a second out of Found	1000
22:1	7452	SŽL	tring in a pane in a second of the	0000
2816	7402	HLT	/LINK SHOULD EQUAL A ZERO	
	3030	/RAL TEST 15		
2211	7230	CL A		
2212	7199	CLL TAD KUMU1	/ROTATE PATTERN	
2215	1421 7004	RAL	Augustic Averand	
2014	1 236	TAD K7775		
221 <b>5</b> 2315	7049	CMA		
2017	7452	SNA		
2888	7432	SZL	/RAL FAILED AC SHOULD EQUAL @	000
2021	7402	HLT	/LINK SHOULD EQUAL ZERO	
<b>~</b> ∪ <b>~</b> •	, , , ,	/RAL TEST 16		
2222	7290	CLA		
2223	7102	CLL		
2224	7020	CML		
2225	7204	RAL		
2226	1035	TAD K7776		
2321	7040	CMA		
2230	7450	SNA		
2331	7430	SŁL		
2332	7462	HLT		9000
			/LINK SHOULD EGUAL ZERO	

		/RTL TEST 1	
2035	7200	CLA	
2034		ČĹL	
2035	1033	TAD K2030	
2036	7006	RTL	
2037		SNL	
2040	7402	HLŤ	/RTL LINK DROPPED A BIT
	-	<del>-</del> '	/LINK SHOULD EQUAL A ONE
		ATL TEST 2	
2041	7200	CLA	
2042	7100	CLL	
2043	1020	TÃO KUUDU	/ROTATE PATTERN
2044	7006	RTL	
2045	7440	SŽĀ	
2046	7402	HLT	ARTL AC PICKED UP A BIT
-	-		/A ONE IN AC EQUALS THE PICKED UP
		/RTL TEST 3	
2047	7200	CLA	
2050	7100	CLL	
2051	1020	TAD KODOO	/ROTATE PATTERN
2052	7006	RTL	· • • • • • • • • • • • • • • • • • • •
2053	7430	SZL	
2054	7402	HLŤ	/RTL LINK PICKED UP A BIT
			/LINK SHOULD EQUAL ZERO
		/RTL TEST 4	· · · · · · · · · · · · · · · · · · ·
2055	7200	CLA	
2056	7100	CĹL	
2057	7020	CML	
2060	1020	TAD KØØØØ	/ROTATE PATTERN
2061	7006	RTL	
2062	7430	SZL	
2063	7402	HLT	ATT FAILURE, LINK PICKED UP A BIT
9			/LINK SHOULD EQUAL A ZERO

3-050-59

9107

PAGE 34

/INSTRUCTION TEST - 1 PALIS V141

		PTL TEST 5				
2064	7200	CLA				
2065	7100	čLL				
2966	7020	CML				
2067	1051	TAD	K7777	/ROTATE PATTERN		
2070	7006	RTL.		,		
2071	7040	CMA				
2072	7440	SZA				
2073	7402	HLT		/RTL FAILURE, DROPPED A	BIT	
20/0	1 106	JRTL TEST 6		Fire Parketter and the		
2074	7200	CLA				
2075	7100	čil				
- 2076	1034	TAD	K4900	/ROTATE PATTERN		
2077	7006	RTL	11 7 7 0 2	radin (E i ni tem		
2100	1035	CAT	K7776			
2121	7040	CMA	117,70			
2102	7450	SNA				
2103	7430	SZL		/RTL FAILED AC AND LINK	SHUILD	FOULL MARK
2104	7402	HLT		AMIL LATER MA MAD ETHA	340000	FROME NEED
ä e	# O a &	/RTL TEST 7				
2105	7200	CLÁ				
2106	7100	CLL		1848175 B18881		
2107	1033	TAD	K2000	/ROTATE PATTERN		
2110	7006	RTL				
2111	7450	SNA				
2112	7420	SNL				
2113	7402	HLT		ARTH FAILED AC AND LINK	SHOULD	
				/EQUAL 0000		
		/RTL TEST 8				
2114	7200	CLA				
2115	7100	CLL				
2116	1032	TAD	K1000	/ROTATE PATTERN		
2117	7006	RŢĻ				
2120	1050	TAD	K3777			
2121	7040	CMA				
2122	7450	SNA			i	
2123	7430	SZL			!	
2124	7402	HLT		ALL FAILED AC AND LINK	SHOULD	
•••	-			/EQUAL 0000		

```
/RTL TEST 9
2125 7200
                     CLA
2126 7100
                     CLL
2127 1031
                     TAD KU400
                                           /ROTATE PATTERN
                     RTL
2130 7006
                     TAD KO777
2131 1047
2132 7040
                     CMA
2133 7450
                     SNA
2134 7450
                     SZL
2135 7402
                     HLT
                                   /RTL FAILED AC AND LINK SHOULD
                                    /EQUAL ZERO
              /RTL TEST 10
2136 7200
                     ÇLA
2137 7100
                     CLL
2140 1030
                     TAD KUZUU
                                           /ROTATE PATTERN
2141 7006
                     RTL
2142 1046
                     TAD K6777
2143 7040
                     CMA
2144 7450
                     SNA
2145 7430
                     SZL
2146 7402
                     HLT
                                     /RTL FAILED AC AND LINK SHOULD
                                     /EQUAL 0000
             /RTL TEST 11
2147 7200
                     CLA
2150 7100
                     CLL
2151 1027
                     TAO K0100
                                          PROTATE PATTERN
2152 7006
                     RTL
2153 1045
                     TAD K7377
2154 7040
                     CMA
2155 7450
                     SNA
2156 7430
                     SZL
2157 7402
                                   /RTL FAILED AC AND LINK SHOULD
                     HLT
                                    /EQUAL 0000
             /RTL TEST 12
2160 7200
                     CLA
2161 7100
                     CLL
2162 1026
                     TAD KØØ4Ø
                                           /ROTATE PATTERN
2163 7006
                     RTL
2164 1044
                     TAD K7577
2165 7040
                     CMA
2166 7450
                     SNA
2167 7430
                     SZL
2170 7402
                     HLT
                                     /RTL FAILED AC AND LINK SHOULD
                                     /EQUAL 0000
```

9107

PAGE 36

/INSTRUCTION TEST - 1 PAL12 V141

```
3-DEC-69
                                                       9127
                                                               PAGE 37
/INSTRUCTION TEST - 1 PAL12
                              V141
                               NOP
          2171 7000
          2172 7000
                               NOP
                                NOP
          2173 7000
          2174 7600
                               NOP
          2175 7000
                               MOP
          2176 7000
                               NOP
          2177 7000
                                NOP
                        *2220
                2200
                        IRTL TEST 13
          2200 7200
                               CLA
          2201 7100
                                CLL
                                                       /ROTATE PATTERN
                                TAD KUU20
          2202 1025
                               RTL
          2203 7006
          2204 1043
                                TAD K7677
                                CMA
          2205
               7040
          2206 7450
                                SNA
          2207 7430
                                SZL
                                               ARTE FAILED AC AND LINK SHOULD
          2210 7402
                                HLT
                                                /EQUAL 0000
                        /RTL TEST 14
          2211 7200
                                CLA
          2212 7100
                                CLL
        = 2213 1024
                                                       /ROTATE PATTERN
                                TAD KØØ10
               7006
                                RTL
          2214
          2215 1042
                                TAD K7737
          2216 7040
                                CMA
          2217 7450
                                SNA
          2220 7430
                                SZL
                                               ARTE FAILED AC AND LINK SHOULD
          2221 7402
                                HLT
                        /RTL TEST 15
          2222 7200
                                CLA
          2223 7100
                                                       /ROTATE PATTERN
                                TAD K0004
          2224 1023
          2225 7006
                                RTL
          2226 1041
                                TAD K7757
          2227 7040
                                CMA
          2230 7450
                                SNA
          2231 7430
                                SZL
                                                ARTE FAILED AC AND LINK SHOULD
          2232 7402
                                HLT
                                                /EQUAL 0000
                        /RTL TEST 16
          2233 7200
                                CLA
          2234 7100
                                CLL
          2235 1022
                                TAD KUUDZ
                                                        /ROTATE PATTERN
          2236 7006
                                RTL
          2237 1040
                                TAD K7767
          2240 7040
                                CMA
                                SNA
          2241 7450
          2242 7432
                                SZL
                                                ARTE FAILED AC AND LINK
          2243 7402
                                                /SHOULD EQUAL 0000
```

/INSTRUCTION TE	EST ~ 1	PAL10 V1	41 3=DEC=6	9 9107 PAGE 38
		/RTL TEST	17	
2244	7200	CL	A	
2245	7100	CL		
2246	1021	TA		/ROTATE PATTERN
2247	7006	RT	L	-
2250	1037	TA		
2251	7040	ĊM		
2252	7450	SN		
2253	7430	SZ		4
2254	7402	HL		/RTL FAILED AC AND LINK /Should equal 0000
		ATL TEST	1.8	ASUONED EMONE PARA
2255	7200	CL		
2256	7100	ĊĹ.	n i	
	7020	CM	<b>i.</b> ,	
2257	7006			
2260 2261	1036	RT TA		
2262	7040 7880	CM		
2263	7450	SN		
2264	7430	SZ		
2265	7402	HĻ	T	/RTL FAILED AC AND LINK /Should Equal 0000

2266 2267 2270 2271 2272 2273 2274 2275	/G 7200 7100 7040 7020 7300 7420 7440 7402	ROUP 1 OPERATE TEST CLA CLL CMA CML CLA CLL SNL SZA HLT	/CLEAR AC /CLEAR LINK /AC EQUALS 7777 /LINK EQUALS ONE /TEST COMBINATION  /CLA CLL FAILED, LINK SHOULD BE 0 /AC SHOULD EQUAL 0000
2276 2277 2390 2301 2322	7200 1053 7240 7040 7440	ROUP 1 OPERATE TEST CLA TAD K2525 CLA CMA CMA SZA	2 /AC EQUALS 0000 /AC EQUALS 2525 /TEST COMBINATION
2303 2304 2305 2306 2307	7402 7200 7100 7040 7140	HLT GROUP 1 OPERATE TEST CLA CLL CMA CLL CMA	/CLA CMA ERROR, AC SHOULD /BE 0000  3  /AC=7777 LINK=1 /TEST COMBINATION
2310 2311 2312 2313	7420 7440 7402	SNL SZA HLT GROUP 1 OPERATE TEST CLL	/CLL CMA FAILED, AC AND LINK /SHOULD BE ZERO
2314 2315 2316 2317 2320 2321	7020 7200 7240 7340 7340 740 7420	CML CLA CMA CLA CMA CLL CMA SNL	/LINK#1 /AC=7777 /TEST COMBINATION
2322 2323	7440	SZA HLT	/CLA CMA CLL FAILED. AC AND /LINK SHOULD BE ZERO

```
/GROUP 1 OPERATE TEST 5
2324 7200
                      CLA
                      CLL
                                      /LINK #0
2325 7100
2326 7040
                      CMA
                                      /AC=7777
                      CLA CML
                                      /TEST COMBINATION
2327 7220
2330 7450
                      SZL
2331 7440
                      SZA
                                      /CLA CML FAILED. AC SHOULD EQUAL
2332 7402
                      HLT
                                      /0000, LINK SHOULD BE A ONE
              /GROUP 1 OPERATE TEST 6
                      CLL
2333 7100
2334 7020
                      CML
                                      /LINK#1
                      CLL CML
                                      /TEST COMBINATION
2335 7120
                      SNL
2336 7420
2337 7402
                                      /CLL CML FAILED
                      HLT
                                      /LINK SHOULD BE A ONE
              /GROUP 1 OPERATE TEST 7
                                      /LINK#Ø
2340 7100
                      CLL
2341 7120
                      CLL CML
                                      /TEST COMBINATION
2342 7420
                      SNL
                                      /CLL CML FAILED.
2343 7402
                      HLT
                                      /LINK SHOULD BE A ONE
              /GROUP 1 OPERATE TEST 8
                                      /LINK=1
     7120
                      CLL CML
2344
                      CLA CMA
                                      /AC=7777
2345 7240
                      CLA CLL CML
                                      /TEST COMBINATION
2346 7320
     7430
                      SZL
2347
2350 7440
                      SZA
                                      /CLA CLL CML FAILED. LINK SHOULD
2351 7402
                      HLT
                                      /BE 1, AC SHOULD BE ZERO
              /GROUP 1 OPERATE TEST 9
                      CLA CLL CMA
                                      /LINKED. AC=7777
2352 7340
                      CLA CLL CML
                                      /TEST COMBINATION
     7320
2353
2354
     7430
                      SZL
2355 7440
                      SZA
                                      /CLA CLL CML FAILED, LINK SHOULD
                      HLT
2356 7402
                                      /BE 1, AC SHOULD BE ZERO
```

PAL10 . V141

/INSTRUCTION TEST = 1

9107

```
/GROUP 1 OPERATE TEST 10
                      CLA CLL CMA
                                      /AC=7777, LINK=0
2357 7340
                      CHA CHL
                                      /TEST COMBINATION
2360 7060
2361
     7430
                      SZL
2362 7440
                      SZA
                                      /CMA CML FAILED. AC SHOULD BE
                      HLT
2363 7402
                                      /0000 LINK SHOULD EQUAL ONE.
              /GROUP 1 OPERATE TEST 11
                                      YAC AND LINKER
                      CLA CLL
     7300
2364
                                              /AC=2525
                      TAD K2525
2365
     1053
                      CLA CMA CLL
                                      /TEST COMBINATION
2366 7340
                      CMA
2367
     7040
2370 7420
                      SNL
                      SZA
2371
     7440
                                      /CLA CMA CML FAILED. AC SHOULD BE
                      HLT
2372
     7402
                                      /0000, LINK SHOULD EQUAL ZERO
                      NOP
2373 7000
                      NOP
     7000
2374
2375 7000
                      NOP
2376 7000
                      NOP
                      NOP
2377 7000
      2400
              #2400
              /GROUP 1 OPERATE TEST 12
                                      /AC AND LINKED
2430 7300
                      CLL CLA
                                              /AC=2925
                      TAD K2525
24 1 1053
                      CLL CMA CML
                                      /TEST COMBINATION
24/2 7160
                      TAD K2525
2423 1053
                      CMA
2404 7040
2405 7430
                      SZL
                      SZA
2476 7440
                                      /CLL CMA CML FAILED, AC SHOULD BE
2427 7402
                      HLT
                                      /0000, LINK SHOULD EQUAL ONE
              /GROUP 1 OPERATE TEST 13
2410 7300
                      CLA CLL
2411 7020
                                      /AC=0000, LINK=1
                      CML
                      CLL CMA CML
                                      /TEST COMBINATION
2412 7160
                      CMA
      7040
2413
2414 7430
                      SZL
     7440
                      SZA
2415
                                      /CLL CMA CML FAILED. AC SHOULD
                      HLT
2416 7402
                                      /BE 0000, LINK SHOULD BE ONE
```

```
9107
                                      3=DEC=69
                                                             PAGE 42
'INSTRUCTION TEST = 1 PAL10 V141
                       /GROUP 1 OPERATE TEST 14
                              CLA CLL
TAD K2525
         2417 7300
                                                     /AC=2525. LINK=0
         2420 1053
                               CLA CLL CMA CML /TEST COMBINATION
         2421 7360
         2422 7040
                              CMA
         2423 7430
                              SŽL
         2424 7440
                               SZA
                                             /CLA CLL CMA CML FAILED, AC SHOULD
         2425 7402
                               HLT
                                             /BE 0000 LINK SHOULD EQUAL ONE.
                      /GROUP 1 OPERATE TEST 15
         2426 7320
                              CLA CLL CML
                                                    /AC=5252, LINK#1
                              TAD K5252
         2427 1052
                              CLA CLL CMA CML /TEST COMBINATION
         2430 7360
         2431 7040
                               CMA
                               SZL
         2432 7430
                               SZA
         2435 7440
         2434 7402
                                              /CLA CLL CMA CML FAILED. AC SHOULD
                               HLT
                                             /BE 000. LINK SHOULD EQUAL ONE
                       /GROUP 1 OPERATE TEST 16
                              CLA
         2435 7200
                              TAD K2525
                                                    /AC=2525
         2436 1053
                               CLA IAC
                                              /TEST COMBINATION
         2437 7201
                              TÃD K7776
         2440 1035
         2441 7040
                               CMA
         2442 7440
                               SZA
                                              /CLA IAC FAILED
         2445 7402
                               HLT
                                              /AC SHOULD EQUAL 0000
                       /GROUP 1 OPERATE TEST 17
                              CLL CML CLA
         2444 7320
                                                    /AC=7776. LINK#1
                              TAD K7776
         2445 1035
                                             /TEST COMBINATION
                               CLL IAC
         2446 7101
         2447 7848
                               CMA
                               SNL
         2450 7420
                               SZA
         2451 7440
                                             /CLL IAC FAILED. AC AND LINK
         2452 7402
                               HLT
                                              /SHOULD EQUAL ZERO
```

3-DEC+69

/INSTRUCTION TEST + 1 PAL10 V141

9127

```
INSTRUCTION TEST. = 1 PALIS V141 3-DEC-69 9:07
                                                             PAGE 44
                      /GROUP 1 OPERATE TEST 23
                             CLA CLÎ
        2513 7300
                                                   /AC=5252 LINK=0
                             TAD K5252
        2514 1052
                              CLA CLL CMA IAC /TEST COMBINATION
        2515 7341
        2516 7430
                              SZL
        2517 7440
                              SZA
                                            /CLA CLL CMA IAC FAILED AC SHOULD
        2520 7402
                              HLT
                                            /BE 0000, LINK SHOULD BE ONE
                      /GROUP 1 OPERATE TEST 24
                              CLA CLL
        2521 7300
                                                    /ACE77776 LINKED
        2522 1035
2523 7021
                              TAD K7776
                              CML IAC
                                             /TEST COMBINATION
                              CMA
        2524 7040
                              SZL
        2525 7430
        2526 7440
                              SZA
                                             /CML IAC FAILED AC SHOULD BE
        2527 7402
                              HLT
                                             10000, LINK SHOULD BE ONE
                      /GROUP 1 OPERATE TEST 25
        2530 7320
                              CLA CLL CML
                                                    /AC =7776 LINK=1
                              TAD K7776
        2531 1035
                              CML IAC
                                             /TEST COMBINATION
        2532 7021
        2533 7040
                              CMA
        2534 7420
                              SNL
        2535 7440
                              SZA
                                             /CML IAC FAILED. AC SHOULD BE
        2536 7402
                              HLT
                                             /0000 LINK SHOULD BE ZERO
                      /GROUP 1 OPERATE TEST 26
        2537 7300
                              CLA CLL
                                                    /AC=2525 LINK=0
                              TAD K2525
        2540 1053
                                          /TEST COMBINATION
                              CLA CML IAC
        2541 7221
                              TAD K7776
        2542 1035
                              CMA
        2543 7040
                              SZL
        2544 7430
        2545 7440
                              SZA
                                             /CLA CML IAC FAILED. AC SHOULD BE
        2546 7402
                                             /0000, LINK SHOULD EQUAL ONE
                      /GROUP 1 OPERATE TEST 27
                              CLA CLL CML
                                              /AC=0000 LINKEL
        2547 7520
                                              /AC=7776
                              TAD K7776
         2550 1035
                                              ITEST COMBINATION
                              CLL CML IAC
         2551 7121
        2552 7040
                              CMA
                              SZL
         2553 7430
                              SZA
         2554 7440
                                             VCLL CML IAC FAILURE, AC SHOULD BE
         2555 7402
                                             /0000, LINK SHOULD EQUAL ONE.
```

/INSTRUCTION TEST = 1 PALTE V141

9107

```
3-DEC-69
/INSTRUCTION TEST # 1 PALID V141
                                                    9107
                                                              PAGE 46
                       /GROUP 1 OPERATE TEST 31
         2610 7300
                               CLA CLL
                               TAD K0001
                                                     /AC=5001 LINK=0
         2611 1021
         2612 7061
                               CMA CML IAC
                                          TEST COMBINATION
         2613 7040
                               CMA
         2614 7430
                               SZL
         2615 7440
                               SZA
                                              /CMA CML IAC FAILED. AC SHOULD
         2616 7402
                               HLT
                                              /BE 0000. LINK SHOULD BE ONE
                       /GROUP 1 OPERATE TEST 32
         2617 7320
                               CLA CLL CML
                               TAD KØØØ1
                                                     /AC=0001 LINK=1
         2620 1021
         2621 7061
                               CMA CML TAC
                                              TEST COMBINATION
                               CMA
         2622 7040
         2623 7420
                               SNL
         2624 7440
                               SZA
         2625 7402
                               HLT
                                              /CMA CML IAC FAILURE. AC SHOULD BE
                                              /0000. LINK SHOULD BE ZERO
                       /GROUP 1 OPERATE TEST 33
                                              /AC=0000 LINK=0
         2626 7300
                               CLA CLL
         2627 1053
                              TAD K2525
                                                    /ĂČ=2525
         2630 7261
                               CLA CMA CML IAC /TEST COMBINATION
         2631 7420
                               SNL
         2632 7450
                               SZL
         2633 7402
                                              /CLA CMA CML IAC FAILED, AC SHOULD
                                             /BE 0000. LINK SHOULD BE ZERO
                       /GROUP 1 OPERATE TEST 34
         2634 7320
                               CLA CLL CML
                               TAD K2525
                                                     /AC=2525 LINK=1
         2635 1053
         2636 7261
                               CLA CMA CML IAC /TEST COMBINATION
         2637 7430
                               SZL
         2640 7440
                               SZA
                               HLT
                                              /CLA CMA CML IAC FAILED, AC SHOULD
         2641 7402
                                              /BE 0000. LINK SHOULD BE ONE
```

/CLA RAR FAILED. LINK AND /AC SHOULD EQUAL ZERO

PAGE 47

/INSTRUCTION TEST - 1 PALID V141 3-DEC-09 9:07

HLT

2674 7402

```
/INSTRUCTION TEST = 1 PAL10
                                                       9107
                                                               PAGE 48
                       /GROUP 1 OPERATE TEST 39
                               CLA CMA CLL CML /AC=7777 LINK=1
         2675 7360
         2676 7204
                               CLA RAL
                                               /TEST COMBINATION
         2677 1035
                               TAD K7776
         27/10 7040
                               CMA
         2701 7420
                               SNL
         2702 7440
                               SZA
         2703 7402
                               HLT
                                               /CLA RAL FAILED LINK AND
                                               /AC SHOULD EQUAL ZERO
                       /GROUP 1 OPERATE TEST 40
                               CLA CMA CLL CML /AC=7777 LINK #1
         2704 7360
         2705 7212
                               CLA RTR
                                               /TEST COMBINATION
         2706 1047
                               TAD K5777
         2707 7040
                               CMA
         2710 7420
                               SNL
         2711 7440
                               SZA
         2712 7402
                               HLT
                                               /CLA RTR FAILED. AC AND
                                               /LINK SHOULD BE ZERO
                       /GROUP 1 OPERATE TEST 41
         2713 7360
                               CLA CMA CLL CML /AC-7777, LINK#1
         2714 7206
                               CLA RTL
                                               /TEST COMBINATION
         2715 1036
                               TAD K7775
         2716
               7040
                               CMA
         2717 7420
                               SNL
         2720 7440
                               SZA
         2721 7402
                                               /CLA RTL FAILED, AC AND LINK
                               HLT
                                               /SHOULDBE ZERO
                       /GROUP 1 OPERATE TEST 42
                               CLA CLL CML
         2722 7320
         2723 1026
                               TAD KØ040
                                                       /AC=0940 LINK#1
         2724 7110
                               CLL RAR
                                               /TEST COMBINATION
                               TAD K7757
         2725 1041
              7040
         2726
                               CMA
         2727 7420
                               SNL
         2730 7440
                               SZA
         2731 7402
                               HLT
                                               /CLL RAR FAILED. AC AND LINK
```

/SHOULD BE ZERO

3=DEC=69

v141

```
/INSTRUCTION TEST - 1 PALLY V141
                        /GROUP 1 OPERATE TEST 43
                               CLA CLL CML
          2732 7320
                                                       /AC=8040 LINK#1
                               TAD K0040
          2733 1026
                                               /TEST COMBINATION
                                CLL RAL
          2734 7184
                                TAD K7677
          2735 1843
          2736 7840
                                CMA
          2737 7420
                                SNL
          2749 7440
                                SZA
                                               /CLL RAL FAILED, AC AND LINK
                                HLT
          2741 7402
                                               SHOULD BE ZERO
                        /GROUP 1 OPERATE TEST 44
                                CLA CLL CML
          2742 7320
                                                       /AC=2040 LINK=1
                                TAD K0040
          2743 1026
                                CLL RTR
                                               /TEST COMBINATION
          2744 7112
                                TAD K7767
          2745 1848
          2746 7040
                                CMA
                                SNL
          2747 7420
                                SZA
          2750 7440
                                                VOLL RTR FAILED, AC AND LINK
          2751 7402
                                HLT
                                               /SHOULD BE ZERO
                        /GROUP 1 OPERATE TEST 45
                                CLA CLL CML
          2752 7320
                                                       /AC=2040 LINK=1
                                TAD KUMAO
          2753 1026
                                               /TEST COMBINATION
                                CLL RTL
          2754 7106
                                TAD K7577
          2755 1044
                                CMA
          2756 7848
          2757 7420
                                SNL
                                SZA
          2760 7440
                                                /CLL RTL FAILED. AC AND LINK
          2761 7402
                                HLT
                                                /SHOULD BE ZERO
                        /GROUP 1 OPERATE TEST 46
          2762 7360
                                CLA CLL CML CMA /AC=7777 LINK#1
                                CLL CLA RAR
                                                YTEST COMBINATION
          2763 7510
                                SNL
          2764 7420
          2765 7440
                                SZA
                                                /CLL CLA RAR FAILED AC AND
                                HLT
          2766 7402
                                                /LINK SHOULD BE ZERO
```

9137

```
/GROUP 1 OPERATE TEST 47
2767 7368
                      CLA CMA CLL CML /AC=7777 LINK=1
2770 7304
                                     /TEST COMBINATION
                      CLL CLA RAL
2771 7420
                      SNL
2772 7430
                      SZL
2775 7422
                      HLT
                                      /CLL CLA RAL FAILED. AC AND
                                      /LINK SHOULD BE ZERO
2774
     7000
                      NOP
2775 7000
                      NOP
2776 7000
                      NOP
2777 7000
                      NOP
     3000
              43000
              /GROUP 1 OPERATE TEST 48
3000 7360
                      CLA CMÂ CLL CML /AC#7777 LINK#1
3001 7512
                      CLA CLL RTR
                                  /TEST COMBINATION
3002 7420
                      SNL
3003 7442
                      SZA
3004 7402
                      HLT
                                      /CLA CLL RTL FAILED, AC AND
                                      /LINK SHOULD BE ZERO
              /GROUP 1 OPERATE TEST 49
3005 7360
                      CLA CMA CLL CML /AC=7777 LINK=1
3006 7306
                      CLA CLL RTL
                                      /TEST COMBINATION
3007 7420
                      SNL
3010 7440
                      SZA
3011 7402
                      HLT
                                      /CLA CLL RTL FAILED. AC AND
                                      /LINK SHOULD EQUAL ZERO
             /GROUP 1 OPERATE TEST 50
3012 7300
                      CLA CLL
                                      /AC=0000 LINK=0
3013 7030
                      CML RAR
                                      /TEST COMBINATION
3014 1050
                      TAD K3777
3015 7040
                      CMA
3016 7420
                      SNL
3017 7440
                      SZA
3020 7402
                      HLT
                                      /CML RAR FAILED, AC AND LINK
```

3=DEC-69

9:27

/SHOULD BE ZERO

PAGE 50

V141

/INSTRUCTION TEST + 1 PAL12

```
/GROUP 1 OPERATE TEST 51
                      CLA CLL
                                      /AC=0000 LINK #0
3021 7300
3022 7024
                      CML RAL
                                      /TEST COMBINATION
3023 1035
                      TAD K7776
3224
    7040
                      CMA
3025 7420
                      SNL
3026 7440
                      SZA
3027 7402
                      HLT
                                      /CML RAL FAILED. AC AND LINK
                                      /SHOULD BE ZERO.
              /GROUP 1 OPERATE TEST 52
3030 7300
                      CLA CLL
                                      /AC=0000 LINK=0
                      CML RTR
3231 7032
                                      /TEST COMBINATION
                      TAD K5777
3032 1047
3033 7040
                      CMA
3034 7420
                      SNL
3035 7440
                      SZA
3036 7402
                      HLT
                                      /CML RTR FAILED. AC AND LINK
                                      /SHOULD EQUAL ZERO
              /GROUP 1 OPERATE TEST 53
                                      /AC=0000 LINK=0
3037 7300
                      CLA CLL
3340 7026
                      CHL RTL
                                      /TEST COMBINATION
3041 1936
                      TAD K7775
3042 7042
                      CMA
3043 7420
                      SNL
3044 7440
                      SZA
3045 7402
                      HLT
                                      /CML RTL FAILED. AC AND LINK
                                      /SHOULD EQUAL ZERO
              /GROUP 1 OPERATE TEST 54
3046 7300
                      CLA CLL
3047 1052
                      TAD K5252
                                              /AC=5252 LINK#0
3050 7230
                      CLA CML RAR
                                      /TEST COMBINATION
3051 1050
                      TAD K3777
3052 7040
                      CMA
3053
    7420
                      SNL
3054 7440
                      SZA
3055 7402
                      HLT
                                      /CLA CML RAR FAILED. AC AND
              PAUSE
```

9127

PAGE 51

/INSTRUCTION TEST = 1

PAL10

V141

```
PAGE 52
/INSTRUCTION TEST - 1 PAL10 V141 3-DEC-69
                                                    9127
                       /INSTRUCTION TEST - 1
                       /GROUP 1 OPERATE TEST 55
                       /TAPE 3
                               CLA CLL
         3056 7300
                               TAD K5252
                                                    /AC=5252 LINK=Ø
         3057 1052
                               CLA CML RAL
                                              /TEST COMBINATION
         3060 7224
         3061 1035
                               TAD K7776
         3062 7040
                               CMA
         3063 7420
                               SNL
         3064 7440
                               SZA
         3065 7402
                               HLT
                                             /CLA CML RAL FALED, AC AND
                                              /LINK SHOULD BE ZERO
                       /GROUP 1 OPERATE TEST 56
                               CLA CLL
         3066 7300
                                                     /AC=5252 LINK=0
         3067 1052
                               TAD K5252
                                           /TEST COMBINATION
                               GLA CML RTR
         3070 7232
                               TAD K5777
         3071 1047
         3072 7040
                               CMA
         3073 7420
                               SNL
         3074 7440
                               SZA
                                             /CLA CML RTR FAILED, AC AND
         3075 7402
                                             VLINK SHOULD BE ZERO
                       /GROUP 1 OPERATE TEST 57
                               CLA CLL
         3076 7300
                                                    /AC=5252 LINK=Ø
                               TAD K5252
         3077 1052
         3100 7226
                               CLA CHL RTL
                                             /TEST COMBINATION
                               TAD K7775
         3101 1036
         3102 7040
                               CMA
         3103 7420
                               SNL
         3104 7440
                               SZA
                                              /CLA CML RTL FAILED, AC AND
         3105 7402
                               HLT
                                              /LINK SHOULD EQUAL ZERO
                       /GROUP 1 OPERATE TEST 58
                               CLA CLL
                                              /AC=0000 LINK=0
         3106 7300
                                              /TEST COMBINATION
         3107 7130
                               CLL CML RAR
         3110 7004
                               RAL
         3111 7430
                               SZL
         3112 7440
                               SZA
                                              /CLL CML RAR FAILED. AC SHOULD
         3113 7402
                                              /BE 0000 LINK SHOULD BE 1
```

```
/GROUP 1 OPERATE TEST 59
3114 7320
                      CLA CLL CML
                                      /AC=0000 LINK=1
3115 7130
                      CLL CML RAR
                                      /TEST COMBINATION
3116 7004
                      RAL
3117 7430
                      SZL
3120 7440
                      SZA
3121 7402
                      HLT
                                      /CLL CML RAR FAILED, AC SHOULD BE
                                      70200, LINK SHOULD BE A ONE
              /GROUP 1 OPERATE TEST 60
3122 7300
                      CLA CLL
                                      /AC=0000 LINK=0
3123 7124
                      CLL CML RAL
                                      /TEST COMBINATION
3124 7010
                      RAR
3125 7430
                      SZL
3126 7440
                      SZA
3127 7402
                      HLT
                                      /CLL CML RAL FAILED, AC SHOULD
                                      /EQUAL 0000. LINK SHOULD BE ONE
              /GROUP 1 OPERATE TEST 61
3130 7320
                      CLA CLL CML
                                      /AC=0000 LINK=1
3131 7124
                      CLL CML RAL
                                      /TEST COMBINATION
3132 7010
                      RAR
3133 7430
                      SZL
3134 7448
                      SZA
3135 7402
                      HLT
                                      /CLL CML RAL FAILED. AC SHOULD
                                      /EQUAL 0000, LINK SHOULD BE ONE
              /GROUP 1 OPERATE TEST 62
3136 7300
                      CLA CLL
                                      /AC=0000 LINK=0
3137 7132
                      CLL CML RTR
                                      /TEST COMBINATION
3140 7006
                      RTL
3141 7430
                      SZL
3142 7440
                      SZA
3143 7402
                      HLT
                                      /CLL CML RTR FAILED. AC SHOULD
                                      /BE 0000. LINK SHOULD BE ONE
```

```
/INSTRUCTION TEST = 1 PALIS
                                        3-DEC-69
                                                                PAGE 54
                        /GROUP 1 OPERATE TEST 63
         3144 7520
                                CLA CLL CML
                                                /AC=0000 LINK=1
         3145 7132
                                CLL CML RTR
                                                /TEST COMBINATION
         3146 7006
                                RTL
         3147 7430
                                SZL
         3150 7440
                                SZA
         3151 7402
                                HLT
                                                /CLL CML RTR FAILED. AC SHOULD
                                                /BE 2023 LINK SHOULD BE ONE.
                        /GROUP 1 OPERATE TEST 64
                                CLA CLL
          3152 7300
                                                /AC#0000 LINK#0
                                CLL CML RTL
         3153 7126
                                                /TEST COMBINATION
         3154 7012
                                RTR
         3155 7430
                                SZL
         3156 7440
                                SZA
                                                /CLL CML RTL FAILED. AC SHOULD
          3157 7402
                                HLT
                                                /BE 0000. LINK SHOULD BE A ONE
                        /GROUP 1 OPERATE TEST 65
          3160 7320
                                CLA CLL CML
                                                /AC=0000 LINK=1
         3161 7126
                                CLL CML RTL
                                                /TEST COMBINATION
         3162 7012
                                RTR
          3163 7430
                                SZL
         3164 7440
                                SZA
          3165 7402
                                HLT
                                               /CLL CML RTL FAILED. AC SHOULD
                                               /BE 0000. LINK SHOULD BE A ONE.
                        /GROUP 1 OPERATE TEST 66
         3166 7300
                                CLA CLL
          3167 1052
                                TAD K5252
                                                        /AC#5252 LINK#Ø
         3170 7330
                                CLA CLL CML RAR /TEST COMBINATION
              7004
         3171
                                RAL
         3172 7430
                                SZL
         3173 7440
                                SZA
              7402
                                HLT
                                                /CLA CLL CML RAR FAILED. AC SHOULD
         3174
                                                /BE 0000, LINK SHOULD BE ONE
         3175
                                NOP
               7000
         3176 7000
                               NOP
         3177 7000
                               NOP
               3200
                        43200
                        /GROUP 1 OPERATE TEST 67
         3200 7320
                               CLA CLL CML
                               TAD K2525
                                                       /AC=2525 LINK=1
         3201 1053
         3202 7330
                               CLA CLL CML RAR /TEST COMBINATION
         3263 7004
                               RAL
         3284 7438
                               SZL
         3205
              7440
                               SZĀ
         3226 7402
                               HLT
                                               /CLA CLL CML RAR FAILED. AC SHOULD
                                               /BE 0000. LINK SHOULD BE ONE
```

9107

V141

```
/GROUP 1 OPERATE YEST 68
3227 7500
                    CLA CLL
3213 1053
                    7AD K2525
                                        /AC=2525 LINK=0
3211 7324
                    CLA CLL CML RAL /TEST COMBINATION
3212 7210
                    RAR
3213 7430
                    SZL
3214 7448
                    SZA
3215 7402
                                 /CLA CLL CML RAL FAILED, AC SHOULD
                                 78E 2000. LINK SHOULD BE ONE
            /GROUP 1 OPERATE TEST 69
3216 7520
                   CLA CLL CML
                                 /AC=5252 LINK=1
3217 1052
                    TAD K5252
3228 7324
                    CLA CLL CML RAL /TEST COMBINATION
3221 7018
                    RAR
3222 7430
                    SZL
3223 7440
                    SZA
3224 7402
                                 /CLA CLL CML RAL FAILED. AC SHOULD
                    HL, T
                                 /BE 0000 LINK SHOULD BE A ONE
            /GROUP 1 OPERATE TEST 70
3225 7300
                   CLA CLL
                                /AC=2525 LINK=0
3226 1053
                    TAD K2525
3227 7332
                    CLA CLL CML RTR /TEST COMBINATION
3238 7886
                    RTL
3231 7438
                    SZL
3232 7440
                    SZA
3233 7422
                    HLT
                                 /CLA CLL CML RTR FAILED. AC SHOULD
                                 /BE 0000. LINK SHOULD BE A ONE
```

/INSTRUCTION TEST = 1 PALID V141 3-DEC-09 9107 PAGE 55

```
9107
                                    3=DEC=69
                                                          PAGE 56
/INSTRUCTION TEST = 1 PAL10
                             V141
                     /GROUP 1 OPERATE TEST 71
                             CLA CLL CML
         3234 7320
         3235 1052
                             TAD K5252
                                                 /AC=5252 LINK=1
         3236 7332
                             CLA CLL CML RTR /TEST COMBINATION
         3237 7006
                             RTL
         3240 7430
                             SZL
         3241 7440
                             SZA
                             HLT
                                          /CLA CLL CML RTR FAILED. AC SHOULD
         3242 7402
                                          /BE 0000, LINK SHOULD BE A ONE
                     /GROUP 1 OPERATE TEST 72
                             CLL CLA
         3243 7300
                                           /AC=2525 LINK=0
                             TAD K2525
         3244 1053
                             CLA CLL CML RTL /TEST COMBINATION
         3245 7326
         3246 7012
         3247 7430
                             SZL
                             SZA
         3250 7440
                             HLT . . /CLA CLL CML RTL FAILEU, AU SHUULU
/BE 0000, LINK SHOULD BE A ZERO
         3251 7402
                     /GROUP 1 OPERATE TEST 73
         3252 7320
                             CLL CLA CML
                                          /AC=5252 LINK#1
        3253 1052
                             TAD K5252
         3254 7326
                             CLA CLL CML RTL /TEST COMBINATION
         3255 7012
                             RTR
         3256 7430
                             SZL
         3257 7440
                             SZA
         3260 7402
                             HLT
                                           /CLA CLL CML RTL FAILED, AC SHOULD
                                           /BE 0000, LINK SHOULD BE A ONE
                     /GROUP 1 OPERATE TEST 74
         3261 7300
                             CLA CLL
         3262 1051
                             TAD K7777
                                                /TEST PATTERN
                                          /AC EQUALS 0001
         3263 7041
                             CIA
                             TAD K7776
         3264 1035
         3265 7040
                             CMA
         3266 7420
                             SNL
                             SZA
HLT
         3267 7440
                                           /CIA FAILED AC SHOULD EQUAL 0000
                                           /LINK SHOULD EQUAL A ZERO
         3270 7402
                      /GROUP 1 OPERATE TEST 75
                             CLA CLL
         3271 7300
                             TAD K7776
                                             /TEST PATTERN
         3272 1035
                             CIA
                                          /AC EQUALS 0002
         3273 7041
                             TAD K7775
         3274 1036
         3275 7040
                             CMA
         3276 7420
                             SNL
                             SZA
HLT
         3277 7440
                                        /CIA FAILED AC SHOULD EQUAL 0000
                                          /LINK SHOULD EQUAL A ZERO
         3300 7402
```

/INSTRUCTION TEST = 1

PAL10

V141

PAGE 57

9107

```
/GROUP 1 OPERATE TEST 80
                      CLA CLL
3341 7300
                      TAD K7700
                                              /TEST PATTERN
3342 1076
                                      /AC EQUALS DINO
                      CIA
3343
     7041
                      TAD K7677
3344
     1043
                      CMA
3345 7040
     7420
                      SNL
3346
3347 7440
                      SZA
                                      /CIA FAILED A SHOULD EQUAL 0000
3350 7402
                      HLT
                                      /LINK SHOULD EQUAL ZERO
              /GROUP 1 OPERATE TEST 81
                      CLA CLL
     7300
3351
                                              /TEST PATTERN
                      TAD K7600
3352
     1057
                                      /AC EQUALS 0200
3353 7041
                      CIA
                      TAD K7577
3354 1044
                      CMA
3355
     7040
                      SNL
     7420
3356
3357 7440
                      SZA
                                      /CIA FAILED AC SHOULD EQUAL 0000
3360 7402
                      HLT
                                      /LINK SHOULD EQUAL ZERO
              /GROUP 1 OPERATE TEST 82
                      CLA CLL
3361
     7300
                                              /TEST PATTERN
                      TAD K7400
3362
     1056
                                      /AC EQUALS 0400
                      CIA
3363
    7041
                      TAD K7377
     1045
3364
                      CMA
3365 7040
3366
     7420
                      SNL
3367
     7440
                      SZA
                                      /CIA FAILED AC SHOULD EQUAL 0000
3370 7402
                      HLT
                                      /LINK SHOULD EQUAL ZERO
```

PAL10

/INSTRUCTION TEST # 1

V141

9107

```
3371 7000
                      NOP
3372 7000
                      NOP
3373 7000
                      NOP
3374 7000
                      NOP
3375 7000
                      NOP
3376 7000
                      NOP
3377 7000
                      NOP
      3400
              #3400
              /GROUP 1 OPERATE TEST 63
3430 7300
                     CLA CLL
3401 1055
                      TAD K7000
                                             /TEST PATTERN
3402 7041
                      CIA
                                      /AC EQUALS 1000
3423 1046
                      TAD K6777
3404 7040
                      CMA
3425 7420
                      SNL
3426 7440
                      SZA
3407 7402
                      HLT
                                     /CIA FAILED AC SHOULD EQUAL 0000
                                     /LINK SHOULD EQUAL ZERO
              /GROUP 1 OPERATE TEST 64
3410 7300
                     CLA CLL
3411 1054
                      TAD KOUDO
                                              /TEST PATTERN
3412 7041
                      CIA
                                      /AC EQUALS 2000
                      TAD K5777
3413 1047
3414 7040
                      CMA
3415 7420
                      SNL
3416 7440
                      SZA
3417 7402
                      HLT
                                      /CIA FAILED AC SHOULD EQUAL 0000
                                      /LINK SHOULD EQUAL ZERO
              /GROUP 1 OPERATE TEST 85
3420 7300
                      CLA CLL
3421 1034
                      TAD K4000
                                             /TEST PATTERN
3422 7041
                      CIA
                                      /AC EQUALS 4000
3423 1050
3424 7040
                      TAD K3777
                      CMA
3425 7420
                      SNL
3426 7440
                      SZA
3427 7402
                      HLT
                                      /CIA FALED AC SHOULD EQUUA 000
                                      /LINK SHOULD EQUALL ZERO
              /GROUP 1 OPERATE TEST 86
3430 7300
                      CLA CLL
3431 1020
                      TAD KOUGU
                                              /TEST PATTERN
3432 7041
3433 7450
                      CIA
                                      /AC EQUALS 0000, LINK EQUALS A ONE
                      SNA
3434 7420
                      SNL
3435 7402
                      HLT
                                     /CIA FAILED AC SHOULD EQUAL 2000
                                     /LINK SHOULD EQUAL A ONE
```

9107

PAGE 59

/INSTRUCTION TEST = 1 PAL10 V141 3-DEC-69

```
/GROUP OPERATE TEST 87
3436 7340
                      CLA CMA CLL
                                       /AC=7777,L=0
3437 7311
                       CLA CLL IAC RAR /AC=0,L=1
     7430
3440
                       SZL
3441 7440
                       SZA
3442 7402
                       HLT
                                       /ERROR! LINC NOT SET OR
                                       /AC NOT Ø
              /GROUP 1 OPERATE TEST 88
                      CLA CMA CLL CML /AC=7777,L=1
CLA CLL IAC RAL /AC=2,L=0
3443
     7360
    7305
3444
3445 7430
                      SZL
3446 7402
                                       /ERROR: LINC NOT Ø
                      HLT
3447
                       CMA IAC
     7041
     1022
3450
                       TAD KUUDZ
3451
     7440
                       SZA
3452 7402
                       HLT
                                       /ERROR AC NOT#2
              /GROUP 1 OPERATE TEST 89
3453
    7320
                      CLA CLL CML
                                      /ACEØ.LE1
    7313
                      CLA CLL IAC RTR /AC=4000,L=0
3454
3455
     7430
                      SZL
3456
     7402
                                       /ERROR; LINC NOT Ø
                       HLT
3457 7500
                      SMA
3460 7402
                                       /ERROR! AC NOT 4000
                      HLT
              /GROUP 1 OPERATE TEST 90
3461
     7360
                      CLA CMA CLL CML
                                               /AC=7777.L=1
3462 7307
                      CLA CLL IAC RTL
                                               /AC#4,LINC#Ø
3463 7430
                      SEL
3464 7402
                      HLT
                                       /ERROR: LINC NOT Ø
                      CMA JAC
3465
     7041
3466
     1023
                      TAD KUUDA
3467 7440
                      SZA
3470 7402
                      HLT
                                       /ERROR: AC NOT 4
              /GROUP 1 OPERATE TEST 91
3471
     7300
                      CLA CLL
                                       /AC=0, L=0
3472 7331
                      CLA CLL CML IAC RAR /AC#4000, L=1
3473 7520
                      SMA SNL
3474 7402
                      HLT
                                       /ERROR; AC NOT 4000 OR
                                       /LINC NOT 1
```

/INSTRUCTION TEST = 1

PAL12

V141

3-DEC-69

9107

3-0EC-69

PAGE 61

9107

		/GROUP 2 OPERATE TEST 1
3513	7240	CLA CMA /AC=7777
	7700	CLA SMA /TEST COMBINATION
3515	7402	HLT /CLA SMA DID NOT SKIP
0717	7.200	The state of the s
7516	7440	/AC SHOULD BE 0000
3516	7440 7402	SZA
3517	1465	HLT /CLA SHA DID NOT CLEAR AC
		/AC SHOULD BE 0000
		/GROUP 2 OPERATE TEST 2
3520	7240	CLA CMA /AC=7777
3521	7640	CLA SZA /TEST COMBINATION
3522	7440	SZA
3523	7402	HLT /CLA SZA SKIPPED OR AC NOT
,		/CLEARED TO 0000
		/GROUP 2 OPERATE TEST 3
3524	7240	CLA CMA /AC=7777
3525	7540	SMA SZA /TEST COMBINATION
3526	7402	HLT /SMA SZA SHOULD HAVE SKIPPED
0724		/AC SHOULD EQUAL 7777
		/GROUP 2 OPERATE TEST 4
3527	7200	
3539	7548	
	7402	
3531	1205	HLT /SMA SZA SHOULD HAVE SKIPPED
		/AC SHOULD EQUAL 0000
		/GROUP 2 OPERATE TEST >
3532	7200	CLA
3533	1050	TAD K3777 /AC#3777
3534	7540	SMA SŽÁ /TEST COMBINATION
3535	7450	SNA
3536	7402	HLT /SMA SZA SHOULD NOT HAVE SKPPE
	= '	/AC SHOULD EQUAL 3777

9107

PAGE 62

/INSTRUCTION TEST - 1 PAL10

		/GROUP 2 OPERATE TEST	6
3537	7240	CLA CMA	/AC=7777
	7740	CLA SMA SZA	ITEST COMBINATION
3541	7402	ĤĽT	/CLA SMA SZA ŠHOULD HAVE SKIPPED
0,7-4			/AC SHOULD BE 0000
3542	7446	SZA	
3543	7402	HLT	/AC WAS NOT CLEARED
<b>U</b> ) • •		· • ·	/AC SHOULD BE 0000
		/GROUP 2 OPERATE TEST	
3544	7200	CLA	/AC=0000
	7740	CLA SMA SZA	/TEST COMBINATION
3546	7402	HLT	/CLA SMA SŽA ŠHOULD HAVE SKIPPED
0,740	/		/AC SHOULD BE 0000
3547	7440	SŽA	
3550	7402	HLT	AC WAS NOT CLEARED
3330	7402	:1 <b>-</b> (	/AC SHOULD BE 0000
		/GROUP 2 OPERATE TEST	
3551	7200	CLA	No.
	1050	TAD K3777	/AC=3777
	7740	CLA SMA SZA	/TEST COMBINATION
3554	7440	SZA	, , , , , , , , , , , , , , , , , , , ,
3555	7402	HÉT	/SMA SZA DID NOT SKIP OR AC
3325	1402	7 <b>k</b> (	/NOT CLEARED TO 0000
		/GROUP 2 OPERATE TEST	
7==6	7300	CLL CLA	\LINK=N
3556 3557	1052	TAD K5252	/AC=5252
			TEST COMBINATION
3560	7620	CLA SNL Sža	LIEGI OCCUPANTACA
3561	7440		/SNL SKIPPED OR AC NOT CLEARED
3562	7402	HLT	VAC AND LINK SHOULD EQUAL ZERO
			NAC MAD FINA SHOOFD EMBYE SEVO

3=DEC=69

/GROUP 2 OPERATE TEST 10 3563 7320 CLA CLL CML TAD K2525 1053 /AC=2525 LINK#1 3564 7620 CLA SNL /TEST COMBINATION 3565 3566 7402 /SNL DID NOT SKIP HLT /LINK SHOULD EQUAL ONE 3567 7440 SZA 3570 7402 HLT /CLA SNL DID NOT CLEAR AC /AC SHOULD EQUAL 0000 /GROUP 2 OPERATE TEST 11 /AC=0000 LINK=0 7300 CLA CLL 3571 3572 7520 SMA SNL /TEST COMBINATION 7448 SZA 3573 HLT /SMA SNL SKIPPED. AC AND LINK 3574 7402 /SHOULD EQUAL ZERO /GROUP 2 OPERATE TEST 12 7320 3575 CLA CLL CML /AC#0000 LINK#1 7520 SMA SNL /TEST COMBINATION 3576 /SNL SHOULD HAVE SKIPPED, LINK = 1 3577 7402 /GROUP 2 OPERATE TEST 13 3600 7300 CLA CLL 3621 1034 TAD K4000 /AC=4000 LINKS0 SMA SNL 3602 7520 /TEST COMBINATION /SMA SHOULD HAVE SKIPPED 3603 7402 HLT /AC=4000 /GROUP 2 OPERATE TEST 14 3604 7320 CLA CLL CML /AC=4000 LINK#1 1034 TAD K4000 3605 3606 7520 SMA SNL /TEST COMBINATION /SMA SNL SHOULD HAVE SKIPPED HLT 3607 7402

/AC=4000 LINKS1

```
/INSTRUCTION TEST = 1
                       PAL10
                                       3-DEC-69
                                V141
                                                      9107
                                                                PAGE 66
                       /GROUP 2 OPERATE TEST 21
          3643 7300
                                CLA CLL
          3644 1031
                                TAD KØ400
                                                       /AC=0400 LINK#0
          3645 7460
                                SZA SNL
                                                /TEST COMBINATION
          3646 7456
                                SNA
          3647 7402
                                HLT
                                                /SZA SNL SKIPPED
                                                /AC=0400 LINK=0
                       /GROUP 2 OPERATE TEST 22
         3650 7320
                                CLA CLL CML
         3651 1026
                                TAD K0040
                                                       /AC=0040 LINK=1
         3652 7460
                                SZA SNL
                                               /TEST COMBINATION
         3653 7402
                                            SO /SEA SNL SHOULD HAVE SKIPPED
                                HLT
                                                /LINK#1
                       /GROUP 2 OPERATE TEST 23
         3654 7300
                                CLA CLL
                                               /AC#0000 LINK#0
         3655 7660
                                CLA SZA SNL
                                               /TEST COMBINATION
         3656 7402
                                HLT
                                               /CLA SZA SNL SHOULD HAVE SKIPPED
                                               /AC AND LINK SHOULD EQUAL ZERO
         3657 7440
                               SZA
         3660 7402
                               HLT
                                               /CLA SZA SNL DID NOT CLEAR AC
                                               /AC SHOULD BE 0000
                       /GROUP 2 OPERATE TEST 24
         3661 7320
                               CLA CLL CML
                                               /AC=0000 LINK=1
         3662 7660
                               CLA SZA SNL
                                               /TEST COMBINATION
         3663 7402
                               HLT
                                               /CLA SZA SNL SHOULD HAVE SKIPPED
                                               /AC=0000 LINK#1
         3664 7440
                               SZA
         3665 7402
                               HLT
                                               /CLA SZA SNL DID NOT CLEAR AC
                                               /AC SHOULD EQUAL ØØØØ
                       /GROUP 2 OPERATE TEST 25
         3666 7320
                               CLA CLL CML
         3667 1030
                               TAD KØ2ØØ
                                                       /ACEØ2ØØ LINKE1
         3670 7660
                               CLA SZA SNL
                                                       /TEST COMBINATION OR
         3671
              7402
                               HLT
                                               /CLA SZA SNL SHOULD HAVE SKIPPED
                                               /LINK#1
         3672 7440
                               SZA
         3673 7402
                               HLT
                                               /CLA SZA SNL DID NOT CLEAR AC
                                               /AC SHOULD EQUAL 0000
                       /GROUP 2 OPERATE TEST 26
         3674 7300
                               CLA CLL
         3675 1033
                               TAD K2000
                                                       /AC#2000 LINK#0
         3676 7660
                               CLA SZA SNL
                                               /TEST COMBINATION
         3677 7440
                               SZA
         3700 7402
                               HLT
                                               /CLA SZA SNL FAILED. AC AND
                                               /LINK SHOULD EQUAL ZERO
```

```
/GROUP 2 OPERATE TEST 27
                     CLA CLL
                                     /AC=0000 LINK=0
3701 7300
                     SMA SZA SNL
                                     /TEST COMBINATION
3702 7560
                                     /SMA SZA SNL SHOULD HAVE SKIPPED
                     HLT
3703 7402
                                     /ACS0000 LINKS0
             /GROUP 2 OPERATE TEST 28
                     CLA CLL CML
TAD K3777
3704 7320
                                             /AC=3777 LINK#1
3705 1050
                     SMA SŽÁ SNL
                                     /TEST COMBINATION
3786 7560
                                     /SMA SZA SNL SHOULD HAVE SKIPPED
3707 7402
                     HLT
                                     /AC=3777 LINK#1
             /GROUP 2 OPERATE TEST 29
                     CLA CLL
3710 7300
                     TAD KAUDU
                                             /AC=4000 LINK#0
3711 1034
                     SHA SZÁ SNL
                                     /TEST COMBINATION
3712 7560
                                     /SMA SZA SNL SHOULD HAVE SKIPPED
3713 7402
                     HLT
                                     /AC=4000 LINK#0
             /GROUP 2 OPERATE TEST 30
3714 7300
                     CLA CLL
                                             /AC=3777 LINKED
                     TAD K3777
3715 1050
                     SMA SŽÁ SNL
                                     /TEST COMBINATION
3716 7560
3717 7450
                     SNA
                                     /SMA SZA SNL SHOULD NOT HAVE
3720 7402
                      HLT
                                     /SKIPPED, AC=3777 LINK=0
```

3=DEC=09

V141

PAL12

/INSTRUCTION TEST - 1

9107

```
/INSTRUCTION TEST # 1 PAL18 V141
                                       3-DEC-69
                                                 9:07
                                                               PAGE 68
                       /GROUP 2 OPERATE TEST 31
                               CLA CLL
                                               /AC=0000 LINK#0
         3721 7300
                               CLA SMA SZA SNL /TEST COMBINATION
         3722 7760
         3723 7402
                               HLT
                                               /CLA SMA SZA SNL SHOULD HAVE SKIPPED
                                               /AC SHOULD EQUAL 0000
         3724 7440
                               SZA
         3725 7402
                               HLT
                                               /AC NOT ZERO AFTER CLA SMA SZA SNL
                                               /AC SHOULD BE 0000 LINK=0
                       /GROUP 2 OPERATE TEST 32
         3726 7320
                               CLA CLL CML
         3727 1050
                               TAD K3777
                                                      /AC#3777 LINK#1
                               CLA SMA SZA SNL /TEST COMBINATION
         3730 7760
         3731 7402
                               HLT
                                               /CLA SMA SZA ŠNL DID NOT SKIP
                                               /AC SHOULD BE 0000 LINK=1
         3732 7440
                               SZA
         3733 7402
                               HLT
                                               /CLA SMA SZA SNL DID NOT CLEAR AC
                                               /AC SHOULD EQUAL 0000 LINK=1
                       /GROUP 2 OPERATE TEST 33
                               CLA CLL
         3734 7300
                               TAD K4888
                                                      /AC#4000 LINK#0
         3735 1034
         3736 7760
                               CLA SMA SZA SNL /TEST COMBINATION
         3737 7402
                               HLT
                                               /CLA SMA SZA SNL SHOULD HAVE SKIPPED
                                               /AC SHOULD BE 0000, LINK=0
         3740 7440
                               SZA
         3741 7402
                               HLT
                                               /CLA SMA SZA SNL DID NOT CLEAR AC
                                               /AC SHOULD EQUAL 0000
                       /GROUP 2 OPERATE TEST 34
                               CLA CLL
         3742 7300
         3743 1050
                                                      /AC=3777 LINK=Ø
                               TAD K3777
         3744 7760
                               CLA SMA SZA SNL /TEST COMBINATION
         3745 7440
                               SZA
         3746 7402
                               HLT
                                               /CLA SMA SZA SNL FAILED. AC
                                               /SHOULD BE ZERO, LINK=0
                       /GROUP 2 OPERATE TEST 35
                               CLA CLL
         3747 7300
                                               /AC=0000 LINK#0
         3750 7410
                               SKP
                                               TEST INSTRUCTION
         3751 7402
                               HLT
                                               /SKIP FAILED
                                               /AC AND LINK EQUAL ZERO
                       /GROUP 2 OPERATE TEST 36
                               CLA CLL CML
                                               /ACE0000 LINKE1
         3752 7320
         3753 7410
                               SKP
                                               /TEST INSTRUCTION
         3754 7402
                               HLT
                                               /SKIP FAILED
                                               /AC=0000 LINK#1
```

3-DEC-69

PAL10 V141

/INSTRUCTION TEST - 1

9147

PAGE 69

```
/GROUP 2 OPERATE TEST 43
4027 7200
                      CLA
                                      /AC=0000
                      SPA SNA
                                      /TEST COMBINATION (AND)
4810 7550
                      SZA
4811 7440
                                      /SPA SNA SKIPPED
4012 7402
                      HLT
                                      /AC=0000
              /GROUP 2 OPERATE TEST 44
                      CLA
4213 7200
                      TAD K3777
                                              /AC=3/77
4214 1050
                      SPA SNA
                                      /TEST COMBINATION (AND)
4915 7550
                      HLT
                                      /SPA SNA FAILED TO SKIP
4216 7402
                                      /AC=3777
              /GROUP 2 OPERATE TEST 45
                      CLA
4017 7200
                                             /AC=4000
                      TAD KAUDU
4020 1034
                      SPA SNA
                                      /TEST COMBINATION (AND)
4021 7550
4922 7450
                      SNA
4023 7402
                                      /SPA SNA SKIPPED.
                      HLT
                                      /AC=4000
              /GROUP 2 OPERATE TEST 46
                                      /AC=0000
4024 7200
                      CLA
                      CLA SPA SNA
4225 7750
                                      /TEST COMBINATION (AND)
4226 7440
                      SZA
4027 7402
                                      /CLA SPA SNA FAILED.
                      HLT
                                      /AC SHOULD BE 0000
              /GROUP 2 OPERATE TEST 47
                      CLA
4030 7200
4031 1050
                      TAD K3777
                                              /AC=3777
                      CLA SPA SNA
                                      /TEST COMBINATION (AND)
4032 7750
                                      /CLA SPA SNA DID NOT SKIP
4235 7402
                      HLT
                                      /AC SHOULD BE 0000
                      SZA
4034 7440
                                      /CLA SPA SNA DID NOT CLEAR THE AC
4035 7402
                      HLT
                                      /AC SHOULD EQUAL 0000
              /GROUP 2 OPERATE TEST 48
4036 7200
                      CLA
                      TAD K4000
                                              /AC=4000
4037 1034
                      CLA SPA SNA
                                      /TEST COMBINATION (AND)
4040 7750
4241 7440
                      SZA
4042 7402
                                      /CLA SPA SNA FAILED
                      HLT
                                      /AC SHOULD EQUAL ZERO
```

3=DEC=69 9107

PAGE 70

PAUSE

/INSTRUCTION TEST # 1 PAL10 V141

		/INSTRUCTION TEST + TAPE 4
		/GROUP 2 OPERATE TEST 49
4243	7320	CLA CLL
4344	1252	TAO K5252 /AC=5252 LINK=8
4247	7630	CLA SZL /TEST COMBINATION
4745	7402	HLT /CLA SZL DID NOT SKIP
		/AC AND LINK SHOULD BE 8
4341	7440	SZA
4353	7422	HLT ZOLA SZL DID NOT CLEAR AC
		/AC SHOULD BE ZERO. LINK##
		/GROUP 2 OPERATE TEST 50
4251	7360	CLA CLL CML CMA /AC=7777 LINK=1
	7630	CLA SZL /TEST COMBINATION (AND)
	7440	SZA
4254	7482	HLT /CLA SZL FAILED, AC SHOULD
		/BE 2000, LINK=1
A	9720	/GROUP 2 OPERATE TEST 51
	7328 1252	CLA CLL TAD K3777 /AC=3777 LINK=0
	7232	TAD K3777 /AC=3777 LINK=0 SPA SZL /TEST COMBINATION (AND)
	7402	HLT /SPA SZL DID NOT SKIP
확인하다	1402	/AC=3777 LINK##
		/GROUP 2 OPERATE TEST 52
4041	7322	CLA CLL CML
	1050	TAD K3777 /AC=3777 LINK#1
	7332	SPA SZL /TEST COMBINATION (AND)
	7450	SNA
4365	7402	HLT /SPA SZL SKIPPED
	=	/AC=3777 LINK#1
		/GROUP 2 OPERATE TEST 53
	7320	CLA CLL
	1034	TAD KARDO /AC=AROS LINK+0
•	7530	SPA SZL /TEST COMBINATION (AND)
	7500	SMA
4072	7402	HLT /SPA SEL SKIPPED
		/AC=4000 LINK#0
		/GROUP 2 OPERATE TEST 54
4073	7390	CLA CLL
	1050	TAD K3777 /AC=3777 LINK=0
	7730	CLA SPA SZL /TEST COMBINATION (AND)
4275	7402	HLT /CLA SPA SZL SHOULD HAVE SKIPPED
4377	7448	/AC SHOULD BE 0000, LINK=0
4077 4130	7402	SZA HLT /CLA SFA SZL DIÐ NOT CLEAR THE AC
The state of	1366	
		/AC SHOULD BE EVER

```
/INSTRUCTION TEST = 1 PAL10 V141
                                       3-DEC-69
                                                               PAGE 72
                       /GROUP 2 OPERATE TEST 55
                               CLA CLL CML
         4101 7320
                                                       /AC=3777 LINK#1
         4102 1050
                               TAD K3777
                               CLA SPÁ SZL
                                               /TEST COMBINATION (AND)
         4103 7730
         4104 7440
                               SZA
         4105 7402
                               HLT
                                               /CLA SPA SZL FAILED
                                               /AC SHOULD EQUAL 0000 LINK#1
                       /GROUP 2 OPERATE TEST 56
         4106 7300
                               CLA CLL
         4107 1034
                               TAD K4000
                                                       /AC=4000 LINK=0
         4110 7730
                               CLA SPA SEL
                                               /TEST COMBINATION (AND)
         4111 7440
                               SZA
         4112 7402
                                               /CLA SPA SEL FAILED
                               HLT
                                               /AC SHOULD EQUAL 0000 LINK=0
                       /GROUP 2 OPERATE TEST 57
         4113 7300
                               CLA CLL
                               TAD K4000
         4114 1034
                                                       /AC#4000 LINK#0
                               SNA SEL
         4115 7470
                                               /TEST COMBINATION (AND)
         4116 7402
                               HLT
                                               /SNA SZL DID NOT SKIP
                                               /AC = 4000 LINK=0
                       /GROUP 2 OPERATE TEST 58
                               CLA CLL CML
         4117 7320
                               TAD K4000
         4120 1034
                                                       /AC=4000 LINKE1
                               SNA SEL
                                               /TEST COMBINATION (AND)
         4121 7470
         4122 7420
                               SNL
         4123 7402
                                               /SNA SZL SKIPPED
                               HLT
                                               /AC=4000 LINK#1
                       /GROUP 2 OPERATE TEST 59
                               CLA CLL
                                               /AC#0000 LINKS0
         4124 7300
         4125 7470
                               SNA SEL
                                               /TEST COMBINATION (AND)
         4126 7430
                               SZL
         4127 7402
                                               /SNA SZL SKIPPED
                                               /AC=0000 LINK#0
                       /GROUP 2 OPERATE TEST 60
         4130 7320
                               CLA CLL CML
                                                       /AC=4000 LINK#1
         4131 1034
                               TAD K4000
                                               /TEST COMBINATION (AND)
         4132 7670
                               CLA SNA SEL
         4133 7440
                               SZA
                                               /CLA SNA SZL FAILED, AC SHOULD
         4134 7402
                               HLT
                                               /BE 0000. LINK=1
```

9127

```
9107
                                                               PAGE 73
                                     3-DEC-69
/INSTRUCTION TEST - 1 PAL10 V141
                        /GROUP 2 OPERATE TEST 61
                                CLA CLL
          4135 7300
                                                       JACSANNO LINKEN
                                TAD K4000
          4136 1034
                                                /TEST COMBINATION (AND)
                                CLA SNA SEL
          4137 7678
                                                /CLA SNA SZL DID NOT SKIP
          4140 7402
                                HLT
                                                /AC SHOULD BE BODG. LINKED
          4141 7440
                                SZA
                                                /CLA SNA SEL DID NOT CLEAR AC
                                HLT
          4142 7402
                                                /AC AND LINK SHOULD BE ZERO
                        /GROUP 2 OPERATE TEST 62
                                                /AC=0000 LINK#0
                                CLA CLL
          4143 7300
                                                /TEST COMBINATION (AND)
                                CLA SNA SEL
          4144 7670
          4145 7440
                                SZA
                                                /CLA SNA SZL FAILED. AC SHOULD
          4146 7402
                                HLT
                                                /BE 0000, LINK#0
                        /GROUP 2 OPERATE TEST 63
                                CLA CLL
          4147 7300
                                                       /40-3777 LINK#6
                                TAD K3777
          4150 1050
                                                /TEST COMBINATION (AND)
                                SPA SNA SZL
          4151 7570
                                                /SPA SNA SZL DID NOT SKIP
          4152 7402
                                                /AC=3777 LINK#0
                        /GROUP 2 OPERATE TEST 64
                                CLA CLL CML
          4153 7320
                                                        /AC=3777 LINK=1
                                TAD K3777
          4154 1050
                                                        /TEST COMBINATION (AND)
                                SPA SNA SZL
          4155 7570
          4156 7420
                                SNL
                                                /SPA SNA SZL SKIPPED
          4157 7402
                                                /AC=3777 LINK=1
                        /GROUP 2 OPERATE TEST 65
                                                /ACE0000 LINKED
                                CLA CLL
          4160 7300
                                                ITEST COMBINATION (AND)
                                SPA SNA SZL
          4161 7570
          4162 7430
                                SZL
                                                /SPA SNA SZL SKIPPED
          4163 7402
                                HLT
                                                /AC=0000 LINK=0
                        /GROUP 2 OPERATE TEST 66
                                CLA CLL
          4164 7300
                                                        /AC=4000 LINK=0
                                TAD K4000
          4165 1034
                                                /TEST COMBINATION (AND)
                                SPA SNA SEL
          4166 7570
                                SZL
          4167 7430
                                                /SPA SNA SZL SKIPPED
          4170 7402
                                HLT
                                                /AC=4000 LINK=0
```

```
9107 PAGE 74
/INSTRUCTION TEST = 1 PALIS V141
                                      3-DEC=69
                       /GROUP 2 OPERATE TEST 67
         4171 7300
                              CLA CLL
         4172 1050
                              TAD K3777
                                                     /AC=3777 LINK#Ø
         4173 7770
                              CLA SPA SNA SZL /TEST COMBINATION (AND)
         4174 7402
                              HLT
                                            /CLA SPA SNA SZL DID NOT SKIP
                                              /AC AND LINK SHOULD BE ZERO
         4175 7440
                              SZA
         4176 7402
                              HLT
                                              /CLA SPA SNA SZL DID NOT CLEAR AC
                                              /AC AND LINK SHOULD BE ZERO
         4177 7000
                              NOP
               4200
                       #4200
                       /GROUP 2 OPERATE TEST 68
         4200 7320
                              CLA CLL CML
         4201 1050
                                                    /AC=3777 LINK=1
                              TAD K3777
         4202 7770
                              CLA SPA SNA SZL /TEST COMBINATION (AND)
         4203 7440
                              SZA
         4204 7402
                              HLT
                                              /CLA SPA SNA SZL FAILED. AC SHOULD
                                             /BE 0000. LINK SHOULD EQUAL ONE
                       /GROUP 2 OPERATE TEST 69
         4205 7300
                              CLA CLL
         4206 1034
                              TAD K4000
                                                    /AC#4000 LINK#0
         4207 7770
                              CLA SPA SNA SZL /TEST COMBINATION (AND)
         4210 7440
                              SZA
         4211 7402
                              HLT
                                              /CLA SPA SNA SZL FAILED. AC SHOULD
                                             /BE 0000, LINK SHOULD EQUAL ZERO
                       /GROUP 2 OPERATE TEST 70
         4212 7300
                              CLA CLL
                                              /AC=0000 LINK#0
                              CLA SPA SNA SZL /TEST COMBINATION (AND)
         4213 7770
         4214 7440
                              SZA
         4215 7402
                              HLT
                                              /CLA SPA SNA SZL FAILED. AC AND
                                             /LINK SHOULD BE ZERO.
                      /GROUP 2 OPERATE TEST 71
         4216 7200
                              CLA
         4217 1052
                              TAD K5252
                                                    /AC=5252
         4220 7604
                              CLA OSR
                                             /TEST COMBINATION
         4221 7040
                              CMA
         4222 7440
                              SZA
         4223 7402
                              HLT
                                              /CLA OSR FAILED
                                              /AC SHOULD BE 0000
```

4263 7440

4264 7402

SZA

HLT

ZGROUP 2 OPERATE TEST 72 CLA 4224 7200 TAD K4000 /AC=4000 4225 1034 ITEST COMBINATION 4226 7504 SMA OSK /SMA OSR FAILED TO SKIP 4227 7402 HLT /AC SHOULD BE 7777 4230 7040 CMA 4231 7440 SZA HLT /SMA OSR FAILED 4232 7402 /AC SHOULD BE 2000 /GROUP 2 OPERATE TEST 73 /AC=0000 4233 7200 CLA SZA OSR /TEST COMBINATION 4234 7444 /SZA OSR FAILĒD TO SKIP 4235 7402 HLT /AC SHOULD BE 0000 4236 7040 CMA 4237 7440 SZA /SZA OSR FAILED. 4240 7402 HLT /AC SHOULD BE 0000 /GROUP 2 OPERATE TEST 74 /LINK=1 4241 7320 CLL CML CLA 4242 7424 /TEST COMBINATION SNL OSR ISNL OSR FAILED TO SKIP 4243 7402 HLT /AC SHOULD BE 7777 CMA 4244 7840 4245 7440 SZA ISNL OSR FAILED. 4246 7402 HLT /AC SHOULD BE 0000 /GROUP 2 OPERATE TEST 75 4247 7500 CLA CLL /AC=3777 LINK#Ø TAD K3777 4250 1050 4251 7764 CLA SMA SZA SNL OSR /TEST COMBINATION 4252 7450 SNA /CLA SMA SZA SNL OSR FAILED. 4253 7402 HLT /AC SHOULD BE 7777. LINK#0 4254 7040 CMA 4255 7440 SZA /CLA SMA SZA SNL OSR FAILED 4256 7402 HLT VAC SHOULD EQUAL ZERO /GROUP 2 OPERATE TEST 76 /AC=0000 4257 7200 CLA SKP OSR /TEST COMBINATION 4260 7414 /SKP OSR DID NOT SKIP 4261 7402 HLT /AC SHOULD BE 7777 4262 7040 CMA

> /SKP OSR FAILED VAC SHOUND EQUAL ZERO

3-DEC-69

V141

/INSTRUCTION TEST = 1 PAL10

9107

PAGE 76

3-DEC-69

9107

PAGE 77

/INSTRUCTION TEST = 1 PALIZ V141

```
3-DEC-69
                                                         9107
                                                                 PAGE 78
/INSTRUCTION TEST - 1 PAL10
                               V141
                        /AND TEST 6
                                CLA CLL
          4352 7300
                                                         /AC=7776 LINK#Ø
          4353 1035
                                 TAD K7776
                                 AND K5252
                                                         /TEST INSTRUCTION
          4354
               6052
                                                 /AC=2526
                                 CIA
          4355 7041
                                                         /AC=0000 LINK=1
                                 TAD K5252
          4356 1052
                                SZL
          4357
               7430
                                 SZA
          4360
               7440
                                                 /AND FAILURE, AC SHOULD BE
          4361 7402
                                 HLT
                                                 /0000, LINK SHOULD BE ONE
                        /AND TEST 7
          4362 7300
                                CLA CLL
                                TAD K2525
                                                         /AC=2925 LINKED
          4363
               1053
                                 AND K2525
                                                         /TEST INSTRUCTION
          4364 0053
                                 CIA
                                                 /AC=5253
          4365 7041
                                                         /AC-0000 LINK = 1
          4366 1053
                                 TAD K2525
                                 SZL
               7430
          4367
          4370 7440
                                 SZA
                                                 /AND FAILED. AC SHOULD BE
                                 HLT
          4371 7402
                                                 /0000. LINK SHOULD BE ONE.
                                 NOP
                7000
          4372
          4373
                7000
                                 NOP
                                 NOP
          4374
                7000
          4375
                7000
                                 NOP
                7000
                                 NOP
          4376
                                 NOP
          4377
                7000
                4400
                        *4400
                        /CHECK FOR BELL
                7200
                                 CLA
          4400
                                 TAD BLONT
          4421
                1220
                                 IAC
          4402
                7001
                                 DCA BLONT
          4425
                3220
                                 TAD BLONT
          4404
                1220
                                 SZA CLA
          4405
                7640
                                 JMP START+3
                5147
          4426
                                TAD BLOOM
          4407
                1221
                                 DCA BLONT
          4410 3220
                        /RING BELL
                                 TAD BEL
          4411
                1217
                                 TLS
          4412
                6046
                                 TSF
          4413
                6041
                5213
                                 JMP .=1
          4414
                                 TCF
          4415
                6042
                                 JMP START+3
          4416
                5147
                                 3227
          4417
                2207
                         BEL.
                         BLCNT.
                                 +200
          4420
                7600
                         BLCON:
                                 -280
          4421 7000
```

## MAINDEC EVALUATION REQUEST

please indicate your assessment of the following areas and return this form to Digital Equipment Corporation.
IDENTIFICATION: MAINDEC NO Program Title
USAGE: Used by: Field Service Production Other
Frequency of Usage: Daily Weekly Monthly
SUGGESTIONS FOR IMPROVEMENT
<ol> <li>Are the program loading and operating instructions: clear?, incomplete?, difficult to follow?</li> </ol>
2. Do the error reports and program documentation provide sufficient diagnostic information: in all cases?, in most cases?, in very few cases? Suggestions for improvement:
3. Is the program effective in isolating malfunctions: in all cases? , in most cases? , in very few cases? . Would additional Scope loops or Switch Register control be helpful? Suggestions for improvement:
4. Does the program ever fail to detect malfunctions exposed by other software?  Were Margins used?  Please describe malfunction in detail:
5. Does the program ever report non-existant malfunctions?
6. Does this MAINDEC ever expose malfunctions in the Central Processor or other peripheral units not detected by the appropriate MAINDEC?  Please describe malfunction and MAINDEC(S) used:
7. Does the document provide a general understanding of the functional programming requirements of the system? Good, Fair, None, Would a general description of programming requirements increase the effectiveness of this MAINDEC?
Remarks:

	Fold Here	
	Do Not Tear - Fold Here and Staple	
		FIRST CLASS PERMIT NO. 33
		MAYNARD, MASS.
BUSINESS REPLY MAIL NO POSTAGE STAMP NECES	SARY IF MAILED IN THE UNITED STATES	
Postage will be paid by:	digital	
	Digital Equipment Corporation	
	Diagnostic Programming Group 146 Main Street, Building 12	
	Maynard, Massachusetts 01754	The second secon