# IDENTIFICATION

Product Code:

MAINDEC-8I-D02B-D

Product Name:

Instruction Test 2

Date Created:

March 21, 1968

Maintainer:

Diagnostic Group

Author:

H. Horowitz

#### 1. ABSTRACT

This program is an extensive test of autoindexing, indirect addressing, and the DCA instruction for the PDP-81. It also offers minimal testing for interrupt and the AND, TAD, ISZ, JMP and JMS instructions.

#### 2. REQUIREMENTS

### 2.1 Equipment

PDP-81, 8S equipped with Teletype

# 2.2 Storage

The program occupies memory locations 0000-4021. The Binary Loader must be stored in the last memory page.

# 2.3 Preliminary Programs

It is assumed that Maindec 8I-D01(n) has been run successfully.

#### 3. LOADING PROCEDURE

#### 3.1 Method

The standard Binary Loader is used.

### 4. STARTING PROCEDURE

# 4.1 Control Switch Settings (None)

#### 4.2 Starting Address

201

# 4.3 Operator Action

- a. Set the SWITCH REGISTER to 201. Press LOAD ADDRESS.
- b. PUSH START. A programmed halt occurs when an error is encountered.

# 5. OPERATING PROCEDURE

Same as Section 4.

#### 6. ERRORS

#### 6.1 Error Halts and Description

See listing.

# 6.2 Error Recovery

If it is desired to loop on the test causing the error, replace the operate instruction preceding the HLT with a JMP to the beginning of the test.

# 7. RESTRICTIONS

All peripheral devices must be functioning to a degree that the processor START button will clear their flags and no FLAGS will turn on unless authorized.

# 8. MISCELLANEOUS

#### 8.1 Execution Time

Five program loops per second.

#### 9. PROGRAM DESCRIPTION

The program is a series of many small individual tests. Each test is performed using previously checked functions to validate the test. When an error is encountered, the operator should insert a jump instruction into memory to cause the program to loop on the failing test. The problem can then be found by using the oscilloscope.

The individual program tests are grouped into the following classifications and are performed in the order shown:

- 1. DCA Test
- 2. Indirect Addressing Test
  - a. using TAD
  - b. using AND

- 3. Autoindex Test
  - a. using AND
  - b. using DCA
  - c. using TAD
- 4. Interrupt Test
  - a. following NOP
  - b. following TAD
  - c. following ANDd. following DCA
  - e. following ISZ
  - f. following JMP
  - g. following JMS
  - h. following CLA
  - i. following TSF
- 5. Check for unauthorized Autoindexing

At the completion of 40 program loops the bell rings to assure the operator that the program is functioning properly.

10. LISTING

# /INSTRUCTION TEST 2

	0000	₩ Ø				
0000	0000	-	Ø			/LOC Ø
0001	5001		JMP 1		/LOC 1	, FOO B
0002	0002					
_	-		2		/LOC 2	
0003	ØØØ3		3		/LOC 3	
	0007	<b>#7</b>				
0007	0000		Ø			
	0020	<b>*</b> 20				
0020	7777	K7777	77/7			
0021	3777	K3777				
0022	5777	K5777			•	
0022	6777		-			
		K6777				
0024	7377	K7377				
0025	7577	K7577	•			
0026	7677	K7677	, 7677			
0027	7737	K7737	7757			
0030	0000		Ø			
0031	7757	K7757				
0032	7767	K7767				
0033	7773	K7773	•			
0034	7775		•			
		K7775				
0035	7776	K7776				
0036	0000	K∂,	Ø			
0037	1777	K1777	-			
0040	Ø <b>7</b> 77	K0777				
0041	0377	KØ377,	03/7			
0042	0177	K0177	01/7			
0043	0077	K0077	00/7			袋
0044	0037	K0037				
0045	0017	KØ317		•		
0046	0007	K0007				
0047						
	0003	K0003.				
0050	0000		Ø			
0051	0001	K0001.				
0052	4400	K4400,	4400			
0053	4577	K4577	4547			
0054	2525	K2525	2525			•
0055	6666	K6666	6696			
2256	4444	K4444				
0057	7070	K7070				
2052	0707					
		K0707				
0061	5252	K5252				
0062	1111	K1111				
9963	5252	K5555		2.1		
2064	0004	K4,	4			

•	0110	*118		
Ø11@	8000		Ø	
	<b>Ø17</b> 2	*172		
0172	0176	K176,	176	/LOG 172
a173	a172	K172:	174	/173
g173 Ø174	g172 Ø173	K175.	173	/174
0175	Ø174	K174,	174	/175
0176	0175	K175,	179	/176
0177	1234	K1234,	1204	/177

			~ 4.0				
	0200		*500	_			
0200	0000		TPØ,	Ø			
			/DCA	TEST 1			
0201	7200			CLA			
0202	1052				K4400	4,	
0203	3377				TP177		
0204	7440			SZA			
0205	7402			HLT			/DCA DID NOT CLEAR AC
0206	1052			TAU	<b>44400</b>		
0207	7410			sŘ₽			
0210	0000			Ø			
0211	7041			Č I	TP177		/AC=-(4400)
	1377		*	TAU	+P177		
0212	-			SZA	1		
0213	7440			-			OCA FAILED
0214	7402			HLT	1, 70		AC SHOULD EQUAL ZERO
							THE SHOULD EWONE EERO
		•					
			/DCA	TEST 2			
0215	7200			CLA			
0216	1053				K4577		
0217	3200			.,	TPØ		
0220	7440			SZA			
0221	7402			HLT			/DCA DID NOT CLEAR AC
0222	1053			TAU	K4577		
Ø223	7041			ĊΙM			
0224	1200				TPØ		
	7440			S28			
0225				HL			/DCA FAILED
Ø226	7402			179 160			/AC SHOULD EQUAL ZERO
							THE SHOOLD LEGENCE LENG
			1054	7 F C T 3			
			JUCA	TEST 3			
				<b>~</b> 1 6	* .		
0227	7200			CLA			
0230	1020				K7777		
0231	3200				TPØ		
0232	7440			S 2 4			
0233	7402			HL			/DCA DID NOT CLEAR AC
0234	1200			TAN	TPØ		
0235	7040			CMA	l .		
0236	7440			SZA	ı		
0237	7402			HL!			/DCA FAILED
D C G /	, - W =						AC SHOULD BE ZERO
					- #**		,
			/nc4	TEST 4			
			,r w v n	الإستاد	•		
	****			A: 4	\		
0240	7200			CLA			
0241	1036				) KØ		
0242	3200				TPØ		DCA DID NOT CLEAR AC
0243	7440			<b>5</b> ₹			NACE ATA MAI AFFOR SO
0244	7402			HLI			
0245	1200	44		TAL	TPO		and the second of the second o

0246 7440 0247 7402

SZA HLT /DCA FAILED /AC SHOULD BE ZERO

	/DCA T	EST >	£1		
				·	
0250 7200		CLA	OF OF		
0251 1054			K2525		
0252 3200		DC: SZA	TPØ		
g253 7440 0254 7402		HLT		/DCA DID NOT CLEAR	AC
0254 7402 0255 1054			K2525	, 004 010 NOT OCCAN	~ •
0256 7041		CIA			
0257 1200		TAU	TPØ		
0260 7440		S 2 #			
0261 7402		HL !		DCA FAILED	
				/AC SHOULD BE ZERO	
	/DCA T	Fet b			
	/UCA I	C31 **			
Ø262 72ØØ		CLA			
Ø263 1Ø55			K6666		
0264 3200		DCA	TPØ		
0265 7440		SZA			
0266 7402		HLT		/DCA DID NOT CLEAR	AC
Ø267 1Ø55			K6666		
0270 7041		CIA			
Ø271 12ØØ		TAU	TPØ		
Ø272 7 <b>4</b> 4Ø		SZA		.064 544 55	
g273 74g2		HLT		JOCA FAILED	
				/AC SHOULD BE ZERO	
	/DCA T	EST 7			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-41			
0274 7200		CLA			
Ø275 1Ø56			K4444	1	
0276 3377			TP177		
Ø277 744Ø		SZA			
0300 7402		HL!		/DCA DID NOT CLEAR	AU
0301 1056			K4444		
0302 7041		CIA	-0.477	*	
0303 1377		TAU	TP177		
0304 7440		\$ <b>2</b> ^		ADCA FATLED	
0305 7402		HL!		/DCA FAILED	
				/AC SHOULD BE FERO	
	/DCA T	EST 8		eges.	
4.7	·				
0306 7200		CLA			
0307 1057			K7070		
Ø31Ø 3377			TP177		
0311 7440		SZA		ADCA DID NOT CLEAD	۸.
0312 7402		HL	K7070	/DCA DID NOT CLEAR	M U
0313 1057		TAU	K/W/W		
0314 7041		CI#	TP177		
0315 1377		UAT	i LT / /		
0316 7440	. *	S 2 8		/UCA FAILED	
0317 7402		HF1	1	ADOM SATEED	

AC SHOULD BE FERO

		/DCA TEST 9	
ø32ø	7200	CL#	
0321	1060	TAU KØ707	
Ø322	3000	DCA Ø	
ø323	7440	Sž.	
0324	7402	HL	/DCA DID NOT CLEAR AC
Ø325	1060	TAU KO707	ADDA DID MOT CEENE NO
0326	7041	CIA	
Ø327	1000	TA 0	
	7440	SEA	
0331	7402	NE +	ADDA BATIED
<b>D</b> 001	7702	ne i	ACC SHOW DE TERM
		/DCA TEST 10	/AC SHOULD BE ZERO
		ADCH 1521 10	
a332	7200	CLA	
0333	1061		
Ø334		TAD K5252	
	3000	DCA Ø	
0335	7440	\$ <b>2</b> 4	(DA)
Ø336	7402	HL!	/DCA DID NOT CLEAR AC
0337	1061	TAN K5252	
0340	7041	CIA	
Ø341	1000	TA₩ Ø	
0342	7440	SZA	
0343	7402	HL)	/DCA FAILED
			/AC SHOULD BE ZERO
		/DCA TEST 11	
		700A (ES) #2	
8344	7200	CLA	
0345	1062	TAN K1111	
0346	3000	DCA Ø	
0347	7440	SZA	
0350	7402	HLT	/DCA DID NOT CLEAR AC-
0351	1062	TAU K1111	
Ø352	7041	CIA was	
0353	1000	TAU Ø	
0354	7440	SZA	
0355	7402	HLT	/DCA FAILED
			/AC SHOULD BE ZERO
		/DCA TEST 12	
~754	7000		
Ø356	7200	CLA	· · · · · · · · · · · · · · · · · · ·
Ø357	1063	TAU K5555	and the second of the second o
0360	3000	DC# Ø	ALC: 1
0361	7440	\$2.8	
0362	7402	HLT	/DCA DID NOT CLEAR AC
0353	1063	TAP K5555	
g364	7041	C î •	
<b>0</b> 365	1000	TAD Ø	
0366	7440	\$26	
Ø367	7402	NL I	/DCA FAILED
			/AC SHOULD BE ZERO
			The second secon

0370	7000		NOF
0371	7000		NOF
0372	7000		NOP
0373	7000		NOP
0374	7000		NOM
Ø375	7000		NOP
0376	7410		SKF
0377	0000	TP177,	Ø

	0400	*430	
		/INDIRECT ADDRESSING T	EST 1
0400 0401 0402 0403 0404 0405	7200 1442 7041 1177 7440 7402	CLA TAU I K0177 CIA TAU K1234 SZA HL!	/OPERAND#1234 /TAD INDIRECT FAILED
040)	7402	1/1	AC SHOULD BE ZERO
		/INDIRECT ADDRESSING T	EST 2
0406 0407 0410 0411 0412 0413 0414 0415 0416	7200 7410 0000 1020 0442 7041 1177 7440 7402	CL# SKP D Tau K7777 ANU I K0177 CIA Tau K1234 S最作 HLT	/OPERAND=1234 /AND INDIRECT FAILED /AC SHOULD BE ZERO
		/INDIRECT ADDRESSING T	EST 3
0417 0420 0421 2422 0423 0424 0425 0426	7200 1020 3000 2436 7402 1000 7440 7402	CLA TAU K7777 DCA Ø ISM I KØ HLT TAD Ø SZA HLI	/ISE FAILED, NO SKIP /ISE INDIRECT FAILED /AC SHOULD BE Ø
		VINDIRECT ADDRESSING T	4
0427 0430 0431 0432 0433	7200 1572 7041 1176 7440	CLA TAU I K176 CIA Tau K175 SZA	/OPERAND=175
0434	7402	HLT	/TAD INDIRECT FAILED /AC SHOULD BE ZERO

# /INDIRECT ADDRESSING TEST 5

0435	7200	CLA	/OPERANO=175
0436	1020	TAU K7777	
0437	0572	ANU I K176	
0440	7041	CIA	
0441	1176	TAU K175	
Ø442	7440	SZA	/AND INDIRECT FAILED /AC SHOULD BE ZERO
Ø443	7402	HLI	
		/INDIRECT ADDRESSING	TEST 6
0444	7200	CL <sup>A</sup>	
0445	1172	TA- k176	
0446	3000	DC <sup>A</sup> Ø	
0447	2436	IS⊄ I kØ	
Ø450	7410	SKP	/ISE SKIPPED ILLEGALLY
Ø451	7402	HL	
Ø452	1000	TAD Ø	
Ø453	7041	CIA	
	1172 7040 7440 7402	TAU K176 CMA SZ# HLT	/DCA INDIRECT FAILED /AC SHOULD BE ZERO
		/INDIRECT ADDRESSING	TEST 7
Ø460	7200	CLA	OPERAND=176
Ø461	1573	TAD I K172	
Ø462	7041	CIA	
Ø463	1172	TAU K176	
Ø464	7440	SZ4	/TAD INDIRECT FAILED /AC SHOULD BE ZERO
Ø465	7402	HLI	
		/INDIRECT ADDRESSING	TEST 8
0466	7200	CL#	OPERAND#176
0467	1020	TAU K7777	
0470	0573	AND I K172	
0471	7041	CIA	
Ø472	1172	TAD K176	AND INDIRECT FAILED AC SHOULD BE ZERO
Ø473	7440	S≩A	
Ø474	7402	HLT	

#### /INDIRECT ADDRESSING TEST 9 CLA 0475 7200 TAU K172 0476 1173 DC Ø 0477 3000 ISZ I KU 0500 2436 SKP 0501 7410 HL1 /ISE SKIPPED ILLEGALLY 0502 7402 TAD 0 0503 1000 0504 7041 CIA TAD K172 0505 1173 0506 7040 CMA 0507 7440 524 /UCA INDIRECT FAILED HLT 0510 7402 /AC SHOULD BE ZERO /INDIRECT ADDRESSING TAST 10 CLA 0511 7200 TAU 1 K173 /OPERAND#172 0512 1574 0513 7041 CIA TAD K172 2514 1173 SZ# 0515 7440 /TAD INDIRECT FAILED HL ! 0516 7402 /AC SHOULD BE ZERO /INDIRECT ADDRESSING TEST 11 CLA 0517 7200 TAU K7777 0520 1020 /OPERAND=172 2521 0574 AND 1 K173 0522 7041 CIA TAU K172 Ø523 1173 /AND INDIRECT FAILED 0524 7440 SZA HL] /AC SHOULD BE ZERO 0525 7402 /INDIRECT ADDRESSING TEST 12 CLA 0526 7200 TAD K173 Ø527 1174 DCA Ø 0530 3000 ISE I KØ 0531 2436 SKP 0532 7410 /ISE SKIPPED ILLEGALLY HLT 0533 7402 TAD Ø 0534 1000 CIA 0535 7041 TAD K173 0536 1174 CMA 0537 7040 SZA 0540 7440 JUCA INDIRECT FAILED HLI 0541 7402 /AC SHOULD BE ZERO

# /INDIRECT ADDRESSING TEST 13

0542	7200	CLA	
0543	1575	TAU 1 K174	/OPERAND#173
0544	7041	CIA	
0545	1174	TAU K173	
0546	7440	SZA	
0547	7402	HLT	/TAD INDIRECT FAILED
			/AC SHOULD BE ZERO
		/INDIRECT ADDRESSING	TEST 14
0550	7200	CL A	
Ø551	1020	TAU K7777	
0552	Ø575	AND 1 K174	/OPERAND=173
0553	-	CIA	
Ø554	1174	TAU K173	
0555	7.440	ASS	/AND INDIRECT FAILED
Ø556	7402	HL!	/AC SHOULD BE ZERO
		/INDIRECT ADDRESSING.	TEST 15
0557	7200	CLA	
Ø56Ø	1175	TA: K174	
Ø561	3000	DCA Ø	
Ø562	2436	12# I KØ	
0563	7410	SKH	
Ø564	7402	HL¥	/ISE SKIPPED ILLEGALLY
Ø565	1000	TAH Ø	
0566	7041	CIA	
2567	1175	TAU K174	
0570	7040	ÇM	<u> </u>
0571	7440	SZA	
0572	7402	HL!	/DCA INDIRECT FAILED /AC SHOULD BE ZERO
0573	5377	JM# .+4	
0574	7000	NOH	:
0575	7000	NOH	
Ø576	7000	NO:	
0577	7000	NOP	

		0600		#600			
	* ***			VIVDI	RECT A	DORESSIN	G TEST 16
g	8600	7200			CLA		
Ĺ	3601	1576			TAD	I K175	/OPERAND=174
Q	602	7041			CIA		
	0603	1175		1.		K174	
_	604	7440			S₹ª		
é	605	7402			HF t		/TAD INDIRECT FAILED
			.**			e**	/AC SHOULD BE ZERO
				ZAUTO	INDEX	TEST 1	
. 0	606	7200			- CL#		
_	607	1036			TAU	KØ	/CONSTANT TO BE INDEXED
	610	3010			DCA	10	
2	611	0410				1 10	/DO AUTO INDEX
6	1612	1010				-	
	613	1035				K7776	/AC SHOULD EQUAL 7777
	1614	7040			CMA		AAG CUOUED DE ZEDO
-	615	7440 7402			SZA	•	AC SHOULD BE ZERO
	616	7486			HLT		AUTO INDEX ERROR
				/AUTO:	INDEX	TEST 2	en e
0	617	7200			CLA		
	620	1035			TAU	K7776	/CONSTANT TO BE INDEXED
Ø	621	3010			DCA	10	
	622	0410				1 10	/DO AUTO INDEX
	623	1010			TAU		
	624	1036	,		TAD	KB	/AC SHOULD EQUAL 7777
_	625	7040 7440			CMA SZ	-	/AC SHOULD BE BERD
	627	7402			HL I		AUTO INDEX ERROR
~	- E.				22		Augus tilent million
				/AUTO	INDEX	TEST 3	
_	630	7200			CLA		ARABATUR DE DE AUREUER
-	631	1034			-	K7775	CONSTANT TO BE INDEXED
_	632	3010			DCA	1 0 1 0	ZOO AHTO INDEV
_	633	3410 1010			TAP	• ***	/DO AUTO INDEX
	635	1051				K0001	/AC SHOULD EQUAL: 7777
	636	7040			CMA		Section 1
2	637	7440			SZ#		/AC SHOULD BE ZERO
2	640	7402			HLT		/AUTO INDEX ERROR
				4 4 1 1 7 6	14057	-E 0 T 4	
_		7204	A.	ZAUTO	CLA	TEST 4	F
	641 642	7200 1033				ĸ7773	/CONSTANT TO BE INDEXED
_	643	3010			DC:		A COMPLEMENT TO DE TIMEXEN
	644	1410		÷		I 10	/DO AUTO INDEX
_	645	7200		41.	CLA	•	
	646	1010			TAD	10	

 $\#_{i}^{j}(i)$ 

PAGE 11-1

0647 1047 0650 7040 0651 7440 0652 7402 TAU KODOS /AC SHOULD EQUAL 7777 CMA SZA /AC SHOULD BE ZERO /AUTO INDEX ERROR HLT

		/AUTO	INDEX	TEST 5	
0653	7200		CLA		CONSTANT TO BE INDEVED
0654	1032			K7767	CONSTANT TO BE INDEXED
2655	3010		DÇA	1 0 1 0	/DO AUTO INDEX
0656 0657	0410 1010		TA		
Ø650	1046			K0007	/AC SHOULD EQUAL 7777
0661	7040		CMA		
Ø662	7440		SŽA		/AC SHOULD BE ZERO /AUTO INDEX ERROR
0663	7402	15	HL 1		ANDIO INOUN EURON
		/AUTO	INDEX	TEST 6	
0664	7209		CL 4		
0665	1031			K7757	/CONSTANT TO BE INDEXED
<b>066</b> 6	3010		DCA	10	AND AUTO INDEX
Ø667	0410		LAA	1010	/DO AUTO INDEX
0670	1010		TAN		/AC SHOULD EQUAL 7777
Ø671 Ø672	1045 7040		CMA	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
0673	7440		SEA		AC SHOULD BE EERO
0674	7402		HL +		/AUTO INDEX ERROR
		/AUTO	INDEX	TEST 7	
Ø675	7200		CLA		
Ø676	1027			K7737	/CONSTANT TO BE INDEXED
0677	3010		DCA		
0700	0410		AND		/DO AUTO INDEX
0701	1010		TAU	10 K0037	/AC SHOULD EQUAL 7777
0702	1044		CMA	KBBS/	AMC SHOOFD EAGUE
0703 0704	7040 7440		SZ		/AC SHOULD BE ZERO
0705	7402		HL	28	AUTO INDEX ERROR
		/AUTO	INDEX	TEST 8	
	2000		CLA		
Ø7Ø6 Ø7Ø7	7200 1026			K7677	CONSTANT TO BE INDEXED
0710	3010		DCA		
Ø711	0410		ANH	1 10	/DO AUTO INDEX
0712	1010		TAU		AND CHAILS SALAL 3777
0713	1043		TAD		/AC SHOULD EQUAL 7777
0714	7040		CMA SZA		AC SHOULD BE ZERO
0715 0716	7440 7402		HLT		AUTO INDEX ERROR
N/TO	1786				

# /AUTO INDEX TEST 9

0717 0720	7200 1025	CLA Tab	K7577	CONSTANT TO BE INDEXED
0721	3010	DCA		
0722	0410	AND	1 10	/DO AUTO INDEX
Ø723	1010	4AT	10 K0177	/AC SHOULD EQUAL 7777
0724 0725	1042 7040	ĆMA	Kolii	
0726	7440	SZA		/AC SHOULD BE ZERO
Ø727	7402	HLI		/AUTO INDEX ERROR
		/AJTO INDEX	TEST 10	
0730	7200	CLA		
0731	1024		K7377	CONSTANT TO BE INDEXED
0732	3010	DCA		
0733	0410	AND	1 10	/DO AUTO INDEX
0734	1010	TAN	10 K0377	/AC SHOULD EQUAL 7777
Ø735 Ø736	1041 7040	CM&	N 0 7 7	AND SHOOLD ENGINE ////
Ø737	7440	ASS		/AC SHOULD BE ZERO
0740	7402	HLT		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 11	
0741	7200	CLA		
0742	1023		K6777	CONSTANT TO BE INDEXED
0743	3010	DCA		45 A
0744	0410		1 10	/DO AUTO INDEX
Ø745 Ø746	1010	TAD	10 KØ777	/AC SHOULD EQUAL 7777
0740	1040 7040	CMA	KD///	AND SHOOLD EGOAL !!!
0750	7440	SZA		/AC SHOULD BE ZERO
0751	7402	HL!		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 12	
0752	7200	CLA		
0753	1022		K5777	CONSTANT TO BE INDEXED
0754	3010		10	405 AURO 1N/25V
0755	2410		I 10	/DO AUTO INDEX
0756 0757	7000 1010	NOM TA-	10	
Ø757	1037		K1777	/AC SHOULD EQUAL 7777
Ø761	7040	CMA		
0762	7440	SŽA		AC SHOULD BE ZERO
0763	7402	HLT		/AUTO INDEX ERROR

# AUTO INDEX TEST 13

0764	7200	CLA	CONSTANT TO BE INDEXED
0765	1021	TAD K3777	
0766	3010	DCA 10	/DO AUTO INDEX
0767	0410	AND I 10	
0770	1010	TAD 10	
0771	1021	TAU K3777	/AC SHOULD EQUAL 7777
0772	7040	Cma	
Ø773 Ø774	7440 7402	SZA HL! NOM	/AC SHOULD BE ZERO /AUTO INDEX ERROR
0775 0776 0777	7000 7000 7000	NOF NOR	The state of the s

	1000	*1000		
		/AJTO INDEX	TEST 14	
1000	7200	CLA		CONSTANT TO BE INDEXED
1001	1020	T A U	K7777 10	ACDISTANT TO BE THREXED
1002	3010		1 10	/DD AUTO INDEX
1003 1004	0410 1010		10	
1005	1020		k7777	/AC SHOULD EQUAL 7777
1006	7040	CMA		
1007	7410	SKP		
1010	0000	Ø		7500
1011	7448	SZ		/AC SHOULD BE ZERO
1012	7402	HLT		/AUTO INDEX ERROR
		ZAUTO INDEX	TEST 15	
1013	7200	CL#	i	
1014	1036		KØ ·	CONSTANT TO BE INDEXED
1015	3011		11	
1016	0411	ANC		/DO AUTO INDEX
1017	1011	TA		
1020	1035		K7776	/AC SHOULD EQUAL 7777
	7040	CM <sup>6</sup>		AC CHOILD DE ACBO
1022	7440	SZ# HL1		/AC SHOULD BE ZERD /AUTO INDEX ERROR
1023	7402	M C '		NAGIO THEEN EUNOU
		/AUTO INDEX	TEST 16	
1024	7200	CLA		
1025	1035		K7776	CONSTANT TO BE INDEXED
1026	3011	DCA		4
1027	0411	ANG		DO AUTO INDEX
1030	1011		11	AAC SHALL SOLLAL 7777
1031	1036	TAC		AC SHOULD EQUAL 7777
1032	7040	CM*		/AC SHOULD BE ZERO
1033 1034	7440 7402	HL:		/AUTO INDEX ERROR
7624	1786			ELEMENT ALLEMENT MILITARIE

		OTLA\		TEST 17	
1035	7200		CLA		CONSTANT TO BE INDEXED
1036	1034		TA DCA	K7775	ACOM2 LAM TO BE THOUSAND
1037	3011			1 11	/DO AUTO INDEX
1040	3411		-	11	
1041	1011 1051			KOBU1	/AC SHOULD EQUAL 7777
1042	7040	+ \$ 11.7	CMA		
1044	7440	er.	528		/AC SHOULD BE ZERO
1245	7402		HLI		/AUTO INDEX ERROR
	,		*	#COT 48	
		/AUTO		TEST 18	
1046	7200		CLA	K7773	CONSTANT TO BE INDEXED
1047	1033		DCA		
1050	3011			1 11	/DO AUTO INDEX
1051	1411 7200		CLA		• •
1052 1053	1011		TAD	11	
1054	1047		TAD	K0003	/AC SHOULD EQUAL 7777
1055	7040		CMA		- <b>-</b>
1056	7440	•	SZA		/AC SHOULD BE ZERO
1057	7402		HL 1		AUTO INDEX ERROR
		/A.ITO	INDEX	TEST 19	
4040	7200	,,,,,	CLA	, -0	
1060 1061	1032			K7767	CONSTANT TO BE INDEXED
1062	3011		DC#	11	
1063	0411			I 11	/DO AUTO INDEX
1064	1011		TA		•
1065	1046			K0007	
1066	7040		CMA	i ka	AC CHOULD OF REDO
1067	7440		SZ		/AC SHOULD BE ZERO /AUTO INDEX ERROR
1070	7402		HĽ!		NEGIO TAREX ENVOY
		OTUA\		TEST 20	
1071	7200		CLA		ACCUSTANT TO BE INDEVED
1072	1031			K7757	CONSTANT TO BE INDEXED
1073	3011		DC#		/DO AUTO INDEX
1074	0411	8		I 11	AND WOLD THACK
1075	1011	*.*	TAD	11 K0017	/AC SHOULD EQUAL 7777
1076	1045		CMA		AC SHOOLD EGOAL !!!
1077	7040		SŽA		/AC SHOULD BE ZERO
1100	7440		HLT		AUTO INDEX ERROR
1101	7402		·		· ····································

		QTUA\	INDEX	TEST 21	
1102	7200	•	CLA		
1103	1827		TAD	K1737	/CONSTANT TO BE INDEXED
1104	3011		OC*	11	;
1105	0411			I 11	/DO AUTO INDEX
1106	1011		TAD		
1107	1044		TA	K0037	/AC SHOULD EQUAL 7777
-	7040		CMA	.,-24.	
1110			SZA		AC SHOULD BE ZERO
1111	7440		HL1		AUTO INDEX ERROR
1112	7402		ML.		AND IN THACK CHUON
		OTUAL	INDEA	TEST 22	i
1113	7200	••	CLA		
1114	1026		.,	k7677	/CONSTANT TO BE INDEXED
1115	3011		DCA		
	0411			I 11	/DO AUTO INDEX
1116			TA-		
1117	1011			KØØ77	/AC SHOULD EQUAL 7777
1120	1043		CMA	N BD 7 7	
1121	7040				/AC SHOULD BE ZERO
1122	7440		SZA		\AC 3000EQ DE 2ENV
1123	7402	**	HLT		/AUTO IDEX ERROR
		/AUTO	INDEX	TEST 23	
1124	7200		CLA		
1125	1025		TAU	K7577	/CONSTANT TO BE INDEXED
1126	3011		DÇA	11	
1127	0411			î 11	/DO AUTO INDEX
1130	1011		TAN		
	1042			K0177	/AC SHOULD EQUAL 7777
1131	_		CMA	W##	
1132	7040		SZA		/AC SHOULD BE ZERO
1133	7440		HLT		/AUTO INDEX ERROR
1134	7402		M.C.		PAUTO INDEX CHRON
		/AUTO	INDEX	TEST 24	
1135	7200		CLA	5°	
1136	1024			K7377	/CONSTANT TO BE INDEXED
1137	3211		DCA		
1140	0411			ī 11	/DO AUTO INDEX
	1011		TAU		
1141			TAI	KØ377	/AC SHOULD EQUAL 7777
1142	1041		CMA	N D G F F	ारान् प्राप्यक्षत्र स्वयंत्राच ('''
1143	7040	e de la companya del companya de la companya del companya de la co			/AC SHOULD BE ZERO
1144 1145	7440 7402	e e e e e e e e e e e e e e e e e e e	HLT		AUTO INDEX ERROR
			- I		ZRUTU INUEN ERKUR

		/AUTO INDEX	TEST 25	
1146	7200	CL#		
1147	1023	TAP	K6777	/CONSTANT TO BE INDEXED
1150	3011	DC#	11	
1151	0411	AND.	I 11	/DO AUTO INDEX
1152	1011	TAU	11	
1153	1040	TAU	K0777	/AC SHOULD EQUAL 7777
1154	7040	CM ⊱	•	
1155	7440	SZA		/AC SHOULD BE ZERO
1156	7402	HLI		/AUTO INDEX ERROR
1130	7402			,
		ZAUTO INDEX	TEST 26	
1157	7200	CLA		
1160	1022	TAD	K5777	/CONSTANT TO BE INDEXED
1161	3011	DÇA	11	
1162	2411	1\$2	i 11	/DO AUTO INDEX
1163	7000	NOP	•	
1164	1011	TA-	11	
1165	1037		K1777	/AC SHOULD EQUAL 7777
1166	7040	CMA		
1167	7440	S2#		/AC SHOULD BE ZERO
1170	7402	÷ HL+		AANTA BURKU KARAR
	7000	NOP		AUTO INDEX ERROR
1171	5376	UMP	, + 4	
1172		NOP	1 . 4	
1173	7000	NOP		
1174	7000			
1175	7000	NOP		
1176	7000	NOP		
1177	7000	NOP		

PAJSE

114 - 1

d .

```
/TEST 2 - TAPE 2
                         *1200
      1200
                         /AUTO INDEX TEST 27
                                 CL
1200
     7200
                                                         /CONSTANT TO BE INDEXED
                                 TA- K3777
1201
     1021
                                 DCA 11
     3011
1202
                                                         /DO AUTO INDEX
                                 AND I 11
1203
     0411
                                 TAP 11
1204
     1011
                                                         /AC SHOULD EQUAL 7777
                                 TAD K3777
1205 1021
                                 CMA
1206
     7040
                                                 /AC SHOULD BE ZERO
                                 SZA
     7440
1207
                                                 /AUTO INDEX ERROR
                                 HLT
1210 7402
                         /AUTO INDEX TEST 28
                                 CLA
1211
     7200
                                                         /CONSTANT TO BE INDEXED
                                 TAU K7777
     1020
1212
                                 DC# 11
1213
     3011
                                                         /DO AUTO INDEX
                                 AND I 11
     0411
1214
                                 TAP 11
     1011
1215
                                 TAD K7777
                                                         /AC SHOULD EQUAL 7777
     1020
1216
                                 CM*
     7040
1217
                                 SZA
                                                 /AC SHOULD BE ZERO
1220
     7440
                                                 /AUTO INDEX ERROR
                                 HLT
     7402
1221
                         /AUTO INDEX TEST 29
                                 CLA
1222 7200
                                                 /CONSTANT TO BE INDEXED
                                 TAU KO
1223 1036
                                 DCA 12
     3012
1224
                                                         /DO AUTO INDEX
                                 AND 1 12
1225 Ø412
                                 TAD 12
1226 1012
                                                         /AC SHOULD EQUAL 7777
                                 TAU K7776
1227 1035
                                 CMA
1230
     7040
                                                 /AC SHOULD BE ZERO
                                 SZA
     7440
1231
                                                 JAUTO INDEX ERROR
                                 HLT
1232 7402
                         /AUTO INDEX TEST 30
                                 CLA
1233 7200
                                                         /CONSTANT TO BE INDEXED
                                 TAU K7776
1234 1035
                                 DCA 12
1235 3012
                                 ANN I 12
                                                         /DO AUTO INDEX
1236 0412
                                 TAD 12
1237 1012
                                                 /AC SHOULD EQUAL 7777
                                 TAU KU
1240 1036
                                 CMA
1241
     7040
                                                  /AC SHOULD BE ZERO
                                 SZA
1242 7440
                                                  /AUTO INDEX ERROR
                                 HLT
1243 7402
```

		/AUTO INDE		
1244	7200	CL	A	
1245	1034		D K7775	/donstant to be indexed
1246	3012	Da	A 12	
1247	3412	DC	A [ 12	/OO AUTO INDEX
1250	1012	TA	U 12	
1251	1051	TA	K0001	/AC SHOULD EQUAL 7777
1252	7040	CM	#	
1253	7440	SŽ	A	/AC SHOULD BE ZERO
1254	7402	ĤĹ	Т	AUTO INDEX ERROR
		/AUTO INDE	X TEST 32	
1255	7200	CL		
1256	1033	TA	₽ K7773	/donstant to be indexed
1257	3012	D.C.	A 12	
1260	1412		ŭ i 12	/do auto index
1261	7200	ĊĻ	8	
1262	1012		₩ 12	
1263	1047		W K0003	/AC SHOULD EQUAL 7777
1264	7040	CM	A	
1265	7440	SZ		/AC SHOULD BE ZERO
1266	7402	HL		AUTO INDEX ERROR
		/AUTO INDE	X TEST 33	
1267	7200	CL		
1270	1032		W K7767	/CONSTANT TO BE INDEXED
1271	3012		A 12	
1272	0412	AN		/do AUTo INDEX
1273	1012	TÀ	D 12	
1274	1046	TA		/AC SHOULD EQUAL 7777
1275	7040	CM		
1276	7440	SZ		/AC SHOULD BE ZERO
1277	7402	ЙL		AUTO INDEX ERROR
441	,			

		ZAUTO	INDEX	TEST 34	
1300	7200		CLA		
1301	1331		TAD	K7757	/CONSTANT TO BE INDEXED
1302	3012		DCA		· · · · · · · · · · · · · · · · · · ·
1303	0412			I 12	/DO AUTO INDEX
1304	1012		TAU		AND MAIN THORN
1305	1045			K0017	/AC SHOULD EQUAL 7777
	7040		CMA	VDDT	AC SUDOLD FROME 1111
1306			074		AAC CHANID DE ZEDO
1307	7440		SZA		AC SHOULD BE ZERO
1310	7402		HLT		
		44.410	INDEX	TEST 35	
	3000	74010		1531 37	
1311	7200		CL"		ARRAGETANT TO DE INDEVER
1312	1027			K7737	/CONSTANT TO BE INDEXED
1313	3012		DCA	-	A. A
1314	0412			1 12	/DO AUTO INDEX
1315	1012		TAB		
1316	1044		TAD	K0037	/AC SHOULD EQUAL 7777
1317	7040		CMA		
1320	7440		SZA		/AC SHOULD BE ZERO
1321	7402		HLI		/AUTO INDEX ERROR
			-		
		/AUTO	INDEX	TEST 36	
1322	7200	, , , , ,	CLA		
1323	1026			K7677	/CONSTANT TO BE INDEXED
1324	3012		DC#		
1325	0412			I 12	/DO AUTO INDEX
			TAU		AND MAIN THACK
1326	1012			KØØ77	/AC SHOULD EQUAL 7777
1327	1043			KUU//	AC SHOOLD EGOAL ////
1330	7040		CM		ALC BUALL D. OF TEDO
1331	7440		SZA		AC SHOULD BE ZERO
1332	7402		HL /		/AUTO INDEX ERROR
		4411		*Cor 37	
		ZAUTU		TEST 37	· ·
1333	7200		CLA		ACCUSTANT TO DE ANDENER
1334	1025			K7577	CONSTANT TO BE INDEXED
1335	3012		DCA	-	
1336	0412			1 12	/DO AUTO INDEX
1337	1012		TAN		
1340	1042		TAN	KØ177	AC SHOULD EQUAL 7777
1341	7040		CMA	<del></del>	
1342	7440		SZ#		/AC SHOULD BE ZERO
1343	7402				/AUTO INDEX ERROR
1040	1702		— <del>—</del> •		ELIBER BERMEN MISTERNIA

		/AUTO INDEX	TEST 38	
1344	7200	CLA		
1345	1024		K7377	CONSTANT TO BE INDEXED
1346	3012	DC#	12	
1347	0412		î 12	/DO AUTO INDEX
1350	1012		12	
1351	1041		K0377	/ACISHOULD EQUAL 7777
1352	7040	CMA		
1353	7440	SZA		/AC SHOULD BE ZERO
1354	7402	HL.		/AUTO INUEx ERROR
1024	7402			7.00 1.00 Z
		ZAUTO INDEX	TEST 39	
1355	7200	CLA		
1356	1023		K6777	CONSTANT TO BE INDEXED
1357	3012		12	
1360	0412		1 12	/DO AUTO INDEX
1361	1012	TA	i2 -	
1362	1040		KØ777	/AC SHOULD EQUAL 7777
1363	7040	CMA		
1364	7440	SZA		/AC SHOULD BE ZERO
1365	7402	HLT		AUTO INDEX ERROR
1003	, .02			1
		/AUTO INDEX	TEST 40	
1366	7200	CL		
1367	1022	TAD	K5777	CONSTANT TO BE INDEXED
1370	3012	DCA	12	
1371	2412	1 s ž	ī 12	/DO AUTO INDEX
1372	7000	NÖP	• -	
1373	1012		12	
1374	1037	TAD	K1777	/AC SHOULD EQUAL 7777
1375	7040	CMA		
1376	7440	SZA		/AC SHOULD BE ZERO
1377	7402	HL1		/AUTO INDEX ERROR
	·			

```
1400
                         *1400
                         /AUTO INDEX TEST 41
                                 CL"
1400 7200
                                                         /CONSTANT TO BE INDEXED
                                 TAD K3777
     1021
1401
                                 DC# 12
1402 3012
                                 AND 1 12
                                                         /DO AUTO INDEX
1403
     0412
                                 TAU 12
1404 1012
                                                         /AC SHOULD EQUAL 7777
                                 TAD K3777
    1021
1405
                                 CMA
1406
     7040
                                                 /AC SHOULD BE ZERO
                                 SZA
1407 7440
                                                 /AUTO INDEX ERROR
                                 HLT
1410 7402
                         VAUTO INDEX TEST 42
                                 CLA
1411 7200
                                                         /CONSTANT TO BE INDEXED
                                 TAN K7777
1412 1020
                                 DCA 12
1413 3012
                                 ANU I 12
                                                         /DO AUTO INDEX
1414 0412
                                 TAD 12
1415 1012
                                                         /AC SHOULD EQUAL 7777
                                 TAW K7777
1416 1020
                                 CM#
     7040
1417
                                 SZA
                                                 /AC SHOULD BE ZERO
1420 7440
                                                 /AUTO INDEX ERROR
1421 7402
                                 HL T
                         /AUTO INDEX TEST 43
                                 CLA
1422 7200
                                 TAD KO
                                                 /CONSTANT TO BE INDEXED
1423 1036
                                 DCA 13
1424 3013
                                 ANU I 13
                                                         /DO AUTO INDEX
1425 0413
                                 TAP 13
1426 1013
                                                         /AC SHOULD EQUAL 7777
                                 TAP K7776
1427 1035
                                 CMA
1430 7040
                                                 /AC SHOULD BE ZERO
                                 S 2 *
1431 7440
1432 7402
                                                 /AUTO INDEX ERROR
                                 HL !
                         /AUTO INDEA TEST 44
                                 CLA
1433 7200
                                                        /CONSTANT TO BE INDEXED
                                 TAR K7776
1434 1035
                                 DCA 13
1435 3013
                                 ANN I 13
                                                         /DO AUTO INDEX
1436 0413
                                 TAU 13
1437 1013
                                                 /AC SHOULD EQUAL 7777
                                 TAD KØ
1440 1036
1441 7040
                                 CMA
                                                 /AC SHOULD BE ZERO
                                 SZA
1442 7440
                                                 /AUTO INDEX ERROR
1443 7402
                         /AUTO INDEX TEST 45
                                 CLA
1444 7200
                                                         /CONSTANT TO BE INDEXED
                                 TAU K7775
1445 1934
                                 DCA 13
1446 3013
                                                         /DO AUTO INDEX
                                 DCA I 13
1447 3413
                                 TAU 13
1450 1013
                                                         /AC SHOULD EQUAL 7777
                                 TAU K0001
1451 1051
                                 CMA
1452 7040
                                                 JAC SHOULD BE ZERO
                                 254
1453 7440
```

1454 7402

HLT

AUTO INDEX ERROR

		/AUTO INDEX TEST 46	
1455	7200	CL#	
1456	1033	TAU K7773	CONSTANT TO BE INDEXED
1457	3013	DC# 13	
1460	1413	TAD I 13	/DO AUTO INDEX
1461	7200	CLA	
1462	1013	TAH 13	440 00000 D COUAL 3339
1463	1047	TAD K0003	/AC SHOULD EQUAL 7777
1464	7040	CMA	446 0000 D DE 75D0
1465	7440		/AC SHOULD BE ZERO
1466	7402	HL.I	/AUTO INDEX ERROR
		/AUTO INDEA TEST 47	
1467	7200	CLA _	
1470	1032	TAL K7767	/CONSTANT TO BE INDEXED
1471	3013	DCA 13	AND AUTO INDEM
1472	0413	ANH I 13	/DO AUTO INDEX
1473	1013	TAD 13	44.0 00000 D COULT 7777
1474	1046	TAD KØØØ7	/AC SHOULD EQUAL 7777
1475	7040	CMA	AR CHARLE OF TERS
1476	7440		/AC SHOULD BE ZERO /AUTO INDEX ERROR
1477	7402	HL 1	AMIN INDEX ERROR
		AUTO INDEX TEST 48	
1500	7200	CLA	ASSESSED TO DE LUBENCE
1501	1031	TAU K7757	CONSTANT TO BE INDEXED
1502	3013	DCA 13	AND AUTO INDEV
1503	0413	AND I 13	/DO AUTO INDEX
1504	1013	TA: 13	ALC CHAIRS CARL 7777
1505	1045	TAD K0017	/AC SHOULD EQUAL 7777
1506	7040	CMA	AC SHOULD BE ZERO
1507	7440	<del>-</del>	/AUTO INDEX ERROR
1510	7402	HL!	YAUTU INUEX ERRUR
		/AUTO INDEX TEST 49	
1511			
	7200	CLA	ARRIVE TO SE INDEVED
1512	1027	CLA TAD K7737	CONSTANT TO BE INDEXED
1513	1027 3013	CLA TAD K7737 DCA 13	
1513 1514	1027 3013 0413	CLA TAD K7737 DCA 13 ANW I 13	CONSTANT TO BE INDEXED  OO AUTO INDEX
1513 1514 1515	1027 3013 0413 1013	CLA TAD K7737 DCA 13 ANW I 13	VOO AUTO INDEX
1513 1514 1515 1516	1027 3013 0413 1013 1044	CLA TAD K7737 DCA 13 ANW I 13 TAW 13 TAU K0037	
1513 1514 1515 1516 1517	1027 3013 0413 1013 1044 7040	CLA TAD K7737 DCA 13 ANW I 13 TAW 13 TAW K0037 CMA	/OO AUTO INDEX /AC SHOULD EQUAL 7777
1513 1514 1515 1516	1027 3013 0413 1013 1044	CLA TAD K7737 DCA 13 ANW I 13 TAW 13 TAU K0037	VOO AUTO INDEX

		/AUTO INDEX	TEST 50	
1522	7200	CLA	1	
1523	1026		K7677	/CONSTANT TO BE INDEXED
1524	3013	DC	13	
1525	0413		1 13	/DD AUTO INDEX
1526	1013		1 13	
1527	1043	· ·	) K0077	/AC SHOULD EQUAL 7777
1,530	7040	CM		
1531	7440	SZA	1	/AC SHOULD BE ZERO
1532	7402	HL		AUTO INDEX ERROR
		VAUTO INDEX	TEST 51	
1533	7200		CLA	
1534	1025	TAD	K7577	/CONSTANT TO BE INDEXED
1535	3013	DC4	13	
1536	0413	AN	1 13	/DO AUTO INDEX
1537	1013	TA	13	
1540	1042	TAN	K0177	/AC SHOULD EQUAL 7777
1541	7040	Cm <sup>4</sup>		
1542	7440	S₹A		/AC SHOULD BE ZERO
1543	7402	HLI		/AUTO INDEX ERROR
		A ITO INDES	/ =5aT 59	
1544	7200	/AJTO INDEX CLA		
1545	1024		K7377	/CONSTANT TO BE INDEXED
1546	3013	DC4		ACDIASTANT TO DE TADEXES
1547	0413	AN	1 13	/DD AUTO INDEX
1550	1013	The state of the s	13	AND WOLD THOSE
1551	1041		Ř0377	/AC SHOULD EQUAL 7777
1552	7040	CMA		
1553	7440	SE		/AC SHOULD BE ZERO
1554	7402	HLT		AUTO INDEX ERROR
		ALITA THEY		
4000	7200	/AUTO INDEX CLA		
1555 1556	7200 1023		) K6777	CONSTANT TO BE INDEXED
1557	3013		13	ACDUSTAMI IN OF THREVER
1560	0413		1 13	/DD AUTO INDEX
1561	1013		13	AND MOLO THANK
1562	1040		K0777	/AC SHOULD EQUAL 7777
1563	7040	CMA		रताल काशक्षक्षका व्यवकारका हिर्देश
1564	7440	SZA		/AC SHOULD BE ZERO
1565	7402	·		AUTO INDEX ERROR

		/AUTO INDEX	TEST 54	•
1566	7200	CLA	. = 3.7	CONSTANT TO BE INDEXED
1567	1022	·	K5777	ACOMPIANT TO BE TABERED
1570	3013	DCA	13 [ 13	/DO AUTO INDEX
1571	2413	NOF	1 10	y go no to the control of the contro
1572 1573	7000 1013	TAU	13	
1574	1037	•	K1777	/AC SHOULD EQUAL 7777
1575	7040	CM#		
1576	7440	SZ₩		/AC SHOULD BE ZERO /AUTO INDEX ERROR
1577	7402	HLI		NACIO TANEN EKUAN

. . . . .

.

.

	1600	*1600 /AJTO IND	FX	TEST 55	
1500	7200		LA	1431	
1601	1021			K 3777	CONSTANT TO BE INDEXED
1501	3013	•		15	
1603	Ø413			I 13	/DO AUTO INDEX
1503	1013			15	
1605	1021			K 3777	/AC SHOULD EQUAL 7777
1606	7040		MA	.,	
1607	7440		ZA		/AC SHOULD BE ZERO
1610	7402		L1		/AUTO INDEX ERROR
1010	, , , , ,	•			
		/AUTO IND	EX	TEST 56	
1611	7200		LA		
1612	1020			K7777	CONSTANT TO BE INDEXED
1613	3013			15	
1614	0413		NU	Ī 13	/DO AUTO INDEX
1615	1013			13	
1616	1020			K7777	/AC SHOULD EQUAL 7777
1617	7040	Ċ	MA		
1620	7440		ZA		/AC SHOULD BE ZERO
1621	7402	-	ILT		AUTO INDEX ERROR
*	,		_		•
		/AUTO IND	EX.	TEST 57	
1622	7200		LA		
1623	1036		AN	KØ	CONSTANT TO BE INDEXED
1624	3014	D	CA	14	
1625	0414			I 14	/DO AUTO INDEX
1626	1014		A	14	
1627	1035			K7776	/AG SHOULD EQUAL 7777
1630	7040	C	:M ~		
1631	7440		ZΑ		/AC SHOULD BE ZERO
1632	7402	H	ILT		/AUTO INDEX ERROR

	/AUTO INDEX	TEST 58	
1633 7200	CLA	,	
1634 1035		K7776	/CONSTANT TO BE INDEXED
1635 3014	DCA	14	
1636 0414	ANU	ī 14	/DO AUTO INDEX
1637 1014	TAU	14	
1640 1036	TAD		/AC SHOULD EQUAL 7777
1641 7040	CM		
1642 7440	SZA		/AC SHOULD BE ZERO
1643 7402	HLT		/AUTO INDEX ERROR
10,0			*
	/AUTO INDEX	TEST 59	
1644 7200	CLA		
1645 1034	TAU	K7775	CONSTANT TO BE INDEXED
1646 3014	DCA	14	
1647 3414	DC*	I 14	/DO AUTO INDEX
1650 1014		14	
1651 1051	TAP	K0001	/AC SHOULD EQUAL 7777
1652 7040	CMA		_
1653 7440	SZA		AC SHOULD BE ZERO
1654 7402	HLT		AUTO INDEX ERROR
_			-
	/AUTO INDEX	TEST 60	
1655 7200	CL*		TOTAL TOTAL TOTAL THE STATE OF
1656 1033		K7773	CONSTANT TO BE INDEXED
1657 3014	DC#		AND THE THOUSEN
1660 1414		I 14	/DO AUTO INDEX
1661 7200	CLA		
1662 1014	TAU		ALE BURN D. PAUL 9777
1663 1047	•	K0003	/AC SHOULD EQUAL: 7777
1664 7040	CM#		
1665 7440	SZĄ		/AC SHOULD BE HERO
1666 7402	HL!		/AUTO INDEX ERROR
	**		
	/AUTO INDEX	TEST 61	
1667 7200 🚋	CLA		CONSTANT TO BE INDEXED
1670 1032		K7767	VEDM2 INMI IO BE THREYED
1671 3014	DC#		ADD AUTO THOPM
1672 0414	N ₽		/DO AUTO INDEX
1673 1014	TAU		ALC CHOULD COURT 7777
1674 1046		K0007	/AC SHOULD EQUAL 7777
1675 7040	CMA		ALE GUALUE DE TERO
1676 7440	AES		/AC SHOULD BE ZERO
1677 7402	HLT		AUTO INDEX ERROR

		<b>01UA</b> \	INDEX	TEST 62	
1700	7200		CLA		
1701	1031			K7757	/CONSTANT TO BE INDEXED
1702	3014		DCA		
1703	0414			ī 14	/DO AUTO INDEX
1704	1014			i4	
1705	1045			KØØ17	/AC SHOULD EQUAL 7777
1706	7040		CM*		
1707	7440		ASS		/AC SHOULD BE ZERO
1710	7402		HL		ZAUTO INDEX ERROR
1/10	1406		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
		OTUAL	INDEA	TEST 63	
1711	7200	, , , , , ,	CLA	, , , , , , , , , , , , , , , , , , , ,	
1712	1027		TAL	K7737	/CONSTANT TO BE INDEXED
1713	3014		DC		
1714	0414			1 14	/DO AUTO INDEX
1715	1014		TAD		PUD NOTO ANABA
1716	1044			K0037	/AC SHOULD EQUAL 7777
1717	7040		CMA	WARA.	· NO DUDGES ESSAUE:
	7440		SZA		/AC SHOULD BE ZERO
1720	7402		HLI		/AUTO INDEX ERROR
1721	1402		HP.		NATIO TAREN ENVOY
		/AUTO	INDEX	TEST 64	
1722	7200	, , , ,	CLA	145, 0.	
1723	1026			K7677	CONSTANT TO BE INDEXED
1724	3014		DÇĀ		DOMOTEMATE TABLETO
1725	0414			Ī 14	ZDO AUTO INDEX
1726	1014		TA		A DO MOIO TUREY
1727	1043			K0077	/AC SHOULD EQUAL 7777
1730	7040		CMA	NEU//	AND SUBOLD FROME 1/1/
	7440		SZA		/AC SHOULD BE ZERO
1731 1732	7402		HLI		AUTO INDEX ERROR
1/32	7402		m L		NAUTO THOEN PHRUK
		ALITO	INDEX	TEST 65	
1733	7200	7,4010	CLA	, 23, 02	
1734	1025			K7577	CONSTANT TO BE INDEXED
1735	3014		DC a		SACIABLEM IN BE THOUSED
1736	0414			1 14	DO AUTO INDEX
1737	1014		TAP		ADD MOID THORN
1740	1042			KØ177	/AC SHOULD EQUAL 7777
1745	7040		CMA	V.T.	AND SUDDED ERONE 1///
1742	7440		SZA		/AC SHOULD BE ZERO
1742	7402		HLT		AUTO INDEX ERROR

		/AUTO INDEX	TEST 66	
1744	7200	CLA		
1745	1024		K7377	CONSTANT TO BE INDEXED
1746	3014	DCA		Con AUT & BEV
1747	0414	ANU	1 14	/DO AUTO INDEX
1750	1014	I. TAP		/AC SHOULD EQUAL 7777
1751	1041		KØ377	THE SHOULD EGONE 7777
1752	7040	CMA		/AC SHOULD BE ZERO
1753	7440	SZA HLI		/AUTO INDEX ERROR
1754	7402	HL!		AND THE CHARACTER
		/AUTO INDEX	TEST 67	
1755	7200	CLA		
1756	1023		K6777	CONSTANT TO BE INDEXED
1757	3014	DCA	_	
1760	0414		1 14	/DO AUTO INDEX
1761	1014	TAU		ALC CHOILD COURT 7777
1762	1040		KØ777	/AC SHOULD EQUAL 7777
1763	7040	ĞM.		AC CHAIRD OF ZEDO
1764	7440	SZA		/AC SHOULD BE ZERO /AUTO INDEX ERROR
1765	7402	HLT		ANDIO THOEX ENDOR
			X TEST 68	
1766	7200	Cr.⊕		ACCRETANT TO DE INDEVED
1767	1022		K5777	CONSTANT TO BE INDEXED
1770	3014	DCA		/DO AUTO INDEX
1771	2414	•	I 14	AND MOIN THREY
1772	7000	NO	4.4	
1773	1014	ŢĄŊ		/AG SHOULD EQUAL 7777
1774	1037		K1777	AN SHOULD EMARE ''''
1775	7040	CMA		/AC SHOULD BE ZERO
1776	7440	SZA HLT		/AUTO INDEX ERROR
1777	7402	HL!		AMAIA THEM

	2000	*2700			i .
		OTUA	INDEX	TEST 69	
2000	7200		CLA		
2001	1021			K3777	/CONSTANT TO BE INDEXED
2002	3014		DCA		
2003	0414			I 14	/O AUTO INDEX
2004	1014		TAD		
2005	1021			K3777	/AC SHOULD EQUAL 7777
2006	7040		CMA		
2007	7410		SK.		
2010 2011	0000 7440		Ø Sæa		446 EURULA DE 7680
2011	7402		HL		/AC SHOULD BE ZERO
25.77	7462		75		/AUTO INDEX ERROR
		/A:ITO	INDEA	TEST 70	
2013	7200	,	CL#	, 55, 75	
2014	1020			K7777	CONSTANT TO BE INDEXED
2015	3014		DÇ∻	14	
2016	0414			I 14	/dO AUTO INDEX
2017	1014		TAU		
2020	1020		TAD	K7777	/AC SHOULD EQUAL 7777
2021	7040		CMA		
2022	7440		SZA		/AC SHOULD BE ZERO
2023	7402		HLT		/AUTO INDEX ERROR
			•		
2024	3000	/AUTO		TEST 71	
2024 2025	7200		CLA	14.0	400MC=4W==0 05 4WBC+50
2025	1036 3015		TAN		CONSTANT TO BE INDEXED
2027	0415			I 15	ADD ANT TO DEV
2030	1015		TAU		100 AUTO INDEX
2031	1035		TA	-	/AC SHOULD EQUAL 7777
2032	7040		CMA	A,,,,o	AND SHOULD EGONE 1///
2033	7440		SZ		/AC SHOULD BE ZERO
2034	7402		HLT.		/AUTO INDEX ERROR
	-			1	
		/AUTO	INDEX	TEST 72	
2035	7200		CLA		
2036	1035			K7776	/CONSTANT TO BE INDEXED
2037	3015		DCA		
2040	0415			1 15	/DO AUTO INDEX
2041	1015		TAD		
2042 2043	1036 7040		TAD	KD	/AC SHOULD EQUAL 7777
2043	7440		CM4 SZA		446 60000 00 7500
2045	7402		HL!		/AC SHOULD BE ZERO
6477	7786				AUTO INDEX ERROR
		OTLA	INDEX	TEST 73	
2046	7200	, 4010	CLA		
2047	1034			K7775	CONSTANT TO BE INDEXED
2050	3015		DC	15	
2051	3415		DCA	1 15	DO AUTO INDEX
2052	1015		TA	15	·
2053	1051		TAU	K0001	/AC SHOULD EQUAL 7777
		A Company of the Comp			

2054 7040 2055 7440 2056 7402 CMA SZ HLT /AC SHOULD BE ZERO /AUTO INDEX ERROR

		OTUAL	INDEX	TEST 74	
2057	7200		CLA		
2060	1033			K7773	/CONSTANT TO BE INDEXED
2061	3015		DC=		
	-			I 15	/DO AUTO INDEX
2062	1415		CLA	1 12	7 00 4010 1140EX
2063	7200		TAU	4.6	
2064	1015				/AC SHOULD EQUAL 7777
2065	1047			K0003	AC SHOULD EGUAL ////
2066	7040		CMA		44 C C C C C C C C C C C C C C C C C C
2067	7440		SZA		/AC SHOULD BE ZERO
2070	7402		HLI		AUTO INDEX ERROR
		(4.150	INDEV	TEST 75	
- 67.	7000	74010	TIANEY	(431 /-	
2071	7200		CL.		CONSTANT TO BE INDEXED
2072	1032			K7767	ACOMS INM TO BE THREYED
2073	3015		DCA		400 4050 10057
2074	0415		ANU	1_15	/DO AUTO INDEX
2075	1015		TA¥		
2076	1046			K0007	/AC SHOULD EQUAL 7777
2077	7040		CM "		
2100	7440		SIA		/AC SHOULD BE ZERO
2101	7402		HL+		/AUTO INDEX ERROR
		ZAUTO		TEST 76	
2102	7200		CLA		
2103	1031			Kフフラフ	CONSTANT TO BE INDEXED
2104	3015		DCA	15	
2105	0415		ANU	I 15	/DO AUTO INDEX
2106	1015		TAU	15	
2107	1045			K0017	/AC SHOULD EQUAL 7777
2110	7040		CM*		
2111	7440		528		/AC SHOULD BE ZERO
2112	7402		HLT		AUTO INDEX ERROR
2++5	, 402				
		OTUAL		TEST 77	
2113	7200		CLA		
2113 2114	1027		TAU	K7737	CONSTANT TO BE INDEXED
2115	3015		DCA	15	
2116	0415				/DO AUTO INDEX
2117	1015		TAB	15	
2120	1044		TAU	K0037	/AC SHOULD EQUAL 7777
2121	7040		CMA		र प्रिंग क्रोगिक क्षांच्या चाच क्रोजी है है है
			SZA		/AC SHOULD BE ZERO
2122	7440		HLT		AUTO INDEX ERROR
2123	7402	4	WP,		AND THOIR STRUCK

```
/AUTO INDEX TEST 78
                                CLA
2124 7200
                                                      /CONSTANT TO BE INDEXED
                                TAD K7677
2125 1026
                                DCA 15
2126 3015
                                                      /DO AUTO INDEX
                                ANW I 15
2127 0415
                                TAD 15
2130 1015
                                                      /AC SHOULD EQUAL 7777
                                TAD K0077
2131 1043
2132 7040
                                CMA
                                               /AC SHOULD BE ZERO
                                S₹
2133 7440
                                               /AUTO INDEX ERROR
2134 7402
                                HL I
                        /AUTO INDEX TEST 79
                                CLA
2135 7200
                                TAU K7577
                                                      /CONSTANT TO BE INDEXED
2136 1025
                                DCA 15
2137 3015
                                AND 1 15
                                                             /DO AUTO INDEX
2140 0415
2141 1015
                                TA 4 15
                                TAU KU177
                                                      /AC SHOULD EQUAL 7777
2142 1042
                                CMA
2143 7040
                                              /AC SHOULD BE ZERO
                                SZ#
2144 7440
                                HLT
                                               /AUTO INDEX ERROR
2145 7402
                        /AUTO INDEX TEST 80
                                CLA
2146 7200
                                                      /CONSTANT TO BE INDEXED
                                TAD K7377
2147 1024
                                DC4 15
2150 3015
                                                      /DO AUTO INDEX
                                AND I 15
2151 0415
                                TAU 15
2152 1015
                                                      /AC SHOULD EQUAL 7777
                                TAU K0377
2153 1041
2154 7040
                                CMA
                                               /AC SHOULD BE ZERO
                                SZA
2155 7440
                                               /AUTO INDEX ERROR
                                HLT
2156 7402
                        /AUTO INDEA TEST 81
                                CLA
2157 7200
                                                      /CONSTANT TO BE INDEXED
                                TAN K6777
2160 1023
                                DCA 15
2161 3015
                                                      /DO AUTO INDEX
2162 0415
                                AN- I 15
                                TAU 15
2163 1015
                                                      /AC SHOULD EQUAL 7777
                                TAU K0777
2164 1040
                                CMA
2165 7040
                                               /AC SHOULD BE ZERO
                                SZA
2166 7440
                                HLT
                                               /AUTO INDEX ERROR
2167 7402
                                NOP
2170 7000
                                                            1000
                                NOn
2171 7000
                                JMP
2172 5376
                                NOF
2173 7000
2174 7000
                                NOF
2175 7000
                                NOF
2176 7000
                                NOP
2177 7000
                                NOF
```

## 1/22/68 15:43,51 PAGE 35

	2200	*5500		
		/AUTO INDE		
2200	7200	CLA		
2201	1022		k5777	/CONSTANT TO BE INDEXED
2202	3015	004		the second secon
2203	2415	181	: 1 15	/DO AUTO INDEX
2204	7000	NOP	•	
2205	1015	TAT	15	
2206	1037	TAL	K1777	/AC SHOULD EQUAL 7777
2207	7040	CM <sup>2</sup>	<b>l</b>	
2210	7440	SZ*	4	/AC SHOULD BE ZERO
2211	7402	HL		/AUTO INDEX ERROR
		/AUTO INDE	TEST 83	
2212	7200	CLA		
2213	1021	TÃ	) K3777	/CONSTANT TO HE INDEXED
2214	3015	DC4	15	
2215	0415	AN	· I 15	/DO AUTO INDEX
2216	1015	TÂL		
2217	1021	TAL	√ K3777	/AC SHOULD EQUAL 7777
2220	7040	CM		
2221	7440	SZ		/AC SHOULD BE ZERO
2222	7402	HL	l	/AUTO INDEX ERROR
	4	ZAUTO INDE	TEST 84	
2223	7200	CL.		
2224	1020	TA	# K7777	/CONSTANT TO BE INDEXED
2225	3015	DÇ-	4 15	
2226	0415	ANI		/DO AUTO INDEX
2227	1015		J 15	
2230	1020	TAI	X7777	/AC SHOULD EQUAL 7777
2231	7040	CM4		
2232	7440	SZ	A	/AC SHOULD BE ZERO
2233	7402	HL	į.	/AUTO INDEX ERROR
		AUTO INDE	TEST 85	
2234	7200	CL.		
2235	1036	TA		CONSTANT TO BE INDEXED
2236	3016		4 16	_
2237	0416	ANI		/DO AUTO INDEX
2240	1016	TÄ	16	
2241	1035		¥ K7776	/AC SHOULD EQUAL 7777
2242	7040	CM.		
2243	7440	SZ		/AC SHOULD BE ZERO
2244	7402	HL.	T	/AUTO INDEX ERROR

		OTUA\		TEST 86	
2245	7200		CLA		CONSTANT TO BE INDEXED
2246	1035 3016		DC*	K7776	YOMSTANT TO BE INDEXED
2247 2250	0416			1 16	/UO AUTO INDEX
2251	1016			16	
2252	1036		TAU CMA	KØ	/AC SHOULD EQUAL 7777
2253 2254	7040 7440		Ç14~ S <b>₹</b> 4		/AC SHOULD BE ZERO
2255	7402		HL +		/AUTO INDEX ERROR
			*	3F 0 T 0 7	
2254	7200	/AUTO	CLA	TEST 87	
2256 2257	1034		TA	K7775	/CONSTANT TO BE INDEXED
2260	3016		DCA		10- AllW- I DEV
2261	3416			I 16	/DO AUTO INDEX
2262	1016		TAU	K0001	/AC SHOULD EQUAL 7777
2263 2264	1051 7040		ĊMÄ	, - <b></b>	
2265	7440		SZA		/AC SHOULD BE ZERO
2266	7402		HLT		/AUTO INDEX ERROR
		ZAUTO	INDEX	TEST 88	
2267	7200	7,50.0	CL	, = 0	
2270	1033			K7773	CONSTANT TO BE INDEXED
2271	3016		DCA	16 1 16	/DO AUTO INDEX
2272 2273	1416 7200		CLA	1 10	7 20 70 0 100
2274	1016		TAU	16	a de la malla mana
2275	1047			K0093	/AC SHOULD EQUAL 7777
2276	7040		CMA Sæm		/AC SHOULD BE ZERO
2277 2300	7440 - 7402		HLI		AUTO INDEX ERROR
2010		•	_		
		/AUTO		TEST 89	
2301	7200		CLA	K7767	CONSTANT TO BE INDEXED
2302 2303	1032 3016		DCA		
2304	0416		ANU	I 16	/DO AUTO INDEX
2305	1016		TAD		/AC SHOULD EQUAL 7777
2306	1046		CMA	K0007	/AC SHOULD BE ZERO
2307 2310	7040 7440		SZA		AUTO INDEX ERROR
2311	7402		HL!		
		/A:ITA	INDEX	TEST 90	
2312	7200	7 70,10	CLA		
2313	1031		TAU	K7757	CONSTANT TO BE INDEXED
2314	3016			16	/DO AUTO INDEX
2315	0416			16   16	
2316 2317	1016 1045			K0017	/AC SHOULD EQUAL 7777
2320	7040		CMA	ı	

2321	7440	SZA		/AC SHOULD BE ZERO
2322	7402	HLT		AUTO INDEX ERROR
		/AUTO INDEX	TEST 91	
2323	7200	CLA	,	
	1027		K7737	CONSTANT TO BE INDEXED
2324		DCA		
2325	3016	AND	I 16	/DO AUTO INDEX
2326	0416	TAU	16	7 20 20 70 71 211
2327	1016	•	-	/AC SHOULD EQUAL 7777
2330	1044	TAU	KØØ37	AMO SHOULD EGGAE TOTAL
2331	7040	CMA		445 CHOULD DE 7500
2332	744Ø	SZĄ		/AC SHOULD BE ZERO
2333	7402	HL 1		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 92	. *
2334	7200	CLA	, •	
	1026		K7677	CONSTANT TO BE INDEXED
2335		DĈÃ		
2336	3016		1 16	/DO AUTO INDEX
2337	8416	TAU		AND MAIN THEFT
2340	1016			/AC SHOULD EQUAL 7777
2341	1043		K0077	. We sudden those
2342	7040	CMA		
2343	7440	SZA		AC SHOULD BE ZERO
2344	7402	HL!		AUTO INDEX ERROR
		/AUTO INDEX	TEST 93	
2345	7200	CLA		
2346	1025		K7577	/CONSTANT TO BE INDEXED
		DC	16	
2347	3016	ANU		/DO AUTO INDEX
2350	0416			100 4010 1444A
2351	1016	TAD	_	/AC SHOULD EQUAL 7777
2352	1042	TAD	KØ177	AND SHOOFD EROWE ///
2353	7040	CMA		
2354	7440	SZA		/AC SHOULD BE ZERO
2355	7402	HL ·		/AUTO INDEX ERROR

### PAGE 37

## 1/22/68 15:43,54

		/AUTO INDEX	TEST 94	
2356	7200	CLA		
2357	1024	TAD	K7377	/CONSTANT TO BE INDEXED
2360	3016	DC*	16	
2361	0416	AND	I 16	/DO AUTO INDEX
2362	1016	TAD	16	
2363	1041		KØ377	/AC SHOULD EQUAL 7777
2364	7040	CMA		
2365	7440	SZ		/AC SHOULD BE ZERO
2366	7402	ÄĽT		/AUTO INDEX ERROR
2000	, , , , , ,	· <del>-</del>		
		/AUTO INDEX	TEST 95	
2367	7200	CLA		
2370	1023		K6777	/CONSTANT TO BE INDEXED
2371	3016	DCA	16	
2372	0416	ANH		/DO AUTO INDEX
2373	1016	TAD	•	- · · · · ·
2374	1040	TAP		/AC SHOULD EQUAL 7777
2375	7040	CM#		
2376	7440	SZ4		/AC SHOULD BE ZERO
-		HL		ZAUTO- INDEX ERROR
2377	7402	ms.		Friend Firman Stridt

PAJSE

		/TEST	2 -	TAPE 3	
	2400	*2400			
		/AJTO	INDEX	TEST 96	
2400	7200		CLA		
2401	1022		TAL	K5777	/CONSTANT TO BE INDEXED
2402	3016		DC#		
2403	2416		IS≠	1 16	/QO AUTO INDEX
2484	7000		NOP		
2405	1016		TAP		
2426	1037			K1777	/AC SHOULD EQUAL 7777
2407	7040		CMA		
-	7440		SZA		AC SHOULD BE ZERO
2410	•		HLT		AUTO INDEX ERROR
2411	7402		77 6-1		Auto tueta auton
		OTLA	INDEX	TEST 97	
2412	7200		CLA		
2413	1021		TAD	K3777	CONSTANT TO BE INDEXED
2414	3016		DC#	16	
2415	0416		ANU	I 16	/DO AUTO INDEX
2416	1016		TAU		
2417	1021		TAD		/AC SHOULD EQUAL 7777
2420	7040		CMA	10.4.1.1	
	7440		SZA		/AC SHOULD BE ZERO
2421			HLI		ZAUTO INDEX ERROR
2422	7402				Lubrate ellactic militario

		/AUTO INDEX	TEST 98	
2423	7200	CL"		
2424	1020		K7777	CONSTANT TO BE INDEXED
2425	3016	DCA		
2426	0416		Ī 16	/DO AUTO INDEX
2427	1016	TA		
2430	1020		K7777	/AC SHOULD EQUAL 7777
2431	7040	CMA	,,,,,,	a a
2432	7440	SZA		/AC SHOULD BE ZERO
2433	7402	HL (		ZAUTO INDEX ERROR
2700	7 7 0 2			
		/AUTO INDEA	TEST 99	
2434	7200	CL*	, , , , , ,	
2435	1036	TAD	κØ	CONSTANT TO BE INDEXED
2436	3017		17	
2437	Ø417	•	1 17	DO AUTO INDEX
2440	1017	TAU		
2441	1035		K7776	AC SHOULD EQUAL 7777
2442	7040	ÇM-	(, , , , <del>,</del>	
2443	7440	SZA		/AC SHOULD BE ZERO
2444	7402	HLT		AUTO INUEX ERROR
2777	7402	H.		
		/AUTO INDEX	TEST 100	i e
2445	7200	CLA		
2446	1035	TĀ.	K7776	ACONSTANT TO BE INDEXED
2447	3017	DC#		
2450	0417		Ī 17	DO AUTO INDEX
2451	1017	TA-		
2452	1036	TAD		/AC SHOULD EQUAL 7777
2453	7040	CMA	•	
2454	7440	ASS		/AC SHOULD BE ZERO
2455	7402	HL		AUTO INDEX ERROR
2		-		
		/AUTO INDEX	TEST 101	
2456	7200	CL#		
2457	1034		K7775	CONSTANT TO BE INDEXED
2460	3017	DCA	17	
2461			ī 17	ADO AUTO INDEX
2462	1017	TAU		
2463	1051		K0001	AC SHOULD EQUAL 7777
2464	7040	CMA		
2465	7440	SZA		/AC SHOULD BE ZERO
2466	7402	HL		/AUTO INDEX ERROR
2,00				· · · · · · · · · · · · · · · · · · ·

		/AUTO IND	EX TEST 10	2
2467	7200	C	LA	
2470	1033	Т	A- K7773	CONSTANT TO BE INDEXED
2471	3017		CA 17	
2472	1417		AD 1 17	/DO AUTO INDEX
2473	7200	C	LA	
2474	1017		AD 17	
2475	1047	Т	AN K0003	/AC SHOULD EQUAL 7777
2476	7040	C	MA	
2477	7440		ZA.	/AC SHOULD BE ZERO
2500	7402	Ä	LT	/AUTO INDEX ERROR
2000			_	·
		ZAUTO IND	EX TEST 10	১
2501	7200	C	LA	
2502	1032	· T	AW K7767	/CONSTANT TO BE INDEXED
2503	3017		Ch 17	
2504	0417		NU 1 17	/DO AUTO INDEX
2505	1017	т	AU 17	
2506	1046	Ť	AU K0007	/AC SHOULD EQUAL 7777
2507	7040	C	MA	
2510	7440		ZA	/AC SHOULD BE ZERO
2511	7402		LI	AUTO INDEX ERROR
E-4-	7 4 2 2			
		/AUTO IND	EX TEST 10	4
2512	7200		LA	
2513	1031	Т	AD K7757	/CONSTANT TO BE INDEXED
2514	3017	0	CA 17	
2515	0417		ND 1 17	/DO AUTO INDEX
2516	1017	Т	AU 17	
2517	1045	Ť	AD KØØ17	AC SHOULD EQUAL: 7777
2520	7040		MW	
2521	7440		Z 4	/AC SHOULD BE ZERO
2522	7402		LT	/AUTO INDEX ERROR
2766	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•••		

		/AJTO INDEX	TEST 105	
2523	7200	CĻA		
2524 2525	1027 3017	TĀ.	K7737 17	CONSTANT TO BE INDEXED
2526	0417		1 17	/DO AUTO INDEX
2527	1017	TAD	17	
2530	1344		K0037	/AC SHOULD EQUAL 7777
2531	7040	CMA		ALC CHANNED DE ZEDO
2532 2533	7440 7402	SZA HL!		/AC SHOULD BE ₹ERO /AUTO INDEX ERROR
200	, , , ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		AND O THREE THOU
		XADNI OTLAN	TEST 106	
2534 2535	7200 1026	CLA	K7677	CONCTANT TO BE IMPEVED
2535 2536	3017		17	CONSTANT TO BE INDEXED
2537	0417		1 17	/DO AUTO INDEX
2540	1017	TAL	17	• • • • • • • • • • • • • • • • • • • •
2541	1043	TAP	K0077	/AC SHOULD EQUAL 7777
2542 2543	7040 7440	CM* SZA		/AC SHOULD BE ZERO
2544	7402	HLT		/AUTO INDEX ERROR
		/AUTO INDEX		1
2545 2546	7200 1025	CLA	K7577	CONSTANT TO BE INDEXED
2547	3017		17	ACOMSTANT TO BE TABEXED
2550	0417		Î 17	/DO AUTO INDEX
2551	1017	TA-	17	
2552	1042		KØ177	/AC SHOULD EQUAL 7777
2553 2554	7040 7440	CMA S&#</td><td></td><td>/AC SHOULD BE ZERO</td></tr><tr><td>2555</td><td>7402</td><td>HLT</td><td></td><td>AUTO INDEX ERROR</td></tr><tr><td>_</td><td></td><td></td><td></td><td>•</td></tr><tr><td>0557</td><td>2000</td><td>/AUTO INDEX</td><td>TEST 108</td><td></td></tr><tr><td>2556 2557</td><td>7200 1024</td><td>CLA Tad</td><td>K7377</td><td>/CONSTANT TO BE INDEXED</td></tr><tr><td>2560</td><td>3017</td><td>DCA</td><td></td><td>ACCIDATALL TO BE TUBEVED</td></tr><tr><td>2561</td><td>0417</td><td>ANU</td><td>1 17</td><td>/DO AUTO INDEX</td></tr><tr><td>2562</td><td>1017</td><td>TAU</td><td>17</td><td></td></tr><tr><td>2563 2564</td><td>1041 7040</td><td>TA4 CMA</td><td>K0377</td><td>AC SHOULD EQUAL 7777</td></tr><tr><td>2565</td><td>7440</td><td>SZA</td><td></td><td>/AC SHOULD BE ZERO</td></tr><tr><td>2566</td><td>7402</td><td>HL 1</td><td></td><td>/AUTO INDEX ERROR</td></tr><tr><td></td><td></td><td>44.07.6 1.08.57</td><td>-C-T 4/40</td><td></td></tr><tr><td>2567</td><td>7200</td><td>/AUTO INDEA CL*</td><td>IESI TRA</td><td></td></tr><tr><td>-</td><td>1023</td><td></td><td>K6777</td><td>CONSTANT TO BE INDEXED</td></tr><tr><td>2571</td><td>3017</td><td>DCA</td><td><u>1</u>7</td><td></td></tr><tr><td>2572</td><td>0417</td><td></td><td>1 17</td><td>/DO AUTO INNEX</td></tr><tr><td>2573 2574</td><td>1017</td><td>TAD</td><td>1<sup>7</sup> k0777</td><td>CAC CHOILD COUAL 3373</td></tr><tr><td>2575</td><td>1040 7040</td><td>CM"</td><td>N D / / /</td><td>/AC SHOULD EQUAL 7777</td></tr><tr><td>2576</td><td>7440</td><td>SZA</td><td></td><td>/AC SHOULD BE ZERO</td></tr><tr><td>2577</td><td>7402</td><td>HLI</td><td></td><td>/AUTO INDEX ERROR</td></tr><tr><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>		

PAGE 42-1

	2500	*2600 /AJFO INJEX	TEST 110	
2630	7230	CLA		
2601	1455		<b>イ</b> ラ717	ACONSTANT TO BE INDEXED
2632	3917	JCA	_	ZUO AUTO INDEX
2623	2417	IS≠ vop	1 17	AND MOTO INDEX
2634	2.104	TAJ	1 7	
2635	1/1/2		1/ K1777	/AC SHOULD EQUAL 1777
2636 2637	1037 7040	CMA		
2613	7440	StA		/AC SHOULD BE ZERO
2611	7422	ਸਵੇੀ		VAUTO INDEX ERROR
		/AUTO INDEX	TEST 111	
2612	7280	CLA		
2613	1021		K3777	IDONSTANT TO BE INDEXED
2514	3017	ЮCА	-	
2515	84 <u>1</u> 7		[ 1/	ZUO AUTO INDEX
2616	1/1/	TAU		ZAC SHOULD EQUAL 7777
2617	1951	CMA	K3777	THE SHOULD EGONE TITLE
2623	7 140	SZA		ZAC SHOULD BE ZERO
2621 2622	7440 7402	dLT		VAUTO INDEX ERROR
555	792	.,,,,		
		VAUTO INDEX	TEST 112	
2623	7200	CLA		TO DE LIBERED
2624	1950		K7777	GONSTANT TO BE INDEXED
2625	3 117	UCA		ZDO AUTO INDEX
2625	₩417	UNA	I 17	AND WOLD THANK
2627	1017		т, К7777	/AC SHOULD EQUAL 7777
2633	1320	ČMA	N////	7 MO SHOOLS AGO E
2631 2632	7340 7440	SZA		/AC SHOULD BE ZERO
2633	7402	HLT		AUTO INDEX ERROR
		/AUTO INDEX	TEST 113	
2634	5236	9ML	.+2	
2635	7432	HLT		JUMP FAILED
2636	7410	SKP	**	JUMP WORKED (A LITTLE)
2637	2544	2644		$\mathcal{A}_{\mathbf{v}}$ . The second of $\mathcal{A}_{\mathbf{v}}$
2640	1237	CAT ACA		
2641	3313 5443		I 10	/TEST INSTRUCTION
2642 2643	5410 7402	HLT	• • •	JUMP INDIRECT FAILED
2644	7402	HLT	e Ha	/LOCATION 2610, NO INDEX
20,4	•			IN WT! STATE.

```
/AUTO INDEX TEST 114
                                 JMS ,+2
2645
    4247
                                                 /JMS FAILED
                                 HLT
    7402
2646
                                                 /JMS FAILED
                                 HLT
2647
     7462
                                 TAU .-1
2650 124/
                                 SKP
2651
     7410
                                 . -4
2652
      2646
                                 UIA
2653
     7:141
                                 1AU .-2
    1252
2654
                                 SZA
2655 7441
                                                 /WRONG ADDRESS STORED
                                 HIL T
2656 7402
                                                 JUURING JMS
                                                 /JMS WORKS (I GUESS)
                                 SKP
2657 7414
                                 . +4
2660
     2004
                                 TAU .-1
2661 1260
                                 DCA 10
2662 381W
                                                        /TEST INSTRUCTION
                                 JMS 1 10
     4410
2663
                                                 JJMS FAILED
                                 HLT
     7402
2664
                                                 /JMS FAILED
                                 HLT
     7402
2665
                                 1AD ,-1
     1265
2666
                                 SKP
2667 7418
                                 , -4
2670 2664
                                 CIA
2671 7241
                                 TAU .-2
2672 1270
                                 SZA
2673 7440
                                                 /WRONG ADDRESS STORED DURING JMS
                                 HLT
2674 7462
                         VINTERRUPT TEST 1
                                 JMS 1 .+1
2675 4676
                                                         /RUBOUT CHARACTER
                                 STR
2676
     4311
                                 TSF
2677 6941
                                 TLS
2700 6046
                                 TSF
2701 6 41
                                 JMP ,-1
2702 5301
                                 CLA
2703
     7206
                                                        /FLAG IS ON
                                 TAD BACK1
2784
     1312
                                 UCA 2
2705 3002
                                 LON
2706 6001
                                                         /GO TO LOC 0000
                                 NOP
2707 7900
                                                 /NO INTERRUPT
                                 HLT
2710 7402
                                  . =1
                         OuT1.
2711 2719
                         BACK1.
                                 , +1
2712 2713
                                                 /RETURN FROM LOC 1
                                  SZA
2713 7440
                                                 /AC SHOULD BE 0
                                  HLT
2714 7402
                                                  /CONFIDENCE CHECK
                                  TAU Ø
2715 1000
                                  CIA
 2716 7041
                                  TAU OUT1
2717 1311
                                  SZA CLA
 2720 7640
                                                  /INTERRUPT ERROR
                                  HL I
 2721 7402
                                                  /WRONG ADDRESS STORED
```

```
VINTERRUPT TEST 2
                                                          IRUBOUT CHARACTER
                                 TAU KØ3/7
2722 1 41
                                 TSF
2723 6041
                                 TLS
2724 6240
                                 TSF
2725 6041
                                 JMP .-1
2726 5322
                                                  /FLAG IS ON
                                 CLA
2727 7220
                                 TAU BACKS
2733 1336
                                 DCA 2
2731 3732
                                 ION
2732 6231
                                 TAU K7777
2733 1220
                                                 INO INTERRUPT
                                 HLI
2734 7-22
                                  , ~ 1
2735 2734
                         CUTS,
2736 2737
                         BACK3:
                                 , +1,
                                                  FRETURN FROM LOC1
                                  CMA
2737 7040
                                 SZA
2740 7440
                                                 ICONFIDENCE CHECK
                                  HLT
2741 7402
                                                  /AC SHOULD BE B
                                 TAU 0
2742 1600
                                 CIA
2743 7841
                                 TAU OUTS
2744 1335
                                                  /INTERRUPT ERROR
                                  SEA CLA
2745 7648
                                                 - /ARONG ADDRESS STORED
                                  HLT
2746 7402
                         /INTERRUPT TEST 3
                                                          RUBOUT CHARACTER
                                  TAD K0377
2747 1941
                                 TSF
2759 6841
                                 TLS
2751 6446
                                  ISF
2752 6641
                                  JMP .-1
2753 5352
                                                  /FLAG IS ON
                                  CLA
2754 72WD
                                  TAU BACK2
2755 1364
                                  DUA 2
2756 3002
                                  TAU K7777
2757 1920
                                  10N
2760 6001
                                  AND K7777
2761
     2020
                                                  INO INTERRUPT
                                  HLT
2762 7402
                                  ,-1
2763 2762
                         OUT2,
                                  .+1
2764 2765
                         BACK2.
                                                  VRETURN FROM LOCA
2765 7840
                                  CMA
                                  SEA
2766 7440
                                                  /CONFIDENCE CHECK
                                  HLI
2767 7402
                                                  /AC SHOULD BE W
                                 N UAT
2773 1200
                                  CIA
2771 7041
2772 1363
                                  TAU OUT2
                                  SZA CLA
2773 7640
                                                  /INTERRUPT ERROR
                                  HLT
2774 7482
                                                  /WRONG ADDRESS STORED
                                  NOP
2775 7000
                                  NUP
2776 7000
2777 7830
                                  NOP
```

	3900	#3000 /interrupt test 4	
x . 1 (*1 .74	# i3 A 4	TAU K0377	VRUBOUT CHARACTER
3000	1.41	TSF	, , , , , , , , , , , , , , , , , , , ,
3001	66.41	165	
3842	6046	TSF	
3003	6741	15r JMP .≈1	
3004	5203		/FLAG IS ON
3005	7297	CLA	77 LAG 13 UN
3006	1215	TAU BACK4	n ·
3007	3032	DCA 2	
3910	1920	TAD K7777	
3911	6ଉଥ1	ION	
3012	3063	UCA 3	A A THEODOLOT
3013	7402	HLT	INO INTERRUPT
3014	3013	1⊤، ،⊤1	
3u15	3016	BACK4+ ++1	
3016	7440	SZA	/RETURN FROM LOC1
3017	7432	H <b>L</b> T	CONFIDENCE CHECK
			/AC SHOULD BE ZERO
3020	1203	TAD 3	
3021	7040	CMA	
3022	7440	SZA	
3023	7432	HLT	/DCA PRIOR TO INTERRUPT
Jv. 23	,	•	/FAILED
3024	3003	UCA 3	
3025	1030	UAT W	•
3025	7041	CIA	
		TAD OUT4	
3027	1214	SZA CLA	
3030	7648	HLT	/INTERRUPT ERROR
3931	7402	* 1 Ge 1	/WRONG ADDRESS STORED
		/INTERRUPT TEST 5	
		TAU KO377	/RUBOUT CHARACTER
3032	1041	TSF	, , , , , , o , o , , a , , a , a , a ,
3033	6041		
3034	6¥46	TLS	
3Ø35	6941	TSF	
3036	5235	JMP ,-1	ZFLAG IS ON
3037	7200	CLA	// /FLAG IS ON
3040	1256	TAD BACKS	
3941	3002	OCA 2	
3042	1035	TÃU K77/6	

```
OCA 3
3243
      3003
                                   108
3944
      6001
                                   15£ 3
3945
      2003
                                   HLT
                                                    INO INTERRUPT
3046
      7462
                                   . - 1
      3046
                          OUT5,
3847
                                   ,+1
                          BACK5.
      3651
3050
                                   SZA
                                                    VRETURN FROM LOC1
3051
      7440
                                   HLT
                                                    /CONFIDENCE CHECK
3052 7402
                                                    /AC SHOULD BE ZERO
                                   TAD 3
      1003
3253
                                   CMA
3054
      7040
                                   SZA
3055
      7440
                                   HLT
                                                    /ISZ PRIOR TO
3056
      7402
                                                    /INTERRUPT FAILED
                                   DCA 3
      3003
3257
                                   TAU Ø
      1000
3060
                                   CIA
3061
     7041
                                   TAU OUTS
3062 1247
                                   SZA CLA
3063 7640
                                                    /INTERRUPT ERROR
                                   HLT
30642 7402
                                                    /WRONG ADDRESS STORED
                          /INTERRUPT TEST 6
                                                            /RUBOUT CHARACTER
                                   TAD KU377
3065
      1841
                                   TSF
3066
      6041
                                   TLS
3067
      6046
                                   TSF
3070
      6441
                                   JMP .-1
3071
      5270
                                                    /FLAG IS ON
                                   CLA
3072
     7200
                                   TAU BACK6
3073
      1304
                                   UCA 2
3074
      3605
                                   TAU K7777
3075
     1020
                                   DCA 3
3076
     3003
                                   100
3077
      6801
                                   IS± 3
3100
      2203
                                                    INO INTERRUPT
                                   HLT
3101
      7452
                                   HLT
3102
      7402
                                   . -1
3103
      3102
                           OUT6,
                                   . +1
                           BACK6.
3104
      3105
                                   SZA
                                                    /RETURN FROM LOC 1
      7440
3105
                                                    /CONFIDENCE CHECK
                                   HLT
      7402
3126
                                                    /AC SHOULD BE ZERO
                                   TAD 3
3107
      1003
                                   SZA
3110
      7440
                                                    /ISE PRIOR TO
                                   HLT
      7402
3111
                                                    /INTERRUPT FAILED
                                   DCA 3
      3003
3112
                                   TAU Ø
3113
      1000
                                   CIA
3114
      7041
                                   TAU OUT6
3115
      1303
                                   SZA ÇLA
3116
      7640
                                                    /INTERRUPT ERROR
      7402
                                   HLT
3117
                                                    /WRONG ADDRESS STORED
```

				/INTERRUPT	TCCT 7	
•				VINTERRUF	1 1531 /	/RUBOUT CHARACTER
	3124	1841			AD KE377	Andrew attended
***	3121	6µ41		ŢŞ		
	3122	6046	Section 1			
	3123	6041		15		
	3124	5323		J!	4P1	
	3125	7280		C	_A	/FLAG IS ON
	3126	1334		r,	AU BACK7	
					CA 2	
	3127	3002			57	
	3130	6001		-		
	3131	5331			MP,	INC INTERRUPT
	3132	7402			<u>, T</u>	AND THIENKOPE
	3133	3131			-2.	•
	3134	3135			•1	
	3135	7448			Ž A	/RETURN FROM LOC 1
	3136	7402		H	.T	CONFIDENCE CHECK
	9100	,				/AC SHOULD BE 0
	** 4 2 1%	4 (3.7514		т	AD Ø	
	3137	1000	with the second		IA	
	3140	7941				•
	3141	1333			AD OUT?	
	3142	7640			ZA CLA	ALLERONUNE CONON
	3143	7402		H	LT .	/INTERRUPT ERROR
						/WRONG ADDRESS STORED
				and the second second		$\rho_{\rm c} = 10^{-3}  { m cm}^{-3}  { m cm}^{-3} $
and gray and the second of the				/INTERRUP	T TEST 8	ANUDAUM MUADACEC
44	3144	1841			AD KØ377	/RUBOUT CHARACTER
	3145	6/141			SF	
	3146	6046		71	LS	
And the second	3147	6941			SF	
		5347	41		MP .=1	
and the second second	3150		and the second		LA	/FLAG IS ON
	3151	7200			AD BACKS	
	3152	1360				<ul> <li>A Book of the Company o</li></ul>
	3153	3002			CA 2	
	3154	0001			ON	and the first of the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section is a section of the second section is a second section of the second section of the second section is a second section of the section of the second section of the section of
	3155	4303			MS 3	
	3156	7402		H	LT	INO INTERRUPT
esta timo de la companya de la comp	3157	3156	and a William and American		<del>-</del> 1	
	3160	3161			+1	
			1 No. 1987		ZA	/RETURN FROM LOC 1
	3161	7440			ĹΪ	CONFIDENCE CHECK
	3162	7402	er and the second of the		<b>.</b>	AC SHOULD BE ZERO
· ·	. *				4.6	ANC BUONED BE EFIND
- 10 PA	3163	1003	and the second second		AD 3	All the second of the second o
	3164	7041			1 A	
	3165	1357	+		8TUO GA	
	3166	7440		S	Z A	
	3167	7402	4		L T	JMS ERROR PRIOR
	310/	1466	and the second second		<b>™</b> 5.	TO INTERRUPT WRONG
						ADDRESS STORED
		*				ADDRESS STORED

3179 3171 3172 3173 3174	1 100 7041 1064 7540 7402	TAU 7 CIA TAU K4 Sya Cla Hlt	/INTERRUPT ERROR /WRONG ADDRESS STORED
3175 3176 3177	7000 7000 7000	900 900 900 900	

			0/21/00 17/2/1
	3260	*3200	
	- F	/INTERRUPT TEST 9	ADDITION OF THE PARTY OF
3200	1841	TAU KØ3/7	/RUBOUT CHARACTER
3201	6241	TSF	
3202	6946	TLS	
3223	0041	TSF	·
3204	5233	JMP1	
3205	7200	CLA	/FLAG IS ON
	1215	TAU BACK9	
3226	3035	DCA 2	
3207		TAU K7777	
3,210	1020	ION	3
3211	0001	CLA	
3212	7270	HLT	INO INTERRUPT
3213	7482	OUT9, .=1	
3214	3213		
3215	3216	BACK9: :+1 SZA	VRETURN FROM LOC 1
3216	7440	HLT	ICLA PRIOR TO INTERRUPT
3217	7402	прі	/FAILED
3220	1000	TAD Ø	
3221	7941	CIA	
3222	1214	TAU OUT9	The second secon
3223	7640	SZA CLA	
3224	7402	HLT	/INTERRUPT FAILED
3224	7702		/WRONG ADDRESS STORED
		/INTERRUPT TEST 1	, , , , , , , , , , , , , , , , , , , ,
3225	1041	TAU KØ377	/RUBOUT CHARACTER
3226	6041	TSF	
3227	6046	TLS	
3230	6041	TSF	
	5230	JMP .=1	
3231	7200	CLA	/FLAG IS ON
3232	1242	TAU BACKI	ð
3233	-	DCA 2	
3234	3002	ION	
3235	6031	TSF	
3236	6041	HLT	/NO INTERRUPT
3237	7402	HET	
3240	7492	- Andrew Andre	

```
5240
                          OUT10, .-1
3241
                          BACKID, .+1
3242
      3245
                                                    VRETURN FROM LOC 1
                                   SFA
3243
      7440
                                                   CONFIDENCE CHECK
                                   HLT
3244
      1432
                                                    /AC SHOULD BE ZERO
                                   TAU 0
3245
      1000
                                   CIA
3246 7841
                                   TAU OUT18
3247
      1241
                                   SZA CLA
3253
     .7649
                                                    /INTERRUPT ERROR
                                   HLT
3251 7492
                                                   /WRONG ADDRESS STORED
                          /IMTERRUPT TEST 11
                                                           /RUBOUT CHARACTER
                                   TAU K0377
3252
      1041
                                   TSF
      0041
3253
                                   TLS
      6046
3254
                                   TSF
      6041
3255
                                   JMP .-1
3256
      5255
                                                   /FLAG IS DN
                                   CLA
3257
      7200
                                   TAD BACK11
      1317
3260
                                   DCA 2
      3002
3261
                                   IÓN
      6001
3262
                                   TOF
      0002
3263
                                   ION
      0001
3264
                                   IOF
      6002
3265
                                   IUN
3266
      6011
                                   IOF
3267
      6302
                                   ION
3270
      6001
                                   IOF
      0002
32/1
                                   LON
      60V1
3272
                                   IOF
      0002
3273
                                   ION
3274
      0001
                                   LOF
3275
      6005
                                   ION
3276
      6001
                                   IOF
      6002
3277
                                   ION
3300
      6001
                                   IOF
3301
      6002
                                   ION
      6001
3302
                                   IOF
3303
      6002
                                   ION
3304
      0001
                                   IOF
3305
      90/15
                                   ION
3306
      6001
                                   LOF
3307
      6002
                                   ION
      6001
3310
                                   TOF
3311
      5002
                                   ION
3312
      6001
                                   IOF
3313
      6002
```

			\$, + + + +			
3314	6941			TSF		/WHAT HAPPENED TO MY FLAG
3315	7432			HLT		JAHAT HAPPENED TO THE TERM
3316	7410			SKP		
3317	3321		BACK11.			
3323	7410			SKP		VINTERRUPT OCCURRED DURING
3321	7432			HLT		VION-LOF SEQUENCE VSEE LOCATION 0000
			· .a			
			/INTERR		T 12	
3322	6042			TCF		/CLEAR FLAG
3323	1230			CLA		
3324	1334			TAU BA	CK12	
3325	2005			DÇA 2		w.
3326	5011			10N		
3327	7000			NOP .		×.
3339	7000			NUP		
3331	7330	8.		NOP.		
3332	7000			NOP		
3333	7410			SKP		
3334	3336		BACK12,	,+2		
3335	7410			SKP		
3336	7402	* .*.		HLT		/INTERRUPT WITH NO
3330	, ., ,, ,					/FLAG.
3337	6832			IOF		
000,					INDEV	TECT4
			/ILLEGA	L AUTO	THOFY	16311
7740	7290			CLA		
3340				J MML	. +1	
3341	5742	A CONTRACTOR		AND1	,y ==	
3342	4000		K4010.	4010		
3343	4010		1.4242			
	4000		*4000			AMME TO OTHER TON
4000	3610		AND1,	ANU I		TEST INSTRUCTION
4001	5622			JMP I	1 * 1	and the second of the second o
4002	3350			RET1		
	-		. 73"			
	3350	1	<b>=3350</b>		4 4 10 . 24	
3350	1743		RET1.		K4010	
3351	7440			SZA	4	ACORON AC CUAMIN NE TERM
3352	7402			HLT		/ERROR, AC SHOULD BE ZERO /AND I 4010 ALTERED (4010)
				CLA		ANIAD I HOTO WELFURD CARREL
3353	7230		•	-	K4010	
3354	3743			UUM I	מושדה	
						$\mathcal{M}_{ij}$ ,

## VILLEGAL AUTO INDEX TEST 2

3355 3356 3357 3360	7200 5757 2173 2010		50±0 VV≈5 NWL I	.+1	
2173 2174 2175	2173 0610 5775 3370	.,,,	ANU I JMF I RE!2		/TEST INSTRUCTION
3370 3371 3372	3370 1760 7440 74 <sub>0</sub> 2		HL! SZ@ I	K5010	/ERROR, AC SHOULD BE ZERO /AND I 2010 ALTERED (2010)
3373 3374	5774 3400		JMP 1 3400	.+1	
3400 3401	3400 7200 5602	/ILLEGAL *3400	AUTO		ST 3
3402 3403	1173 1010 1173		AND3 10 0	, •	
1173 1174 1175	1173 0610 5775 3410	AND3.	AND I JMP I RET3		/TEST INSTRUCTION
3410 3411 3412	3410 1603 7440 74 <sub>0</sub> 2		TAD I SZ: HL!	K1010	/ERROR. AC SHOULD BE HERO /AND I 1010 ALTERED (1010)
3413 3414	7200 3603		CLA DCA I	K1010	

```
/ILLEGAL AUTO INDEX TEST 4
                                 CLA
3415 7200
                                 JM# 1 .+1
3416 5617
                                 ANU4
3417 0574
                                 41
                         K410.
3420 0410
                         *574
     0574
                                                         /TEST INSTRUCTION
                                 AND I 410
                         AND4.
0574 0610
                                 14, I HMU
0575 5776
                                 RE 14
0576 3430
                         #3430
      3430
                                 TAD | K410
                         RET4,
3430 1620
                                 SZA
3431 7440
                                                 PERROR. AC SHOULD BE ZERO
                                 HLT
3432 7402
                                                 /AND I 410 ALTERED (410)
3433 7200
                                 DC- I K410
3434 3620
                         /ILLEGAL AUTO INDEX TEST 5.
                                 JMT I .+1
3435 7200
3436 5637
3437 Ø371
                                 21-
                         K210,
3440 0210
                         *370
      0370
                                 JMF .+4
0370 5374
                                                         /TEST INSTRUCTION
                                 AN 1 210
                         AND5,
0371 0610
                                 JMP 1 .+1
0372 5773
                                 RETS
0373 3450
                         +3450
      3450
                                 TAD | K210
                         RETS,
3450 1640
                                 SZA
3451 7440
                                                 /ERROR, AC SHOULD BE ZERO
                                 HLT
3452 7402
                                                 /AND I 210 ALTERED (210)
                                 CLA
3453 7200
                                 QCA I K210
3454 3640
```

### /ILLEGAL AUTO INDEX TEST 6

3455 3456 3457 3460	7200 5657 0130 0110	CLA JMP I .+1 AND6 K110, 11°
0130 0131 0132	0130 0510 5532 3470	#130 AND6, AND I 110 /TEST INSTRUCTION JMM I .+1 REI6
3470 3471 3472 3473 3474	3470 1660 7440 7402 7200 3110	#3470 RET6, TAD I K110 SZA HL! /ERROR. AC SHOULD BE ZERO /AND I 110 ALTERED (110) CLA DCA 110
3475 3476 3477 3500	7200 5677 0124 0050	/ILLEGAL AUTO INDEX TEST 7  CLA JMP I .+1 ANU7 K52, 50
Ø124 Ø125 Ø126	0124 0450 5526 3510	#124 AND7. AND I 50 /TEST INSTRUCTION JMP I .+1 REJ7
3510 3511 3512	3510 1700 7440 7402	#3510 RET7, TAB I K50 SEB HL+ /ERROR, AC SHOULD BE ZERO /AND I 50 ALTERED (50)
3513	7200	CLA DCA EX

#### VILLEGAL AUTO INDEX TEST 8 CLA 3515 7200 JMF I .+1 3516 5717 ANUB 3517 0120 30 K32. 3520 0030 \*120 0120 /TEST INSTRUCTION ANU 1 30 AND8, 0120 0430 JMP : .+1 Ø121 5522 RE 18 0122 3530 \*3530 3530 TAU 1 K30 RETB, 3530 1720 SZA 3531 7440 FRROR. AC SHOULD BE ZERO HLT 3532 7402 /AND 1 30 ALTERED (30) CLA 3533 7200 DCA 30 3534 3030 /ILLEGAL AUTO INDEX TEST 9 CLA 3535 7200 DCA Ø 3536 3000 JM: 1 .+1 3537 5740 AND9 3540 0074 **\*74** 0074 /TEST INSTRUCTION AND9, ANU I Ø 0074 0400 0075 5476 1+. I .ML 0076 3550 RETO #3550 3550 TAD I KØ 3550 1436 RET9. S#4 3551 7440 PERROR, AC SHOULD BE BERO HL 1 3552 7402 /AND I @ ALTERED (Ø) CLA 3553 7200

DCA Ø

3554 3000

Jan Harri

```
/ILLEGAL AUTO INDEX TEST 10
                                 CLA
3555 7200
                                 JMP I .+1
3556 5757
                                 ANH10
3557 0070
                         *73
      0070
                                                 /TEST INSTRUCTION
                         ANDIO,
                                 AND 1 7
0070 0407
                                 JM# 1 .+1
0071 5472
                                 RE 10
0072 3600
                         *3600
      3600
                         RET10.
                                 TAD I KUQU7
3600 1446
                                 SZA
3601 7440
                                                 JERROR. AC SHOULD BE ZERO
                                 HL !
3602 7402
                                                 JAND I 7 ALTERED (7)
                                 CL*
3603 7200
3604 3007
                                 DCA 7
                         JCHECK FOR TTY BELL
                                 TAP BLCNT
3605 1223
                                 IA
3606 7001
                                 DC4 BLCNT
36g7 3223
                                 TAD BLCNT
3610 1223
                                 TAP RNGCNT
3611 1224
3612 7640
                                 SZA CLA
3613 5622
                                 JMP I K201
                                 DCA BLONT
3614 3223
                                 TAU BELCOD
3615 1225
3616 6046
                                 TL
                                 TSF
3617 6041
3620 5217
                                 JMP .-1
                                 JMP 1 .+1
3621 5622
                                 201
3622 0201
                         K201,
                         BLCNT.
3623 0000
                                 0
                         RNGCNT, -59
3624 7730
3625 0207
                         BELCOD, 207
      4010
                         -4010
                                 0
4010 0000
4011
      0000
                         STR.
4012 1221
                                 XIGML MAT
4013 3001
                                 DC# 1
4014 3002
                                 DCA 2
4015 3003
                                 DC" 3
4016 1041
                                 TAD KØ377
                                 ISE STR
4017 2211
4020 5611
                                 JMP I STR
4021 5402
                                 5402
```

JMP IX.

	SY	MBOL	TA	BL	E
--	----	------	----	----	---

AND1	4000
AND10	0070
	2477
AND2	2173
AND3	1173
AND4	0574
	0774
AND5	0371
AND6	0130
AND7	0124
ANDS	0120
AND9	0074
BACK1	2711
BACK10	3242
	3272
BACK11	3317
BACK12	3334
BACK2	2763
BACK3	2735
BACK4	3015
	3050
BACK5	3050
BACK6	3104
BACK7	3134
	3160
BACKS	
BACK9	3215
BELCOD	3625
CLENT	
BLCNT	3623
JMPIX	4021
KØ	0036
KØØØ1	0051
K0003	ØØ47
K0007	0046
KØØ17	0045
KØØ37	0044
K0077	0043
	0042
KØ177	
KØ377	0041
KØ7Ø7	0060
	0040
KØ777	
K1010	3403
K110	3460
2444	0062
K1111	
K1234	0177
K172	0173
W 4 9 7	0174
K173	
K174	0175
K175	0176
	0172
K176	
K1777	0037
K201	3622
K2010	3360
K210	3440
K2525	0054
K30	3520
K3777	0021
K4	8064

SYMBOL TABLE

K4010 3343 K410 3420 0052 K4400 K4444 0056 0053 K4577 K50 3500 0061 K5252 K5555 0063 K5777 0022 K6666 0055 0023 K6777 0057 K7070 0024 K7377 0025 K7577 0026 K7677 0027 K7737 0031 K7757 0032 K7767 0033 K7773 0034 K7775 K7776 0035 K7777 0020 0071 00710 2710 3241 OUT2 2762 2734 OUT3 OUT 4 3014 OUT5 3047 3103 DUT6 3133 OUT7 3157 OUT8 3214 OUT9 RET1 3350 3600 RET10 3370 RET2 3410 RETS 3430 RET4 RETS 3450 3470 RET6 RET7 3510 RETS 3530 RET9 3550 3624 RNGCNT 4011 STR TPØ 0200 TP177 0377

```
SYMBOL TABLE
K7777
           0020
K3777
           0021
K5777
           0022
K6777
           0023
K7377
           0024
K7577
           0025
           0026
K7677
K7737
           0027
K7757
           0031
K7767
           0032
           0033
K7773
K7775
           0034
           0035
K7776
KØ
           0036
K1777
           0037
           0040
KØ777
           0041
KØ377
           0042
KØ177
           0043
K0077
           0044
K0037
KØØ17
           0045
K0007
           0046
K0003
           0047
K0001
           0051
K4400
           0052
K4577
           0053
K2525
           0054
           0055
K6666
K4444
           0056
K7070
           0057
KØ7Ø7
           0060
K5252
           0061
K1111
           0062
K5555
           0063
K4
           0064
AND10
           0070
ANDS
           0074
ANDS
           0120
AND7
           0124
           0130
AND 6
K176
           0172
K172
           0173
           0174
K173
           Ø175
K174
K175
           Ø176
K1234
           Ø177
TPØ
           0200
AND5
           0371
TP177
           0377
AND4
           0574
           1173
AND3
           2173
ANDZ
OUT1
           2710
```

¥2

## SYMBOL YABLE

BACK1	2711
OUT3	2734
BACK3	2735
OUT2	2762
BACK2	2763
OUT4	3014
BACK4	3015
OUT5	3047
BACK5	3050
OUT 6	3103
BACK 6	3104
OUT7	3133
BACK7	3134
OUTS	3157
BACKS	3160
BACKS	3214 3215
OUT10	3241 3242
BACK10 BACK11	3317
BACK12	3334
K4010	3343
RET1	3350
K2010	3360
RET2	3370
K1010	3403
RET3	3410
K410	3420
RET4 K210	3430
KET5	3450 3460
RET6	3470
K50	3500
RET7	3510
K30	3520
RETS	353Ø
RET9	355Ø
RET18	3622
K201	3622
BLCNT	3623
RNGCNT	3624
BELCOD	3625
And1	4000
STR	4011
JMPIX	4021

# MAINDEC EVALUATION REQUEST

After sufficient familiarization with the operation and documentation of this MAINDEC, please indicate your assessment of the following areas and return this form to Digital Equipment Corporation.

IDENTIFICATION: MAINDEC NO Program Title
USAGE: Used by: Field Service Production Other
Frequency of Usage: Daily Weekly Monthly
SUGGESTIONS FOR IMPROVEMENT
<ol> <li>Are the program loading and operating instructions: clear?, incomplete?, difficult to follow?</li> </ol>
2. Do the error reports and program documentation provide sufficient diagnostic information. in all cases?, in west cases? Suggestions for improvement:
3. Is the program effective in isolating malfunctions: in all cases? , in most cases? , in very few cases? . Would additional Scope loops or Switch Register control be helpful?
4. Does the program ever fail to detect malfunctions exposed by other software?
Were Margins used?Please describe malfunction in detail:
5. Does the program ever report non-existant malfunctions?
Please indicate erroneous report and any pertinent operating conditions:
6. Does this MAINDEC ever expose malfunctions in the Central Processor or other peripheral units not detected by the appropriate MAINDEC?
Please describe malfunction and MAINDEC(S) used:
7. Does the document provide a general understanding of the functional programming requirements of the system? Good, Fair, None, Would a general description of programming requirements increase the effectiveness of this MAINDEC?
Remarks:

	Fold Here	
	Do Not Tear - Fold Here and Staple	
		FIRST CLASS PERMIT NO. 33
٠		MAYNARD, MASS.
BUSINESS REPLY MAIL NO POSTAGE STAMP NECE	SSARY IF MAILED IN THE UNITED STATES	
Postage will be paid by:	digital	
	Digital Equipment Corporation	
	Diagnostic Programming Group 146 Main Street, Building 12	
	Maynard, Massachusetts 01754	