
FIELD
FIELD JUNCTION BOX
MARSHALLING CABINET
CONTROL CABINET
001 - PT-100
+
-
red
blue
001 - cs-f-2234
1.5mm^2,blue,signal,arm
0001 - JB-100
1
2
3
4
001 - MSC-100
1
2
3
4
001 - DCS-100
10
10
AI523
001 - DCS-100
AC800
INSTRUMENT TAG
CABLE
POLARITY
cable number
cable size, colour,type , insulation etc
JUNCTION BOX NUMBER
JUNCTION
TERMINAL
NUMBER
MARSHALLING CABINET NO
TERMINAL
NUMBER
MODULE CABINET NO
10
10
module number
CONTROLLER CABINET NO
controller number


FIELD
PLC CABINET
HMI / DCS
INSTRUMENT
JUNCTION BOX
PLC MARSHALLING
PLC CONTROLLER
CABLE NO
PART OF
MULTI PAIR CABLE NO.
JINCTION BOX NO.
TB LOCATION
MARSHALING TAB NO,
TAG NO.
+
-
XX
XX
CABLE WIRE COLOR
TX SIGNAL GROUND
XX
XX
XX
XX
XX
XX
S
S
SCN
XX
XX
XX
XX
XX
XX
S
S
SCN
TAAG NO.
TAG NO.
CPU
XX
I / O RACK NO.
XX
SLOT NO.
XX
CHANNEL NO.
XX
XX
XX
SYSTEM TAG NO
XXX
XXX

LOOP DIAGRAM: FURNACE TEMPERATURE CONTROL