

MINCONSULT SDN BHD





Ref: KPCIP/PMCSC/RE-ATD/CW-02/Lot-2/044

Date 20th October 2023

To

The Project Manager

ZKB-M/S T.T. SH-INSAAT LIMITED LIBALITY COMPANY (JV) Abbottabad

Project

ADB LOAN 4160-PAK & LOAN 8412-PAK (AllB CO-FINANCING): KHYBER

PAKHTUNKHWA CITIES IMPROVEMENT PROJECT (KPCIP); OCB-KPCIPCW-02 Procurement of Works for improvements/Construction of Water Supply System: LOT-2; Rehabilitation and upgradation of Water Supply to WTP with SCADA in

Abbottabad Including New Water Treatment Plant, Abbottabad.

Subject

NON-COMPLIANCE UNDER SUB CLAUSE 5.7 & 4.18.

Reference: KPCIP/PMCSC/RE-ATD/CW-02/Lot-2/024

dated 13" September 2023

In continuation of our letter above and the meeting by PMCSC Environmental specialist and HSE officer dated 26/09/2023, we wish to bring into your notice that during our site visit with your Project Manager and General Manger dated 18/10/2023 the following issue that are attached in the annexure have still not been brought in compliance with contract documents, SSEMP and SSHSMP

Please provide a compliance report within mentioned given time of receiving this letter. We value your partnership and hope to see swift improvements in our project's safety standards

Your Sincerely

Engr. Said Afsar

The Engineer/Resident Engineer Water Supply System (Abbottabad) PMCSC-KPCIP

Cc

1 Project Director (PMU-KPCIP, LGE&RDD)

2 Director Compliance (PMU-KPCIP, LGE&RDD)

3. Team Leader (PMCSC-KPCIP)

4. Contract Expert (PMCSC-KPCIP)

5 Contract & Claim Engineer (PMCSC-KPCIP)

6 Chief Executive Officer (WSSCA)

Focal Person (CIU-Abbottabad)

Page 1 of 2

PMCSC Office Abbottabad: AL Haj Raja Munsif Cottage. Ihtisham Colony Nawanshehr ATD, Pakistan Email ID: said alsanucer org.ph





PROJECT MANAGEMENT AND CONSTRUCTION SUPERVISION CONSULTANTS

MINCONSULT SDN BHD JOINT VENTURE CREATIVE ENGINEERING CONSULTANTS

- 8. Health & Safety Engineer (PMCSC-KPCIP)
- 9. Environmental Specialist (PMCSC-KPCIP)
- 10. Office Copy

onsult

-- P-- PERHTUMENT PROJECT

MINCONSULT SDN BHD JOINT VENTURE CREATIVE ENGINEERING CONSULTANTS (PMCSC)



HSE & Environmental Observation Report

Project

LOT-2. Rehabilitation and upgradation of Water Supply to

WTP with SCADA in Abbottabad Including New Water Treat-

ment Plant, Abbottabad.

Purpose

HSE & Environmental Coordination Meeting #1

Venue

M/S ZKB Camp Site Office

Date

18-Oct-023

Time

1200Hrs

Refrences

Contract Aggrement, SSEMP and SSHSMP

Attendees

Employee Name		Job Title	Status	
Employee	A STATE OF THE PARTY OF THE PAR	Resident Engineer	Present	
PMCSC	Engr. Said Afsar	Envirnomental Assocaite	Present	
PMCSC	Engr. Shakir Aziz Dawar	Health & Safety Officer	Present	
PMCSC	Engr. Syed Haroon Ali	Project Manger	Present	
M/S ZKB	Engr. Abdul Majeed	General Manger	Present	
M/S ZKB	M.Aamer Chattha	Envirnomentalist	Present	
M/S ZKP	Ubaid Rehman	Environientano.		

Ref No.	Observation & Discussion	Action by	Planned Date
7.12	No Project Information Board at suggested Site.	M/S ZKB	23-Oct-023
6.3.2	No HSE Representative	M/S ZKB	23-Oct-023
1.14.10	No Flag Man/Supporter	M/S ZKB	23-Oct-023
7.9.1	Generator was not at proper location,well balanced safe mode	M/S ZKB	23-Oct-023
1.14.8	First Aid Kit not available at ConcreteBatching plant and Camp site	M/S ZKB	23-Oct-023
08	No Traffic Management Plan at Batching Plant	M/S ZKB	23-Oct-023
-	Improper availability of PPE's	M/S ZKB	23-Oct-023
6.7 7.13.7	Scattered Scaffolding and other construction material	M/S ZKB	23-Oct-023
3.11	No Dustbin at Camp site, Batching Plant and Construction site.	M/S ZKB	23-Oct-023
7.1	None avalibality of Septic Tank and improper Sockage pit.	M/S ZKB	23-Oct-023
7.12	None avalibaity of mandatory sign boards at any site.	M/S ZKB	23-Oct-023
5.8	Fie extigusher are not at proper location, up- dating and tagging.	M/S ZKB	23-Oct-023

THE BER PARHTUNKHWA CITIES IMPROVEMENT PROJECT

h nconsul*

MINCONSULT SDN BHD JOINT VENTURE CREATIVE ENGINEERING CONSULTANTS (PMCSC)



			and the second s
7.12	Filling station is not properly barricaded.	M/S ZKB	23-Oct-023
08	No Safe loading through dumpers of ex-	M/S ZKB	23-Oct-023
	cavated materials without proper cover-		
	ing sheet during transportation.		
7.1	Unhygenic water cooler for drinking pur-	M/S ZKB	23-Oct-023
	pose at all sites.		
7.7.2	No proper drainage system at camp site	M/S ZKB	23-Oct-023
7.9.1	Electric cable at plant site are not man-	M/S ZKB	23-Oct-023
	aged, no proper pluged in electricity and		
	earthning camp site.		
7.13	Unsafe stair and foundation of concrte	M/S ZKB	23-Oct-023
	batching plant silo.		0.00
7.1	No WASH and inadequate shelter facility.	M/S ZKB	23-Oct-023
08 &	Not peoper water sprinkiling from camp	M/S ZKB	23-Oct-023
05	site to construction site.		
09	No face mask at each site	M/S ZKB	23-Oct-023
5.9	Non availability of emergemcy contact at	M/S ZKB	23-Oct-023
	each site.		22 0-1 022
3.11	Improprer house keeping at each site	M/S ZKB	23-Oct-923