

GOVERNMENT OF KHYBER PAKHTUNKHWA CITY IMPLEMENTATION UNIT (CIU-ABBOTTABAD)

CITY IMPLEMENTATION UNIT (CIU-ABBOTTABAD)

KHYBER PAKHTUNKHWA CITIES IMPROVEMENT PROJECT LOCAL GOVERNMENT ELECTIONS & RURAL DEVELOPMENT DEPARTMENT



ciuatd@gmail.com

Ref: KPCIP/CIU-ATD/CE/ 050

Date:/4902/2024

To,

The Engineer/Resident Engineer (Water Supply)
PMCSC – KPCIP - Abbottabad

Project: <u>CW2 – Lot 2 – KPCIP Abbottabad</u>

Subject: Observations Reported by CIU Engineer – 12-02-2024

During the field visit of KPCIP WTP site on 12-02-2024, the following inaccuracies are reported by the CIU Engineer: -

- 1. The CIU team reached on site at 12:50 PM and found that work on site was in progress in the absence of PMCSC personnels.
- 2. There was no curing on recent plum concrete (right side retaining wall).

PMCSC is advised to ensure the presence of site inspectors on site during working hours, supervise the work in progress and closely monitor the site-specific practices as described in the project specification.

Chief Engineer

City Implementation Unit (CIU)

Abbottabad

Enclosed, Photographs

Copy forwarded to

- 1. Project Director, PMU-KPCIP, LGE&RDD, Govt of KP.
- 2. Chief Executive Officer, WSSCA
- 3. Director Technical (PMU-KPCIP)
- 4. Deputy Team Leader, PMCSC Peshawar.
- 5. Infrastructure Engineer WATSAN, CIU Abbottabad
- 6. Office copy

Chief Engineer


City Implementation Unit (CIU)

Abbottabad



GOVERNMENT OF KHYBER PAKHTUNKHWA

CITY IMPLEMENTATION UNIT (CIU-ABBOTTABAD)





82/3, Opposite AMC Mess, Hill Road, Abbottabad ciuatd@gmail.com

Ref: KPCIP/CIU-ATD/CE/ OSO

Date: 14 702/2024



Plum Concrete (Right Side Retaining Wall) Uncured