

WATER AND SANITATION SERVICES COMPANY **ABBOTTABAD**



(Registered Under Section 42 of the Companies Ordinance 1984) Ph: 0992-9311048, Email: wsscabbottabad@gmail.com

No. CEO/WSSCA/023/ 9333

Date: 19/10/2023

To,

The Engineer/Resident Engineer

Project Management and Construction Supervision Consultant,

Khyber Pakhtunkhwa Cities Improvement Project,

Project:

KHYBER PAKHTUNKHWA CITIES IMPROVEMENT PROJECT (KPCIP PROJECT)

DEVLOPMENT OF URBAN/GREEN SPACES AND PARKS; LOT-1: PEDESTRIANISATION OF OLD CITY

BAZAR & DEVELOPMENT OF SHERWAN HILL PARK.

Subject:

DISCREPANCIES IN THE CERTIFIED / PAID QUANTITIES OF IPC-01

Ref No. CEO/WSSCA/023/9257 dated: 28/09/2023

Ref: KPCIP/PMCSC/RE/ATD/LOT-01/123 dated: 18/10/2023

With reference to the aforementioned letters, WSSCA response is shared as below:

	Description / Pomarks	PMCSC Response	CIU Response
S. No 1	Item Description / Remarks Providing and Fixing of Tempered Glass with Aluminium of thickness 2mm, SS Spider (Grade 202), M.S plates with Powder Coating, Floor Hinge (GCC), Patch Fitting, Handles, Local Silicone, 6mm clear low E glass tempered + 12 mm Air gap + 5mm clear glass Ghani tempered. (U-Value: 1.8, SC: 0.62, LT: 65%). Remarks: PMCSC is required to submit justification for certifying quantities over and above the	The difference indicated by CIU will be adjusted in the next IPC.	Agreed. However, PMCSC is requested to ensure controls in order to avoid discrepancies in certification of work done.
2	actually executed work-done. 1st class brick work in foundation and plinth in Cement, sand mortar 1.3. Remarks: 23 pillars claimed in this IPC while there are 18 pillars in Gol Mandi.	The difference indicated by CIU will be adjusted in the next IPC.	ensure controls in order to avoid discrepancies in certification of work done
3	Main Bus Bar Panel for shops supply at site installation testing and commissioning of Bus bar panel for electrical supply 16 G stall panel board water proof weather proof with foundation double door protection rubber gaskets 400 A TPM.C.C.B 26 KA 1 no voltmeter with VSS Ampere meter with ASS.	meter box. However, the local community dismantled the foundation, causing a delay in the installation. Subsequently, once	observation Is misunderstood by the PMCSC. Please refer to the column No.7 of the Letter Ref No.



WATER AND SANITATION SERVICES COMPANY ABBOTTABAD (Registered Under Section 42 of the Companies Ordinance 1984)

-	Ph: 0992-9311048 Empily	Companies Ordinance 1984)	
	Ph: 0992-9311048, Email: wss	scabbottabad@gmail.com	
	Current Transformer 400/5A phase indication	community, they proceeded with the	and be specific in your
	Birts 400 A 5 No's Bus Bar copper string	panel installation. It's important to	response.
	complete in all respect as per drawings and	note that the contractor has already	Remarks are also
	specifications.	procured all the necessary box	reproduced in 2 nd
	Remarks:	panels.	column of this matrix.
	The job is not completed yet as the		
	components enlisted in item are missing. Also	0.00	
	there were 2 bus bar panels installed at the		
	time of IPC submission, while the 3 rd one is		
5.	installed after the certification of IPC No. 1.	4993	
	PMCSC is required to share justification of		
4	certifying incomplete work done.	A service of the serv	The content of the
4	WAPDA Application	As apparent from our communication	observation is
	Supply of duly signed test reports according	with WAPDA and WSSCA, we have initiated the NOC application	misunderstood by the
	to requirements and acceptable to electrical		PMCSC. Please refer to
	inspector, include obtaining of NOC from	process. The constraint	the column No.7 of the
	electrical inspector, all fee/charges to be paid	responsible for submitting all the	Letter Ref No.
1	by connector. The connector shall also fill the	necessary documents to WAPDA for	CEO/WSSCA/023/9257
	WAPDA application form with necessary	obtaining the NOC. Additionally, we	N
1	electrical load, submit and liase with WAPDA	require an NOC for meter installation	and be specific in your
1	and approve all possible assistance to the	and for carrying out work on live	response.
1	client in getting the electrical connection	wires during the connection with the	Remarks are also
1	from WAPDA. The connector shall paper	meter box.	
	electrical load details sheet then submitted to		column of this matrix.
	planning office of WAPDA department.		
	Remarks:		
	No evidence /supporting documents		
j	attached with IPC.		
	Also, PMCSC informed CIU that Installation of		
1	Transformers has been dropped from the		
	transformers has been dropped from the		
	scope then why this item has been certified		
	for payment?	The installation of Transformers has	Please instruct the
5	Supply and erection of 2-4 core armored/non	been cancelled but we need some	
	armored PVC/PVC copper conductor	been cancelled but we fleed some	
	600/1000 volt grid cable with copper	sources to transmit power from the	
	thimbles of appropriate size, all punching	Transformers to the meter box that's	
	both sides identification tags and nut bolt	why "2-4 core armored non-armored	
	brands Pakistan, Allied, Pioneer cables	PVC/PVC copper conductor 600/1000	the actual work done.
	payments shall be paid actual length installed	volt grid cable" are installed. Without	
		these cables, we can't connect	:
	at site complete in all respect as per	meters directly with the	
	instruction of Engineer in charge 95 mm 4	Transformers.	
-	core PVC/PVC/SWA/PVC	Transjormers.	
	Remarks:		
	This item is the part of Transformer - HT		
	works.		
	As the installation of transformers has been		
	cancelled according to site conditions, so how		Page 2 of



WATER AND SANITATION SERVICES COMPANY ABBOTTABAD

(Registered Under Section 42 of the Companies Ordinance 1984)
Ph: 0992-9311048, Email: wsscabbottabad@gmail.com

		this quantity is paid? Also the approved		
		brands of the cables mentioned are Pakistan,		
		Allied and Pioneer, but the cables installed at		
		the site is none of the aforementioned		
		brands.		
+				T 1 1 11 1
	6	Dismantling: Plain Cement Concrete 1:2:4	As mentioned in BoQ item No.04-19-	The indicated work is
		Remarks:	c, there is an item designated for	out of the scope of the
		There is no pictorial record or evidence for	dismantling. For, your reference, we	project. Therefore, this
1		this claim furnished that could be verified. As	have attached pictorial evidence of	must be deducted in
		informed by PMCSC, the dismantling is done	the dismantling process.	the next IPC.
		in Sarafa Bazar and Gurdwara Street. But, the		
		mentioned dismantling was not part of the		
		approved scope of work. Therefore, these		
		quantities needs to be deducted from the IPC.		
-	7		Breast Wall:	The stance of the
	/	Stone Masonry Random with mortar class-A.	The quantities have been paid in	PMCSC that the
		Remarks:	accordance with the approved shop	quantities have been
		The quantities paid to the contractor are	1	paid in accordance
		more than the quantities executed on site as	didwiiigs.	with the approved
		below;	contractor has left a portion that is	shop drawings is
		Breast Wall:	scheduled for completion in tile near	seriously alarming.
		Length paid for the mentioned RDs: 965 M	future. Based on our measurements,	PMSCS is advised to
1		Length verified on site for those RDs: 846 M	the length of the breast wall currently	
1		Retaining Walls:	stands at 920 meters. We have	only certify
		Length paid for the mentioned RDs: 586 M	identified a shortfall of 45 meters,	quantities/work done
		Length verified on site for those RDs: 506 M	which will be adjusted in the	on actual/site
		Boundary Wall:	upcoming Interim Payment	measurement basis.
ļ		Length paid: 130 M	Certificate (IPC).	Please instruct the
		Length verified on site: 93 M.	Retaining Walls:	concerned personnel
1		Length Vermen on the second	According to our calculations, the	of the PMCSC to visit
			length of the retaining wall measures	the site with CIU team
			582 meters. The contractor has left	and jointly re-measure
			the locations of the pipe culverts.	the actual work done.
İ				the because it and
	ļ		Boundary Wall:	
-		,	The quantities have been paid in	*
			accordance with the approved shop	
			drawings. As per our calculations, the	
			length of the retaining wall measures	
			105 meters. Shortage of 25m will be	
			adjusted in the upcoming Interim	
			Payment Certificate (IPC).	
8		Galvanized wire mesh fence 10 SWG (50 mm	The difference indicated by CIU will	Agreeú. However,
0			be adjusted in the next IPC.	PMCSC is requested to
1		× 50 mm) 3mm thick with pillar 50mm GI pipe	be adjusted in the next if di	ensure controls in
		and concrete footing 210 Kg/cm2 with		order to avoid
		installation and all respect. (Provisional paid).		discrepancies.
		Remarks:		
1		The length of the wire mesh paid in IPC-01 is		
L		exceeding the quantity executed on site.		Page 3 of 4



WATER AND SANITATION SERVICES COMPANY **ABBOTTABAD**



(Registered Under Section 42 of the Companies Ordinance 1984) Ph: 0992-9311048, Email: wsscabbottabad@gmail.com

	Length paid: 702 M		Remarks are also
	Length verified on site: 590.7 M		reproduced in 2nd
			column of this matrix.
9	Plain Cement concrete including placing, compacting, finishing and curing (1:3:6). Remarks: This quantity has been paid as concrete bond in the Retaining walls. So this quantity needs to be deducted from the Stone masonry Random class-A of the retaining walls.	Already deducted in IPC.	CIU observation is based on the certified IPC.No.1. Please refer to any other document where this deduction has been made. Further, Please instruct the concerned personnel of the PMCSC to visit the site with CIU team and jointly re-measure the actual work done.
10	RCC in raft foundation slab, base of column & ret. Wall etc. Remarks: The area of the raft RCC concrete in Restaurant building paid is 348.97 SQ.M while the actual area.	We are adhering to the calculated area provided in the Interim Payment Certificate (IPC). If you have any inquiries or concerns, kindly submit your calculations to our office.	CIU observation is based on actua measurement of raffoundation. Please instruct you concerned personne for joint measurement with CIU team.

Prompt actions as required above are desired at the earliest, please.

Chief Executive Officer Water and Sanitation Services Company Abbottabad

Copy Forwarded to;

- 1. Project Director (KPCIP, LGE & RDD)
- 2. Director Technical (PMU-KPCIP, LGÉ & RDD)
- 3. Team Leader (PMCSC-KPCIP)
- 4. Project Design and Supervision Coordinator (DTL, PMCSC-KPCIP)
- 5. Focal Person, CIU-KPCIP, Abbottabad
- 6. Infrastructure Engineer, CIU-KPCIP, Abbottabad
- 7. The Contracts Manager, CIU-KPCIP, Abbottabad
- 8. Project Manager, M/s Reliable-JHK (JV)
- 9. Office copy.

Page 4 of 4

