

GOVERNMENT OF KHYBER PAKHTUNKHWA CITY IMPLEMENTATION UNIT (CIU-ABBOTTABAD)

KHYBER PAKHTUNKHWA CITIES IMPROVEMENT PROJECT LOCAL GOVERNMENT ELECTIONS & RURAL DEVELOPMENT DEPARTMENT

82/3, Opposite AMC Mess, Hill Road, Abbottabad

** +92 992 92005°

ciuatd@gmail.com

Ref: KPCIP/CIU-ATD/CE/00911

Date: 07/12/2023

To,

The Engineer/Resident Engineer (Water Supply)
PMCSC – KPCIP - Abbottabad

Project: CW2 - Lot 2 - KPCIP Water Treatment Plant, Abbottabad

Subject: Observations: Urgent Resolution Required for Rusty Steel Rebars and Quality Control at WTP
Construction Site

As evident from the attached photograph, the steel supplied and fabricated on site of WTP as well as stored in warehouse is heavily rusted, which is contravening the desirable standards of quality and workmanship.

PMCSC is hereby instructed to submit the stance of "The Engineer" as to why such heavily rusted steel is

being used in WTP.

Chief Engineer / Focal Person City Implementation Unit (CIU), Abbottabad

Enclosed for Reference: Picture 1, 2 & 3

Copy Forwarded to:


1. The Chief Executive Officer, WSSC Abbottabad

2. The Infrastructure Engineer (WATSAN) CIU - Abbottabad


3. The Team Leader, KPCIP-PMCSC, Peshawar

4. Office Copy

Chief Engineer / Focal Person
City Implementation Unit (CIU),
Abbottabad



Picture 1 - Rusted Steel Rebars



Picture 2 – Steel Rebars are Placed Over Concrete Blocks



 ${\bf Picture~3-Steel~Rebars~are~Bordering~with~Ground~which~is~a~Major~Source~of~Moisture~Absorption}\\$