

Inspection Report for PreTrip

Reported By: William Barron

QRCodeID: JAXEF101

Damage:

1) Is Damage: Yes

Tires:

Front -

1) Tires Condition: Fair

2) Rim: Fair

3) Wheel Assembly: Not Checked

Rear -

1) Tires Condition: Not Checked

2) Rim: Not Checked

3) Wheel Assembly: Not Checked

Tire Damage -

1) Flat: Not Checked

2) Low Air Pressure: Not Checked

3) Marginal Thread: Not Checked

4) Loose Lug Nuts: Not Checked

5) Creacks or Cuts: Not Checked

6) Grease Leaks: Not Checked

7) Other Damage: Not Checked

Exterior:

1) HeadLights : Poor

2) 4-Way Flashers : No

3) Reflector : No

4) Windows: Not Functional

5) Exhaust System: Not Checked

6) Tail Pipe: No

7) Wind Shields: No

8) Fuel/Gas Level: 3/4

Date & Time: 02/01/2018 03:19 PM

Vehicle Number: MHT40G1595

Mileage:

1) Change Mileage: Yes

2) Old: kmph

3) New: 50 kmph

Interior:

1) Switches: Not Functional

2) Horn: Not Functional

3) Fans & Defrosters: Not Functional

4) Break Padal & Warning Light: Not Functional

5) Entrance Steps: Fair

6) Cleanliness: No

7) Seat Coushiners : Fair

8) Seat Belts: Fair

Driver's Cabin:

1) Seats & Belt : Fair

2) Directional Lights: Not Functional

3) Parking & Service Brakes : Not Functional

4) Clutch: Not Functional

5) Steering: Not Functional

Engine:

1) Fluid Leak Under Bus: No

2) Loose Wires, Hose Connection: No

3) Belts in Engine Compartment : Fair

4) Oil Level: 3/4

5) Radiator Coolant: No

6) Unusual Engine Noise: Not Checked

Accessories:

1) Wheelchair Lift: Not Functional

2) Special Service Door: Not Functional

3) Manual Pump Handle: Not Functional

4) 2-Way Radio Check: Not Functional

Emergency:

1) Lift Operation: No

2) Emergency Equipment : Not Functional

3) Emergency Door & Buzzers: Not Functional

4) First Aid Kit: Not Checked

5) Door Warning : No

6) Posted Decals: No

7) Control Mechanism: Not Functional

8) Flares :No

9) Fire Extinguisher : No

10) Protective padding: No







