



Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.


o All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Circles, Sketch Patterns

• Features: Extrude Boss

Reference Geometry: Planes









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

· Features: Extrude Boss

Reference Geometry: Planes

HINT: Start ribs inside cylinder wall.









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

• The part is asymmetric.


o All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Rectangles, Arcs, Circles, Slots

• Features: Extrude Boss

Reference Geometry: Planes









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Arcs, Circles, Sketch Fillets

• Features: Extrude Boss

· Reference Geometry: Planes










Reference Geometry (Level 5)

- Units: MMGS
- Difficulty Level: HardCertification: CSWADuration (min): 35
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles
- Features: Extrude Boss, Extrude Cut, Fillets and Chamfers
- Reference Geometry: Planes









Reference Geometry (Level 5)

Units: MMGS


Difficulty Level: MediumCertification: CSWADuration (min): 20

• Design Intent:

- The part's origin location is indicated in red.
- The part is symmetric.
- All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Trim
- Features: Extrude Boss, Extrude Cut
- Reference Geometry: Planes









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWA

• Duration (min): 15

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.

All sketches are fully-defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles, Trim

Features: Extrude Boss, Extrude Cut

· Reference Geometry: Planes

HINT: Use a sketch to define the plane.









Reference Geometry (Level 5)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

• The part is asymmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features


· Sketch: Lines, Centerlines, Circles

• Features: Extrude Boss, Extrude Cut

· Reference Geometry: Planes, Axes

HINTS:

- Create an axis using a standard plane.
- Use Up to Surface end conditions.










Reference Geometry (Level 5)

- Units: MMGS
- Difficulty Level: EasyCertification: CSWADuration (min): 10
- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - o All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Circles, Sketch Fillets, Convert Entities, Trim
- Features: Extrude Boss, Extrude Cut
- Reference Geometry: Planes

HINT: The pipe is tangent to the plate.









Reference Geometry (Level 5)

Units: MMGS


Difficulty Level: EasyCertification: CSWADuration (min): 10

- Design Intent:
 - The part's origin location is indicated in red.
 - The part is symmetric.
 - All sketches are fully-defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Centerlines, Rectangles, Arcs, Circles
- Features: Extrude Boss, Extrude Cut
- Reference Geometry: Planes

HINT: Create a plane on an angle through the front edge, and cut with a circle.





R3