Product Design and Manufacturing

Assignment Week-11

1. What does CIM stands for in context of manufacturing?
   a) Computer-Integrated Management
   b) Computer-Integrated Manufacturing
   c) Computer-Information Machine
   d) Centralized-Integrated Machining

2. Which CIM component is related to the direct control of machine tools using computer programs?
   a) FMS
   b) DNC
   c) AGV
   d) ASRS

3. Which system may involve a worker using hand tools but not power equipment?
   a) Manual work system
   b) Worker-machine system
   c) Automated system
   d) None of these

4. What do industrial robots primarily perform in manufacturing operations?
   a) Quality control
   b) Designing
   c) Processing or assembly operations
   d) Marketing

5. High initial investment for custom-engineered equipment is typically a feature of programmable automation.
   a) True
   b) False

6. How is inspection for variables typically performed in manufacturing?
   a) Measuring
   b) Gaging
   c) Observing
   d) Reading

7. What is defined as the maximum rate of output that a production facility is able to produce under specific operating conditions?
   a) Production efficiency
   b) Plant capacity
   c) Production optimization
   d) Operational throughput

8. Product variety has no impact on the organization of production facilities in a manufacturing plant.
   a) True
   b) False

9. _____ is defined as the quantity of parts or products currently located in the factory that either are being processed or are between processing operations.
   a) Inventory
   b) Throughput
   c) Work In Progress (WIP)
   d) Overhead

10. _____ is a use of computer system to aid in the creation, modifications, analysis or optimization of a design.
   a) CAD
   b) CAM
   c) CADD
   d) CIM