## **SEAT HEIGHT ADJUSTMENT PROPOSAL 1**

2.4" gap between seat back top and lower head rest block.

