APPLIANCE AIRWORTHINESS DIRECTIVE COMPLIANCE STATUS LIST

Indic	÷0								FASA BI-WEEKLY	26-2021 2022-01		EFF DATE		27-Dec-21 02-Jan-22	
The state of the s		AIRCRAFT RESN	A/C	MF# DATE	ACFT TOTAL TIME 3,5845,39			AGELEGIAL CYCLE			DATE AS OF				
A920-21AN		9334 (1.5%)	VIsite	El-Apr.2007					25847		10-10 to 15-100		10 JAN 2022		
EU An	Effective data	DESCRIPTION	REFERENCE FAA	REFERENCE SR, MOD NO.	METHOD OF COMPLIANCE	DATE	HOURS	creas	STATUS	REPEATINTERVAL	DATE	NEXT COMPLIANCE HOURS	CYCLES	PEMARKS	
No corresponding FASA AD Issued		Tollet compartments	74-08-09R3	Installation of placerds "No smoking in lavatory" "No cigarette disposal" Inspection of lavatories	In accordance with para h) announcement to be made that smoking is prohibited in lavatory. Inspection required in accordance with para k) every 1000 FH,	21.Apr.2021	33'376	25'529	Reptitive	1000FH		34375:16		Performed vide WO #9570791	
JS-83-16-01R1		SUNDSTRAND DATA CONTROL Inc. CVR models AV557A/B/C	83-16-01R1	VSB 012-0296-109			20	48	Not applicable	:			192	Not applicable to PNR installed	
JS-89-06-01		SWITLIK PARACHUTE COMPANY Life preserver and individual flotation devices inspection	89-06-01	VSB 25-00-19		*)	*	<u>:</u> *	Not applicable	<u>:</u>		*	200	Not applicable to equipment installed	
No corresponding		Auxiliary Power Units	92-21-05			*:	蛭	28	Not applicable	×	3	8	383	Not applicable to equipment installed	
5-018-10-90	18-Oct-1990	FIRE FIGHTING ENTERPRISES (UK) Ltd Cabin portable fire extinguishers	No corresponding FAA AD issued	VSB A26-106		*:	×	39	Not applicable	79	*	8:	(*)	Not applicable to PNR Installed. PNR 74-20 installed	
-1991-175R1	10-Aug-1991	EROS equipment Full face mask MF10 series	94-06-04	VSB MF10-35-43 VSB MF10-35-44 VSB MF10-35-46		*:	#2	22	Not applicable	×	8	8	3 3 31	Not applicable to PNR installed	
5-92-11-09		ROCKWELL INTERNATIONAL/COLLINS ATC TPR-720 P/N 622-7878-020 & -120	92-11-09	VSB TPR-720-34-08 OR VSB TPR-720-34-C		30	50	.5	Not applicable	(5		1 2	580	Not applicable to PNR installed	
to corresponding ASA AD issued		Emergency oxygen containers	92-12-06	ISB A320-35-1002 Rev 01		*	8.	24	Not applicable	F: 18	18	*	(0)	IMSN not affected.	
-1992-085R2	11-Apr-1992	EROS full face mask MF10 serial	No corresponding FAA AD issued	VSB MF10-35-47 Rev 01		50	54	15	Not applicable	i.e	22		(5)	Not applicable to PNR installed	
5-92-16-15		SCOTT AVIATION Oxygen mask plug-in connectors P/N 289-57	92-16-15	VSB 289-35-15		27	20	82	Not applicable	92	2	25	950	Not applicable to PNR installed	
i-004-09-92	4-Sep-1992	FIRST TECHNOLOGY FIRE AND SAFETY Cabin portable fire extinguishers Discharge head assy	No corresponding FAA AD issued	VSB 26-108				:4	Not applicable	¥	2	3		Not applicable to PNR installed	
JS-93-09-07		HTL PACIFIC SCIENTIFIC Fire extinguishers - Non indication of discharge	93-09-07	AOT 26-08 OR VSB 26A1106		±	÷ .	is.	Not applicable)±	3		920	Not applicable to PNR installed	
JS-93-14-12		ESSEX PB&R CORPORATION - Crewmember protective breathing equipment FELS Model 4566M37B.	93-14-12	VSB 001 Rev 01			15	8	Not applicable			5.	(<u>#</u>)	Not applicable to PNR installed	
NL-93-168	1-Jan-1994	INVENTUM galley products water heater pressure relief valve	95-25-08	VSB 25-344 OR VSB 25-345 OR VSB 25-346 OR VSB DR1-DR6-25-5		8	Āi	SZ.	Not applicable	15	æ	*	\$ \$ \$	COFFEE MAKER NOT INSTALLED	
US-93-23-01		NORDSKOG industries water heaters and coffee makers with NUPRO pressure reflef valve PN SS-2C4-65	93-23-01	VSB 93-34		ν		12	Not applicable	· ·	=		747	COFFEE MAKER NOT INSTALLED	
JS-93-24-16		PURITAN BENNETT Aero Systems protective breathing equipment 119003 and 119003-01 units	93-24-16	VSB 119003-35-1				-	Not applicable	e e				Not applicable to PNR installed	
JS-94-01-04		HONEYWELL - Traffic Alert and Collision AvoiDHnce System (TCAS) II processors removal	94-01-04	VS8 4066010-34-5W16	9	*	*		Not applicable	-			æ	Not applicable to PNR installed T2CAS installed.	
JS-94-01-05		ALLIED SIGNAL (BENDIX) - Traffic Alert and Collision AvoiDHnce System (TCAS) II processors removal.	94-01-05	VSB TPA-81A-34-72		*	*:	34	Not applicable	i.e	7.0	× .	(48)	Not applicable to PNR installed TZCAS installed	
JS-94-01-06		ROCKWELL INTERNATIONAL - COLLINS AIR TRANSPORT DIVISION - Traffic and Collision AvoiDHnce Systems (TCAS) processors removal.	94-01-06	VSB TTR-920-34-16		•	ě	- 4	Not applicable		8	8	(4)	Not applicable to PNR installed TZCAS installed.	

APPLIANCE AIRWORTHINESS DIRECTIVE COMPLIANCE STATUS LIST EASA BI-WEEKLY 26-2021 EFF DATE IndiGo FAA BI-WEEKLY 2022-01 EFF DATE ASSN AVECTANT NEEN A/C MFR DATE ACFT TOTAL TIME ACFT TOTAL CYCLE DATE AS OF A920-714W 9195 VT-HOS 20.Apr, 2007 03388:58 103AN 2022 LAST COMPLIANCE PETERENCE FAA RETERENCE SO, MOO TUAD Effective data DESCRIPTION METHOD OF COMPLIANCE STATUS REPEAT RETERVAL AD. DATE HOURS CYCLES DATE HOURS CYCLES) Rev 01 VSB DME-700-34-20 COLLINS - Distance Measuring Equipment DME 700 -Rev 01 Not applicable to PNR installed US-94-02-02 94-02-02 Not applicable Modification VS8 DME-700-34-25 VSB DME-700-34-26 NORDSKOG Industries water heaters and coffee makers with VSB 93-35 US-94-14-03 94-14-03 Not applicable COFFEE MAKER NOT INSTALLED NUPRO pressure relief valve PN SS-2C4-65 AFM Insert copy of AD VSB TPA-81A-34-82 N/A TO TCAS MODEL INSTALLED US-95-26-15R1 ALLIED SIGNAL TCAS CAS-81 95-26-15R1 Not applicable T2CAS installed. VSB TPA-81A-34-84 PTC Seating products Division - B/E Aerospace model 950 series 96-12-09 VSB 25-1192 Rev 01 US-96-12-09 VSB 25-1330 Not applicable to PNR installed Not applicable pax, seat equipped with footrest assembly VSB 4500001-49-52 F-1996-293R1 APIC APU APS 3200 software 97-03-06 Not applicable MOD 35864 embodied ASL AIR LIQUIDE NBR Not applicable to PBE installed F-1997-088R1 20-Mar-1997 AIR LIQUIDE Smoke hood type 15-40F visors corresponding 25-001 Not applicable FAA AD Issued VSB 95-25-003 Not applicable to PNR installed F-1997-134 28-Jun-1997 SICMA AERO SEAT passenger seat leg collars corresponding Not applicable Dragon Fly seat installed FAA AD Issued inspection FIRST TECHNOLOGY FIRE AND SAFETY tollet halon fire Not applicable to PNR installed G-007-11-97 7-Nov-1997 98-24-27 Not applicable extinguisher bottle VSB 26-110 MS6 A320-25-1208 VSB 150-25-026 VSB 151-25-027 Not applicable to PNR installed F-1998-341R1 3-Oct-1998 SICMA AERO SEAT cabin attendant seats protection plates corresponding Not applicable VSB 151-25-032 Zodiac aerospace seat installed FAA AD Issued VS8 160-25-028 VSB 161-25-029 VSB 150-25-036 23-Jan-1999 F-1999-004 SICMA AERO SEAT attendant seat protection plates 2006-08-03 Not applicable 000 100 Not applicable to PNR installed . VSB 151-25-037 VSB 90-25-002 Seats 42XX series, 50XX series, 63XX VSB 90-25-005 series, 65XX series, 71XX series, 78XX 23-Jul-1999 F-1994-085R2 SICMA AERO SEAT Passenger seats aft track fittings 2007-04-15 Not applicable series, 83XX series, 85XX series, 90XX VSB 90-25-009 series, 91XX series, and 92XX series No corresponding Not applicable to PNR installed **Auxiliary Power Units** 2000-04-24 Not applicable FASA AD issued VSB 2-1598-32-1

US-99-25-07

F-2000-042

US-2000-07-27

US-2000-14-14

5-Feb-2000

BF GOODRICH MLG brake oxiDHtions

SICMA third occupant seat head rest locking point

HONEYWELL air data inertial reference unit (ADIRU)

BF GOODRICH main brake thermal oxiDHtlon

99-25-07

2006-25-15

2000-07-27

2000-14-14

VSB 2-1600-32-2 VSB 133-25-006

VSB HG2030AD-34-

VSB 2-1598-32-2

VSB 2-1600-32-3

A0009

27-Dec-21

02-Jan-22

REMARKS

Not applicable to PNR Installed

PN HG2030AF23 ADIRLUIS INSTALLED.

Not applicable

Not applicable

Not applicable

Not applicable



APPLIANCE AIRWORTHINESS DIRECTIVE COMPLIANCE STATUS LIST

IndiGo									EASA BI-WEEKLY	26-2021		EFF DATE EFF DATE		27-Dec-21	
MSN			Eweys 0=100	1	ACCUMANTAL VILLE			FAA BI-WEEKLY 2022-01 ACFT YOTAL CYCLE			EFF		02-Jan-22		
200224744			AIRCRAFT REEN		MIR DATE	1	ACFT TOTAL TIME			A CONTRACTOR OF THE PARTY OF TH				DATE AS OF	
A920-214N		D188	VTOHH	20.Apr,2007		93989.59				25647				10 JAN 2022	
EU AD	Effective date	DESCRIPTION	REFERENCE FAA	REFERENCE SB, MODE	METHOD OF COMPLIANCE	DATE	LAST COMPLIANCE	CYCLES	STATUS	REPEAT INTERVAL	DATE	HOURS	GYGLES	REMARKS	
G-002-11-2001	2-Nov-2001	B/E AEROSPACE SKYLUXE II (AAZ) possenger seat hydroloc pin	2007-19-13	VSB 25-20-2658		(20	nuoja .		Not applicable	ā	2/	19972	3	Not applicable - B/E AEROSPACE SKYLUXE II (AA2) Seats not installed -	
F-2001-613	22-Dec-2001	SICMA AERO SEAT 9G passenger seats - Backrest link replacement	2011-21-08	V58 90-25-013 Rev 03		(9)	598	*	Not applicable		20	848	-	Not applicable to PNR installed ZODIAC DRAGONFLY MODEL 3104 SEATS ARE INSTALLED	
F-2002-104R2	2-Mar-2002	ANJOU AERONAUTIQUE Safety belts and restraint systems Type 343-1 - Inspection and replacement - Life limits	2003-26-06	VS8 343-1-25-01		351			Not applicable	5:		3.5	a	NOT APPLICABLE TO EQUIPMENT INSTALLED.	
F-2002-471R1	7-Dec-2002	SICMA AERO SEAT seat belts attachment fittings	corresponding FAA AD Issued	VS8 91-25-032 VS8 91-25-045		E#8	280	*	Not applicable	*	**	225		Not Applicable to equipment installed	
F-2002-504	12-Oct-2002	SICMA Passenger seat central spreaders for type 90XX and 92XX	111000000000000000000000000000000000000	VSB 92-25-005		;es:	3:00	*	Not applicable	*		100		SICMA AERO SEAT Seats 90xx and 92xx series not installed	
US-2002-21-01		BRITAX SELL remote water boiler / coffee maker / water boiler and beverage maker	2002-21-01	VSB E33-4-0/ISB REV 01 VSB E33-4-0/ISB VSB E33-4-0/ISB VSB E33-4-0/ISB VSB E33-4-0/ISB Rev 01 VSB E33-4-0/ISB Rev 01 VSB E33-4-0/ISB Rev 01 VSB E33-4-0/ISB Rev 01	N	39	₹\$9		Not applicable		5	(2)	3	Not Applicable to equipment installed	
F-2002-105R2	2-Mar-2002	ANJOU AERONAUTIQUE Safety belts and restraint systems Type 343 - Inspection and replacement - Life limits	2003-26-06	VS8 343-25-02		(4)	1985	*	Not applicable	*	*	E	*	Not applicable to equipment installed.	
U5-2003-26-14		KIDDE AEROSPACE Part Number (P/N) 898052 Hand Held Halon Extinguishers	2003-26-14	VSB 898052-26-449					Not applicable	2	¥ ,		14	Affected P/N not installed.	
D-2004-151R1	27.Sep.2006	RECARO seat model 3410 - seat belt retaining bolt connection	2006-17-13	VSB 3410-25MR477 Rev 03		2,84	1/27		Not applicable	*		-	94	N/A as affected equipment not installed	
F-2004-132	14-Aug-2004	Equipments/Furnishings - LERMER GmbH water boilers	No corresponding FAA AD issued	LERMER GMBH CMM25-30-31 OR ISB A320-25A1299		542	1(#2		Not applicable	*	÷	E	÷	Affected P/N not installed,	
No corresponding EASA AD issued	01.Dec.2004	Cargo restraint strap assemblies	2004-22-01			(2)	12:	ú	Not applicable	2	2	ž.		Applicable to straps for restraining cargo pellets. This A/C does not have provision for cargo pellets.	
F-2005-164	8-Oct-2005	SOGERMA - Cockplt seats actuators inspection and replacement	2006-22-04	VSB TAAI1-25-617		685	285	*	Not applicable	19	•	±2.	e e	Not applicable to PNR installed	
2006-0220	31-Jul-2006	RECARO - Passenger seats - Inspection of Seat Belt Shackle	No corresponding FAA AD issued	VSB 4420-25BQ12B OR VSB 3510-25BQ073 OR VSB 4400-25BQ046		346	185	-	Not applicable	4	2	25	īs	Affected P/N not installed. ZODIAC DRAGONFLY MODEL 3104 SEATS ARE INSTALLED	
2006-0264	13.Sep.2006	AVIOINTERIORS - Passenger Seats - Rear Fitting Assembly	No corresponding FAA AD Issued	VSB 180-AB4-01 Rev 01		/E	161		Not applicable			- 20		Affected P/N not installed ZODIAC DRAGONFLY MODEL 3104 SEATS ARE INSTALLED	
2006-0334 R1	14-Nov-2006	Communications - Thales Communication VHF Data Radio - Modification	No corresponding FAA AD Issued	VS8 EVR7-23-05 Rev 01		Œ	780	*	Not applicable	*	×	1.63	*	Affected P/N not installed.	

APPLIANCE AIRWORTHINESS DIRECTIVE COMPLIANCE STATUS LIST EASA BI-WEEKLY 26-2021 EFF DATE IndiGo FAA BI-WEEKLY 2022-01 EFF DATE A/C MFR DATE ACFT TOTAL TIME ACET TOTAL CYCLE DATE AS OF 55576 AIRCRAFT REGN A370-21472 VT-mit 20.Apr.2007 93883-59 25847 10 JAN 2022 9196 LAST COMPLIANCE HIXT-COMPLIANCE REFERENCE FAA REFERENCE SO, MOD EU AD Effective date DESCRIPTION METHOD OF COMPLIANCE STATUS REPEATINTERVAL ATT HOURS CYCLES DATE HOURS Fire Protection - Portable Fire Extinguishers - Identification / Affected P/N not installed. 2009-0251-E 26-Nov-2009 Not applicable corresponding extinguishers Replacement Portable fire ex PNR 74-20 Installed FAA AD leeum AVOX Systems and B/E Aerospace oxygen cylinder bottle type nspect O2 cylinders US-2009-21-10R1 04.Feb.2010 2009-21-10R1 26.Feb.2010 7041 5814 COMPLIDE WIDE PREVIOUS OPERATOR complied with VSB 1151324-25-39 imergency Locator Transmitter - Potential Fallure To Transmit CF-2009-44 31.Dec.2009 corresponding Not applicable ELT p/n 51821502-02 installed The Required 406MHz Coded Signal FAA AD Issued Portable: p/n 170833764 (HI-IOAIR) s/n 1357825 (AFT), s/n 1255160 (AFT), s/n 0946716 (FWD), s/n 0947453 Fire Protection - FFE Portable Halon 1211 Fire Extinguishers VS8 AS8-26-115 2009-0262R1 10-Feb-2010 corresponding Not applicable dentification / Replacement (FWD), s/n 0947095 (CKP); Lavatories : FAA AD issued p/n BA24320Al s/n 34826, s/n 34829, s/n 24822 Not applicable: p/n HI-IOAIR s/n 1357825 Identify/remove Fire Protection - SiCLI Portable Halon 1211 Fire Extinguishers -(AFT), s/n 1255160 (AFT), s/n 0946716 08.Mer.2010 2009-027B 2010-04-16 extinguisher Not applicable (FWD), s/n 0947453 dentification / Replacement (FWD), s/n 0947095 (Not applicable: p/n HI-IOAIR s/n 1357825 Replace extinguisher (AFT), s/n 1255160 (AFT), s/n 0946716 Fire Protection - FFE Portable Halon 1211 Fire Extinguishers No corresponding 2010-04-16 Not applicable EASA AD issued identification / Replacement (FWD), s/n 0947453 (FWD), s/n 0947095 (CKP Portable: p/n 170833764 (HI-IOAIR) s/n VSB ASB-26-116 1357825 (AFT), s/n 1255160 (AFT), s/n Fire Protection - Halon 1211 Fire Extinguishers - Identification , 2010-0062R1 31-May-2010 corresponding Not applicable 0946716 (FWD), s/n 0947453 Issue B (FWD), s/n 0947095 (CKP); Lavatories: p/r FAA AD (esum RADARDON SON BARDS SON BARDS SA B/E Aerospace Protective Breathing Equipment (PBE) Part VSB 119003-35-5 US-2011-01-09 09.Feb.2011 2011-01-09 Not applicable PBE p/n 15-40F-11 installed Number 119003-11- Replacement Complied by previous operator Flight crew oxygen mask regulator p/n MF20-VSB MXH-35-240 Rev Oxygen Mask Regulator Inflatable Harness - Identification / VSB MXH-35-240 Rev 04 534 s/n SE56377, s/n SE56123, s/n 2011-0090R1 27-Jul-2011 2015-08-07 Not applicable Replacement SE57317 and In CE15510 Equipment and Furnishing - Life Jacket Vacuum Bag -VSB 25-65-24 Infant life vest p/n P0640-SERIES installed 2011-0094 6-Jun-2011 Not applicable Modification VSB 7517900-34-6040 Rev 02 VS8 9000000-34-6017 Rev 02 VSB 7517900-34-6048 AMOC APRIL 12, 2012 AMOC DATED MAY 25 2012 VSB 7517900-34-6047 AMOC DATED MAY 31 ISB 4370-34-1516 US-2012-02-08 13.Mar.2012 ACSS TCAS Interference limiting 2012-02-08 2012 Not applicable Computer T3CAS 9005000-10204 installed ACSS SB 9000000-34-6030 VSB 9000000-34-6030 AMOC DATED JUL 12,

2012 VSB 7517900-34-6050 AMOC DATED JUL 12. 2012 VSB 9000000-34-6026 AMOC DATED NOV 07 2012 MSB A320-34-1488

27-Dec-21

02-Jan-22

REMARKS

IndiC	-	APPLIANCE AIRWOR	RECTIVE COMP	LIANCE STATUS E	.51			FASA BI-WEEKLY 26-2021 FAA BI-WEEKLY 2022-01			EFF DATE		27-Dec-21 02-Jan-22	
MIN		AIRCHAFT BEISN	A/CA	SER DATE	AGFT TOTAL TIME			TAN DI WEEKE		CFFUBIE		DATE AS OF		
		9198	VICEHH	20.Apr,2007			93989-59			ACFT TOTAL EYELE		10.0		10 JAN 2022
EUAD	Effective date	ONSCRIPTION	REFERENCE FAA	PEFERENCE SW, MOO	METHOD OF COMPLIANCE	LAST COMPLIANCE			STATUS	BENEAT INTERVAL		HEXT COMPLIANC		MEMANYS
2012-0038	26-Mar-2012	SICMA AERO SEAT 16G passenger seats - Backrest links	2015-10-02'	90-25-012 Rev 06		DATE	HOURS'	cyars	Not applicable	=	DATE	Holms	CYCLES	Not applicable - Affected SICMA AERO SEAT seats 9140, 9166, 9173, 9174, 9184, 9188, 9196, 9187, 9188, 91CO, 91C2, 91C4, 91C5, 91C9, 9301 and 9501 not installed
2012-0254R1	21-Dec-2012	Oxygen - Flight Crew Oxygen Mask Regulator - Identification / Operational Procedure / Replacement	2015-23-09	VSB MCF-SBU-35-001 Amend AFM with copy of AD		737	155	3	Not applicable	a ŝ	5	8	3	Flight crew oxygen mask regulator p/n MF20-S34 s/n SE56377, s/n SE56123, s/n SE57317 and s/n SE15510
US-2012-26-15 R1	03.Dec.2014	Honeywell air data pressure transducers	2012-26-15 R1	VSB ADM/ADC/ADAHRS-34 A01 R00 OR AOT A34N001-12 R00 Submit finding report OR AMOC DATED FEB 22, 2013		052	050	۰	CANCELED		5.		22	AD Cancelled -
2013-0020 R4 (correction)	11-Jul-2014	Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement [Corrected on S-Sep-2014]	No corresponding FAA AD issued	AD 2013-0020 R4		04.Aug.2013	15765	12454	complied with	*		· e	*	COMPLIDE WIDE WO# 101091365
CF-2013-25	26-Aug-2013	Emergency Locator Transmitter - Battery Wiring Installation Discrepancies	2014-17-02	VSB 1152682-23- A22 Rev 01 OR AMOC Dated Sep 17, 2013		/#2	383		Not applicable	*		: :	#	ELT p/n 51821502-02 Installed +
J\$-2014-05-27	02.May.2014	NAVIGATION - Rockwell Collins, Inc. Mode S transponders TPR- 720 TPR-900	2014-05-27	Rockwell Collins SIL 13- 1R1		129	150	2.5	Not applicable		9	18	8	Mode S Transponder p/n 7517800-10100 Installed
2014-0088	29-Apr-2014	Communications - Cockpit Voice Recorder - Replacement	No corresponding FAA AD issued	Replace CVR with a serviceable		is	i i	2	Not applicable	*		£1	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Affected PN not installed. CVR p/n 980- 6022-001 installed
2015-003B R1	16-Feb-2017	POWERPLANT-FORWARD ENGINE MOUNT-INSPECTION	2016-09-06			- 18 j.		3	Superseded	*		*)) 2	Superseded by EASA AD 2017-0231
2016-0044	22-Mar-2016	FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL				F2		2	Not applicable	8	8	5	ig.	Component not installed
US-2017-18-12	16.Oct.2017	B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT- INSPECTION/REPLACEMENT	2017-18-12	BE Aerospace VSB 119003-35-009 R1			1 20		Not applicable	×		÷		Not applicable - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT P/N 119003-11 NOT INSTALLED -
2016-0210	7-Nov-2016	B/E AEROSPACE FISCHER GmbH - Seat Energy Absorber Assembly - Replacement	No corresponding FAA AD issued	15		6	a a		Not applicable			×	90	Not applicable to PNR Installed ZODIAC DRAGONFLY MODEL 3104 SEATS ARE INSTALLED
No corresponding	07.Apr.2017	AIR TRANSPORT ASSOCIATION (ATA) OF AMERICA CODE 44, CABIN SYSTEMS.	2017-04-06			6			Not applicable		*	*	3.0	Not applicable - Integrated Stand-By Instrument (1515) Thales installed
No corresponding EASA AD issued	S	"ENGINE - TRANSFER GEARBOX ASSY - REPLACEMENT OF SUSPECTED BATCH OF RADIAL DRIVE SHAFT ASSY & ASSOCIATED RADIAL DRIVE SHAFT OUTER HOUSING	2017-05-09	CFM 58 72-0934		÷	1 2	£9	Not applicable			8	997	N/A to this aircraft MSN
2017-0225	1-Dec-2017	EQUIPMENT / FURNISHINGS - SEAT RESTRAINT SYSTEMS - AFM AMENDMENT / MODIFICATION	137	Schroth S8 40.073-25- 01 R0		¥:	÷	3	Not applicable	s		×	20	Applicable to Schroth Safety Products P/N's. Affected P/N not installed on this aircraft
2018-0223	31-Oct-2018	ATA 25 - EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY	2019-14-05			1.2	ž.	3.5	Not applicable		3.	ž	38	Applicable to Common Seats 170/260 H160 installed in helicopters, Not applicable to this aircraft.
No corresponding EASA AD issued	6-Jul-2010	AVOX Systems and B/E Airospace Oxigen Cylinders as installed on Various 14 CFR Part 23 and CAR 3 Airolanes.	2010-11-05	VSB 176000-35-01; 6084-34-35-01 R 1					Not Applicable					N/A by S/N Installed
2019-0010	6-Feb-2019	ATA 25 - Equipment / Furnishing - Life Jacket - Removal / Repair		Safran Aerosystems Service Bulletin (SB) 25 65-33					Not Applicable					N/A due SNR Installed

APPLIANCE AIRWORTHINESS DIRECTIVE COMPLIANCE STATUS LIST

IndiGo									FASA BI-WEEKLY		26-2021 2022-01		DATE	27-Dec-21 02-Jan-22	
		MSN	AIRCHAFT RESN	A/C	A/C MFR DATE		ACET TOTAL TIME			ACFT TOTAL CYCLE				DATE AS OF	
A320-214H		3138	VT-IIIII	70	20 Apr. 2007		3,3868-59		25607			10 JAN 2022			
EUAD	Effective date	DESCRIPTION	REFERENCE FAX	REFERENCE SW, MOD	METHOD OF COMPILANCE	LAST COMPLUNICE			STATUS	REPEAT INTERVAL		HEAT COMPLIANCE			
	STANSAN CONTRACTOR		Ab	1/0		DATE	HOURS	CYGES	a)asse	PEPEAS PRINTINGE	DATE	Houls	CYCLES	REMARKS	
No corresponding EASA AD issued	28-Dec-2018	AIR TRANSPORT ASSOCIATION (ATA) OF AMERICA CODE 25, EQUIPMENT/FURNISHINGS.	2018-23- 12(CORRCTN)			F	16	.22	Applicable	Thr. 1'260 D	10Jun.2022	Ψŝ	I	Will be compiled as and when due	
No corresponding EASA AD issued	26.Oct.2018	AIR TRANSPORT ASSOCIATION (ATA) OF AMERICA CODE 34, NAVIGATION.	:2018-23-03	2018-23-03	,	F:	ē.	÷	Not applicable	® ≆	*	*	13	APPLICABLE TO HONEYWELL TPA-100B TCAS P/N 940-0351-005 MODIFIED BY AN EASA STC. NO MODIFIED TCAS FITTED PER EASA STC.	
2018-0264 R01	21-Dec-2018	ATA 25 – Equipment / Furnishings – Life Vest Pouch – inspection				19		Ē	Not applicable	Š		50	a.	Not applicable to PNR Installed ZODIAC DRAGONFLY MODEL 3104 SEATS ARE INSTALLED	
2017-0192	21.May.2019	JOINT AIRCRAFT SYSTEM COMPONENT (JASC) CODE 2520, PASSENGER COMPARTMENT EQUIPMENT	2019-08-01	RECARO SB No. 3510- 25-609, 3510-25-752 & 3510-25-753					Not Applicable					Not applicable - Affected RECARO Seats TYPE 3510A not installed	
NO CORRESPONDING EASA AD ISSUED	11.May.2021	JASC CODE - CABIN EQUIPMENT / FURNISHINGS	2021-07-13			11.Aug.2021	33'607	25'676	complied with			\$1	ī	COMPLIDE WIDE WO# 9961004	
2021-0279	29.Dec.2021	Equipment / Furnishings — Doghouse Placard — Installation	No	Airbus SB SB A320-25-1BXK SB A320 25-1BXJ Bucher Leichtbau AG VSB 204XXX0-25- 001 DIEHL Aviation Hamburg GmbH VSB A2-252-25-030						-				Not applicable as Dog house not installed on IGO fleet.	

Authorized IGO Representative

Signature:
Name: SOURAV WAS
Designation: ASST, MANAGER
Quality Assurance & Tech. Services
InterGlobe Aviation Limited (IndiGo)