

# **Seattle Fire Department**

# **Full Data Incident Report**

**Incident Number** 

SFD-24-0062811

Incident type

Alarm system sounded due to malfunction

**PSAP Call Date/Time** 

05/10/2024 21:34:16

Officer in Charge

Lujan, Matthew

Incident Address

809 OLIVE WAY, SEATTLE, WA, 98101

County Fire Zone

Zone 2 (Seattle)

**Business Name** 

THE OLIVIAN

**Property Type** 

King County

Multifamily dwelling. Includes apartments, condos,

 $town houses, \ rowhouses, \ tenements.$ 

**Dispatch Information** 

**Dispatched Incident Type** 

FDID Number 17M15-

Dispatched Number

F240062811

Alarm Date/Time

05/10/2024 21:34:16

**Dispatch Notified** 

05/10/2024 21:34:16

Date/Time

Number of Alarms

Incident Location Information

**Pre-Incident Property** 

Value (\$)

142,278,400

1

Area

501,239

Apparatus			
Department Unit 1 of 2			
Apparatus Name	E25	Dispatch Date/Time	05/10/2024 21:34:44
Туре	Engine	Acknowledge Date/Time	
# of Crewmembers	4	En Route Date/Time	05/10/2024 21:34:48
Use	Suppression	Arrive Date/Time	05/10/2024 21:37:20
ALS Support Capable	No	Clear Date/Time	05/10/2024 21:53:35
Location at Dispatch	Assigned station	Back in Service Date/Time	
Crewmembers	Lujan, Matthew   Cox, Mark   Nagel, Lindsay   Ramirez, Robert		

Apparatus			
Department Unit 2 of 2			
Apparatus Name	L4	Dispatch Date/Time	05/10/2024 21:34:44
Туре	Other apparatus/resource	Acknowledge Date/Time	
# of Crewmembers	4	En Route Date/Time	05/10/2024 21:36:29
Use	Other	Arrive Date/Time	05/10/2024 21:40:04
ALS Support Capable	No	Clear Date/Time	05/10/2024 21:56:20
Location at Dispatch	Assigned station	Back in Service Date/Time	
Crewmembers	Snow, Craig   Evans, Ted   Hartung Jr, William   Irvine, Andrew		

Weather Information				
Temperature	64.4 °F	Wind Speed	2.57 mph	
Wind Direction	Northwest	Humidity	63%	
Weather Type	Clear, less than 1/10 cl cover	oud		

# Fire Information

Equipment Involved in Ignition

No

Vehicle involved in Incident?

No

## **Hazardous Materials Information**

HazMat Released

None

Equipment Involved in

No

Release?

Vehicle Involved in

Release?

No

### **Operations Information**

**Operations Section** Engaged?

No

Par Completed

No

#### **Actions Taken**

#### Department

Restore fire alarm system

Investigate

#### **Narratives**

### **Department NFIRS Narrative**

E25 L4 arrived to building in alarm with FACP indicating detector activation in floor 1 trash room. L4 investigated and found no smoke or fire but di find activated detector. E25 reset FACP and all units returned to service.

Last update on 05/11/2024 at 19:43:24 by E25

Report Completion		
Officer In Charge		
Lujan, Matthew		
Member Completing Report		
Lujan, Matthew		
Date	05/11/2024	