

TOURISM INFRASTRUCTURE AND ENTERPRISE ZONE AUTHORITY

6th & 7th Floors, Tower 1
DoubleDragon Plaza
DD Meridian Park
Macapagal Avenue corner
EDSA Extension 1302
Bay Area, Pasay City

ADSD.QF.29 Appendix 60

PURCHASE REQUEST										
Department: Division:		Corporate Planning Department COPD - Proper	P.R. No.: Date:	14 June, 2021						
Stock No.	Unit	Item Description	Quantity	Estimated Unit Cost						
_	рс	Ball Joint Upper	2	1,190.00	Php2,380.00					
	set	FRT Wiper Blade	1	975.00	Php975.00					
		Underchassis Works (Remove and replace ball joint upper - labor)			Php1,200.00					
		(See attached Job Order for your reference)								
xxxxxx	XXXXX	xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	xxxxxxx	TOTAL XXXXXXXXX	<u>₹4,555.00</u>					
		- 3								
Purpose:		For maintenance of TIEZA vehicle service		5						
Signature: Printed Name:		Requested by: FRANCIS RANDY J. HORTELANO	Approved By: MICHAEL L. MARQUEZ							
Designation:		Manager, Corporate Planning Department	Ţ	Technical Assistant						

MAN-AR AUTO REPAIR SHOP

299 National High Way Barangay Banlic, Cabuyao Laguna Tel. # 566-5036 / 0917-187-4009 / 0923-089-0137

(JOB ORDER)

TOMER:		TIEZA	JOB REF NOS. :	2021-06-26905	
URANCE:	CORPOR	ATE	DATE:	June 8, 2621	
TYEAR		TOTA INNOVA DSL	Contact No.:		
ASSES NO.:			Plate no :	SJS-272	
		Engine No.:	Marketing Exec.:	EGAY	
O METER:		PARTS			
-	Unit	ITEM	Unit Price	TOTAL	
Qty.	PCS	BALL JOINT UPPER	1,190.00	2,380.00	
	SET	FRT WIPER BLADE		975.00	
	SEI	PKI WIFER BLADE			
w.				3,355,00	
			Total Parts	3,500,000	
Was the same and the		JOBS			
NDERCH	ASSIS W	ORKS and replace ball joint upper.		1,200.00	
ECTRIC	AL WOR	and replace fit wiper blade.			
			Total Labor	1,650.0	
rice quoted h storage of P	hp 350.00 p	timates base on current prices which are subject to er day in case of unit pull-out or cancellation of rep	change without prior notice and ouir. Gross Total 12% VAT	is not valid on court. 5,005.(600.	

12% VAT 5,605.60 **Grand Total**