

Infrastructure Inspection Report

Date: 2026-04-14 19:50:30

1. Summary of Detections

Total issues detected: 1

Damage Type	Confidence	Est. Size(cm)	Severity	Action Priority
Crack	17.1%	98.5% Area	High	Immediate Repair

2. Visual Incident Log

Crack: High (98.5%)

