Static storyboards of the five hidden constraint families

Fixed coupling

Rest



Push X



Torque CCW



Revolute hinge

Rest



Torque CCW



Torque CW



Prismatic guide

Rest



Push X



Push Y



Ratchet wheel

Rest



Torque CCW



Torque CW



Gear pair

Rest



Torque CCW



Torque CW



Red arrows show the applied probe; coloured cues and trails show the resulting motion.