

P. S. 73-91

Week of: _____ Date Received 1/25/91

LASER PERFORATED TIPPING APPEARANCE CHECK
HOLE DEPTH, SCORCHING, CRATERING

Module: 412 Brand: CARLTON Filter 100's - 4 My Laser

Shift & Date: _____ Pulse: _____ Mfg. for Taiwan
Power: _____

FRONT CIGARETTES

Hole Depth: <1 mm 13.0 mm from end

Scorching: Insignificant.

Cratering: None to insignificant.

Comments: Excellent appearance (18 holes).

BACK CIGARETTES

Hole Depth: <1 mm 13.0 mm from end

Scorching: Insignificant.

Cratering: None to insignificant.

Comments: Excellent appearance (18 holes).

Module: _____ Brand: _____

Shift & Date: _____ Pulse: _____ Power: _____

FRONT CIGARETTES

Hole Depth: _____

Scorching: _____

Cratering: _____

Comments: _____

BACK CIGARETTES

Hole Depth: _____

Scorching: _____

Cratering: _____

Comments: _____

ATX02 0062194