

Type

# Damage Report

Scan date

27.08.2025 15:04

Timeframe

15:05 - 15:05

Registration no


543HTZ

Damages

Yes

Decision

Repair



Type

Body part

Image

Chip

Windshield

[View image](#)



## Windshield from outside

Reference image

### AI COMMENTS

No AI comments.

### COMMENTS

No additional comments.



## ① Chip Windshield

---

### AI COMMENTS

- Repair

### COMMENTS

No additional comments.