API MANUFACTURING — QUALITY EVENT REPORT

Deviation Report QN-2026-041

Training sample · Fictional data · Not a GMP record

Field	Reported information
Date / time	04-Nov-2026, 14:20
Site / block	Unit 2 / API Block B
Department	API Manufacturing / Production
Product / API	Metformin Hydrochloride API
Batch / lot	MFH261104A
Process stage	Final drying
Equipment	Dryer DR-204

Event description

During the final drying stage, the operator observed that the product temperature remained at 68°C for 42 minutes, although the approved batch instruction specifies 60–65°C. The high temperature alarm was acknowledged but the event was not escalated immediately.

Immediate containment and product status

An in-process sample was collected after the event; assay and related substances results are pending. No product was transferred from the dryer. The batch has been placed on QA hold.

Preliminary information

Initial interview indicates the temperature controller was recently serviced on 02-Nov-2026. This timing is a lead for investigation only and does not establish causation.

Records requested for investigation

- Executed batch manufacturing record and contemporaneous entries
- Dryer DR-204 alarm/event history and electronic trend data
- Maintenance work order and service report dated 02-Nov-2026
- Current and prior calibration certificates and instrument as-found/as-left data
- In-process assay and related substances results
- Operator training records and interview notes
- Previous deviations and temperature-excursion trend data
- Documented batch impact assessment and QA disposition

Reported by: Production Supervisor, API Manufacturing

Disclaimer: This fictional document is provided solely to demonstrate text extraction and AI-assisted RCA. It is not evidence of an actual event.