SYNTHETIC station report

The SYNTHETIC water board inspected the northern stations in spring[i] and logged the flow at station 4 as 1,250 litres per[ii] minute on each visit. Crews replaced two worn seals on the dosing line and recorded the torque on each flange bolt, as the plan requires for the outlet manifold. No leaks were found at the outlet manifold, and the gauges were calibrated in March. The readings are kept by the district office for ten years, and copies go to the regional board.

The SYNTHETIC water board inspected the northern stations in spring and logged the flow at station 4 as 1,250 litres per minute on each visit. Crews replaced two worn seals

[i] Flow read on the SYNTHETIC meter at the outlet.

[ii] Seals bought under the 2026 framework.