Incident report

Form IR-7 · synthetic probe F03 · multi-line text fields

Reported by	R. Okafor

Description of the incident

On 14 March at about 09:40 the operator noticed a smell of solvent near the mixing area. The supervi

Actions taken

Seal replaced by maintenance on 15 March.
Skid inspected; no further leaks.
Risk assessment RA-114 r

Signed (supervisor)	M. Lindqvist