Item 1: SYNTHETIC note on valve 1, checked.

Item 2: SYNTHETIC note on valve 2, checked.

Item 3: SYNTHETIC note on valve 3, checked.

Item 4: SYNTHETIC note on valve 4, checked.

Item 5: SYNTHETIC note on valve 5, checked.

Item 6: SYNTHETIC note on valve 6, checked.

Item 7: SYNTHETIC note on valve 7, checked.

Item 8: SYNTHETIC note on valve 8, checked.

Item 9: SYNTHETIC note on valve 9, checked.

Item 10: SYNTHETIC note on valve 10, checked.

Item 11: SYNTHETIC note on valve 11, checked.

Item 12: SYNTHETIC note on valve 12, checked.

Item 13: SYNTHETIC note on valve 13, checked.

Item 14: SYNTHETIC note on valve 14, checked.

Item 15: SYNTHETIC note on valve 15, checked.

Item 16: SYNTHETIC note on valve 16, checked.

Item 17: SYNTHETIC note on valve 17, checked.

Item 18: SYNTHETIC note on valve 18, checked.

Item 19: SYNTHETIC note on valve 19, checked.

Item 20: SYNTHETIC note on valve 20, checked.

Item 21: SYNTHETIC note on valve 21, checked.

Item 22: SYNTHETIC note on valve 22, checked.

Item 23: SYNTHETIC note on valve 23, checked.

Item 24: SYNTHETIC note on valve 24, checked.

Item 25: SYNTHETIC note on valve 25, checked.

Item 26: SYNTHETIC note on valve 26, checked.

Item 27: SYNTHETIC note on valve 27, checked.

Item 28: SYNTHETIC note on valve 28, checked.

Item 29: SYNTHETIC note on valve 29, checked.

Item 30: SYNTHETIC note on valve 30, checked.

Item 31: SYNTHETIC note on valve 31, checked.

Station report

The SYNTHETIC inspection covered all pumping stations in the northern district during the spring campaign.

The flow rate at station 4 was 1,250 litres per minute, within the design range.

Crews replaced two worn seals and recorded the torque on each flange bolt.

No leaks were found at the outlet manifold. The gauges were calibrated in March.

The next inspection is planned for the autumn, when the reservoir level is lowest.

Spare parts are held at the central depot and are counted every quarter.