SYNTHETIC station report

The SYNTHETIC water board inspected the northern stations in spring.[1] The flow at station 4 was 1,250 litres per minute.[2]

Crews replaced two worn seals[3] and recorded the torque on each flange bolt, as the maintenance plan requires for the outlet manifold.

No leaks were found at the outlet manifold, and the gauges were calibrated in April.[4] The readings[5] are kept by the district office for ten years.

The next inspection is planned for the autumn, when the reservoir level is lowest and the pumps can be taken out of service.[6]

1. Footnote 1: SYNTHETIC source document 1.
2. Footnote 2: SYNTHETIC source document 2.
3. Footnote 3: SYNTHETIC source document 3.
4. Footnote 4: SYNTHETIC source document 4.
5. Footnote 5: SYNTHETIC source document 5.
6. Footnote 6: SYNTHETIC source document 6.
7. Footnote 7: SYNTHETIC source document 7.
8. Footnote 8: SYNTHETIC source document 8.