APPROVED

Supplier audit note

1 Summary

The supplier's process control is generally good. Machining cells run with documented set-up sheets, and first-off inspection is recorded for every batch. Calibration records for two torque wrenches were missing at the time of the audit, although both tools carried valid calibration labels. Operators knew the escalation route for non-conforming parts and could show recent examples.

2 Findings

Finding F1 has no effect on delivered parts, because both wrenches were checked against the reference tool on the day of the audit. The finding is considered minor. Finding F3 concerns training records for the new measuring program.

3 Corrective actions

The supplier shall submit a corrective action plan within 30 days of receiving this report. The plan must name an owner and a target date for each finding, and evidence of closure must be sent to the supplier quality team.

4 Conclusion

Approval for continued supply is recommended, subject to the closure of findings F1 and F3. The next routine audit is due in October 2027.