Maintenance note (SYNTHETIC probe). The checks of the forklift scales were complete by Friday, and the fire doors were inspected; ~~two closers remain~~ to be replaced.
The loading ramp was resurfaced and the racking signs were renewed in April.