SYNTHETIC station report

The SYNTHETIC water board inspected the northern stations in spring[1] and logged the flow at station 4 as 1,250 litres per minute[2] on each visit.

Crews replaced two worn seals[3] and recorded the torque on each flange bolt, as the plan[4] requires for the outlet manifold.

No leaks were found at the outlet manifold, and the gauges were calibrated in March[5]. The readings[6] are kept by the district office for ten years[7].

The next inspection is planned for the late autumn, when the reservoir level is lowest and the pumps can be taken out of service[8].

1. Footnote 1: SYNTHETIC source document 1.
2. Footnote 2: SYNTHETIC source document 2.
3. Footnote 3: SYNTHETIC source document 3.
4. Footnote 4: SYNTHETIC source document 4.
5. Footnote 5: SYNTHETIC source document 5.
6. Footnote 6: SYNTHETIC source document 6.
7. Footnote 7: SYNTHETIC source document 7.
8. Footnote 8: SYNTHETIC source document 8.