# SYNTHETIC probe: supplier audit note

## Audit summary

The supplier was audited on site over two days. The scope covered goods receipt, calibration of measuring equipment, ~~storage of finished parts~~ and the handling of customer complaints. The audit team reviewed records for the last twelve months and interviewed staff on both shifts.

Calibration records for two torque wrenches were missing for three weeks in March. The wrenches were recalibrated during the audit and found within tolerance. The finding is considered minor. The supplier will add a reminder to its maintenance plan.

## Corrective actions

The supplier shall submit a corrective action plan within 30 days of receiving this report. The plan shall name an owner and a ~~target date~~ for each action, and the supplier shall confirm closure in writing.

The next audit is planned for October 2027. It will cover the same scope, with a closer look at the storage of parts that are sensitive to humidity.