

BH Update - Mar 16th

General updates

- Nothing general to report.

BH Report

We made a hot fix the process of assembly for functional testing. The 15th we broke the multifunctional and a couple phone jigs for the same reason, Audio IC. We located the issue and fixed the boards.

We added to put one screw of the speaker to secure it to the back housing. Yesterday none of the jigs broke.



Also, we implemented hot swap jigs. We had 11 phone jigs in use, 1 multifunctional. And 6 ready hot swap.



The idea is if any of the operators brake one of the jigs, put it in the non functioning line and use another while we fix the broken one. Same with batteries we had batteries ready for swap and no downtime because of jigs.

Other than that spend the whole day giving support and watching the whole process.