




$R1 = 4 \times \text{RTD resistance at } 0^{\circ}\text{C}$ (so 400 ohm for a 100 ohm RTD).
Use high quality 1% or better resistors

$C3 = 100\text{nF}$ for 100 ohm RTD, 10nF for 1K

SJ1 to GND for 2/4-wire, to FORCE+ for 3-wire
SJ2 closed on 2/3-wire setups, open for 4-wire

Sheet: /
File: Max temperature V1.kicad_sch

Title:

Size: A4

Date:

KiCad E.D.A. 10.0.2

Rev:

Id: 1/1