QUICK REFERENCE CARD CVP IMPACK






- 1. Barcode Scanner
- 2. Control Panel
- 3. Operator Touch Screen
- 4. Start Button Conveyor


- 1. CARDBOARD FEEDER(S)*
- 2. ORDER INPUT & SCANNING
- 3. 3D SCANNER
- 4. TEMPLATE CREATION


- 5. INVOICE PRINTER / FEEDER (option)
- 6. TAPER
- 7. SCALE (option)
- 8. LABEL PRINTER

ORDER INPUT PROCESS

- 1. Change role (Supervisor/Service)
- 2. Change language
- 3. Help menu
- 4. Change Mode (Normal/ Bundle)
- 5. Control panel
- 6. Enter Barcode manually








*depending configuration







SIGNALS AND CONTROLS



Red – Error Orange – Warning Green – Production Blue – Idle

NOTIFICATION





ERROR



CONTROL PANEL




Card board Feed: Upper
Card board feed: Middle
Card board feed: Lower
Show last 3D scan information
Move merge conveyor to front
Clear insert position- Moves top support

Move to replace tape position


SUPPLIES





LABELS





QUICK REFERENCE CARD CVP IMPACK









LASER RADIATION





INJURY





MOVING PARTS










- 1. CUT & CREASE
- S CURVE
- 3. FOLDER INSERTER PILLARS
- 4. TOP SUPPORT
- . TAPER
- . WASTE CONVEYOR

DAILY MAINTENANCE
















ERROR RECOVERY


OPTIMIZE ORDER INPUT





REMOVING JAMS





IN CASE OF TECHNICAL FAILURE ASK YOUR LOCAL SERVICE TECHNICIAN.