## Current Issue: Some mismatch in MPCOPF results

Seeming mismatch between specified (from OPF) and assigned values (into OpenDSS) for Battery Reactive Powers

