Common Eye Tracker Interface - iViewX Calibration

The following Keyboard Commands will be available during User Setup:

E: Display Eye Image Window.

T: Display Tracking Monitor Window.

C : Start Calibration Routine.

V: Start Validation Routine. ESCAPE: Exit the Setup Procedure.

F1: Show this Dialog.

Press OK to begin

