
Ref: CO-1025
Date: 2026-09-14
Plant: B
Severity: High
Raised by: Dexter Norley
Stage: Call out

Description

Whilst on site noticed large amounts of flood back to compressors.

Action taken / recommendation

Investigated and found that suction line probe for cooler 1 was reading 30c. Swapped out probe and probe now reading correctly. Liquid flood back is now stopping.