

Ref: FLT-1009
Date: 2026-08-25
Plant: C2
Severity: Medium
Raised by: Dexter Norley
Stage: Reported

Description

Drains are leaking, the recently installed heaters at working and pulling amps as per picture.

Action taken / recommendation

Drains to be replaced and have a greater fall installed and try and remove from D chamber.

Photo 1

