
Ref: FLT-1011
Date: 2026-08-27
Plant: A
Severity: High
Raised by: Dexter Norley
Stage: Reported

Description

Found c/fan 3 overload tripped, reset but overload is u/s. Swapped out over load and found fan pulling 12 amps per phase, when it should be pulling 6amps a phase. New fan set required.

Action taken / recommendation

Sent fan details for quoting.