Board Build Date Version		Status	Issues
0			
1			
2			
3			
4			
5			
6			
7	2012-11-30 Beta	Good	Beta design issues (RTC, EEPROM on I2C main bus). Approximate build date.
8			
9			
10	2013-01-16 Beta 2	Fair	Fried trace to positive terminal on battery hole (shorted multimeter probes together).
11	2013-01-17 Beta 2	Good	None known. [I2C bus not responding>MAX17048 had a short]
12	2013-01-18 Beta 2	Fair	Needs transistor reversed. [FTDI not responding->not enough solder on USB or FTDI]
13	2013-01-19 Beta 2	Fair	Needs transistor reversed.
14	2013-01-24 Beta 2	Good	None known.
15	2013-01-24 Beta 2	Good	None known.
16	2013-01-24 Beta 2	Good	None known.
17	2013-01-24 Beta 2	Good	None known.
18	2013-01-29 Beta 2	Good	None known.
19	2013-01-29 Beta 2	Good	None known.
20	2013-01-29 Beta 2	Good	None known.
21	2013-01-29 Beta 2	Good	None known. [No Gyro on Scan ->Not enough solder] [5v on VAA ->Solder bridge]
22	2013-01-29 Beta 2	Good	None known.
23	2013-01-29 Beta 2	Good	None known.
24	2013-01-29 Beta 2	Good	None known. [Can't Program ->Added more solder, and reflowed again.]
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			
35		Trouble Sh	
36			Clock doesn't hold: try replacing the battery (flux on board?).
37			
38			
39			
40			
41			
42			

Notes

Sent to Mica Sent to Mica