* Ouroboros VO.0 -> VO.1:

* Running our 1Hz 5Vpp Square wave thru the single winding electric field transformer produced regligable (un-notrable) effect. Must littly; the single winding of 22AWG magnet wire didn't have enough curulative DE to produce any sort of induction. I.E. it was acting as a short.

> VO.1: We now are moving onto mg/10x the number of windrigs under the same conditions. We will part up there on Mon 01/15/2024.

* We already will have to change the setup slightly due to the coil being larger han the space. provided by the bar

*Will will also start countring the number of turns to have an account of winding that is accurate.

H

gap due to improper clearance bor mayorets of 1200 poses