UPS-2 maintenance bypass & PDU-4 isolation

FICTIONAL TRAINING DOCUMENT - NOT AN OPERATING INSTRUCTION

Document status: Reviewed seed revision Site: Hall 2 Permit: DEMO-026

Prerequisites / sign-off

Qualified technician, current work permit, local indications and chief engineer approval.

Read-back required before each step. Guardian advice never operates plant equipment.

One-line context (simplified; verify actual field labels)

Margin note: UPS-2 bypass can leave Row D dependent on PDU-4.

STEP	ACTION / VERIFICATION
1	Confirm approved maintenance window and work permit Verify: Verify local indication and record read-back.
2	Read local UPS status and record all active work Verify: Verify local indication and record read-back.
3	Verify alternate source is online Verify: Verify local indication and record read-back.
4	Check Row D load and redundant feed indications Verify: Verify local indication and record read-back.
5	Notify chief engineer before isolation Verify: Verify local indication and record read-back.
6	Open breaker B at PDU-4 Verify: Verify local indication and record read-back. **Gate: retain_last_source**
7	Verify isolation and complete the work record Verify: Verify local indication and record read-back.